


Photograph from Archives circa 1870

MEYER & MEYER



General Overview

Modify Front Area



Rooftop Addition



Rear Yard Addition



Existing Condition Photos



Plans




Details



Sun Study









Modify Front Area Way

12/19/2016 Example of existing gardens Beacon st



Existing Front Yard- Plan





Proposed Front Yard- Plan

Modify Front Area Way










.8. Replace existing non-original window and door ground level, Beacon St

7d. Existing railing to remain


- 7b. Replace existing non-original metal railing

- 7d. Existing railing to remain,
 Beacon St.
- 8. Replace existing non-original window and door ground level Beacon St.
- 7b. New granite curb at new 5 garden,
 Beacon St.
- 7a. New low cast iron railing,
 Beacon St.
- 7c. New brick paver sidewalk,
 Beacon St.





MEYER & MEYER
ARCHITECTURE AND INTERIORS



7a. New Cast Iron King

Metals Railing

7a. Install news low custom cast iron railing 7b. Install new low custom granite curb 3 1/4" 3/4" 3 1/4" 7c. Install new brick pavers over concrete

Modify Front Area Way

Existing View from Corner of Boston Public Garden on Beacon St and Charles St




Proposed View- Addition not visible from street level



 75 Beacon street proposed facade

 75 Beacon street existing facade




Location of where photo was taken










- 5c. Rooftop addition, install new wood windows and door, Beacon St.
- 6. Remove existing nonoriginal elevator shaft
- 6a. Line of new rooftop addition
- 12. Restore existing windows 4th floor, Beacon St.
- 11. Restore existing windows3rd floor, Beacon St.
- 10. Restore existing windows and copper roofs 2nd floor, Beacon St.
- Restore existing window 1st floor, Beacon St.
- 8. Replace existing nonoriginal window and door ground level, Beacon St. —
- 7. Install new brick sidewalk, garden with granite curb, and low cast iron rail, Beacon St.












Existing View from Brimmer Street



Proposed View from Brimmer Street



Proposed Condition at Bryon Street



Existing View from River Street



Existing condition at Bryon Street

Proposed View from River Street



Proposed Addition at



Location of where photo was taken

Comparing our original proposal (left) to our new proposal (right)-

Previous Proposed View from River Street




New Proposed View from River Street



 Previous Proposed Condition at Bryon Street New Proposed Condition at Bryon Street




6a. Line of new rooftop addition



6. Remove existing non-original elevator shaft.

5. New common brick rooftop addition, install new wood windows and door, Byron St.

- 5a. New black painted railing, Byron St.
- 5b. Screening for Mechanical units (beyond), Byron St.Byron St.
- 4. New common brick wall and wood windows to add stories above, Byron St.
- Level top of existing wall to match adjacent building, Byron St.
- Restore existing wood windows, Byron St.
- 1a. Remove existing fire escape, Byron St.
- Remove non-original door and install new wood garage doors, Byron St.





- 3a. Replace existing roof deck and metal railing with new recessed roof deck and new wrought iron black railing, Byron St.
- 3. Level top of existing wall to match adjacent building (tooth in repurposed brick to existing parapet wall. Install new copper parapet cap, Byron St.


- 1e. Remove steel bars.
- Remove non-original wood door, Byron St. Install new wood garage door, Byron St.
- 1 d. Replace non-original window, with fixed wood window to profile to match existing wood windows, Byron St.











- 3a. Replace existing roof deck and metal railing with new recessed roof deck and new wrought iron black railing, Byron St.
- 3. Level top of existing wall to match adjacent building (tooth in repurposed brick to existing parapet wall. Install new copper parapet cap, Byron St.
- 4a. Rear Yard Addition New common brick wall and wood windows (not visible from public way)
- 1 d. New painted metal railing in background, Byron St. (not visible from public way)
- Install new painted wood garage doors, sandstone lintel (color to match existing brick), Byron St.
- 1c. Replace existing non-original with fixed wood window, profile to match existing above, Byron St.

Rear Yard Addition





Rear door, Byron St




Bay window, 2nd Floor, Beacon St



BHAC Submission - September 27, 2017

Bay window, 1st floor, Beacon St



Bay Window, 1st floor, Beacon St.



Front door, Beacon St.



Existing Condition Photos



Front door, Beacon St.



Front basement door, Beacon St.



Rear Elevation,Byron St






Rear Elevation, Byron St.




Front Elevation, Beacon St.

Existing Condition Photos







Existing Condition Photos

MEYER & MEYER ARCHITECTURE AND INTERIORS

STREET

BEACON


Sidewalk at Beacon St.

PLAY ROOM OFFICE

16'

8'

32'





Ground Floor Plans



BYRON STREET

1. Remove non-original door and install new wood garage doors, Byron St.






16'


32'



DRESSING MASTER BATH LAUND BEDROOM BEDROOM BEDROOM BEDROOM





3a. Replace existing roof deck and metal railing with new recessed roof deck and new wrought iron



32'

16'







Fourth Floor Plans

32'

16'



MEYER & MEYER



ALL UNITS

F.S.

7 OF 10


FAX # (508)880-8828 WWW.BOSTONSASH.COM

D. WINDOWS, SASH, AND SHUTTERS will meet the following requirements

- 1. Original or historic elements including existing openings, sash, glass, lintels, sills, shutter hardware, frames, surrounds and brick molds shall be retained unless demonstrated to be beyond repair, in which case they shall be duplicated in the same material and style. No changes in dimensions are to be made to jambs or sashes.
- 4. Windows have true divided lights. The width and profile of the muntins on the exterior of the window shall match the existing.
- 5. Through-glass muntins are required.
- 6. Clear, insulated glass may be permitted (the width of the replacement muntin matches the width of the historic muntin). The window must have true divided lights. The spacer bar must be dark. The depth of the muntin on the
- exterior of the window must be no less than 3/8 inch. The muntin must have a putty line (trapezoidal) profile on the exterior of the window. The material can be putty or wood.
- 7. Only clear, non-tinted glass shall be used (except to replace original stained glass).
- 8. Weights and ropes or chains can be used; spring balances can be used that are set into the wood jamb. Vinyl jamb liners must not be seen. If they are proposed, the top sash will be fixed shut and the lowerportion of the jamb will have a wood cover. No jamb liner will be visible while the window is closed.
- 10. Exterior combination storm windows may be acceptable provided the installation has minimal visual impact upon the original fenestration. Storm windows shall have narrow perimeter framing (which does
- not obscure the glazing and sight lines of the primary window). The meeting rail of the storm sash must align with that of the primary window. The painted finish on the storm window frame must match the color of the window trim. Exterior storm windows will not be approved on arched windows, leaded glass, faceted frames, or bent glass. Interior storm window panels may be an appropriate alternative to exterior combination storm windows.
- 11. Caulk colors and paint colors must be approved. Wood windows must have a paint finish and not a factory applied finish that can not be repainted. The caulk must not cover the profile of the brick mold.
- 12. Shop drawings must be submitted illustrating all of the above requirements.


Window Details





Window Details





New Painted Metal Railing

Proposed Cornice at secondary facade on Byron Street


Proposed Corbel


New sandstone to match Lintel to match color of existing lintel from Byron Street

> New wood window to match existing Byron Street profiles

Painted Wood Flat Sash 6 over 6 true divided light windows









Existing Plan View- Summer Solstice 7am

Proposed Plan View- Summer Solstice 7am









Existing Plan View- Summer Solstice 12pm

Proposed Plan View- Summer Solstice 12pm









Existing Plan View- Summer Solstice 5pm


Proposed Plan View- Summer Solstice 5pm












Existing Plan View- Winter Solstice 7am

Proposed Plan View- Winter Solstice 7am









Existing Plan View- Winter Solstice 12pm


Proposed Plan View- Winter Solstice 12pm











Existing Plan View- Winter Solstice 5pm

Proposed Plan View- Winter Solstice 5pm



