


#### Windows:

The windows on level 2 and 3 are original windows with curved sashes w/ factted lites at center mullion. Windows will be restored and a clear storm window will be installed in front in front of existing, with horizontal muntin to alignt with middle sash.



Provide details/scope of masonry repairs - methods and materials:

### **Masonry Cleaning.**

- Sample cleaning of discreet locations using various means and methods including different products to be completed and reviewed in advance.
- Typically use Prosoco family of cleaning products varying from mild to stronger cleaners depending on requirements of the project and results achieved.
- Building to be washed down with water only to wet surfaces initially. Diluted cleaning product (dilution rates to be determined during sample phase) to be applied to surface and scrubbed into wall. Wall to be rinsed with water.

#### Repointing.

- Typically, we complete samples of repointing for review and approval of color and finish.
- Existing mortar joints to be cut out using a combination of mechanical grinders and hand tools to complete head joints.
- Mortar typically Type N for repointing or a custom mix to match existing.

### **Brownstone Repair**

• Brownstone to be cut back to stable material and replaced with concrete/stucco mix and brownstone coat.

Door:

### Door is not original - We will repair if possible or replace as indicated



**Front Door** 




511 Mass Ave. - 1972









8 Railing at Front - Typ Section 1" = 1'-0"













Lightwell to provide egress window for bedroom. Detail Below.








Garden Level Windows @ Bow






**Existing Cornice Non-existent** 

515 Mass Cornice to be Replicated



Bay Windows @ 507 Mass Ave - Will Replicate





PAGE 11




### **Deck Railing**


Deck will be composite decking with black metal picket railing 3'-6" off of deck. Deck is positioned at the back of the poroperty to ensure deck railing can not be seen from street. See additional details below.





### Existing & Demo - Roof







Proposed View 2

