



figure 1 | locus plan



figure 2 | Commonwealth Avenue Facade



figure 3 | Private Alley Facade



figure 4 | view from Leamington Road (view 1 on locus plan)



figure 5 | window A exterior view



figure 6 | window A interior view



figure 7 | window A exterior deterioration



figure 8 | window A interior deterioration



B

figure 9 | window B exterior view
Showing added trim in addition to brick mold.



figure 10 | window B interior view
Showing modified opening



figure 11 | window B exterior sill
Showing added window casing



figure 12 | window B interior view
Showing damaged sash cord



figure 13 | window C exterior view
After overhead door was removed



figure 14 | window C interior view
Showing overhead door



figure 15 | existing Private Alley Facade



figure 16 | proposed Private Alley Facade

