South End Landmark Historic District Commission

Project Review Hearing

34 East Springfield Street

February 2, 2021



Brief history of 34 East Springfield Street

Ca. 1865

Building constructed as a single-family dwelling

Ca. 1930

Building converted into a multi-family dwelling, remains multi-family throughout the 20th century

1980

Building acquired by BHA and converted into 4 affordable housing units. Windows and doors were replaced and other modifications made, later garden level unit converted to mechanical space

2009

Units vacated and has remain vacant since, deferred maintenance continues



1972 photo of facade



Current facade

Proposed Project

- State and Federal Historic Tax Credit rehabilitation of the building into 5 affordable housing units with one unit being handicap accessible
- Reconstruction of the façade due to continued water infiltration of the façade causing bricks to bow outward creating a safety hazard and deteriorated lintels. Modest masonry repairs and repointing at the rear elevation and the installation of 6 small vents for ductwork
- Replacement of modern windows matching historic muntins patterns.
 Replacement of modern entrances with historically sensitive entrances with historic front entrance retained and repaired with new entry hood
- Replacement of the rear dormer with mechanical equipment on top

Deterioration and issues at 34 East Springfield Street







View of thirdfloor unit, cavity
between inner
and outer wythes
due to water
damage
bowing out outer
brickwork

Proposed project
would
disassemble and
reconstruct the
façade with
existing and
matching brick

Deterioration and issues at 34 East Springfield Street



View of skimcoated and damaged lintels to be replaced with matching lintels

Granite steps to be retained and reset with new metal handrails, doors will be retained and repaired with new entry surround. New windows will be installed with 2/2 pattern



Deterioration and issues at 34 East Springfield Street



View of garden level entrance to be replaced with arched metal gate and new entry door. Steps and fence/railing to be retained

Masonry at rear elevation is in much better condition will be repointed and repaired. Entry door will be replaced and dormer will be replaced




Precedent images for 34 East Springfield Street




View of 32 East
Springfield Street
used as a
precedent for the
proposed entry
surround

View of garden level entry at 30 East Springfield Street used as precedent for garden level gate.

























Proposed Plans Facade







Proposed Plans Rear Elevation






Dormer will be replaced with a larger dormer similar to a neighboring building with equipment on top




NEIGHBORING REAR DORMER

Proposed Plans Roof




Proposed Plans Roof


Dormer will be clad in wood shingles and trim with paired aluminum windows similar to neighboring property



Proposed Plans Window Shop Drawings



Proposed Plans Site Plan



At the rear along the alleyway an accessible entrance for the garden level unit will be created with a handicap parking spot with pervious pavers and a concrete accessible walkway. The boards on the wood fence will be replaced and the existing chain-link fence removed.