


Rear of 125 W. Concord St


Drawing is of Current Conditions as of Oct. 2025
Wrought iron landings & railings not shown, but exist



*Drawing is not to scale, for illustrative purposes only

Rear of 125 W. Concord St

Drawing is of proposed change with middle window removed
brought iron landings & railings to remain unchanged
Window molding to be wooden brick mold
No change in size or locations of windows & door
20'3"



Brick

* Drawing is not to scale, for illustrative purposes only