34 Beacon St – Scope of Work

Roof

- Remove upper railing at upper roof
- Remove Roof Hatch.

Window

- Remove/Replace (2) Dormer windows on upper level
- Replace (3) 6 over 6 windows with (3) 6 over 6 windows.
- Replace (1) 2 over 2 windows with (1) two over 2 window.

Flag Pole

• Replace existing in kind






Roof Scope

Remove upper railing at upper roof

Section C

Remove and dispose of existing rails and pitch pockets at the perimeter of the flat roof.

Alternate (Previously Approved): Cut the existing post at the base just above the existing pitch pockets prepare, paint, and reinstall by welding. Repair pitch pockets and fill to receive new railing.



South Elevation – Beacon Street



North Elevation



Roof Scope

Remove roof Hatch

Section 10: Hatch Detail Section 11: Roof Hatch Infill and Removal detail.



NEW TPO ROOF SYSTEM:


INSULATION, (4'X4' MAX BOARDS)

W/BONDING ADHESIVE

• TPO 80 MILL REINFORCED FIELD MEMBRANE FULLY ADHERED

•NEW 5/8" FIRE RATED COVER BOARD FULLY ADHERED TO

• PROVIDE NEW CLOSED CELL TAPERED POLYISOCYANURATE INSULATION FULLY ADHERED, (4'X4' MAX BOARDS); WITH STAGGERED





Window Scope

Remove/Replace 2 x Dormer windows on upper level Elevator Window: Non original window, propose a 6 lite set piece. Office Window: Non original, Replace with 6 over 6. **Both are not visible from public way**



DORMER ROOF AT BACK OF HOUSE - EXISTING 1 SCALE: 3" = 1'-0"





OFFICE WINDOW - EXISTING

3

SCALE: 3" = 1'-0"

REMOVE EXISTING WINDOWS AND REPLACE WITH WINDOWS AS SPECIFIED




Window Scope


Remove/Replace (3) 6 over 6 non original windows on Joy Street with (3) 6 over 6 windows.

















Window Scope

Remove/Replace (1) non original 2 over 2 windows at the Garage










Historic Window & Door Holdings 12 Forest Road, Junction 123&123A P.O. Box 138 Alstead, N.H. 03602-0138







SEA-DAR CONSTRUCTION