

### **PROJECT INFORMATION**

### **ADDRESS:**

6 Louisburg Square, Boston MA

### **RUHL STUDIO ARCHITECTS**

281A Mt Auburn St, Watertown, MA 02472 P. 617.744.8722 E. Will@ruhlstudio.com

### **CAFCO CONSTRUCTION**

77 Charles St, Boston, MA 02116 P. 617.426.7600 E. Aamontea@cafcoconstruction.com

### MCLD, LLC

411 Main St, Stoneham, MA 02180 P. 617.905.2246 E. Matthew@matthewcunningham.com

### **SCOPE OF WORK**

### 1. RESTORE OR REPLACE IN KIND

Note: All restoration and replacement shall be compliant with Historic Beacon Hill District Architectural Guidelines

- Repair and/or reconstruct select areas of Masonry Façade
- Reconstruct both **Chimneys** to match existing details
- Repair/replace existing **Slate Roof**
- Replace non-original Windows to match original details
- Replace **Door Frame and Sidelites** (Restore existing door slab) to match original details
- Repair existing Metal Rail at roof

### 2. MODIFICATIONS


- Install EV charger at street
- Replace non-original **Door at Garden Level** and recess 2'
- Paint existing first floor door to Louisburg Square, color 'Rembrandt Red"
- Install new **Door Systems** at garden and first floor (not visible from public way)
- Install new **Recessed Door System** to replace non-original windows at 5th floor rear dormer.
- Replace non-original **Skylights** with singular Low-Profile Skylight
- Install **HVAC Equipment** on roof (not visible from public way)

### 3. APPENDIX A


- Existing window photographic documentation

**BHAC SUBMISSION**YOUNISS RESIDENCE – 6 LOUISBURG SQUARE, BOSTON











**HISTORICAL IMAGES**6 Louisburg Square, Boston, MA 02108


YOUNISS RESIDENCE – 6 LOUISBURG SQUARE, BOSTON SEP 30th, 2020











## 1. RESTORE OR REPLACE IN KIND - FRONT FACADE

**Existing Conditions - Proposal** 

RUHL
STUDIO
ARCHITECTS







#8 Louisburg Sq (North)

## 1. RESTORE OR REPLACE IN KIND - REAR FACADE **Existing Conditions - Proposal**

RUHL **STUDIO ARCHITECTS** 

Remove existing non-original skylights;

low-profile skylights

New bi-folding metal

doors set back 3'-0" from face of brick

Repair / refinish existing

Replacement fire excape/balcony


fire escapes

#4 Louisburg Sq (South)

New balcony and stair to grade

Replace in kind Modifications

replace with













1. RESTORE OR REPLACE IN KIND - MASONRY AND RAILING RESTORATION Existing Conditions





# 1. RESTORE OR REPLACE IN KIND - WINDOWS & DOORS REPLACEMENT Proposal










Existing conditions photos






Schematic renderings




# 2. MODIFICATIONS - EV CHARGING STATION Proposed Strategy Plan





# 2. MODIFICATIONS - DOOR AT GARDEN LEVEL Basement Door Setback











**2. MODIFICATIONS - DOOR SYSTEMS** Product Images

YOUNISS RESIDENCE – 6 LOUISBURG SQUARE, BOSTON SEP 30th, 2020








## 2. MODIFICATIONS - RECESSED DOOR SYSTEMS

Rear Facade / Close-up View at 5<sup>th</sup> Floor
YOUNISS RESIDENCE - 6 LOUISBURG SOUARE, BOSTON









# 2. MODIFICATIONS - MECHANICAL EQUIPMENT ON ROOF Dormer Visibility from Mt Vernon street



Individual window photographic documentation to be provided



## 3. APPENDIX A

Existing Window Photographic Documentation: East Facade



Individual window photographic documentation to be provided





## 3. APPENDIX A

Existing Window Photographic Documentation: West Facade

