

78 Beacon St – Front Entry Restoration

6/4/2025

Description of Work



Granite Curbs:

- Existing granite curbs have deteriorated in several locations.
- Repair curbs using dutchman's where applicable with granite of matching size, color, and finish.
- If curbs cannot be replaced using dutchman's, the stone will be replaced with new granite in matching size, color, and finish
- Existing metal components will be removed and reinstalled.
- Façade is excluded from scope

Decorative Exterior Sconces:


Replace existing sconces with new fixtures that replicate existing style & finish

Front Steps:


 Repoint existing staircase using mortar color and composition tha tmatches the original in both texture and color



Existing Conditions – Granite Curbs










Existing Conditions – Front Entry







Existing Conditions – Exterior Lights





New Front Entry Pendant



TEAR SHEET

Front Entry Pendant Replacement



Darlana Small Hanging Lantern


Item # CHO 5084BZ

Designer: Chapman & Myers

Height: 18.5" Width: 12.5" Canopy: 6" Round Finishes: BZ - Bronze

Glass Options: CG - Clear Glass Socket: 4 - E12 Candelabra

Wattage: 4 - 40 C11 Weight: 19 Pounds ©EFC DESIGNS









TEAR SHEET

Garden Front Entry Sconce Replacement



Darlana Mini 3/4 Wall Lantern

Item # CHO 2045BZ-CG

Designer: Chapman & Myers

Height: 10" Width: 6.5" Extension: 6"

Backplate: 5.5" x 7" Trapezoid

Finishes: BZ - Bronze

Glass Options: CG - Clear Glass Socket: E12 Candelabra

Wattage: 60 C11 Weight: 6 Pounds ©EFC DESIGNS

