Report for Intensive (Locational) Archaeological Survey at the
Malcolm X / Ella Little-Collins House
72 Dale Street, Boston (Roxbury), Massachusetts

Joseph Bagley
Andrew Glyman
Sarah Johnson

2018
City of Boston Archaeology Program

Cover: Compilation of images illustrating (left to right) Ella and Malcolm Little at house site in 1940s, mid-century plastic eyeglasses frame, 18th century staffordshire slipware from site, and excavation unit 1.

Report for Intensive (Locational) Archaeological Survey at the Malcolm X / Ella Little-Collins House 72 Dale Street, Boston (Roxbury), Massachusetts

Joseph Bagley
Andrew Glyman
Sarah Johnson

Submitted by:
City of Boston Archaeology Program
Boston Landmarks Commission
Environment Department
City of Boston

To:
Malcolm X / Ella Little-Collins Foundation
72 Dale Street Roxbury, MA

2018

Table of Contents

Table of Contents **3**

List of Figures **7**

Abstract **13**

Acknowledgements **14**

Introduction **15**

Introduction 15

Compliance with Legislation 18

Project History 18

Personnel 18

Site Background History **19**

Native American History of Site 19

Post-contact History of Site 19

1630-1776 72 Dale Street History 19

Post-Revolutionary War History of 72 Dale Street 22

1840-1940 History of 72 Dale Street 25

Little-Collins History 28

Ella Little-Collins and Malcolm X 32

Field Results **38**

Intensive (Locational) Archaeological Survey 38

Project Area Description 38

Walkover Survey 55

GPR Results 56

Utility Line Survey 57

Unit Results 58

STP N117 E081 58

STP N117 E074 58

STP N111 E072 58

STP N110 E084 58

STP N110 E081 62

STP N110 E079 63

STP N109 E102 63

STP N108 E089 63

STP N108 E086 63

STP N106 E094 66

STP N106 E089 66
STP N106 E087 67
STP N103 E095 67
STP N099 E084 68
STP N099 E082 68
Unit 1 68
Unit 2 70
Unit 3 72
Feature Results 74
Feature 1 74
Feature 2 79
Feature 3 79
Feature 4 79
Feature 5 80
Feature 6 81
Feature 7 81
Strata Results 82
Surface/Developing A 82
Cobbles 82
Utilities 82
Brick Vault Trench Fill (Feature 7) 82
Fill 1 Over Cistern (Feature 4) 82
Fill 2 Over Cistern (Feature 3) 83
Utility Fill 83
Foundation at Rear of Property (Feature 6) 83
Feature 6 Interior Sand Fill (Unit 3.2 Str 6) 83
Feature 6 Organic Fill (Unit 3.2 Str 8) 83
Feature 6 Ash Fill (Unit 3.2 Str 9) 83
Outbuilding Foundation (Feature 6) 83
Post Hole (Feature 1) 83
Post Hole Coal Ash (Feature 1 Str 1) 83
Post Hole A Soil Fill (Feature 1 Str 2) 83
Construction related 83
Redeposited B 83
Foundation Builder’s Trench 84
Redeposited Foundation Soil 84
Inverted A 84
Gravel Fill 84
Rock Fill 84

Rubble Fill 84
Sand Fill 84
Slag 84
Fill 84
Buried APZ 85
B1 85
B2 85
C 85

Laboratory Methods 86

Analysis Results 87
Site Results Summary 87
Surface and Developing A 87
General surface collection 88
Berm Below Door on East Side of the Addition 109
Berm on East Foundation of Main Building 114
Material from Bulkhead 126
Rock Garden 128
Alley on Grid-North side for GPR Survey 131
Screened Backdirt 132
Unit 1 136
STP N099 E84 Level 1 0-10, MXH 126 137
Gravel Fill 137
Post Hole 138
Coal ash core (Feature 1 strata 1) 138
A-soil fill (Feature 1 strata 2) 138
Cistern and Utility Fills 139
Cobblestone Pavement 139
Foundation Builder's Trench 139
Inverted A soils 139
Outbuilding Foundation (Feature 6) 139
Sand Fill (Unit 3.2 Strata 6) 140
Sand Fill 2 (Unit 3.2 Strata 7) 140
Organic Fill (Unit 3.2 Strata 8) 140
Ash Fill (Unit 3.2 Strata 9) 143
Buried Plowed A 144
Buried Plowed A Dating 144
Architecture 149
Arms 149

Food and Beverage 149
Food Acquisition 149
Food Consumption 150
Food Preparation 150
Food Service 150
Food Storage 154
Heating, Plumbing, and Lighting 154
Industry and Trade 154
Medical 154
Personal 155
Recreation and Leisure 157
Literacy, Arts, and Education 159
B1 160
B2 160
C 160

Discussion 161

Conclusions and Recommendations 167

References Cited 168

Appendix A- Occupancy Documents 171
City of Boston Tax Records 171
Census Data 175
Boston City Directory 1869-1981 176

Appendix B- Provenience Context Code Guide to Malcolm X Site 189
Context codes organized by provenience 189
Proveniences listed in order by context code 198

Appendix C- Artifact Catalog 207

List of Figures

Compilation of images illustrating (left to right) Ella and Malcolm Little at house site in 1940s, mid-century plastic eyeglasses frame, 18th century staffordshire slipware from site, and excavation unit 1.....Cover
Figure 1-Project area at 72 Dale Street in red..... 15
Figure 2- Map of 72 Dale Street property with excavations labeled..... 17
Figure 3 - Withington map of property. 72 Dale Street would be in the right parcel. Outline of right parcel measures 17 acres..... 23
Figure 4- Detail view of Withington map with what is presumed to be the Seaver house digitally enhanced from rectangular impressed mark (without ink) in red. Highly approximate boundaries of parcel indicated in white on modern aerial view from google.com..... 24
Figure 5- Malcolm Little (left) with friends and Ella Collins (right) in a Boston Park in 1941. (Image Credit: Collins 1998)..... 33
Figure 6- Malcolm and Ella Little at 72 Dale Street in 1941 near the location of excavation unit 1. (Photo credit: Collins 1998)..... 34
Figure 7- Malcolm Little in driveway at 72 Dale Street in 1941. (Photo credit: Collins 1998)..... 35
Figure 8- 72 Dale Street as it appeared in the mid 20th century with Ella (forefront) and her aunt, Sarah Little (on porch). (Photo Credit: Rodnell Collins)..... 35
Figure 9: Map of project area with individual images keyed in photo…..... 39
Figure 10- 1, view of front yard and porch..... 40
Figure 11- 2 view down rock garden to south of driveway..... 41
Figure 12- 3 View to southeast corner of project area showing driveway intersection with Dale Street (see Figure 7 for 1941 view)..... 42
Figure 13- 4 View towards front of yard in eastern portion of project area showing Dale Street homes and driveway..... 42
Figure 14-5 View of front yard with gas line marked by Dig Safe in yellow. Note Dale street and front porch of 72 Dale Street..... 43
Figure 15- 6 View south from front yard looking towards driveway with Dale and Walnut streets visible in upper left corner. Note historic maker for 72 Dale Street on granite block..... 44

Figure 16-7 View of northeast corner of property showing side of porch stairs looking west down alley beside house..... 45
Figure 17-8 View of southeast corner of house showing gas connection, foundation, and trellis-style cover under front porch..... 46
Figure 18- 9 view towards rear of yard from south yard of main house showing 72 Dale Street home and foundation..... 46
Figure 19- 10 View to west from south yard showing unpaved area of driveway, dirt pile in front of garage (under blue tarp), garage, rear ell, and a small portion of rear (west) yard..... 47
Figure 20- 11 View southwest from southern yard area at dirt pile (under tarp), and rear portion of driveway..... 47
Figure 21- 12 View from southern yard to southeast showing driveway and eroded portion of yard formerly occupied by trees..... 48
Figure 22- 13 View from rear portion of the yard showing back of dirt pile (blue tarp) and front of garage protected by brown tarp..... 48
Figure 23- 14 View from south of rear ell towards western (rear) yard. Buried electrical line marked in orange spray paint..... 49
Figure 24- 15 View of rear door on south facade of the rear ell on 72 Dale Street. 49
Figure 25- 16 View of expanded bulkhead area where soils in dirt pile originated. View is of the rear of 72 Dale Street and rear ell..... 50
Figure 26- 17 View west to rear yard between rear ell of 72 Dale (right) and garage (left)..... 50
Figure 27-18 View of southwestern corner of house showing corner of rear ell (left), trash collection container (lower left), driveway (upper right), and garage (left). Orange spray paint marks buried electrical line..... 51
Figure 28- 19 View behind Garage and western edge of property..... 52
Figure 29- 20 View of rear yard looking towards northwest corner of yard with concrete supports for former deck visible..... 53
Figure 30- 21 View of rear of ell to 72 Dale Street showing boarded-up door and ghost of staircase to second floor deck. View also shows rear yard of home, site of unit 3.
……...53

Figure 31-22 View east down alley along northern edge of property, 72 Dale street to right..... 54
Figure 32- Map of surface collection areas..... 55
Figure 33- GPR Survey results overlay on map of project area..... 56
Figure 34- Map of utility lines identified via GPR survey with units identified...57
Figure 35- Profiles of STPs part 1 of 3..... 59
Figure 36- Profiles of STPs part 2 of 3..... 60
Figure 37- Profiles of STPs part 3 of 3..... 61
Figure 38- STP N110 E081 with drain in bottom of excavations..... 62
Figure 39- Cobbled surface encountered in N108 E086. Trowel pointing North ……..64
Figure 40- North profile wall of N108 E086 showing fill, cobbles, and more fill deposits overtop of an intact, buried plowed A horizon on left, with cut nearly in center of the profile and an entirely disturbed profile on the right side. B soils visible at bottom of stp..... 65
Figure 41- Purple roots of former trees..... 66
Figure 42- Google street image from 2014 showing dense trees in area of south yard of house..... 67
Figure 43- Profile of west wall of Unit 1..... 69
Figure 44- Photo of west wall of Unit 1..... 69
Figure 45- Drawing of east wall profile of Unit 2..... 71
Figure 46- Photo of east wall profile of Unit 2..... 71
Figure 47- Profile drawing of north wall of Unit 3..... 73
Figure 48- Photo of North wall of Unit 3..... 73
Figure 49- Plan of Unit 2 at 40 cmbd showing location of features 1-4…..... 75
Figure 50- Photo of Unit 2 at 30 cmbs showing Features 1-4..... 76
Figure 51- Profile of Feature 1 bisection in Unit 1..... 77
Figure 52- Photo of bisected Feature 1..... 78
Figure 53- Photo of bisected Feature 1 profile..... 79
Figure 54- Plan of Unit 1 at 20 cmbs showing Feature 5..... 80
Figure 55- plan photo of Unit 2 at 80cmbs showing Feature 7, a brick cistern, in lower right corner (southeast) of unit. Note brick cistern dome in lower right corner. ……...81

Figure 56- Rodnell's globe toy, artifact #99588..... 88
Figure 57- 2015 photo facing grid west showing location of former rabbit hutch on grid-north side of garage (left) based on Rodnell's description. Western edge of property in background..... 89
Figure 58- Peach pits from peach tree that grew in the backyard of the house, artifact #99587..... 91
Figure 59- Photo of area between ell (right) and garage (left) where rose arbor and peach tree was once located..... 92
Figure 60- Hong Kong two dollar coin from 1988, artifact #99555..... 93
Figure 61- File from yard, artifact 99637..... 94
Figure 62- Chisel from yard, artifact #99685..... 95
Figure 63- Blue decorated earthenware from 72 Dale Street. Artifact #99553….96
Figure 64- Porcelain plate with overglaze decoration from Ella Little's collection. Artifact #99608..... 97
Figure 65- Doorbell cover, artifact 99678..... 98
Figure 66- Hair tie bead, Artifact #99550..... 100
Figure 67- Possible gas utility fixture, Artifact 99595..... 103
Figure 68- Gutter downspout brace from 72 Dale Street. Artifact # 99639….. 104
Figure 69- Window weight pulley from 72 Dale Street. Artifact #99677……..... 106
Figure 70- Beads from surface collection, Artifact #99557..... 108
Figure 71- Photo showing berm below door on the eastern side of the addition. Record found in soils just under door.....109
Figure 72- Intact record from surface collection. Artifact #108336..... 110
Figure 73- clay tobacco pipes from surface collection #108360……..... 111
Figure 74- Button from surface collection..... 112
Figure 75- Wire nails from the surface survey #108344..... 113
Figure 76- photo of berm transition between grass and soil on east foundation of 72 Dale street near front yard. Ridge had to be scraped to smooth for GPR survey resulting in a surface collection of artifacts…….. 114
Figure 77- Dark blue vessel from Ella Little's collection, #108513..... 115
Figure 78- Rodnell's red car, #108421..... 115
Figure 79- Decorative fence element from property #108428..... 116
Figure 80- Pulley from 72 Dale Street yard..... 117

Figure 81- Securement for temporary rubber roof on 72 Dale Street at the time this report was being written #108407..... 118
Figure 82- Possible oil can element #108431..... 118
Figure 83- Ella's perfume bottle #108396..... 119
Figure 84- Milk Bottle from 72 Dale Street yard. #108447..... 120
Figure 85- Another plate from Ella Little's collection #108420..... 121
Figure 86- Flower pot from 72 Dale Street #108410..... 122
Figure 87- Door lock escutcheon from 72 Dale St. #108436..... 123
Figure 88- Embossed scales on bottle #108393..... 123
Figure 89- Ella's comb..... 124
Figure 90- Pink ceramic from surface collection..... 125
Figure 91- Blue and white ceramic with "zig zag" decoration (Blue transferprint pearlware #108507)..... 125
Figure 92- Surface around bulkhead before surface collection..... 126
Figure 93- Wheel from stolen chair #108560..... 127
Figure 94- Rock Garden area..... 128
Figure 95- Carnival glass bowl fragment..... 129
Figure 96- Transfer print ceramic fragment #99736..... 130
Figure 97- Alley on North side of property..... 131
Figure 98- Prattware from alley of 72 Dale Street #108650..... 132
Figure 99- Photo of back dirt pile. Visiting students for scale..... 132
Figure 100- Cutex nail polish remover bottle #108661..... 133
Figure 101- Button from Ella Little's white sweater..... 134
Figure 102- Marble slab from pathway #108668..... 135
Figure 103- Paper doll toy..... 136
Figure 104- Plastic eyeglasses frame #102659..... 137
Figure 105- Intact tumbler from Feature 6, Artifact #107171..... 141
Figure 106- Intact food or pharmacy bottle from Feature 6, artifact #107175....142
Figure 107- Intact food bottle from Feature 6, artifact #107172……..... 142
Figure 108- Burnetts medicine bottle from Feature 6, artifact #107170……..... 143
Figure 109- False tooth from Feature 6, Artifact #107577..... 143
Figure 110- Blue Hills rhyolite flake from the southern yard of the house, artifact #103409..... 147

Figure 111- Argillite flake from buried APZ, southern yard of the house, Unit 1.2, artifact 105924..... 148
Figure 112- Massachusett Hornfels flake from buried APZ, south yard of house, Unit 1.1, artifact 104795..... 148
Figure 113- Musket ball from buried APZ, Unit 1.1, artifact #105000……..... 149
Figure 114- Rim of porcelain bowl from buried APZ, artifact #105574……..... 151
Figure 115- Gold decorated porcelain mug rim from buried APZ, 106187….. 151
Figure 116- Westerwald mug rim from buried APZ, artifact 106166……..... 152
Figure 117- Redware teapot lid from buried APZ, artifact #103342..... 152
Figure 118- Overglaze enamel porcelain with ship sails from buried APZ, Artifact #104821..... 153
Figure 119- Porcelain fragment with painted ship, immediately after being excavated on-site from buried APZ, Artifact # 104821..... 153
Figure 120- Aqua glass free-blown pharmaceutical bottle from buried APZ, Artifact #103286..... 155
Figure 121 - Westerwald chamberpot rim from from buried APZ, Artifact #103824 ……..156
Figure 122- Clay wig curler from buried APZ, Artifact #105166……..... 156
Figure 123- Copper alloy buttons or cufflinks from buried APZ, Artifact #105171 157
Figure 124- Pipe bowl with “ER” makers mark from buried APZ, artifact #104790 ……...158
Figure 125- Pipe bowl fragment with British royal crest from buried APZ, artifact #106182..... 158
Figure 126- Slate pencil from buried APZ, artifact #105124..... 159
Figure 127- Nottingham ink bottle shoulder from buried APZ, artifact #106755 ……...160
Figure 128- Jack Hallion (Left) visits dig and speaks with Rodnell Collins (right) ……...164
Figure 129- Some of the hundreds of BPS Social Studies students visiting the Malcolm X House during the archaeological dig there, April 8, 2015..... 165

Abstract

In 2015, a team of archaeologists from the City of Boston Archaeology Program conducted an intensive (locational) phase 1 archaeological survey at 72 Dale Street in Roxbury, a home known as the Malcolm X / Ella Little-Collins House. The survey was in preparation for planned excavations and repairs on the foundation of the house and had the overall goal of determining the archaeological integrity and significance of the site. Excavations included 19 50x50 cm Shovel Test Pits and two 1x2 meter test trenches recovering 18,207 artifacts. The team also conducted an extensive surface collection of the site to recover 20th century artifacts from the Ella Little-Collins and Malcolm X occupation of the home. The artifact assemblage documents a near-complete cross section of Roxbury history. New data revealed through this excavations includes: the presence of Native lithic resource processing of Blue Hills rhyolite, Cambridge slate, and Massachusett hornfels; a robust deposit of 17th-18th century historic artifacts, many of them representing a high-status lifestyle, associated with the estate of Abijah Seaver; a dense deposit of 19th century household waste representing a poor immigrant population from the early occupants of the property deposited in an abandoned foundation from a probable Seaver estate outbuilding; and a remarkable and personal set of artifacts from the Little-Collins household revealing the significant impacts of Ella Little-Collins on the homelife and daily activities of her household, which included the young man who would become Malcolm X.

Acknowledgements

I would like to acknowledge the many volunteers who participated in the field and laboratory aspects of this dig. I would especially like to thank the Fiske Center for Archaeological Research at UMass Boston for their Ground Penetrating Radar Survey. Finally, my greatest appreciation to Rodnell Collins, owner of the home, for his support and openness to exploring the history of his home and his family.

Introduction

Introduction

The City of Boston Archaeology Program conducted an Archaeological survey at 72 Dale Street, the Malcolm X-Ella Little-Collins house, in Boston's Roxbury neighborhood (Figure 1), began on March 28, 2015, and was completed May 20, 2016.



Figure 1- Project area at 72 Dale Street in red

These excavations were in response to proposed excavations of the foundations of the landmark-designated home to repoint and repair the foundation, requiring extensive excavation of the land abuting the foundation around the entire house. These excavations had two purposes: to document the conditions of archaeological deposits throughout the property, and to more-specifically determine if the work to the foundations would impact significant archaeological deposits.

Excavations included the entire property 19 50x50 cm shovel test pits (STPs) and three 1x2 meter units totaling 10.75 square meters in area (Figure 2). The team also conducted an extensive surface collection of the site to recover 20th century artifacts from the Ella Little-Collins and Malcolm X occupation of the home. In total, 18,207 artifacts were recovered.



Figure 2- Map of 72 Dale Street property with excavations labeled.

Compliance with Legislation

As a Boston Landmark-designated property, proposed changes to the property are reviewed by the City Archaeologist of Boston. During the review of the proposed work, this survey was requested.

Project History

This project began with a proposal to the Boston Landmarks Commission for repair work to the foundation of the house. After extensive conversations, it was agreed that an archaeological survey was necessary to mitigate the impacts to the foundations of the house and to determine the overall archaeological sensitivity and integrity of the property. As the property was owned by a non-profit and as the dig would be open to the public for educational purposes, the City Archaeologist agreed to conduct the archaeological survey.

Personnel

The dig itself was staffed primarily by UMass Boston graduate students and a team of volunteers from the community. All laboratory work was performed by volunteers and part-time contracted employees for the City of Boston Archaeology Program.

Site Background History

Native American History of Site

No Native archaeological resources have been documented within 500 meters of the project area. The closest Native sites include the Hogs Bridge Fishweir (19SU80), Meeting house site (19SU96), and Dillaway-Thomas Prehistoric sites (19SU77).

The Hogs Bridge Fishweir was an ancient Massachusett fish trap constructed within the Stony Brook river at what is now the Jackson Square MBTA station on the Orange Line. This fishweir was documented in the 17th century by European settlers, but may have been in use for centuries or more. The Meeting House Site was a small workshop site where lithics (stone tools) were processed. Due to a lack of datable artifacts, the site can not be thoroughly dated beyond being present prior to the arrival of Europeans. The Meeting House Site is located within open space surrounding the extant First Church of Roxbury. Finally, the Dillaway-Thomas Prehistoric site is a Middle to Late woodland (3,000-7,500 year old) Native site on a stone ridge overlooking the Shawmut peninsula (now Boston). This site is located within the yard of the Dillaway-Thomas house in Roxbury. These three Roxbury sites are located more than 1 kilometer northwest of the project area and are associated with the former Stony Brook and Roxbury Highlands geologic features.

Post-contact History of Site

A detailed analysis of available historic written documents has revealed as complete a picture as possible of the ownership history of 72 Dale Street property and building.

1630-1776 72 Dale Street History

The Euro-american history of Roxbury dates back to 1630 with the laying out of early town boundaries in the Boston area by early settlers and land grants. The ownership of the land that later became 72 Dale Street can be traced to Reverend Thomas Weld, or Welde, Sr. a Puritan minister who traveled to the Massachusetts Bay Colony to escape persecution.

“After a spell at Haverhill, Suffolk, from 1619, he became vicar of Terling, Essex, in 1624, and he became an important figure in the circles of spiritual exercises in the county. He was prominent in the fasts and conferences established by Thomas Hooker and attended by ministers like John Rogers and Stephen Marshall. In concert with the parish elite he advanced a program of reformation of manners and established a household seminary, one of whose pupils was Shepard. In late 1630 Bishop William Land summoned him and required him to sign the Three Articles. After several months Of equivocation, he refused and was thus excommunicated. At the end of 1631, with a number of other ministers, he remonstrated with Laud after a visitation sermon and was called before High Commission for entering the church

while excommunicated. After considering Scotland and Ireland, he emigrated to Amsterdam and then Massachusetts in 1632." (Francis & Webster 2005, 267)

Weld arrived in 1632, but his home location at this time is not known. In 1638, he successfully petitioned that 4,000 acres of land be transferred from Dedham to Roxbury (Middlesex County Deeds [MCD] Book 4 page 1), in admiration, Weld was deeded 533 acres of land in the area around Dudley square and to the south and east. Weld's brother, Joseph owned land to the west including what would later be known as Jamaica Pond and the Arnold Arboretum (Putnam, 1913, 27). Documents discuss the presence of Thomas' 533 acre lot as situated opposite of Joseph's to the east. It is likely that both Joseph and Thomas' homes were near each other in the central area of Roxbury in the Dudley Square area (Putnam, 1913, 28-29) with their large farm estates located behind their homes, therefore there is likely no early 17th century homesite on the property of 72 Dale Street, but it is likely that the house present today was originally on Thomas Weld's estate.

Thomas Weld was the first pastor for the Church of Roxbury as well as one of the prosecutors during the heresy trial of Anne Hutchinson. Hutchinson was held under house arrest at Joseph's home in Roxbury during the trial (Putnam, 1913, 27-28).

In 1641, Weld left his home and family in Roxbury to travel back to England to unsuccessfully petition for the annexing of land, now Rhode Island, that had been settled by Roger Williams and the now-banished Anne Hutchinson (Robinson, 1938, 53). His large estate would descend down to his son, Rev. Thomas Weld, Jr. Both Welds played major roles in the founding and management of the 1645 Roxbury Grammar School.

The 1682 probate of Thomas Weld , Jr. (Suffolk County Probate Records) divided his estate equally among his four sons. It is believed that the following portion of the estate includes the area of the 72 Dale Street property. It states:

"I give unto my son Samuel the land where his house stands fenced in containing about ten acres be it more or less, also about twenty acres more or less lying near the other land as afore stated reserving firewood for my wife to be by him brought home to her so long as she shall remain my widow, and also I give unto him the land lately bought of William Hopkins."

This land description includes three main parcels of land in Roxbury: A 10-acre house lot, a 20-acre land lot, and the another lot of unknown size formerly belonging to William Hopkins.

At this point, the history of the ownership of this land becomes problematic due to the rather vague descriptions of the lot sizes and abutters in the deeds as well as the numerous transitions of ownership that appear to occur outside of deeds and other readily-available written documentations.

Included in this section are two viable histories of the next few land transitions, both ultimately end with the land that contains 72 Dale Street belonging to Captain Samuel Stevens.

Samuel Stevens was Samuel Weld's son-in-law through marriage to Weld's daughter, Dorothy.

In 1702, Samuel Weld purchased land adjoining his land from the estate of Jonathan Peake (SCD Book 21 Page 137), then in 1726 gave it to Samuel Stevens his son in law eighteen years after his marriage to Dorothy in 1708. (Robinson, 1938, 67) This may be an additional lot added to Weld's land holdings and may have contained 72 Dale street, though it is less likely.

Alternatively and more likely, 72 Dale Street was part of a 100 acre lot which was sold by Samuel Weld to John Sumner, the husband of Weld's granddaughter, Susanna, in 1732. (Suffolk County Deeds [SCD] Book 47 Page 122). Sumner sold half of this land in 1733 to Samuel Stevens (SCD Book 47 Page 200), Sumner's father-in-law, soon after his (Sumner) wife's (Samuel Stevens's daughter's) death. The deed states Sumner's love and affection for his children Samuel and Susanna and for their betterment and advancement in the world he includes a large portion of land and half of their house for his children's grandparents, Samuel and Mary Stevens. This implies that Samuel and Mary Stevens would help John raise his children, and are awarded half of John's land when the children become adults as appreciation. Whereas Samuel Sumner would inherit two thirds and Susanna Sumner would inherit one third of half the land.

Regardless, by 1733, Samuel Stevens was in possession of most of Samuel Weld's estate, including the land that would eventually become 72 Dale street, and the transitions that happened in the early 18th century were likely all done within the Weld-Stevens-Sumner family.

In 1741 Samuel Stevens sold a portion of his estate to his son, Timothy Stevens, a physician (SCD Book 61 Page 269).

Five indenture records in the 1740s deeds indicate that Timothy and Samuel Stevens owed 100 ounces of silver to James Smith, a merchant, with the estate used as collateral (SCD Book 64, Page 182, SCD Book 70, Page 47, SCD Book 73, Page 232, SCD Book 75, Page 36, SCD Book 78, Pg 224). It appears that they were unable to pay back this debt as a 1750 deed indicates that the land is transferred from Timothy and Samuel Stevens to James Smith (SCD Book 78, Pg 224).

James Smith was a large landowner, and while he owned the property, he likely did not live on the home. If the property was occupied, it is not known by whom. In 1761, the property returned to the Stevens family when it was purchased by Elizabeth (36) and Hannah (81) Stevens. Elizabeth was Samuel Stevens' daughter, and Hannah was Samuel Stevens' sister, both spinsters.

It appears that the Stevens family money issues remain, as the Stevens women take out a mortgage on the land through Commodore Joshua Loring. This is the same Loring as the Loring-Greenough Estate in Jamaica Plain. Loring was a wealthy retired military man who owned large amounts of land in the Roxbury area.

In 1765, the home and two of the land lots finally leaves the Weld-Sumner-Stevens family when it was purchased by Abijah Seaver, a yeoman or non-slave owning farmer (SCD Book 105, Page 189). Seaver likely purchases the land due to his marriage to Anne Winchester the year prior. The deed states that Seaver was already living on the property, but Seaver was 28 in 1765 so it is unlikely that he lived there previously for a significantly long period. Anne and Abijah had seven children at the site: William, Benjamin, Anne, Joseph, Nathaniel, Ann, and Mary.

Once again, Joshua Loring becomes the owner of the property as Abijah takes out a mortgage with Loring in 1765 (SCD Book 105, Page 191). In 1774, Abijah appeared to stop making payments on the mortgage, and in 1776, Loring, a Tory, fled Boston on Evacuation Day, March 17, 1776.

Post-Revolutionary War History of 72 Dale Street

Like many living on or desiring land formerly owned by fled Tories, Abijah applies for the right of Administration of the property which was granted, presumably, due to Joshua Loring's Loyalist ties (George 1895, 141)

However, in 1798 Joshua Loring Jr. filed for the right to be the administrator of his father's affairs and property and sent a letter to the Seavers demanding either the ownership of the seaver property or the missing payments on the property between 1774 onwards (Norfolk County Deeds [NCD] Book 8, Page 13).

This letter was either ignored or successfully disputed, because in 1821, the land, now owned by the children of Abijah and Anne's son, William Seaver, was sold. The death date of Abijah is not known, but a document dated 1787 refers to the land as Abijah Seaver's "estate" (NCD Book 8, Page 13).

In 1821, the deeds reference for the first of several times, to a property map drawn by Mather Withington (Bostonian Society Library). Today, that map is held by the Bostonian Society.

While the map only shows the outline of three parcels still within the Seaver estate (Figure 3), a faint but deliberately executed rectangular structure, likely a house, is included in the northern of the three lots. This northern lot is 17 acres and is roughly the location of the land bounded today by Washington, Dale, Warren streets, and MLK Blvd (Figure 4). If accurate, the house drawn on the map would today be approximately near the Higginson-Lewis K-8 School.

Figure 3- Withington map of property. 72 Dale Street would be in the right parcel. Outline of right parcel measures 17 acres.



Figure 4- Detail view of Withington map with what is presumed to be the Seaver house digitally enhanced from rectangular impressed mark (without ink) in red. Highly approximate boundaries of parcel indicated in white on modern aerial view from google.com.

Based on the historic map and the descriptions provided in the deeds, it is likely that these are the lots discussed as early as the 1680s deeds, but the presence or absence of a house on the property near 72 Dale Street during the 18th century is not possible to be determined without archaeological evidence (see below).

In 1821, the Seaver estate was sold to John H. Hawes, yeoman, by the children of William Seaver. (NCD Book 64, Page 132) In this deed, a specific 2.5 acre lot containing a house is mentioned alongside an additional 15 acre parcel. This 2.5 acre area would be the equivalent of the corner of Dale and Warren streets including the homes to either side of 72 Dale Street and the school behind. The additional 15 acres may be the area to the west including Malcolm X Park.

The properties were then sold to John Lemist, merchant, in 1833 (NCD Book 100, Page 214), then John Clarke, esq. in 1836 (NCD Book 114, Page 15).

In 1837, only the 2.5 acre lot containing the extant Seaver home is sold to a conglomerate of wealthy investors who together make up the Roxbury Land Company (NCD Book 113, Page 349).

The Roxbury Land Company was an investment group who bought large quantities of Roxbury properties, likely for land speculation. During the Industrial Revolution, land in Roxbury changed from agricultural uses to residential around the new industries formed along Roxbury's rivers.

1840-1940 History of 72 Dale Street

A complete catalog of individuals appearing in tax, directory, and census records beginning in 1850 is available in Appendix A.

Nelson Curtis, housewright, purchased a 7,895 square foot parcel (.18 acre) from the Roxbury Land Company in 1842 (NCD Book 135, Page 109). At this time, no home is described in the deed, which makes sense as it likely does not include the area of land that had the Seaver building.

Dale street was laid out in 1845 (City of Boston 1910, 145) along the lots divided by the Roxbury Land Company. It is likely that Curtis and other housewrights purchased plots of land along proposed streets in order to build new homes on newly-laid out streetscapes.

Curtis was an apprentice mason at the age of 18 in the early 19th century. When he became a housewright, he started his own construction company that by 1850 resulted in a personal real estate portfolio valued at $50,000 and 50 employees producing $175,000 of building value annually (U.S., Selected Federal Census Non-Population Schedules 1850).

A historical genealogy describes Curtis as a self-made man who was a “friend to the worthy poor” and responsible for building structures including the Fitchburg Railroad Station, Boston Museum, United States Hotel, and many Roman Catholic Churches in Boston (Fulham 1910, 134). Nelson Curtis is also responsible for tearing down the old brick prison in 1850 located at 47 Village Ave in Dedham and putting up the stone prison standing today (Tuttle 1890, 30). In 1860 Nelson Curtis also updated the Norfolk County Superior court house (Cook 1918, 46). In addition to his buildings, Curtis worked as the treasurer and as an agent for The Atlantic Ironworks company (Adams 1857, 300). In the mid 1800s up to the start of the Civil War, Curtis was a mechanical engineer and was engaged as a machinist and constructor of steam engines, monitors, and vessels for the United States, and an agent of the Atlantic Works at Boston. (Board of Harbor and Land Commissioners of Massachusetts 1892, 142) He was also responsible for the construction of the USS Nantucket 1862 and the USS Casco 1864, two monitor vessels used during the Civil War (Roberts 2003, 57) (Roberts 2003, 156).

Curtis owned 72 Dale Street property until 1866 when he sold it to a 29 year old Frederic W. Dorr (NCD Book 339, Page 305). Notably, this deed indicates the presence of a house on the property. The 1998 Boston Landmarks Commission report on 72 Dale Street indicated that the home was built in 1874 by William Rumrill. The research presented here, suggests an alternative history: Sometime between 1845 and 1866, a home was built at 72 Dale Street and is likely the same house seen today.

Dorr, like Curtis, was involved with the Union causes during the Civil War. Dorr was a trained mapmaker responsible for drawing coastal maps and surveys. Frederic W. Dorr had been mapping for the U.S Coast survey since at least 1858. (Bache 1859, 227-228) During the war, Dorr was responsible for drawing accurate maps of Confederate positions and locations at battlefields including Yorktown and Chattanooga (Donn 2006). After a near-fatal attack that killed several men near him while at his drafting table, he began to conduct surveys via horseback traveling behind enemy lines to clandestinely map Confederate locations alongside his partner, John Donn (Donn 2006).

Dorr contracted a disease, possibly malaria, during his surveys (Donn 2006). He was present during the final surrender of General Joe Johnston a week after the surrender of General Lee he is also credited with creating with creating along with his mapping partner John W. Donn the battle map of Chattanooga which has been called “one of the best examples of Civil War topographical work ever produced...” (Donn 2006). After the war, he returned to Boston and purchased 72 Dale Street where he lived with his wife, brother, father, and mother (NCD Book 339, Page 305).

Boston city tax records indicate a home at 72 Dale Street, annually, between 1868 and 1873. Town Directories indicate the Dorrs as residents in 1869 and 1870. Both data sources suggest an date of construction before 1874.

Dorr's ownership continues until 1873. During Dorr's ownership, the house value is listed continually at $5,000 suggesting a fairly substantial building on the property. William Rumrill, builder and carpenter, purchased the home in 1873 (SCD Book 1180, Page 262) and lived in a home at 74 Dale Street.

Rumrill only owned the house for one year, selling it in 1874 to Caroline Nichols (SCD Book 1213, Page 94.) It is possible that Rumrill modified the home's style to its current Italianate appearance, but it is unlikely that the home was built anew. Tax records indicate that between 1874 and 1875, the house increases in value by $500 to $5,500, and the home is described as owned by Nichols and "vacant" in 1874. Both suggest a modest renovation in late 1873 or early 1874. In 1880 one horse and stable is listed at 72 Dale Street, suggesting this as an approximate construction date for the carriage house that existed prior to the current c. 1925 garage.

The Massachusetts-born Nichols family move into the home and remain there until they sold the home in 1890 (SCD Book 1937, Page 621, SCD Book 1951, Page 487). City of Boston tax and city directories indicate the home was occupied by Daniel and Caroline Nichols. Daniel owned his own business, Nichols and Co. Carriage Factory, located at 118 West Brookline in the South End. The 1880 Federal Census documents Daniel, 50, with Caroline, then a 43 year old homemaker, lived in the home with their 19 year old son, Wendell, a bookkeeper for his father's business, their 4 year old, Mary, and 25 year old Irish-born servant, Kate Connolly.

Mary and John Murphy purchased the home in 1890 and it remained in the possession of several Irish-born individuals through the 1920s and 1930s. More important than who owned the property was who was living in the home and contributed to the site during this time.

John Murphy worked in periodicals at the Old Colony and Providence railroad depot. By 1896 he was working in south station as a news dealer he was said to be selling around 100 books a day with his most popular book The Twentieth century library selling for 50 cents each. (Quinn 1896, 36) Between 1899 and 1900, the Murphys moved out (though remain owners) and the property was rented to Alonzo or Anthony D. Patten, Janet, and their children Samuel, Jessie, and Ida, all born in Canada (US Census, 1900, Boston City Directories). Anthony Patten was a physician who listed his work and home as 72 Dale Street. A Stephen Patten, also a physician, possibly the same person as Samuel, is also listed at 72 Dale Street. The Patten family remained in the home until 1913 with only one border, a woman, in 1912.

The home appears to be vacant in 1914.

The 1915 tax records indicate Kilderry Nora Shannon, widow, and Parker J. Shannon lived in the home. They remained until 1918.

Occupants appear again in the directories beginning in 1921 with the McDonald family, who live there until 1927. Census records do not appear to indicate presence of individuals in the home in 1920.

The Great Depression appeared to impact the occupation of the home. Beginning in 1928, Mary Linehan is listed the owner (SCD 4858, 118) and occupant and remains so until 1937 renting the home out to other Irish immigrants. The property changed hands again in 1937 (SDB 5646, 568). The Scottish and English born Hallion family appear in tax records in 1937 and remained in the house until it is sold to Ella Little in 1941. Charles and Frank Sullivan, Francis Herlihy, as well as Mary Carol were renters of the house at this time. Perhaps the Hallion family lived in the main/front portion of the house, and the rear apartments were rented to the Sullivan, Hurlihy, and Carol occupants.

Kenneth and Ella Little-Collins purchased the property in 1941.

Little-Collins History

The Littles have owned 72 Dale Street since 1941. As the most significant occupants of the property, their background history will begin before their arrival to the home.

In the early 1800s, Ajar was kidnapped from somewhere in the vicinity of Nali, West Africa and brought to Charlestown, South Carolina, where he was sold into slavery (Collins 1998, 5). Ajar's third great grandchildren include Ella and Malcolm Little. Ajar was a skilled carpenter, was rebellious, and a proud African, instilling these traits onto his son, Tony. Ajar disappeared, having been sold, traded, or fled, and his final resting place is unknown (Collins 1998, 6). After the disappeared, Ajar's son, Tony, and Tony's wife, Clarrie, were sold to the family of Allen LIttle (Collins 1998, 6). The threat of breaking up families was used to deter the escape of enslaved people, and it is possible this sale indicates that Ajar escaped enslavement (Collins 1998, 6). Clarrie was of mixed African and Native ancestry and shared Tony's pried for identity and culture (Collins 1998, 7). The white Littles and their enslaved men, women, and children moved on to Talbotton Georgia in Talbot County. There, Tony and Clarrie remained with the family working in the Little's Big House avoiding being sold away broken up until the Civil War (Collins 1998, 7-8).

After emancipation, Tony and Clarrie remained in Talbot County, where their last name became "Little," based on the standard practice of that era of naming former enslaved people after their enslavers (Collins 1998, 8). Tony was able to buy land for his large family including 22 children by working as a carpenter for white and black families and building black churches in Talbot and Taylor Counties (Collins 1998, 9). Tony's son, Pa John, would be Ella and Malcolm's grandfather. Tony's explicit goal of land ownership allowed the Littles to avoid sharecropping, which would rarely allow for land ownership, and the goal and practices of purchasing land early

and often was a Little family tradition appearing frequently in Malcolm's and Ella's public and private teachings (Collins 1998, 9)

In the 1920s, many of the Littles left Georgia to settle in the midwest and northeast.

Ella Little-Collins was born in 1912 in Butler, Georgia, to Earl Lee Little and his first wife, Daisy Mason. Earl was the son of Pa John, one of Tony's 22 children. Ella moved with her mother first to New York City, then Everett, later Roxbury, where she worked at her mother's store. While employed there, Ella diligently saved money allowing her to first purchase part ownership of the store, then begin her self-made career in real estate investment (Collins 1998, 51).

Earl Little, Ella's father moved frequently around the midwest marrying his second wife, Louisa, and having seven additional children, including Malcolm. Malcolm was born in Omaha, Nebraska. Earl was a carpenter like most of his male ancestors. In Omaha, Earl built his family's home and he and Louisa had their fourth child, Malcolm. Earl and Louisa were both activists and supporters of Jacque Garvey and the Universal Negro Improvement Association (Collins 1998, 13). Garvey preached self-reliance and the need for black people to develop respect and power in order to fight white supremacy (Collins 1998, 14). This directly threatened the power of white people, making Garvey and his supporters reviled by white supremacist.

The Little family decided to move from their Omaha home as reaction to Garveyism was causing fears among black residents due to harassment by Omaha Klansmen towards UNIA attendees (Collins 1998, 15). The littles moved next to Milwaukee, briefly, but moved again to Lansing, Michigan hearing about better economic prospects there by Bud Little, Earl's brother, who lived there (Collins 1998, 15). Bud was a renowned storyteller, and created homemade alcohol with reputed medicinal properties from peaches (Collins 1998, 15).

The littles found similar fear in Lansing's black population towards Garveyism, especially the UNIA's position to return to Africa to form a powerful black contenant, as many black residents in Michigan felt that Africans were uncivilized (Collins 1998, 16). Malcolm would later preach that these concepts were put upon black people by white people, and that fear controlled most black resident's ability to resist (Collins 1998, 16).

Earl died on September 28, 1931. While official records say that Earl was struck by a Lansing streetcar after becoming inebriated, the Little family believe this was the product of a racist police who covered up a lynching: white residents of Lansing attacked and brutally murdered Earl, leaving his body on the tracks as coverup (Collins 1998, 17).

Insurance companies went further, labeling the death a suicide. The struggle with her husband's death, creditors, and raising seven young children alone led to Louise Little's nervous breakdown (Collins 1998, 17). Michigan branded her "insane," insittuionaliezd her, and spread

her seven children including Malcolm to multiple foster families (Collins 1998, 17). Unfortunately, the Little's Garveyism was often seen by blacks to be as radical as it was to whites, and infighting within the Little family resulted in little support for the family after Earl's death (Collins 1998, 18).

While the extended Little family may have been powerful enough to stop the breaking up of Earl and Louisa's family, their distance from Lansing, their unawareness of the state's seeming preference to break up the family over keeping them together, and internal disagreements meant that they were never able to unify to keep the family together (Collins 1998, 19).

Back in Boston, The success of the Ella, her mother, and her aunt's Roxbury store brought first jealousy then resentment from neighboring white store owners, who pressured suppliers away from the store (Collins 1998, 52). Regardless, the store's success allowed Ella to be ⅓ owner of 200 acres in Duxbury with her mother and aunt. After additional feuds with her mother's family over supporting her father's children, Ella asked for her mother and aunt to buy her shares out. After years of delayed payments, family feuding, personal loans, and a legal settlement, Ella received her aunt's ⅓ ownership of the Duxbury land, giving her 2/3rds ownership.

Ella little traveled from Boston to visit her family during the 1930s, become interested in Malcolm in particular, finding him "'bright, intelligent, and inquisitive,' though somewhat undisciplined (Collins 1998, 19)."

In Boston, Ella had utilized her savings to become a support for other members of the Little family, especially those in the south including her Aunt Sas and Aunt Gracie (Collins 1998, 20). Initially, Ella wished to take all seven of Earl and Louisa's children plus Louisa's young son, Robert, fathered by a family friend after Earl's death, to Boston to live with her, but several factors prevented this. First, welfare workers had instilled conflict between the Little children, second, Earl's abandonment of Daisy and their three children including Ella had left animosity among Ella's mom and other family members preventing their full support for the care of the children from Earl's second marriage, and finally Aunt Sas and Aunt Gracie were not interested in supporting non-siblings such as Louisa's son, (Collins 1998, 20). Ella chose to focus on Malcolm, who had been placed with a white foster family (Collins 1998, 21).

During an earlier trip, Ella had left an impression on Malcolm: "I think the major impact of Ella's arrival, at least upon me, was that she was the first really proud black woman I had ever seen in my life. She was plainly proud of her very dark skin. This was unheard of among Negroes in those days, especially in Lansing." (X 1965, 34).

While Malcolm excelled in school in the 1930s, he was demoralized by his teacher's indifference to his desires to become a lawyer, suggesting instead that he pursue other careers that have fewer obstacles to African Americans such as carpentry (BLC 1998, 14). Malcolm was expelled from his local school in 1938, transferring to another school further away that required him to board with a white family to make the commute easier (BLC 1998, 14). In the Autobiography of

Malcolm X, this lack of support ended Malcolm's interest in formal education, ultimately leading to his dropping out of school temporarily after his freshman year.

Having been declared wards of the court, Malcolm was placed into the Ingham County juvenile Home in Mason, Michigan in 1939. That same summer, Malcolm made his first visit to Boston to visit Ella (BLC 1998, 14). At the time, Ella was living with her second husband, Frank Johnson. Ella, Frank, Aunt Sas, and Aunt Gracie received a quiet and well behaved Malcolm in 1939.

During the summers of 1939 and 1940, Malcolm would live with his sister in Roxbury, where he lived for the first time within a large black community. Returning to Michigan, Malcolm requested Ellan petition for legal custody of the 16-year-old Malcom, which she did successfully, resulting in Malcolm moving to Roxbury in February of 1941. In 1941, Ella, Aunt Sas and Aunt Gracie, expecting the same Malcolm who visited prior, received an equally intelligent and respectful, but far more curious and temptable 14 year old Malcolm (Collins 1998, 23).

Ella believe Malcolm to be intelligent enough to be a lawyer and had first-hand experience seeing that "the law worked only for those who understood how it works or who had sufficient money to hire someone who understood how it works (Collins 1998, 23)." Within 48 hours after arriving in Boston, Ella brought Malcolm to her uncle's parking business in Boston's Chinatown, and Malcolm began his first Boston job on his third day in town.

During this time, Ella, now separated from Frank, was attempting to purchase a property at the corner of Dale and Warren streets (now demolished). When this became unsuccessful, Ella began to work on purchasing 72 Dale Street. At the time, the Linehan family who owned the house were under threat of foreclosure since 1937(Collins 1998, 54) but 14 individuals from the Hallion and Sullivan families were occupying the home as renters. Working with a sympathetic Jewish realtor and a black realtor, she discovered that only $500 cash for overdue taxes were owed, and that was all the family wanted for the property (Collins 1998, 54). Ella's offer of $600 cash for the house was rejected by the family and the price raised to $900 (Collins 1998, 54). Knowing her race was a primary impediment to buying from the family and with $1,200 in her house buying budget, Ella went directly to the bank who were happy to have their debts settled and pressured the racist owners to sell (Collins 1998, 54). The owners still refused for over a year. Finally, she went to the family with an offer for $1,200 with $900 deposit on the spot and the rest paid the following day. The family agreed and signed, hoping to ignore the deal and use the $900 to pay their debts to the bank. Ella immediately went to the bank with the owner's signed contract and $1,200 offer. The bank seeing the deal and knowing the family had the money contacted the owners and immediately demanded their late payment that day. When the owners arrived expecting to pay off their debt, Ella was at the bank waiting. The bank insisted that the signed agreement be upheld. After paying their owed $500 mortgage, and their $600 overdue tax payment to the bank that day, the were left with $100 and Ella owned the house (Collins 1998, 54).

72 Dale street would become home to Ella's extended family including her new husband, Kenneth Collins, their son Rodnell, Ella's and intending on using the home to house her extended family.

Today the house remains in ownership of Rodnell Collins, Ella's son.

Ella Little-Collins and Malcolm X

Ella and Malcolm are both significant individuals in US History. At 72 Dale Street, the home was owned, occupied, and perhaps most significantly, furnished by Ella Little-Collins. The majority of artifacts recovered from domestic archaeological sites are the personal possessions and household goods owned by the individuals within the home. The household goods, in particular, will reflect the personal taste and world view of Ella most predominantly, and therefore, it is she who may play the most significant factor in the mid-late 20th century artifact assemblage recovered from 72 Dale Street.

When Malcolm entered Ella's life in Roxbury, he had already experienced dissatisfaction with his schoolings, the loss of his father, the institutionalization of his mother, and a move from the midwest to urban Boston.

At 72 Dale Street, Malcolm heard many stories from Ella, Aunt Sas, and Aunt Gracie about the effects of white supremacy on members of the Little Family. Rodnell Little covers these atrocious stories in great detail in *Seventh Child, A Family Memoir of Malcolm X,* cited frequently, here. While the stories are too detailed to cover here, they document many efforts by whites to deter, threaten, belittle, rob, murder, and otherwise prevent members of the Little family from pursuing opportunities for self advancement and improvement. They also detail efforts by the LIttle family to support each other. These stories and lessons would become part of the basis for Malcolm's beliefs in black supporting each other, the terrorism of white supremacy, and the lessons that history provide.

While Ella wished to provide Malcolm with a strong family, the anger and animosity of Ella's mom, Daisy Mason, and other members of her family towards Earl's second family were constant strains on Malcolm's Boston family. While city dwellers, Ella, Malcolm, Aunt Sas, and Aunt Gracie were all products of small rural towns, and all but Malcolm grew up in the south. With this, the four all possessed knowledge of rural life, and Ella's ownership of a farm in Duxbury brought with it a taste of rural life with frequent trips between Duxbury and Roxbury, especially in later decades, and movement of animals and plants between the two resulting in some farmland influences on the property in Roxbury

While in Roxbury, Malcolm became enamored with entertainers and enjoyed city living, which attracted him to a nightlife lifestyle that Ella did not approve of (Collins 1998, 40). This rebellious nature was supported by Ella, who saw it as a means to resist oppression, but she

was very against his use of drugs, clothing styles, and dealing (Collins 1998, 41). Malcolm and Ella spent time with Bazeley Perry, a jazz performer who was also an Ahmadiyya Muslim. This particular sect of Muslim faith has its origins in late 19th century Pakistan. Malcolm was a fan of jazz and would attend Perry's performances and visit Perry's home.

Malcolm spent his time in multiple locations, but always considered 72 Dale Street his home (Figures 5-7) . This is emphasized by Malcolm appearing in Boston city directories at 72 Dale Street every year between 1954 and 1962 (Appendix A), and in an 1955 FBI interview, Malcolm describes his residence as 72 Dale Street between 1941 and 1943 (FBI 1955, 85)

Figure 5- Malcolm Little (left) with friends and Ella Collins (right) in a Boston Park in 1941. (Image Credit: Collins 1998).

Figure 6- Malcolm and Ella Little at 72 Dale Street in 1941 near the location of excavation unit 1. (Photo credit: Collins 1998).

Figure 7- Malcolm Little in driveway at 72 Dale Street in 1941. (Photo credit: Collins 1998)

Figure 8- 72 Dale Street as it appeared in the mid 20th century with Ella (forefront) and her aunt, Sarah Little (on porch). (Photo Credit: Rodnell Collins)

Ella was fierce in her demand for respect for herself and her family, even successfully becoming the first black woman to win a case against the Boston Police Department over false charges of bicycle theft (Collins 1998, 58). When Rodnell was assigned a essay on George Washington in social studies class at a Julia Ward Howe Elementary School, a Boston Public School, Ella encouraged him to write two essays, one on George Washington and one on George Washington Carver. The Carver essay was ignored and Rodnell was given a poor grade on the George Washington essay. Ella's confrontation to the school went ignored so she became one of if not the first black person to confront the Boston public school system for its failure to teach black history. One particularly racist school board member, Louise Day Hicks, declared that black history did not belong in Boston Public Schools resulting in a physical altercation between Ella and Hicks. Rodnell was transferred to Davis A ellis Elementary school where he was taught by Agatha Guilford. Ms. Guilford would later become a US Congresswoman from Massachusetts. (Collins 1998, 56)

In 1946, the then 20-year-old Malcolm was sentenced to prison for larceny. While incarcerated, it was Ella writing to Malcolm who encouraged him to make something of his time in prison and to better himself while there. Ella was also instrumental in having Malcolm transferred from Concord to Norfolk Prison where he was able to access an experimental education program, attend college-level lectures, read at the prison library, and learn debate skills (BLC 1998, 19). It was in Norfolk Prison where Malcolm's oratory skills, political activism, and knowledge base blossomed.

While at Norfolk, letters from Malcolm's siblings in Michigan introduced him to the work of the Honorable Elijah Muhammad, the leader of the Nation of Islam (BLC 1998, 20). The Nation advocated a separatist black nationalist agenda.

Malcolm was imprisoned from 1946 to 1952. Very soon after his release, Malcolm headed to Detroit where he met with Elijah Muhammad (BLC 1998, 20). Malcolm formally converted to the Nation of Islam and was given the name "Malcolm X." The "X" name was given by Elijah Muhammad to converts in an effort to remove last names which were usually tied directly to the names of enslavers who imposed their name upon those they enslaved (BLC 1998, 20). Little was the last name of the enslavers of Malcolm's great grandparents, Tony and Clarrie.

Malcolm X quickly became a leader within the Nation of Islam (BLC 1998, 20). Malcolm's siblings including those in Michigan and Ella in Roxbury, were responsible for the propagation and enlargement of Nation of Islam, and two of Malcolm's brothers administered several midwest mosques (BLC 1998, 20).

In 1954, Malcolm traveled back to Boston to begin recruiting efforts there, establishing a temple in Roxbury, and holding meetings in the South End (BLC 1998, 20). 72 Dale street served as a meeting place and home for Malcolm X. Ella, now converted, participated in Nation of Islam

activities including the founding of a child-care center at the mosque Malcolm founded, Temple Number Eleven, which would become the Sarah A. Little School of Preparatory Arts in 1958.

In 1959, Ella's relationship with the Temple's ministry deteriorated, and at the request of Elijah Muhammad, Malcolm X expelled Ella from the Nation of Islam.

As Malcolm's leadership grew beyond just the Nation of Islam, he became a national leader and figurehead of the Civil Rights Movement. Malcolm was suspended from the Nation in 1963 when he remarked upon the assassination of President Kennedy: "the chickens have come home to roost," and later separated from the Nation of Islam in early 1964.

Though separated from the Nation, Malcolm and his family continued the Muslim faith, organizing a new organization, Muslim Mosque, Inc., that included Islamic faith and black nationalism, to improve living conditions for all individuals in America and support the repatriation of black Americans to Africa (BLC 1998, 21). That same year Ella funded Malcolm's pilgrimage to Mecca, where he converted to Sunni Islam and took on the name El-Hajj Malik El-Shabazz (BLC 1998, 21).

El-Shabazz traveled extensively across Africa, experiencing a wide variety of Islamic cultures there resulting in a denouncement of Elijah Muhammad (BLC 1998, 21). Upon returning to America, El-Shabazz founded the Organization of Afro-American Unity (OAAU) in 1964, whose mission was to fight for equality, freedom, and justice for all regardless of religion (BLC 1998, 21).

As his public persona became increasingly controversial, politicians and government entities grew increasingly concerned. Additionally, the Nation of Islam began to threaten and intimidate El-Shabazz. In January 1965, El-Shabazz, his wife Betty, and their children were evicted from their Queens, NY residence by the Nation of Islam. On February 21, 1965, three men shot El-Shabazz while speaking in Harlem.

Significantly, Ella Little-Collins never returned to the house at 72 Dale Street after the death of her brother. Ella took over her brother's leadership role with the OAAU, but its influence began to diminish. Ella would remain a civil rights activist participating in lectures and rallies. Ella Little-Collins passed away on August 3, 1996. 72 Dale Street passed on to her only child, Rodnell, who owns the property today.

In the 1970's, the house was vandalized by a construction crew. During this break=in, objects belonging to Ella and Malcolm were stolen, many items and windows in the house were broken, and goods were thrown out the windows. In 1998, 72 Dale Street was made a Boston City Landmark by the Boston Landmarks Commission protecting the property from demolition and recognizing the house's occupant's contribution to US culture and history. In 2012, 72 Dale Street was listed as one of the 11 most endangered historic places by the National Trust for Historic Preservation. Today, the property remains in need of complete restoration.

Field Results

Intensive (Locational) Archaeological Survey

Project Area Description

The entire property was part of this survey, with a goal of establishing overall sensitivity, locate features, and determine site stratigraphy. In total, the site was surveyed with surface collections, 15 individual shovel test pits (STPs), and three 1x2 meter units. A map of the excavations and survey areas can be found in Figure 34.

The following images document the surface conditions of the site. The key to the images is Figure 9, with the images of the existing conditions prior to survey seen in Figures 10-31



Figure 9: Map of project area with individual images keyed in photo.

Figure 10- 1, view of front yard and porch

Figure 11- 2 view down rock garden to south of driveway

Figure 12- 3 View to southeast corner of project area showing driveway intersection with Dale Street (see Figure 7 for 1941 view)

Figure 13- 4 View towards front of yard in eastern portion of project area showing Dale Street homes and driveway.

Figure 14-5 View of front yard with gas line marked by Dig Safe in yellow. Note Dale street and front porch of 72 Dale Street.

Figure 15- 6 View south from front yard looking towards driveway with Dale and Walnut streets visible in upper left corner. Note historic maker for 72 Dale Street on granite block.

Figure 16-7 View of northeast corner of property showing side of porch stairs looking west down alley beside house.

Figure 17-8 View of southeast corner of house showing gas connection, foundation, and trellis-style cover under front porch.

Figure 18- 9 view towards rear of yard from south yard of main house showing 72 Dale Street home and foundation.

Figure 19- 10 View to west from south yard showing unpaved area of driveway, dirt pile in front of garage (under blue tarp), garage, rear ell, and a small portion of rear (west) yard.

Figure 20- 11 View southwest from southern yard area at dirt pile (under tarp), and rear portion of driveway.

Figure 21- 12 View from southern yard to southeast showing driveway and eroded portion of yard formerly occupied by trees.

Figure 22- 13 View from rear portion of the yard showing back of dirt pile (blue tarp) and front of garage protected by brown tarp.

Figure 23- 14 View from south of rear ell towards western (rear) yard. Buried electrical line marked in orange spray paint.

Figure 24- 15 View of rear door on south facade of the rear ell on 72 Dale Street.

Figure 25- 16 View of expanded bulkhead area where soils in dirt pile originated. View is of the rear of 72 Dale Street and rear ell.

Figure 26- 17 View west to rear yard between rear ell of 72 Dale (right) and garage (left).

Figure 27-18 View of southwestern corner of house showing corner of rear ell (left), trash collection container (lower left), driveway (upper right), and garage (left). Orange spray paint marks buried electrical line.

Figure 28- 19 View behind Garage and western edge of property

Figure 29- 20 View of rear yard looking towards northwest corner of yard with concrete supports for former deck visible.

Figure 30- 21 View of rear of ell to 72 Dale Street showing boarded-up door and ghost of staircase to second floor deck. View also shows rear yard of home, site of unit 3.

Figure 31-22 View east down alley along northern edge of property, 72 Dale street to right.

Walkover Survey

An extensive walkover survey was conducted prior to Ground Penetrating Radar survey to both recover surface artifacts and to remove items that may impede the GPR survey. These artifacts were bagged by yard zone. A map of the eight surface collection zones is seen in Figure 32. A complete description of the artifacts found in the zones is found in the analysis section, below.



Figure 32- Map of surface collection areas.

GPR Results

A full analysis and discussion of the GPR survey will be submitted as an addendum to this report when completed by the Fiske Center for Archaeological Research at UMass Boston. An overlay of the project area, buildings, and a single GPR “slice” map is provided in Figure 33.



Figure 33- GPR Survey results overlay on map of project area.

Utility Line Survey

The GPR survey resulted in the identification of numerous utility lines and the identification of what was later determined to be a large and intact dome-capped cistern. A map of these utilities is provided in Figure 34 and will serve as areas to repair or avoid in future projects or archaeological survey.



Figure 34- Map of utility lines identified via GPR survey with units identified. Red circular area is a cistern.

Unit Results

The following section describes each of the excavation units, their location within the site, and an overall description of their stratigraphy and interpretation. Artifact analysis will be presented in the analysis section. Profiles of all STPS can be found in Figures 35-37

STP N117 E081

This STP was located on the northern side of the home in a narrow passageway between the north side of the house and the fence dividing 72 Dale Street and the neighboring property to the north. A thin developing A covered a nearly 50-cm thick deposit of furnace waste coupled with historic 19th and 20th century artifacts. This covered a fill deposit that terminated at 80 cmbs due to collapsing coal walls of the shovel test pit. It appears that this area of the home experienced significant deposits of furnace waste from the coal furnace. Similar deposits in the southern side of the property suggests that in the late 19th and early 20th centuries, coal furnace waste was deposited in between homes along property lines, rather than in rear areas of the properties suggesting these were the least-used or least-visible areas of the yard in these times.

STP N117 E074

This STP was located in the rear of the home near the northwest corner of the property. Unlike areas to the east and south, the rear of the yard appears to have less fill on it resulting in a shallower profile, overall. A developing A was found first, likely associated with the use of the property in the 19th and 20th century. A re-deposited B soil was found under, likely soils coming from the excavation of the house foundation in the early 1870s. A buried APZ was found under followed by a B and C soil indicating the original agrarian landscape was preserved under the late 19th century building and occupation episodes.

STP N111 E072

Like STP N117 E074, this STP had a shallower profile consisting of a developing A directly over an intact agrarian APZ. Unlike N117 E074, this STP did not have a re-deposited B soil. Below the APZ was an intact B1, B2, and C representing original undeveloped Boston soils and subsoil in the rear of the yard.

STP N110 E084

This STP was located just next to Unit 2 near the recently-excavated basement access between the main part of 72 Dale Street and the rear ell. A developing A was found overlying fill. At 40 cmbs, a dense deposit of brick and mortar was encountered, which is likely associated with a fill episode over or surrounding the intact cistern deposit found in unit 2.1 or other 19th century utility deposits. This STP was terminated at 50 cmbs after being impeded by rubble.



Figure 35- Profiles of STPs part 1 of 3

Figure 36- Profiles of STPs part 2 of 3

Malcolm X Ella Little-Collins Site
Intensive (Locational)/Phase 1 Archaeological Survey
Shovel Test Pit Profiles pg 2 of 3



Malcolm X Ella Little-Collins Site
Intensive (Locational)/Phase 1 Archaeological Survey
Shovel Test Pit Profiles pg 3 of 3



Figure 37- Profiles of STPs part 3 of 3

STP N110 E081

This STP was located near the side entrance to the rear ell on 72 Dale Street. A developing A was found over a fill deposit that ended at a cut granite stone capping a brick and ceramic drain of probable 19th century origin (Figure 38). The GPR survey results, which arose soon after excavating this STP confirmed the presence of a utility line (Figure 34) likely a water line or sewer line, exiting the rear of the house and traversing the property towards Dale Street. This STP was terminated at 60 cmbs and confirms both the accuracy and the precision of the GPR results.

Figure 38- STP N110 E081 with drain in bottom of excavations. North is up in this image. For scale, the Brick in the image is 10 cm wide.

STP N110 E079

This STP was excavated in response to finding utility lines in N110 E081, but still wanting a STP in the area to determine other potentially significant strata or deposits. Unfortunately, after excavating through a thin developing A and 20 cmbs of fill, a wire was encountered and the STP terminated. The GPR results indicate that this entire area was heavily disturbed due to a large buried structure (later determined to be a dome-topped cistern), and the crossroads of numerous utility lines into and out of the house and garage.

STP N109 E102

This STP was located in the front yard of the home and strategically placed in between numerous utility lines into the front of 72 Dale Street based on results of the GPR survey. This was the only STP in the "front" yard of the property. As expected from the steep drop off between the yard and Dale Street, significant filling occured in the front yard to build up the yard to have a wall structure dividing the yard from the street. A developing A extended to 20 cmbs followed by filling episodes to 64cmbs. A B soil was reached at 85 cmbs, but subsoils were not reached when the STP was terminated at 120 cmbs.

STP N108 E089

This STP was located near the southwest corner of the main portion of 72 Dale Street. Its stratigraphy included an eroded developing A over a fill deposit down to 45 cmbs. A buried APZ extended to 90 cmbs before transitioning to a B soil. A Native flake (see Buried Plowed A analysis, below) was recovered in this unit from the fill deposit, which appears to be mottled A, B, and C soils. Though the STP reached 125 cmbs, a C soil was not reached.

STP N108 E086

This STP was located in the transition area between the rear of the main building and the Ell, close to an area of extensive utility disturbance in the GPR survey. A developing A transitioned at 13 cmbs to a cobbled surface (Figure 39). Below this was fill eventually reaching a buried APZ at 55 cmbs (Figure 40). A B1 and B2 soil was reached before terminating the STP at 121 cmbs. Upon completion of the STP, while cleaning the wall for profiling, a cut was found in the north wall of the STP extending from the surface to the bottom of the STP. This cut is likely for a utility line on the property.

Figure 39- Cobbled surface encountered in N108 E086. Trowel pointing North. For scale, trowel measures 25 cm in length.

Figure 40- North profile wall of N108 E086 showing fill, cobbles, and more fill deposits overtop of an intact, buried plowed A horizon on left, with cut nearly in center of the profile and an entirely disturbed profile on the right side. B soils visible at bottom of STP. Photo taken facing North. For scale, test pit surface cut measures 50x50 cm square.

STP N106 E094

This STP was located in a side yard area near the transition from yard to driveway on the property. A developing A transitioned to a fill, which overlaid a re-deposited B soil, likely associated with the construction of the house. A buried APZ was reached at 60 and later transitioned at 90 cmbs first to a B then C soil by 110 cmbs.

STP N106 E089

This STP was located in the yard near several other STPS, a back dirt pile from previous non-archaeological excavations on the property, and utility lines from the GPR survey. A developing A overlaid a fill deposit, but at 30 cmbs, extensive roots (Figure 41) blocked access to deeper deposits. It is likely that these roots are related to recently-removed trees in this area of the property. Historically, trees were present here in older photographs (Figure 42).

Figure 40- Purple roots of former trees. North is up in this image. Scale: test pit is 50x50cm

Figure 42- Google street image from 2014 showing dense trees in area of south yard of house.

STP N106 E087

Like STP N106 E089, This STP was located in the yard near several other STPS, a back dirt pile from previous non-archaeological excavations on the property, and utility lines from the GPR survey. A developing A extended to 7 cmbs before reaching a gravel fill. This gravel overlaid several layers of fill and rock down to 85 cmbs. A truncated B1 was encountered at 85 cmbs implying extensive erosion or excavation in the area. The lack of an intact buried APZ is likely due to planting or utility excavations.

STP N103 E095

This STP was located on an eroding slope near the driveway of 72 Dale Street. Fill was encountered on a slightly developing A which overlaid a fill down to 33 cmbs. A relatively thin buried APZ was encountered from 33-44 cmbs before transitioning to a deep B down to 92 cmbs. C soils were reached there and the STP terminated at 98 cmbs.

STP N099 E084

This STP was located on the southern edge of the property near the front of the garage. A Developing A transitioned to a fill from 20-35 cmbs. A buried APZ began at 35 and extended to 65 cmbs. A B soil transitioned to a C at 85 and the STP was terminated at 100 cmbs.

STP N099 E082

This STP began with a developing A that transitioned to a coal and slag-rich soil down to 37 cmbs. This is similar to the slag found in N117 E081. A buried APZ was found between 37 and 53 cmbs, followed by a B1 to 60 cmbs, a B2 to 93 cmbs, and a C soil that ended the unit at 95 cmbs.

Unit 1

Unit 1 was a 1x2 meter test trench placed south yard on the grid-eastern side of the main house structure (Figure 34) This unit was subdivided into two parts, unit 1.1 and 1.2, with 1.1 abutting the eastern foundation of the home. The purpose of this unit was to determine what the stratigraphy was like abutting the house foundation as well as to determine if there were significant deposits that would be disturbed if and when the excavations occured along the foundation for foundation repair. This unit is also located towards the street-facing facade of the house in what would have been a more-public location within the property. This unit should document activities that occurred near the front of the house in a semi-private side yard. This is also the same area where a historic photo of Malcolm was taken with his sister, Ella (Figure 6).

Excavations terminated at 120cmbs having documented five distinct soil strata (Figures 43-44) . Strata 1 was the surface and developing A soils, consisting of 18th-20th century materials, but the majority were of 20th century in origin. Strata 1 was fairly thick reaching a depth of 23-40 cms across the unit with the deepest portions on the east end in sub-unit 1.2. Strata 2 was a mottling of A, B, and C soils, with B soils being the most dominant, and is likely a builder's trench extending 88cm from the foundation of the house and plunging 70 cm deep. Strata 2 cuts through Strata 3. Strata 3 was a mottled A soil with B intrusions and was only found in the eastern end of the unit 1.2. It appears to be a re-deposited A soil on top of a buried A (strata 4). Strata 3 was likely inverted from the site of the house during excavations of the foundation and deposited on the surrounding A soils in the late 19th century. Strata 4 is the buried A surface found throughout the site, with Strata 5 being a truncated B2 soil. The Strata 4 plowing appears to have eliminated most of the B1 soils, leaving behind a nearly sterile subsoil under the buried A.



Figure 43- Profile of west wall of Unit 1.

Figure 44- Photo of west wall of Unit 1. Scale: Unit is 2-meters long.

Unit 2

Unit 2 was a 1x2 meter test trenche placed at the foundation of the rear ell of the house. Unit 2.1's west wall is the house foundation. This unit was placed for similar purpose of unit 1: to document if ground disturbance along the house's foundation will negatively impact significant archaeological resources. It also was placed in an area of heavy foot traffic between the house, rear yard, garage, and kitchen.

Unit 2 had a four features and complex stratigraphy (Figures 45 and 46). Strata 1 was the surface deposit and developing A, which was on top of a modest builder's trench/deposited subsoil deposit (Strata 2). The third strata was the buried plowed A, which was over strata 5 (B1 and B2 soils), all over an intact C soil. Unit 2 extended to 120 cmbs and stopped having reached intact C soils in the western portion of the unit and the boundaries of a large intact domed cistern feature in the east, which likely continued in depth.

Cutting through these broad strata were four distinct features, all visible by 30 cmbs (See feature descriptions, below, for plans and photos). Feature 1 was a round post mold consisting of a coal ash core (Feature 1 strata 1) surrounded by a A-like outer fill (Feature 1 strata 2). Feature 2 was a narrow strip of dense gravel along the southern edge of the feature and likely continued into the excavated area to the south. Feature 3 was a band of darker soils spanning the eastern side of the unit, and Feature 4 was a narrow deposit in the extreme northeast of the unit. Features 3 and 4 appear to be associated with a large buried cistern. Detailed descriptions of these features can be found in the feature section, below.

Unit 2 appears to be located in a heavily used space for both the home's utilities as well as the occupants of the house.



Figure 45- Drawing of east wall profile of Unit 2

Figure 46- Photo of east wall profile of Unit 2. Scale: Unit is 2-meters long. North is to left.

Unit 3

Unit 3 is located in the southern rear end of the house, essentially the “backyard” where a former deck and staircase to the second floor apartment was located but was removed prior to the survey.

Unit 3 was a 2x1 meter unit oriented east-west with unit 3.1 being located on the eastern end of the unit against the Malcolm X House rear ell foundation.

The strata of the unit were fairly typical of the overall site, with the exception of a large feature on the western half of the unit (Figures 47-48). Strata 1 was the developing A and surface artifact scatter. Strata 2 was the ejecta of the foundation builders trench overtop of strata 3, a buried plowed A soil. Strata 4 was a thin intact B soil over strata 5, an intact C subsoil.

Nearly bisecting Unit 3 north-south was a very unexpected mortared stone foundation feature (Feature 6). Because the wall was so unexpected, we were unable to quickly determine which side of the wall was “inside” or “outside” of the foundation so our strata numbers continued in order for Feature 6 instead of re-starting at feature strata 1. Feature 6’s upper deposits were the same as Strata 2 and appeared to be continuous from inside to outside of the feature. To the south (inside Feature 6 as it was later apparent) strata 2 sloped deeply into the feature suggesting Feature 6 was a significant depression in the landscape during the excavations done to build 72 Dale Street. Below strata 2 was a mottled sandy deposit we called Strata 6. Under strata 6 was two deposits side-by-side including a sterile sand (strata 7) and a much darker and more-organic deposit (strata 8). Strata 8 appears to be a trash deposit dating to the late 19th century occupation of 72 Dale street. This deposit was over a ashy deposit, strata 9, which ended in a puddingstone floor of the interior of the Feature 6 structure. Additional descriptions of Feature 6 can be found in the feature section, below.

Unit 3 appears to have been the location of a early outbuilding structure, which was used for trash disposal in the late 19th century. It is likely that the outbuilding is related to the earlier 18th century occupation of the property, but the interior contents date to later periods. When the house was first occupied, the occupants used



Figure 47- Profile drawing of north wall of Unit 3

Figure 48- Photo of North wall of Unit 3. Scale: Unit is 2-meters wide. Photo facing north.

Feature Results

Seven features were documented during this phase of work. Below is a brief summary of each feature as it appeared in the field with a statement of significance. Full analysis and conclusions will be presented later in this report.

Feature 1

Feature was found in unit 2. It 1 appears to be a post hole near the entrance to the rear ell apartment at 72 Dale Street (Figures 49-53). The post itself appears to have measured 10 cm wide and was packed with re-deposited A soils. When the post was ultimately removed, its void was filled with coal ash. As this post feature cuts through re-deposited builder's trench soils, it likely dates to after the construction of the house in 1872. Based on its location, it may be a laundry pole or some other type of support structure. Feature 1 is significant, but 100% of the feature was excavated during this phase of survey.

Figure 48- Plan drawing of Features 1-4 at



Figure 49- Plan of Unit 2 at 40 cmbd showing location of features 1-4

Figure 50- Photo of Unit 2 at 30 cmbs showing Features 1-4. North arrow is 20 cm long.



Figure 51- Profile of Feature 1 bisection in Unit 1

Figure 52- Photo of bisected Feature 1. North arrow is 20 cm long.

Figure 53- Photo of bisected Feature 1 profile. Image board is 30 cm wide. Photo facing North.

Feature 2

Feature 2 was found in unit 2. It is a dense deposit of gravel fill (Figure 49 and 50). Only a minimal portion of the feature was encountered in Unit 2, but its close proximity to several utility lines and a large domed cistern suggests it is a gravel deposit fill over and associated with one of these deposits. Feature 2 does not appear to have many artifacts associated with it and also does not appear to be significant.

Feature 3

Feature 3 was found in unit 2 (Figure 49 and 50). It is a fill deposit found surrounding a domed brick cistern feature. It is associated with Features 4 and 7. The cistern appears to be significant as it is associated with the home, but this feature fill surrounding it is partially disturbed A soils and does not appear to be significant.

Feature 4

Feature 4 was found in unit 2 (Figure 49 and 50). It is a fill deposit directly abuting a brick cistern feature. It is associated with Feature 3 and 7. The cistern appears to be significant as it is associated with the home, but this feature fill surrounding it is partially disturbed fill and does not appear to be significant.

Feature 5

Feature 5 appeared towards the upper 20-30 cm of Unit 1 against the wall of the foundation of the front portion of 72 Dale Street (Figure 54). It consists of redeposited A, B, and C soils of the builder's trench. Though it at first disappeared in mottled fill, strata 2 of Unit 1 later appeared to be a continuation of both Feature 5 and the builder's trench. As a feature associated with the initial building episode of the house, this feature is considered significant.



Figure 54- Plan of Unit 1 at 20 cmbs showing Feature 5

Feature 6

Feature 6 is the foundation and interior fill of a out building (Figures 47 and 48). It is hypothesized that this feature is 18th century in origin, but the fills inside it appear to be 19th century in origin. As a feature directly associated with the earliest owners of the property in the 18th century as well as the first occupants of 72 Dale Street, this feature is significant.

Feature 7

Feature 7 is the fill surrounding the brick vaulted cistern in Unit 2 (Figure 55). It is associated with features 3 and 4. As re-deposited disturbed fill, the feature 7 fill is not significant, but the cistern it surrounds is significant.

Figure 55- plan photo of Unit 2 at 80cmbs showing Feature 7, a brick cistern, in lower right corner (southeast) of unit. Note brick cistern dome in lower right corner. Arrow is 20 cm long.

Strata Results

25 distinct strata were identified at 72 Dale Street. They will be broadly described here in roughly chronological order, but a full analysis of their contents can be found in the analysis section, below. A catalog of each context, or a bag list, organized first by unit, then by context code, is included in Appendix B

Surface/Developing A

This strata is the most ubiquitous strata on the site appearing in all areas of the site. This strata is a combination of the surface artifacts deposited in the 20th century through use and as the result of ransacking of the house in the 1970s that resulted in large quantities of the home's contents being thrown into the yard. Due to the large amount of soil inversion on the site and the fill typically found directly under this strata, artifacts from all periods of occupation can be found in this strata. While this makes earlier artifacts of less significance to the interpretation of the site, overall, the highly significant later artifacts from the 20th century occupation of the house are exclusively found in this strata. To complicate matters even further, Rodnell Collins' oral history of the site, indicates that Ella LIttle-Collins was a collector of blue-and-white ceramics, which may have included earlier 18th-20th century ceramics found on the site at both surface and much deeper deposits. Telling the difference between early blue and white ceramics collected in the 20th century is nearly impossible.

Cobbles

This cobble layer is only found in STP N108 E86 (MHX.063-064), with some evidence in the wall of Unit 2.2. This strata suggests that at some period in time, the roughly triangular area between the main house and the ell was partially or fully surfaced in rounded, fist-sized cobbles. Efforts to restore the appearance of the landscape of the home should take this fact into consideration.

Utilities

Many utility lines and features were encountered, they are grouped here, together.

Brick Vault Trench Fill (Feature 7)

This strata was encountered in Unit 2.2 between 60 and 120 cmbs. It surrounds the wide (c. 2 meter) domed-topped brick cistern likely represented by a large red anomaly in the GPR study (Figures 33 and 55). Artifacts from this deposit are from multiple strata having been excavated through, mixed, and back-filled when the soils were returned.

Fill 1 Over Cistern (Feature 4)

This strata is similar to the Brick Vault Trench Fill (Feature 7), but appears to be located on top of the cistern and is the first strata encountered. It consists of mixed strata backfill.

Fill 2 Over Cistern (Feature 3)

This strata is similar to the Brick Vault Trench Fill (Feature 7) and Fill 1 Over Cistern (Feature 4), but appears to be located on top of the cistern and is the second strata encountered. It consists of mixed strata backfill.

Utility Fill

Utility fill was found in STP N110 E081 and N106 E87, both located near dense concentrations of utility lines. Other STPs encountered utilities directly, but this strata refers to fill surrounding or filling trenches for utility installation episodes. All are assumed to be 19th or 20th century in origin, but see analysis section for further info.

Foundation at Rear of Property (Feature 6)

Feature 6 Interior Sand Fill (Unit 3.2 Str 6)

This strata is a layer of sandy fill deposited into the foundation (Feature 6) found to the rear of 72 Dale street in unit 3.2. It is the latest fill within Feature 6.

Feature 6 Organic Fill (Unit 3.2 Str 8)

This strata is an artifact-rich layer of dark fill deposited into the foundation (Feature 6) found to the rear of 72 Dale street in unit 3.2. It is the the strata most-associated with 19th century occupation of the home.

Feature 6 Ash Fill (Unit 3.2 Str 9)

This strata is a coal ash layer deposited into the foundation (Feature 6) found to the rear of 72 Dale street in unit 3.2. It is the lowest/first layer of fill within Feature 6.

Outbuilding Foundation (Feature 6)

This strata is the actual wall of the foundation found to the rear of 72 Dale Street and the artifacts found between the stones of the wall in the sandy fill there.

Post Hole (Feature 1)

Post Hole Coal Ash (Feature 1 Str 1)

This strata is the filled-in hollow created when a post was removed from the ground near the entrance to the rear ell of 72 Dale street.

Post Hole A Soil Fill (Feature 1 Str 2)

This strata is the fill surrounding the former post near the rear entrance to 72 Dale Street and is comprised of excavated and re-deposited earlier strata dug through to install the post.

Construction related

These deposits are directly associated to the excavations of the hole to create the foundation and cellar of 72 Dale Street.

Redeposited B

Unlike the re-deposited Foundation soils, this is a nearly-exclusive B soil fill that likely originated from the foundation excavations, but somehow avoided mixing during excavation and

re-deposit. This redeposited fill is found in the southern front yard and northern alleyway of the property.

Foundation Builder's Trench

This deposit is found mostly in the test units, which encountered the actual foundation of 72 Dale Street. Within these areas, the actual hole that was dug and backfilled to build the foundation walls of the house were documented including the earlier artifacts from the agrarian history of the property. In theory, these fills should contain few if any artifacts dating to the mid 18th century or later.

Redeposited Foundation Soil

Even though this strata is directly associated with the builder's trench excavations, they can not be exclusively associated with the trench itself, so the deposit is given a separate designation. It is only found in unit 3.2.

Inverted A

Similar to the Inverted B soils, the Inverted A strata appears to be areas where the APZ was reached during excavation for the foundation of 72 Dale Street and re-deposited on top of the existing APZ, but upside-down. This strata was only encountered in Unit 1 where an inverted soil profile was encountered separated by a thin layer of fill on top of natural soil deposits (Figure 43).

Gravel Fill

This strata appears in seval units, but always towards the surface above the buried APZ suggesting it was used as a fill or substrata after the construction of the house.

Rock Fill

Rock fill was found in two shovel test pits, similar to the gravel fill strata, near the upper levels suggesting a 19th century fill or substrate function.

Rubble Fill

The rubble fill was only found in N110 E084 in the area of a utility line suggesting a possible association with utility lines, but its brick and mortar fill makes it different enough to possible be of a separate function. Regardless, it appears to be 19th century in origin.

Sand Fill

This fill was only found in N106 E087 and appears as a relatively clean sand fill, likely a void filler or substrate for a later-removed deposit.

Slag

This deposit refers to N117 E081 slag deposit in the alley way north of and associated with 72 Dale Street and its occupants.

Fill

This wide-spread deposit is found between the post-1872 deposits and the APZ deposit. It likely is a combination of fills brought in to level or fill the area and the combined excavated soils from the foundation of 72 Dale Street and perhaps other nearby buildings. It has a combination of

deposits from pre 1872 strata and is a relatively thick and protective layer over the APZ in most areas of the property.

Buried APZ

The buried APZ is one of the most artifact-rich areas of the site and represents an agrarian history of Roxbury and the occupation of the property in the 18th centuries by the Seaver and possibly earlier families. It is a thick deposit with a crisp transition between itself and lower B soils strongly suggesting the land was plowed. It is also relatively mixed in date due to the plowing, though it is pre-1872 in origin. Due to the site history suggesting relatively little happened on the property between 1830s and 1870s, this deposit could represent intensive plowing during this lul in site use history and a return of the property to farm land, or plowing up to the main house of the Seaver estate. Further analysis below should clarify this if significant amounts of post 1830s artifacts are found mixed into and in deeper portions of the APZ.

B1

These subsoils represent intact deposits found under an APZ soils horizon. The transition between the APZ and B1 was stark, confirming the presence of a plowed area. The B1 were a typical reddish brown color from iron concentrations leaching from the top soils

B2

These subsoils are less stained than the B1 soils above, but still represent areas where occupation by Native peoples may be found. While no Native artifacts were found in B2 soils, their presence represents intact soil profiles on-site, a rarity for the more urban areas of Boston.

C

C Soils were only encountered in areas with relatively shallow soils and no deep disturbance. These subsoils are unmodified glacial deposits and represent periods of time prior to the arrival of Native people to the area.

Laboratory Methods

Upon their return to the lab each artifact was washed according to standard laboratory procedures. Artifacts were dried for a minimum of two days before being bagged in 4-mil thick archival plastic bags with handwritten labels in Sharpie®. All cataloging was completed using the Massachusetts Artifact Tracking System (MATS), which produces an archival tag that was inserted into each artifact lot bag. A complete excel-based catalog was exported from MATS for the catalog provided in Appendix C.

In addition to standard archaeological cataloging, an additional oral history catalog was created through an interview with property owner and son of Ella Little-Collins, Rodnell Collins. A full transcript can be found in the surface artifacts analysis section. Audio recordings are available online at boston.gov/archaeology.

All artifacts recovered from the site have been photographed and will be made available online at boston.gov/archaeology.

Analysis Results

Site Results Summary

In total, 18,207 artifacts were recovered from this phase of archaeological survey. These artifacts came from 19 50x50 shovel test pits, three 1x2 meter units, and a surface artifact collection.

The artifacts fall into four overall occupation periods: Native American flake scatter, 18th century rural wealthy estate, mid-late 19th century immigrant occupation, 20th century.

In total, the excavated areas of the site have been divided into 25 stratigraphic deposits, with some spanning the entire site and others only found in discrete areas. A full discussion and analysis of these deposits can be found, below, and will be discussed in roughly chronological order by date of stratigraphic deposit starting with the most-recent.

Surface and Developing A

This particular project presents an extremely rare opportunity to supplement documented and researchable data and artifacts with oral history. In total, 4,125 artifacts were collected during the surface walkover survey or 22.6% of the entire assemblage. The vast majority of these items are 20th century in origin, but due to the development of the house excavating through and into buried 18th century deposits, a fair amount of earlier materials were mixed into the surface artifacts.

Typically, mixing of deposits makes interpretation difficult; however, at this particular site, Rodnell Collins is available to ask personally what happened at the house and what artifacts are related to the occupation of his family after 1941. This was addressed through an oral history analysis of the artifacts. The audio interview was recorded in early 2017. A fully transcribed and illustrated account of these discussions follows, and will serve as an ideal analysis for the identification, meaning, and significance of the artifacts Rodnell discusses. These discussions do not include all 4,000+ artifacts, but still reveal new and significant data about this unique assemblage of 20th century artifacts associated with a black Muslim family with significant roles in the Civil Rights Movement.

The following is a partial transcription of an oral history catalog and analysis by Rodnell Collins recorded on February 17, 2017 at the City of Boston Archaeology Laboratory. Notes and commentary provided in “[ ]”. Refer to Figure 32 for specific locations of collection areas referenced in the transcription and Appendix C for a full catalog of artifacts recovered.

Participants: Rodnell Collins, owner of the Malcolm X House in Roxbury, Massachusetts, son of Ella Collins, and Malcolm X's nephew; Joseph Bagley, City Archaeologist of Boston; Sarah Johnson, UMass Boston graduate student

General surface collection

JB: So we're recording now
RC: Okay
JB: Uh, so whatever you wanna say about anything or even just about the house itself is
RC: One thing, I'm gonna be childish here, forgive me
JB: Yeah
RC: Because this was my globe ball (Figure 56). I used to carry it in my pocket



Figure 56- Rodnell's globe toy, artifact #99588

JB: Really
RC: Yeah, and I put little things in there. And, uh, wow. Yeah, that's funny. I wonder what, how did the heck
JB: We found it intact
RC: Yeah, cause it was special
JB: Yeah
RC: Like, you know, you know, you ever had marbles?
JB: Oh yeah, there's some marbles here
RC: Yeah, I had, my, my mom, dad just buy a bunch of marbles, you play marble games. And, she'd buy them but then I would collect or trade. And then I would put a little marble sometime in here, you'd shake it, you know. So that was fun. And, find any bugs? 'Cause I collected bugs
JB: I don't think they would have survived. That would've been [overtalk]
RC: Well, I mean, yeah, maybe. Cause, I collected bugs
JB: We got plastic toys but not in this one though

RC: And then we had rabbits, as a matter of fact I'm surprised you didn't run into...
JB: Oh yeah, in the back, right?
RC: …a couple of rabbits…
JB: We didn't find any…
RC: …buried
JB: ...buried. [to Sarah] And that was your unit. Did you guys come across any like intact skeletons? [laughter] Like…
SJ: I mean, I'm trying to remember. I feel like there was like a little pocket of bones
RC: Yeah, there was like two or three rabbits buried back there
JB: Cause the rabbits were up against the side of the garage
RC: The, the garage
JB: Facing the backyard
RC: Right (Figure 57)

Figure 57- 2015 photo facing grid west showing location of former rabbit hutch on grid-north side of garage (left) based on Rodnell's description. Western edge of property in background. Scale: Cinder blocks on left are 40 cm in length.

JB: Yeah

RC: Right
SJ: Okay, and we didn't really go over there
RC: We had two, three pets
SJ: Did we?
JB: Well, if you, if the only place to bury a pet would've been right where your unit was
RC: Yeah
JB: More or less
SJ: Yeah
JB: [laughter]
RC: We didn't want to take the rabbits back to Duxbury cause my mother's uncle had a thousand rabbits
JB: A thousand?
SJ: Holy
RC: A thousand, yeah. That's on record in Duxbury
JB: [unintelligible]
RC: [unintelligible] had a thousand rabbits. And two black ones
JB: Wow
RC: And one gray one. And so, the rabbits that were buried there came from him. They were mine
JB: Oh so they started off at your uncle's
RC: Yeah, in Duxbury
JB: In Duxbury
RC: Right. And, I have a picture of one of them. I have a picture
JB: That's awesome
RC: Yeah. It's a white rabbit, so. But this is, it's interesting. [laughs] So, um, yeah. And, that was my idea of the world at the time, outside of the dictionary, you know? Children's thoughts, you know? Right? Children's, you know, everything is right there. Um
JB: So this is the surface collection, there's a little bit of everything
RC: Right
JB: Some of this stuff that goes all the way back to Seaver [18th century]. Obviously a lot of it's from your family, but just to kind of let you know that there's a little bit of everything
RC: Yeah
JB: We have how many bags like this [of surface artifacts]? About ten?
SJ: Ten, I think, yeah, ten
JB: So this, this is the general collection. This is stuff that was all over the yard. Then we have collections from specific spots within the yard, so like by the back door, the back yard, the side yard. So there's going to be other stuff that'll be a little bit more specific to a spot
RC: Right. Um, is there anything particularly you'd like for me to comment on yourself that you have. Is that, uh, oh. Looks like, uh, oh yeah, peach. These look like, these are peach (Figure 58)



Figure 58- Peach pits from peach tree that grew in the backyard of the house, artifact #99587

JB: Peach pits, yeah
RC: Yeah, cause there was a peach tree there
JB: Yeah
RC: And, right next to the house there was an arbor, um, where the garage door is (Figure 59)

Figure 59- Photo of area between ell (right) and garage (left) where rose arbor and peach tree was once located.

JB: Yup
RC: Right, um, just before it, okay?
JB: Okay
RC: The garage door going in, there was, a rose arbor arch and a little gate and on, and, and my mom had roses over that
JB: Cool
RC: And then just as you open that, it would open this way because, you know, as you're going this way facing
JB: Yeah
RC: the back and
SJ: So it would open
RC: It would open this way facing this way [toward the rear of the property] so you could go to the garage
JB: Yeah
RC: Cause my dad would go into the garage car. Well just a little bit from that gate where that window is

JB: Yeah
RC: That apartment, there was a peach tree there
JB: Oh, okay, right up against the foundation?
RC: Right, right. And, uh, that was, uh, my mother, Georgia, right? Georgia, peach tree state [Ella was born in Georgia]
JB: Yeah, I'm surprised the peaches grew as well as they did
RC: Yeah, well, she, she knew how to [over talk] she was, you know, farm girl
JB: Well, we got flower pots
RC: She could raise anything, she could grow anything
JB: We got a lot of flower pots
RC: Yeah, yeah, that's mom. There were flower pots everywhere. Uh, so that would be from either that tree or we just ate peaches. I mean, whenever they were there, I'd take off and eat them, um, which I was always doing
JB: Do you know anything about where this came from? It's the Hong…
RC: Do you mind if I
JB: No, you can open any of them if you need to, yeah
RC: Hong Kong 1888… oh
JB: 1988
RC: I mean, oh, 1988. (Figure 60)

Figure 60- Hong Kong two dollar coin from 1988, artifact #99555

JB: Changes it a little bit [laughter]
RC: That's interesting because [laughs] this could be mine
JB: Yeah
RC: Yeah, because I, uh, I first played, uh, in Hong Kong, the tennis tournament, Hong Kong Open, which is now, I think it's still called the Hong Kong Open or something, which is down the

street, uh, to the, uh, Victoria Park, which is just down the street from the Excelsior Hotel. So, um
JB: What year was that?
RC: That was back, I started to go to Asia in, uh, 80, 1980. And I was, been going every year, uh, since, basically, because then my wife being
JB: Yeah
RC: Y'know, Indian. I met her in, uh, 84, 85, okay. So, uh,
JB: Globe traveller
RC: So this was, yeah. So this was one of those periods, so that's nine times out of ten. The only other reason, other thing that this could be, but that's unless it was old. This should be a new coin, relatively, 70s or 80s
JB: Yeah, when, when you got it it would've been new, yeah
RC: Yeah, yeah. And if it was, if it goes back on a Hong, further than that, it would be, uh, Uncle JC, who was in the, the Korean War
JB: Oh, okay
RC: Yeah, but this looks like that's what, because I was going back and forth to the house then checking around and I might have had something in my pocket and I was fooling around the house and I dropped something. And I still got a bunch of coins, Hong Kong, Asian coins of different places
JB: Uh, let's see, what else we got here. Um, are any of these tools possibly your father's or somebody else in the family's? We got a file and a chisel [Figure 61 and 62]

Figure 61- File from yard, artifact 99637

Figure 62- Chisel from yard, artifact #99685

RC: Yeah, yeah. This is, this would be mom or dad's, this here, you know, because this is for something, always filing something, and dad was always working on the cars, and then, Perkins, belonged to would be. That was a storage garage for W. W. Perkins
JB: The, the, your garage was?
RC: Yeah
JB: Oh
RC: That happened in the later 60s or 70s
JB: Okay
RC: Uh, because that was the only part of that property that would be occupied other than me going there sometimes staying and just checking the house out
JB: Yeah, yeah
RC: But, uh, Perkins was my godfather, my middle name is Perkins, his last name is Perkins
JB: Oh, cool
RC: So he stored a lot of his carpentry work, uh, wood there
JB: Oh, there you go
RC: And then some of his tools
JB: Because it seemed like a woodworking tool
RC: And, yeah. And, uh, I tried to get him to come take his stuff out, he lives in East, well he was living in Eastham, Massachusetts. But I started taking stuff out of the garage, all his stuff,

and dumping it, I just, he wouldn't take it so I just got rid of it, a lot of wood. So more than likely, this is stuff that, while I was taking it out, um, cause it looks more newer than anything
JB: Yeah, and it rusts
RC: Especially this, this is an old, this is an old style chisel
JB: Yeah
RC: Okay, and he collected those kind of things
JB: Oh
RC: So most likely it was his and not my father's
JB: Okay
RC: Okay
JB: Um, this is probably from about your family's time (Figure 63)

Figure 63- Blue decorated earthenware from 72 Dale Street. Artifact #99553

RC: Yeah, that's, 'member I was telling you that before, my mother, um, what she liked to collect was, uh, tea cups and dinnerware, you know, and the pattern was the blue, you know, the blue pattern. Another pattern was the yellow and then the, uh, the flowery, like, silver. I have one of her plates left. One or two of her plates left
JB: I think we saw one of those in one of these bags
RC: Silver on the edge and flowers
JB: We'll see it, I think

RC: Okay. Um, so there was the, there was the, she collected sets of things. And usually it was a set of four - a plate, a bowl, and then a tea set. And if you come in the house, I have still this, um, uh, built in, uh, and I put some of this stuff, a lot of stuff was taken and broken up. Um, she'd put it on display. There was, like, four shelves there, and then underneath there's a door with counters. And, uh
JB: Is it a corner cabinet type thing?
RC: Yeah, but it's built in with doors, glass doors on it. It's still there. So, uh, I was, you know, hoping that the one or two pieces that were left, you know, one day I'd just, that'd be part of the
JB: Yeah, that makes sense
RC: The exhibit. So this is one of her
JB: Cool
RC: Type of collections that she
JB: We have more pieces of that so
RC: She liked
JB: We might be able to put more of it back together which would be great
RC: Yeah, that'd be good. So that's what that is
JB: Alright, let's look on the table
RC: Mm, ah! Is this, this here
JB: Oh yeah
RC: Yeah. This is, uh, one of the kind of sets [Figure 64]. This is not the specific one I was talking to you just now, but I'm looking at this one. This one's odd because as I recall, right now I'm not sure. This was not as complete [laughs] as others because you know what my mom would do? And I occasionally do it. We're dump pickers

Figure 64- Porcelain plate with overglaze decoration from Ella Little's collection. Artifact #99608

JB: Uh huh
RC: We pick in Duxbury dump. We used to do that because, uh, a lot of people would just decided… There was a lot of wealthy people out in Powder Point in Duxbury, and they decided they wanna, you know, just, we can afford it, we'll dump stuff. But they wouldn't dump good stuff, but sometimes there were mistakes and, uh, you know, because it's right there in Mayflower Street in Duxbury, and we were at the other end. And so Mom would go there and we'd go through stuff. But we also used to go through Brookline and Newton when people put out stuff
JB: Makes sense to me
RC: You know, and then Harvard, Harvard Business School students, they just leave it, oh I'm wealthy enough, I'll just my suit or leave, you'd be surprised what they
JB: Allston Christmas
SJ: Yeah, definitely
RC: Yeah, I got some stuff right now I got from Harvard locker room, because my dad was working there. When the students go, you go find out what's in the locker room! You know, we'd go through it and you'd be surprised. You know they leave a lot of, and students still do that. They just move, they just put it on the side of the curb and home
SJ: Yeah
RC: So we'd do that
SJ: They used to do that at, uh, where I went to undergrad and it's called the dump and run. If you had stuff left over at the end of the year that you didn't want, just put it in the pile and then they would sell it
RC: Right. Well, I know where to go right now, if I want to get one of those half refrigerators, from one of the universities, they just clean out the dorms and if the students bought the little half refrigerators they just sit 'em out, so we'd just go [laughter] you know?
JB: Did, uh, I think this is a doorbell cover (Figure 65)

Figure 65- Doorbell cover, artifact 99678

RC: Right
JB: Um, did the back
RC: The back door, yeah. If you go, if you go right now
JB: Probably a hole
RC: [laughs] Yeah, this should fit
JB: Yeah
RC: This should fit. Right over the right side or left side. Cause that, I have
JB: We should do that actually, that'd be funny
RC: Yeah, I haven't, uh, I don't think I sanded that thing yet
JB: Okay. Probably shouldn't with the asbestos there [laughs]
RC: Well guess what. All the windows were done already. I covered that
JB: Yeah
RC: If you notice, they were already stripped. I did that years ago, so I'm not sure if I finished the back door.
JB: Did the doors inside the house have skeleton keys?
RC: Yeah, still do
JB: Still do, wow
RC: Still do, I, I kept, I have, uh, uh, um, the master bedroom, hall closet, um, I wanted to ke-, um, master bedroom, hall closet, and the front room, den bedroom. So I use it now, you know, it's a den but it's a bedroom. And I kept three, to keep the aesthetics of the property cause Malcolm was there, second floor. I wanted to keep some of the doors cause the kitchen door, going into the kitchen had one, so I took that out, I saved it. Going into the back hall I saved the, yeah, there's four doors there. That door is still there and I have the key for it
JB: Awesome
RC: And I have the lock
JB: I think we have the plate that goes over top of one of the locks too that matches some of yours
RC: Yeah
JB: It's not in this bag, but it's definitely out there
SJ: Yeah
JB: Cool
RC: So that would, that would be there and that's, uh, one of those. Like it could be downstairs too, but
JB: Yeah
RC: Cause I have, uh, I don't have all the keys like that for upstairs but I was able to go to a locksmith and, uh, get some old keys that matched. There's a way you can do that
JB: I think the only things I'm seeing that are probably from your time period - you got a quarter, I think this is one of those beads from hair ties (Figure 66)



Figure 66- Hair tie bead, Artifact #99550

RC: Mm
JB: But you, you didn't
RC: I don't know that one
JB: You didn't have sisters, right? So would it have just, as far as kids living at the house
RC: Well I didn't have, I didn't have, uh, blood sisters
JB: Right
RC: I had adopted sisters
JB: Uh-huh
RC: and, uh, playmates
JB: Uh-huh
RC: Like, uh, Andrea Fuller
JB: Mhm
RC: She's still alive, she's one of 'em, she lives in, uh, Mattapan. And then my, uh, godsister, uh, Melanie Young, um, she's my godsister, she was living in, uh, Yarmouth, Mass, but now she's sold her home and moved back to Randolph or Brockton
JB: Okay
RC: So, uh, and then, um, I had another, at that time, uh, there was her sister Carol, we were closer, but then, uh, Lily, Lily Shepherd. I have a picture of Lily, um, cause we used to have, my parents would have birthday parties for me at the house
JB: Oh, cool
RC: So, uh, even as a little boy there were a couple young ladies in my life, but only playmates [laughter] Along with guys. There was, you know. I mean, it was, uh, those were close family

friends and they had children. And, and that's who my parents had me associate with. Uh, oh and then, oh and then family itself. Uh, I wasn't allowed just to anybody, play with anybody and go anywhere. No, I wasn't allowed to
JB: Even in that, your little street?
RC: Yeah, I couldn't do that
JB: Wow
RC: That was not allowed. Uh, I wasn't allowed to do that. And that was same with everybody in the family, that's why Uncle Malcolm had a problem. Because the family was very close. It's pri-, primarily the family being so big, and since my mother had, uh, been supportive of so many people who came from the south. They were on, uh, Wambach Street primarily, uh, Holland, Harold Street, and over on Wambach and then Hollander, so there was, uh, in Roxbury there was, uh, about twelve family members
JB: Wow
RC: okay, that were just within a few blocks, particularly over where Uncle Malcolm was at, that soda, um, shop, Townsend Street Soda
JB: Okay
RC: just down the street around the corner, uh, there was just family all around there, so they had their eyes on
JB: Coming up from the south
RC: Yeah, up from Dale Street
JB: Okay
RC: And, and so you'd come out of Dale Street, go up Humble Avenue, and you'd go to Townsend Street Baptist Church, because some family members went there.
JB: Mhm
RC: And then as well as in the South End we went to another church, but since there was so many close family right there, and the church at Dale Street was Protestant. But Townsend Street was, uh, Baptist, a lot of family went there, initially, you know, 30s, 40s. And then they started, later on they'd go somewhere else. And, um, I don't know, just up the street there is the pool hall where Uncle Malcolm used to hang out sometime. And I don't know if I took you by the house where he'd go out the back window
JB: No, I don't think so
RC: Well, he'd sneak out. When he was in bed, you know, they'd think he went to bed. But if you see it, there's a little alleyway. So he'd just go out the window and go to the pool hall
JB: From your house he'd sneak out the back?
RC: Well, that was when the, before my parents in 41 bought Dale Street? The negotiations was 1940. But Uncle Malcolm, there's this thing to make their, uh, storyline, some writers they, you know, they, that's what they had, and that's what only information that family would tell them, Malcolm came in 1940-41. But he came, and then the family didn't say anything about him coming earlier because he wasn't supposed to. He was taken from Michigan. His father was assassinated in 32, and Malcolm was brought to Boston like when he was 8 or 10, okay, from, he was put into a home. But the family negotiated to, with the, the, foster parents could, you know, family being my mother and his aunts and could we bring him to Boston for the summer, or for a few months just to see, you know, if he liked it. And my mother wrote a letter regarding

that when he went back, well, you had your experience here, what do you think? See if you like it. You know. And, things, he wanted to come, but then my mother is, uh, at that time she was on her… she had just finished her second husband. [laughter] Divorce. Okay? And my father was the third. And she couldn't, like, women, particularly black women, they didn't have any kind of power or control. And women period didn't have any say-so in America, oh, you know, the wealth or property and that whole thing. So that was no different for a black woman. And for her to want to adopt, let alone buy a house, you needed a man, you had to have a job, and there was all this back and forth, government things. So, but, she had a plan. And her husbands weren't activists, cause her first husband was a doctor, Lloyd Oxley, and he was from Jamaica. And he wasn't, you know, being, Jamaica being where Marcus Garvey was from and these Garveyites. And he wasn't into that, he was a doctor, he was at, uh, Boston City Hospital doing medical work, and he can't, you know, all that activism, so that didn't, that was the friction between him and my mother, so had to do more within a love marriage. And then Frank, Frank, uh, Frank Riley, Frank and James Riley. That Frank was her second husband. And I met Frank years later.

JB: Really

RC: Yeah, after my father and mother divorced. And he ran into my mother at her office on Mass Avenue, and, um, I could clearly see there was still feelings, but my mother, hey, this is over, this is long gone. Cause he figured, you know, [laughter] she's alone, she's divorced. Oh, you're alone now, that's what he's thinking, you know what I mean. And she was still a young woman, that was, I think my mom, that was back in the 50s

JB: Oh wow

RC: Okay? So, um, she, no, it was nice seeing you, okay, fine, thank you very much, talk to you later, you know. And she, she happened to be standing outside on Mass Avenue at the gate, and it was summertime, he just passed by. And he thought he could come in, and I'm there, you know, that was where she stood at the gate, that's as far as, didn't even open to suggest he come in. That was it, you know. And, uh, okay, he, you know, meandered on down the road, right? [laughter] So, cause my mom had said to me after, you know, my father, now that I think of it, that was, my mother and father they had separated. Not divorced but really weren't separated. Cause my mother bought her first property in the South End in 53-54. And Dad was still, was still on Dale Street, 72. And, Uncle Malcolm was coming back and forth. And technically his legal residence and voting registry was still Boston, not New York. 'Cause he shared an apartment in New York and he didn't officially live in New York until he married Aunt Betty, which was 58-59, cause he was getting married, you gotta, where you gonna be, wife, you know, pregnant quick after the, so he had to move out and get a place, and come to Boston to get his stuff. And that's when Aunt Betty came, when she was pregnant with Attallah, and that was in fifty… Attallah was born in 58? Or 59. But anyway, Aunt Betty was six months pregnant. And so, uh, that's… He went to Mecca in, on the 'Umrah. This whole thing like, some people like to twist things around. When he came, you know, and when he, he came to Boston in the 40s. No, he came to Boston when he was 8 or 10, that was in the 30s. The same thing with him going to Mecca. And, but the way, what my uncle's plan was, the way he put it in the autobiography, in the book, uh, there was a methodology, because of the experience of people that would be like chronicling his experience, to leave something for the family and for some

kind of history. Okay, for America. So my mother wanted him, and she paid for the, the original Hajj trip that he went to, and that he put in the book, his autobiography. But he did not put in there that, or, I say “he”, um, that’s not right to say. Because the book, uh, and this movie, by the way, with James Baldwin? It was originally, he was to write, I was surprised. Cause in the movie, if you go see it, there’s a lot of talk about Malcolm, Martin, and Medger. But James Baldwin was the original writer of the book and to be a script. That’s the way it was supposed to come down
JB: Got it
RC: But, um, Malcolm, uh, went in 59 to Mecca, on what they call a ‘Umrah, which isn’t the more open, official Hajj. And that’s not in the book. And that was, you know, the book was rushed and condensed. Okay, because it was supposed to be [laughter] yeah, yeah, it was rushed. He didn’t, he didn’t even want to do a book. Uncle Malcolm didn’t want to do a book. He, the publishers wanted to do something on him, but he wanted to do something on the Nation. So there was that little thing. But, he actually went in 59. So, you know, these kind of stories that, and so things are sort of more coming together now cause of facts that, coming out, and family and things, we agree on what to release, and what to put out, so you know, it’s like that. I hope that helps you
SJ: Yeah, I mean, it’s all [laughter]
RC: Yeah
SJ: Everything is, everything is piecing, piecing the story back together
RC: Yeah
SJ: Bit by bit
RC: Yeah
JB: I think we can switch to another bag, unless you see anything else that, that strikes your fancy
RC: Well, um, I was interested in this, this
JB: Yeah, your guess is as good as mine
RC: This looks like a gas cock (Figure 67). Um, not a gas cock. Um, a coupling

Figure 67- Possible gas utility fixture, Artifact 99595

JB: Between the two pipes in a gas pipe?
RC: Mm
JB: Yeah, that makes sense
RC: Yeah, that's what it looks like
JB: Cause your house started off as coal
RC: Mm
JB: And then went to gas
RC: Mm
JB: Like the original gas
RC: Mm, right
JB: And now it's new gas
RC: Right, right [laughter] Yeah. And I'm putting my finger through the plastic and I feel threads inside
JB: Oh, yeah? Okay
RC: Yeah
JB: Didn't even notice that before
SJ: You can take it out of the bag
JB: Yeah, anything
RC: No, yeah, no. I can tell cause I've seen these enough [laughter] Okay, that's a gasket, I just wanted to be sure
JB: That's one of your gutter holder, or
RC: Yeah, gutter holder, downspout holders in the, yup, yup, to hold the copper (Figure 67)

Figure 68- Gutter downspout brace from 72 Dale Street. Artifact #

JB: And you had
RC: copper pipe
JB: um, clotheslines, right? Across between, across
RC: Clotheslines, this is not a clothesline
JB: Okay
RC: You know what this is?
JB: No
RC: You don't know what that is? Cmon
JB: Oh, is it a flagpole
RC: No. Take it.. You didn't see that?
JB: No, what is it?
RC: What does it look like? What does that look like?
JB: Looks like a clothesline holder to me [laughter]
RC: No, see, you gotta, you have a plate on it. So that means it's gotta flush with something
JB: Right
RC: And if it's gonna go flush with something, then if it's flush, where is this part going?
JB: I dunno
RC: The bigger part
JB: What is it?
RC: Cmon! You, you, you're doing, you're an archaeologist
JB: This is 20th century
RC: You're an anthropologist, not an archaeologist, right?
JB: I'm an archaeologist
RC: Archaeologist, not a, uh, archaeologist, not a, what's the other one
JB: Anthropologist. Oh, architect
RC: Architect
JB: Yeah, yeah, yeah
RC: And so, um, you know, the windows have weights and pulleys
JB: Oh!
RC: And the rope goes through there (Figure 69)

Figure 69- Window weight pulley from 72 Dale Street. Artifact #99677

JB: That makes sense
RC: And this would be interesting because Ellen Lipsey [former Boston Landmarks Commission Executive Director]
JB: Yeah
RC: You know, which is Boston Landmark, now retired, um, when I told Ellen that [laughter] that I had taken out all the windows
JB: Yeah…
RC: Okay, and she says, Mr. Collins, you weren't supposed to do that! And I said, well, I know, but I had to put something, those windows in, and I spent a lot, so I, you know, took out the frame and, you know, you put in replacement windows, right? And so when she told me, I said, well, she said, what did you, what did you do with all that stuff you took out? I said [in a whisper] I threw it out
JB: Yeah
RC: So, you know, like this, out the door. So this is a piece that probably came off, that didn't make the dumpster [laughter] You may, Ellen might want to see that
JB: I know, right? Might need to put that back in the house
RC: Right [laughter]
JB: But the, um, but the windows woulda been broken in the 70s
RC: Yeah, the windows were broken. They were wood frame windows
JB: Yeah
RC: Two over two
JB: Two over two. Okay, that makes sense

RC: And I, and I, and they were all busted. Busted out. They weren't there. Okay, other than the pieces left. So I had, it was boarded up by the city
JB: Oh, okay
RC: And the city, uh, forced my mother to board it up at the time, because we were going back and spending so much time in New York, cause my uncle. And the people who had, uh, done the street over, the contractors, and, uh, my mother ended up taking em to court. But the neighbors had told us while they were working they had gone in the house and they were vandalizing the house, off and on they were taking stuff. And, uh, when we came back to Boston people told us. And they had written down who the person was, and you know, they didn't go approach them, but they had gone and taken a lot of stuff, and it was trashed, the place. And, uh, so, uh, well my mother was taking them to court, and the city told her, and that's a matter of record, you know, you gotta board it up, she said, you're not forcing me to board it up. These people gonna do it. And as the case went, I, I don't remember how that ended up. My mother, something, somehow they ended up, she was kinda happy but not too happy. But in the meantime, the city, well we're boarding up the building. And they boarded it up. Uh, later on, when it becomes my responsibility, executor of estate, I had to, there was a lien put on the house because of that, you have to pay this bill, we boarded up. So, no, so I said, I'm not paying it. Because look at the records. And so this was the thing with, I don't know if you want to say this off the record
JB: We can stop recording if you want
RC: But, but Mayor Menino, you know, and the, the Commissioner Ede and I, we talked about all this. So between, uh, ISD and the Mayor and the Commissioner, oh, okay Rod, we'll just let that, you know, that was a mistake and, you know, we know, because they did the research, and okay that shouldn't've happened. So that the lien was removed, because it was, uh, it was a cost to the estate of my mother. And so, uh, Mayor Menino was quite nice to, okay, just see what you can do to get other things done. So, you know, he was good about that. Except not [in a whisper] giving any money for [laughter] Anyway.
JB: Anything else on the, the beads, those look fairly recent but I don't know what those are. Those might just be beads
RC: Where?
JB: Uh, these guys here
RC: Oh, these guys. Yeah, these could be, they don't look like… They could be my mother's or they could be Aunt Sarah's [Aunt Sarah lived in the rear apartment] (Figure 70).

Figure 70- Beads from surface collection, Artifact #99557

JB: Okay
RC: Cause, and they look like religious beads
JB: Really?
RC: If these are religious beads, these are Aunt Sarah's
JB: Want to take them out?
RC: Yeah. Um, you know, Aunt Sarah had bunch of beads that she put around her neck. Because some people, like Muslims, they count beads. You know, when you wear the rosary thing. So you have Catholics would have the rosaries. But she was a Baptist, Aunt Sarah was a Baptist. You know, something, but she wasn't Catholic, she was a Baptist. So I don't understand all that, you know, and, uh, this would be something, yeah, that she, look like she would wear. Cause I remember her wearing these kinda things. And there was something on the other end of it
JB: Yeah, I wish we had the whole thing
RC: Yeah, I don't know what that would be. But this looks like.. And they were always black. And it was, she didn't wear color beads. It was old fashioned, you know, women
JB: Kinda Victorian almost
RC: Yeah, they were, you know, silver or blue or pink, she was not that kinda thing. In fact, I might, I might, you might see this in a, my mother did a portrait of my Aunt Sarah
JB: Really?
RC: I have the… Yeah, somebody stole the portrait, but I have the picture of the portrait with Aunt Sarah in her Eastern Star banner [Order of the Eastern Star is a fraternal order open to both men and women related to the Freemasons] and she has something around her neck so. If you want to see it I'll show it to you.
JB: I'm going to stop the recording real fast and we'll switch gears to another bag.

Berm Below Door on East Side of the Addition

JB: SO this is from the berm below the door on the east side of the Addition. So this is just outside of the rear door to the apartment by the garage (Figure 71)

Figure 71- Photo showing berm below door on the eastern side of the addition. Record found in soils just under door.

RC: Right, that hole that's there now
JB: Ah, this is the surface collection
RC: Oh, just on the surface, not in the hole, right.
JB: Next to where the hole is that goes down to the basement
RC: Okay, this is that record that you have (Figure 72)

Figure 72- Intact record from surface collection. Artifact #108336

JB: Now that, what did we get the date on that? 60...60 something.
JB: So this was from 1960...I think it was 69. I'm not sure I remember why that year. Record, of folk songs from, I don't think it's the South, but it's like Yankee Doodle, that kind of stuff.
RC: Yeah, that's interesting. And how did you, it's written on here? Can I turn it over?
JB: Yeah!
RC: And you got this, and you got them to play this thing?
JB: We cleaned it up and put it in a record player for about two seconds.
RC: Uh huh.
JB: And it was the first couple of notes to, uh, [sings notes to "Dixieland"]

RC: “Yankee Doodle” [sings notes to “Dixieland” with JB]
JB: That one, yeah.
[The song was “Dixieland”, not “Yankee Doodle”]
JB: There's a scratched in, or stamped in, number around the edge. That’s its actual, like.
RC: Yeah, like the record.
JB: Number, so I looked that up and that’s where we could actually get the name of the album. And then all the contents of it are on YouTube.
RC: And it was called. What was the title of it?
SJ: Oh, gosh.
JB: I can’t remember off the top of my head now.
RC: You should, but you got it?
JB: Yeah, we got it. The whole record has been recorded on YouTube.
RC: Yeah, I think my son was saying something about that. Okay, now this you explained to me this was...
JB. Those are tobacco pipes, so that’s from, probably pre-1900 or so (Figure 73)

Figure 73- clay tobacco pipes from surface collection #108360

RC: Uh huh. This was surface?
JB: Yeah.
RC: Wow!

JB: You've got really early stuff, like the Chinese porcelain, you've got a lot of really early stuff sitting right on the surface. The last bag we looked at had stuff called Staffordshire Slipware, which is at least 300 years old, sitting right on top of everything on top of your site, yeah.
RC: It's amazing, huh?
JB: Well, in between the time that the house, the original property, the Seaver property estate was abandoned and your house getting built, that's when it got farmed.
RC: Right
JB: And that's when everything
RC: Yeah, gets turned up
JB: Kind of mixed up.
JB: Anything?
RC: Sarah
SJ: Yes
RC: There's just so much
SJ: Yeah, I know
RC: Do you have something in mind?
SJ: I mean, we're not
RC: This looks like one of my mother's, she had thousands of these (Figure 74)



Figure 74- Button from surface collection

JB: Yeah?

RC: Yeah, you know, for fixing dad's shirts, or could have been a cuff? Or could have been one of her's, this looks more like a blouse…
JB: Yeah
SJ: Yeah
RC: Thing. She, you know she had a lot of those buttons, a lot of buttons, because she had a big thing like this and like that [mimed container size with hands] that can hold different mismatched buttons, you know?
JB: We had one of those, my mom had one of those
RC: Yeah, and she collect buttons. Trying to see what anything here of mine, what I collect. What's this? What's this?
JB: That looks like a clamp for something, tied up, metal twist
RC: Yeah, it kind of rings a bell to me, something I'm familiar with, but I don't know. I don't know, I can't remember that much. This bag is?
SJ: Ceramic bits, probably flower pot or something similar.
JB: This one doesn't have a lot of stuff. The highlight of this one was probably the record... Seems like most of it.
RC: Nails (Figure 75)

Figure 75- Wire nails from the surface survey #108344

JB: Those should look familiar to you
RC: There were so many nails, when my godfather was there, so many nails and things.

JB: Should we switch it out for another one?
RC: Yeah, let's do that.

In addition to the artifacts discussed on tape, several pig bone fragments were found at the site during excavation. While on site, Rodnell Collins was asked about the pig bones on the surface near the rear kitchen window, especially given that the family had converted to Islam. Rodnell stated that while his Aunt Sarah, who lived in the rear apartment and whose kitchen window these collections were found under, was Muslim, she really enjoyed pigs feet and would on occasion eat one, but throw the bones out the window.

Berm on East Foundation of Main Building

JB: So this is, this is from the berm east of the foundation (Figure 76), I believe this is
RC: East of the foundation.

Figure 76- photo of berm transition between grass and soil on east foundation of 72 Dale street near front yard. Ridge had to be scraped to smooth for GPR survey resulting in a surface collection of artifacts.

JB: I think this is the area where the trees used to be growing. Yeah, you can open that [plastic bag sounds]
JB: That's the area between the grass in the front, the kind of dirt area on the side, with that little berm there.
RC: Yeah, this here, this, there was this dark dark blue set (Figure 77). This look like it was something from that, of my mother's. There's a dark, really all dark blue, and you see them very rarely, glass, and plate, tea set, you very rarely see that anywhere. You can see some in town at maybe some of the finer dish shops but it's very rare. Very rare.



Figure 77- Dark blue vessel from Ella Little's collection, #108513

RC: You know? Oh, here's my little car. The underbody, looks like that's [laughter] that's supposed to represent the transmission box (Figure 78)?

Figure 78- Rodnell's red car, #108421

JB: Yeah, I don't know.
RC: My little race car, you know? You know, you do that [arm motions]
JB: Oh, one of those spring ones
RC: yeah. And I know what this is. That fence, I still have it. Ellen [Lipsey, former BLC director] when she came out the first it was as you go up the steps between my neighbor's yard and by the steps, and I was going to throw it away and when Ellen first came out with the Mayor, and I ask her about it, and I said, "should I throw it away?" And she said, "nope, save everything," (Figure 79)

Figure 79- Decorative fence element from property #108428

JB: this is the decorative element
RC: Yup, that's the decorative part. I still have it, and that's good, you know, the other piece of it. Might have to re-shape
JB: The original spigot for the outside of the house, one of them
RC: one of them, right there at the, you know where that is at the front.
JB: yeah, near the
RC: Near the
JB: Pipe, where it goes into the

RC: Wow, yeah, that's something. You found that. Okay, we know what this is. Now, here's your clothes thing, okay? Put that on the hook and run that clothesline. That's your clothes line piece in the back (Figure 80). This, doesn't look.



Figure 80- Pulley from 72 Dale Street yard

JB: Did you have awnings? Because my grandfather's house has awnings and those would clip the edge of the awnings.
RC: Yeah, we had awnings, but they removed those, my parents, because when they got the house, there was not a full set, so they just got rid of the whole thing, and they did the siding, you know? So that long gone. We don't even have, might have one awning left in the basement. I don't know what that is. Oh, this is recent, I know what that is (Figure 81).
JB: From the roof, sit right on top

Figure 81- Securement for temporary rubber roof on 72 Dale Street at the time this report was being written #108407

RC: Was there a hole there?
JB: Could it be an oil can? Thing that you dribble oil. I'm thinking of the Wizard of Oz (Figure 82)

Figure 82- Possible oil can element #108431

RC: Because I said my dad, he kept his stuff in the garage, and he works on these cars himself. He would change the oil, and lubricant. He did all his tuneup, and stuff, to his own cars. And he left stuff in the garage. And this looks like something that would go to one the oil cans on the shelf.
RC: That's something from a period back.
JB: Yeah. That's probably a perfume bottle.
RC: Yeah, you know what? That's my mom's (Figure 83).



Figure 83- Ella's perfume bottle #108396

JB: Yeah?
RC: Yeah. I can remember this bottle. The shape. Yeah, wow. Oh! You know, it's not only a perfume bottle, you know, there's a little thing that goes down in there and *tsst* *tsst*
JB: Oh, yup
RC: *tsst* *tsst*. That's what that was, squeeze it
SJ: [laughing]
RC: That's what this is, that's my mom's
JB: THat's by the window
RC: Yeah, and it came out, yeah, threw it out. This is, this is, you got to double-label that.
JB: Yeah [laughing]
RC: That's my mom's. Yeah, that one I can never forget, even in my dreams. This one. That looks like one of those. You know what that might be?
JB: Milk bottle (Figure 84)?

Figure 84- Milk Bottle from 72 Dale Street yard. #108447

RC: Yeah. You know what I…? That looks like one of the old, wow, because we used to get, my mom used to have Deerfield Farms which was up in western part of massachusetts, years ago, deliver milk, and i remember they had the paper cap that goes around, crimps around the edge of this thing. And the middle of the cap there was, like a kick up, the cover, that crimps around, and then the middle of it was a thing you could flip up. But this was one of their bottles.
JB: that's awesome
RC: From Deerfield Farms, from western part of the state. I don't know if they traveled that far down, but that's where they were from. Deerfield Mass, not that far.
JB: Pretty long drive.
RC: I think they may be still in business up that way though. Deerfield Farms. That might be something, and that's one of their bottles.
JB: You recognize this plate?
RC: Yeah, yeah, this is one of Mom's (Figure 85). This is one, another one of the flower, and it should be around the edge, yeah, see that? See that? That's a gold one, an edge one. But there's also a silver one directly on the round. This is one of her's and the thing I have now is similar to this.

Figure 85- Another plate from Ella Little's collection #108420

JB: Oh cool.
RC: Yeah, so that's similar to that
JB: I'm glad you still have some of them.
RC: Well that's the only one thing. I might have another, I think I have a piece of a cup, but that, you know, I wish I had a whole set, you know? What's this here?
JB: Rubber
RC: Yeah, old rubber. Anything else?
JB: Lots of Flower pots, she had a lot of flowerpots (Figure 86).

Figure 86- Flower pot from 72 Dale Street #108410

RC: Yeah, oh flowers, we could go all day
JB: Did she put them all over the place, or were they in one specific area?
RC: She would sit some over next to the house, you know what she'd do when she bring stuff from somewhere else, because you leave them, when you're transplanting something, you put it in the pot, when you take something out of the ground, she didn't always put it right back into the ground, she wanted to nurture it for a while, back at the house. She would put it in pots and let the sunshine and water get to it, and then at another times, she would transplant into the actual ground, you know? And, it was healthy, that's how she did a lot of the tulips. That's how she did everything. What's this? Doesn't ring a bell... Yeah, because I have, one of the doors, I have one of these now (Figure 87).



Figure 87- Door lock escutcheon from 72 Dale St. #108436

JB: On the door still, or off?
RC: I took them all off to get the door stripped. I took them over to Old Bostonian to have them strip them, I didn't leave hardware on there.
JB: There's a "justice" thing on that one (Figure 88)

Figure 88- Embossed scales on bottle #108393

RC: Oh, That's interesting.

JB: Maybe it's the company that made it or something, I wonder what else it could be? I've never seen a scale thing on a bottle.
RC: yeah, I don't know, that's interesting. It's got a number or something down there.
JB: Bottle, but again the scale,
RC: Yeah, they wouldn't be on there just for nothing. It represented something, and it's not, but it wouldn't be surprising, if its something from my mother, because she collected stuff that represented the law, that's what she wanted Uncle Malcolm to get into so, law books, and stuff that represented the law at the house... Yup, comb. That looks like my mom's comb, yeah, that looks like one of her combs (Figure 89). This comb should be going that way, and there was a handle, that was more thicker. I remember this design, that amber, like, I remember that. You don't find them to many. More glass. Anything else interesting?

Figure 89- Ella's comb

JB: Lot of stuff, that's for sure. Did she have any pink ceramics, like pink-pink (Figure 90)?

Figure 90- Pink ceramic from surface collection

RC: I don't remember my mom having anything pink, my aunt might have, Aunt Sara. My mother wasn't into pink, she just, for some reason, you know, some reason, some women, pink, I can't remember me and my mother, ever, pink anything, just pink
JB: Wasn't her thing
RC no, my wife likes pink a little bit, and my daughter, but not crazy about it.
JB: A lot of that old stuff too
RC: this keeps catching my eye all the time (Figure 91)

Figure 91- Blue and white ceramic with "zig zag" decoration (Blue transferprint pearlware #108507)

SJ: That zig zag
RC: Yeah, because i keep remembering that, you know
JB: Well she collected blue and white
RC: Those were the number one collection, anything blue and white, you know?
JB: A lot of it on this site. Honestly, if we hadn't heard that, we would have assigned every single one of those to the people that lived on the property before your family. Doesn't make it easier to interpret, but it makes it more interesting to interpret.

Material from Bulkhead

Figure 92- Surface around bulkhead before surface collection

RC: See this? This is off a chair (Figure 93)

Figure 93- Wheel from stolen chair #108560

JB: Was it one of the chairs that got stolen?
RC: Yeah.
JB: How much furniture was left, or anything left? Was it just messed up, or was it mostly gone by the time you got?
RC: All the good stuff, they took the Chippendale dining room set. They took that, and the credenza, that's gone. That's where the dishes, you know. They took the chandelier, they took a chair that was precious, next to the telephone table, that was a collector's thing. That dining room stuff was very valuable. They took my parent's bed. They just took all the old bedroom stuff. That's all taken. Fortunately, we got some, I got the Shaker rocking chair that was Uncle Malcolm's, I got the brass beds, and I have the living room one, the sofa, and the chair, single chair. I still have that. And, nothing from the dining room. Nothing. I have some kitchen, the kitchen, Uncle Malcolm's upstairs kitchen table and a chair left. I did something stupid, I threw out one of the dressers, but my mom had cut the legs off to make it a low thing. I threw that out, but it was out of the 30s, there was nothing wrong with it, she had just cut the legs of and it sat there, but like a fool I got rid of it. That was years ago, back in the 80s when i was cleaning, I gave it away to someone.

Rock Garden

Figure 94- Rock Garden area

RC: this kind of rings a bell (Figure 95).



Figure 95- Carnival glass bowl fragment

JB: popular with candy dishes and bowls
RC: Yeah, that's what i'm thinking because my mom had in the living room, and everything else in that living room on the coffee table went away, she had a dish, and she always kept something for people who would come to visit, in the living room in a dish, because we were not allowed to go into the living room, my dad and I, we were not allowed in the living room. You could go in, look out the window. She was one of those mothers, one of those ladies of the house. "Don't mess with the living room that's for guest". You can pass through, go look out the window, but don't sit that's for guest. My father hated that, you can go anywhere else in the house, play around, but leave one place for guest. So she would keep that where you could sit on the sofa, coffee table, have a tea set there, and it would have a bowl of candy. Sometime two, but no more, because people get crazy.

JB: She had a lot of guests over, all the time
RC: Yeah, family, mostly family and near family friends, and then if you were real close of course you would be in the kitchen or dining room.

[Regarding Transfer print ceramic, Figure 96]

Figure 96- Transfer print ceramic fragment #99736

RC: There was one time she had, but it wasn't a complete set, just pieces. Because what my mom would do if she found something in the dump picking, someone threw out something, but it might not be a set of something, but it was a nice looking bowl or dish, and she didn't care if it was matching she'd take it anyway out of dump picking or trash, because it was nice. She didn't like seeing stuff thrown away, so she was always giving, collecting something.

Alley on Grid-North side for GPR Survey

Figure 97- Alley on North side of property

RC: Look at this!
JB: Oh, so that's stuff called, this is called Pratt Ware (Figure 98). It was really common in, like, the mid-late 1700s [actually late 1700s to early 1800s], probably from the guy before, but.
RC: Yeah, that's not her's, that's not my mother's.



Figure 98- Prattware from alley of 72 Dale Street #108650

Screened Backdirt

Figure 99- Photo of back dirt pile. Visiting students for scale.

RC:That's now [referring to age of object] It might be mom's, little, I'll tell you in a minute. This might be another one of her little colognes, yeah (Figure 100). You know how?

Figure 100- Cutex nail polish remover bottle #108661

JB: I bet if you opened it
RC: Anybody open this?
JB: Not yet, I don't think so
SJ: Go for it
[long pause while bottle opens]
RC: You smell anything
JB: A little bit, but it's really faint
RC: It's faint, very faint. It's not. There's something in there. I can smell it slightly.
SJ: Cutex
JB: Cutex?
SJ: It's a nail polish
JB: Oh
SJ: It's got fingernails all around the edge.
JB: That's weird that it would be empty.
RC: Well, it evaporates. She did her nails. That's when I, you know what made me think of it, I was thinking maybe, when I said "now," but then I saw this [Scratches decoration with fingernail]
SJ: Yeah, it couldn't, it doesn't have the brush or anything
JB: Right?
SJ: You would think if it was a nail polish it would have the little brush
RC: Yeah

SJ: so, maybe it's not.
JB: Could it be a little jar of nail polish remover?
SJ: Could be
RC: 'Cause that I recognize as one of my mother's
SJ: OK
RC: Because of that, when I said, "look at that closely"
JB: The nails on the top
RC: Yeah, yeah, so that's something to go with that other little bottle
SJ: We can reconstruct your mom's dresser
RC: Yeah. And this looks familiar. This button's familiar (Figure 101)



Figure 101- Button from Ella Little's white sweater

JB: The piercings on that
RC: This button's familiar. This was on a sweater
JB: alright
RC: This was a cheap--- if it's... this was a sweater of my mom's. This should have been painted silver. This button was on a sweater
JB: What color was the sweater
RC: White

JB: This is probably part of one of those stepping stones that were all between the garage and the main house (Figure 102). Where those from inside the house, like sinks and stuff? Or were they just extra stones

Figure 102- Marble slab from pathway #108668

RC: You mean those stones you see now laying around?
JB: Yeah, like the marble and the
RC: The marble. Ma would pick those up from places, but this doesn't, this feels a little too heavy. But, then again, it looks like it. It looks like it, yeah.
JB: There were pieces of that all over the place. We found a couple of extra ones
RC: She had a lot of that, 'cause we, you know, it's like flagstones, we'd lay it, you know, she'd put a red one, and a blue one, and a, I mean, a red one, and a white one, and a grey one, you know? There's a bunch of that going from the back door to the garage around the back, that's what she stepped on
JB: That would be to make sure those go back
RC: Yeah, the flagstones, that's why I saved them, a couple of them. I still have some.
JB: Those little touches like that, aren't stuff that anyone would ever think to do so it would be nice to have her ideas represented.

RC: that's a
JB: Pink bow
RC: That's off a doll, paper (Figure 103)



Figure 103- Paper doll toy

SJ: Paper doll?
RC: Paper doll, thing you'd pop out
SJ: Yeah, totally
RC: Thing you'd put together.
SJ: Probably a slit in the head that it inserts into
RC: Yeah, you know you'd peel it off and stick it on.
SJ: Oh yeah, like a sticker
RC: Yeah, 'cause I had a bunch of those sometimes, [inaudible] only on a computer paste and stick, peel it and stick it, only difference, peel it and stick it, I used to love to do that.

Unit 1

RC: So much stuff, coming and going, and she'd get stuff, put stuff, and what she'd do was, we'd take parts and we'd keep them, and then she'd bring stuff from Duxbury, because we had a farm, and she'd grow things and then she'd give people plants and pots to put in their yard, and then she'd get something from somewhere, and put it in the pot. She was always dealing with flowers, I mean that was one of the main things for her, flowers and plants and stuff; putting them in pots, and transplanting them from Duxbury to Boston. So, that's it.

RC: I got to tell you something about nails. My mother used to get nails in kegs
JB: In what?
RC: Kegs.
JB: Really?
RC: You know when you go to the, farming, right? We go and buy them in kegs, we didn't go to no dang gone hardware store

JB & SJ: [laughter]
RC: Go to the [inaudible] put it in your bag, and you go do what you got to do, because we had a lot of land in Duxbury, we had to build fences, build barns, sheds, you know.

STP N099 E84 Level 1 0-10, MXH 126

In addition to these artifacts discussed during the oral history interview, two fragments of a plastic mid-century style glasses frames were found in N099 E084 (Figure 104). According to Rodnell, Malcolm did not start wearing his iconic glasses until after being released from prison. While these may have been left behind by Malcolm during one of his many visits and stays at the house during the periods his official home address was 72 Dale Street, many of the members of the Little family wore similar glasses as they were the style at the time. It is likely that this pair of glasses belonged to one of the family members, possibly Malcolm.



Figure 104- Plastic eyeglasses frame #102659

Gravel Fill

724 artifacts were found in the Gravel Fill deposit. The vast majority represent a 19th and 20th century deposit due to the presence of numerous bottle fragments. It is highly likely that these deposits are associated with the occupants of the house between 1870 and 1970. The artifacts have a large number of plastic, lighting, and other 20th century materials. While these artifacts

may be related to the later families present at the site, the deposits within the foundation to the rear of the home (Feature 6) and the surface collections, provide far better assemblages through which to examine the 19th and 20th century occupants of 72 Dale Street.

Post Hole

The post hole feature, Feature 1, was found about 40 cm east of the rear building ell near the rear entrance to the home. It measured 40 cm across with a 15 cm-wide central core. The feature itself appears to be 19-20th century in origin based on the fact that it cuts through re-deposited soils from the excavation of the house foundation. The core (strata 1) consisted of coal ash, which appears to have been placed into the feature when the post was removed. The surrounding matrix (strata 2) look similar to the buried plowed A soils in appearance and artifact contents. Both strata of the feature extend to 70 cmbd and end abruptly. This feature was bisected to reveal the profile of the feature. The results of this bisection can be seen in Figures 51-53.

Coal ash core (Feature 1 strata 1)

Not every level of the coal ash fill contained artifacts, but the contexts that do are MXH 187-189 from 40-60 cmbd. In total, just 7 artifacts were recovered from the coal ash fill, including brick, window glass, coal, and a wire nail. While these are not significantly datable artifacts, the presence of coal and coal ash and a wire nail suggests an early 20th century date for when the post was removed and the hole filled in. The function of the post can not be determined at the moment, but its close proximity to the rear entrance to the house suggests a decorative purpose or a more-functional purpose such as a pulley for a clothesline, awning support, lantern or light post, or some other purpose.

A-soil fill (Feature 1 strata 2)

The contents of the A soil fill around the post include MXH 191-198. These deposits start 30cmbd and end at 70cmbd.

In stark contrast to the core of the feature, 372 artifacts were recovered from the A-like soil fill from a cylindrical shaped deposit 40x40 cm in size. These artifacts date to the 18th-19th century including Staffordshire slipware, creamware, pearlware, white wares, transfer wares and bottle glass, with an overall assortment of artifacts (bone, ceramic, glass, metal) that strongly resemble the overall buried plowed A soils surrounding the area. The Feature does cut into the intact portions of the buried plowed A soil, but is lighter in color suggesting it was further mixed with B and C soils during initial excavation of the post hole through the mixed A, B, C, and plowed soils and later re-deposition of these now-combined soils into the hole around the post.

Cistern and Utility Fills

The cistern artifacts are associated with features 3 and 7 within unit and the utilities encountered in STPs N110 E081 and N106 E087. While 644 artifacts were recovered from this deposit, they represent a highly mixed and highly disturbed combination of buried APZ deposits coupled with 19th century deposits present in the landscape when the utilities were repaired or installed.

Cobblestone Pavement

As this deposit was primarily stone cobbles, only 6 artifacts were cataloged from this strata function, including an intact cobblestone. The remaining artifacts include 18th and 19th century pearlware fragments and a brick. Regardless, this cobblestone pavement represents a significant landscape feature associated with the 19th century occupants of the house, and may have served as a surface material for much of the area spanning the area between the back of the main house and the southern facade of the rear ell.

Foundation Builder's Trench

While the artifacts found within the builders trench are large in number (n=1906), they represent a re-deposition of the deposit of APZ already disturbed by plowing. As such, it has a similar composition and artifact assemblage to the buried APZ strata.

Inverted A soils

Like the the builder's trench above, this strata represents a redeposited and disturbed deposit of buried APZ. 446 artifacts were cataloged in this deposit.

Outbuilding Foundation (Feature 6)

The outbuilding foundation was located in unit 3 at the western end of the property. The outbuilding foundation fill contained four stratigraphic horizons not including more-recent fill that eroded into the upper levels (strata 2). These artifacts represent the best-preserved intact features and deposits from the earliest occupants of 72 Dale Street.

The structure itself consists of mortared fieldstone wall elements with a flat prepared puddingstone floor. The stone floor indicates a farm-related structure, possibly a dairy building, where cool conditions were necessary and improved by the presence of a stone floor. It is highly likely that significantly more of the foundation are preserved on the property and likely contain a large amount of 19th century materials significant for the interpretation of the earliest occupants of 72 Dale Street.

Sand Fill (Unit 3.2 Strata 6)

The Sandy fill was the first intact 19th century deposit within the feature. Contexts from this deposit include MXH 247-249. This strata contained 98 artifacts, the majority of which are nails, brick, and roofing slate.

Organic deposits were limited to a single bird bone. Two rim fragments of a machine-made milk glass bottle with external threads were recovered. Datable ceramics include creamware, pearlware, yellowware, and whiteware suggesting a late 19th century deposit. Only the whiteware were decorated with a transfer print. The high amounts of architectural debris including bricks, window glass, and plaster compared to domestic goods suggests that this deposit represents the slow erosion and collapse of the outbuilding structure into its foundation.

Sand Fill 2 (Unit 3.2 Strata 7)

This sterile strata was sandier than the previous sandy fill, but contained no artifacts.

Organic Fill (Unit 3.2 Strata 8)

This strata presented as a darker organic-rich deposit with a much higher concentration of artifacts and in larger and more intact conditions. These deposits include contexts MHX 250-252.

409 artifacts were found in total. Of those, a relatively small number (43) were architectural. The contents suggest the foundation was used as a place to throw domestic refuse, likely household trash from the inhabitants of 72 Dale Street.

Food and beverage was the most common artifact function totaling 266 artifacts (65%). Food acquisition, primarily bone (n=200), included lobster (3), bird (99), chicken egg (6), and mammal (67). The large number of lobster and bird bones suggests a poorer occupant in the home or a preference for birds for protein sources over mammals.

Service ceramics were fewer in number than would be expected in a refuse deposit (11 artifacts), and all include smaller fragments of transfer printed and undecorated whitewares and pearl wares post-dating 1820.

Glass artifacts were greater in number than ceramics and were more complete. 55 glass artifacts were recovered, consisting of service and storage vessels. The service vessels included tumblers and tumbler fragments including two intact tumblers (Artifact #107171 Figure 105). Storage glass included cup-molded bottles in clear, olive green, and aqua glass including two intact food storage bottles (Artifact #107175 and 107172, Figure 106 and 107). Artifact 107172 is identified as a chow-chow pickle jar made after the 1870s according to the SHA bottle website. This date is the TPQ for the feature. Finally pharmaceutical bottles and bottle fragments were found including a post-1840s Burnetts pharmaceutical bottle (Artifact #107170, Figure 108).

Figure 105- Intact tumbler from Feature 6, Artifact #107171

Figure 106- Intact food or pharmacy bottle from Feature 6, artifact #107175

Figure 107- Intact food bottle from Feature 6, artifact #107172

Figure 108- Burnetts medicine bottle from Feature 6, artifact #107170

Ash Fill (Unit 3.2 Strata 9)

This deposit was found under the organic deposit (above) and directly on top of the floor of Feature 6. This strata includes contexts MXH 253-254. Far fewer artifacts (n=31) were found in this layer and they are dominated by architectural (brick, window glass, nails, etc.) artifacts. Bird bone and chicken egg (n=7), a rockingham rim sherd (post-1830), and coal fragments round out the artifacts. Finally, a porcelain false tooth, likely part of a denture, was found (Artifact #107577 Figure 109). As ash was not collected but was present in the description of the strata, this deposit likely reflects the use of the foundation as a coal ash depositional area as appears was common with most depressions and holes (see Feature 1 post hole fill) on the site.



Figure 109- False tooth from Feature 6, Artifact #107577

It appears that sometime in the 1830s, the Seaver home nearby was demolished leading to a period of time when the outbuildings and main home were either in collapsed or absent condition. The foundation hole of Feature 6 appears to have only been 2-3 feet deep relative to today's surface and likely even shallower in earlier periods, which did not appear to be filled quickly. Sometime after the building of 72 Dale Street in 1872, the exposed foundation interior was filled first with ash and domestic debris, and later with larger quantities of household and kitchen wastes before being finally filled with demolition debris or the final collapse of whatever remained of the superstructure. Overall, this feature represents two significant periods of occupation of the site, and a large portion of the feature likely remains on the property in good condition and would benefit from additional testing.

Buried Plowed A

This was one of the two largest stratigraphic deposits both in area and in artifact quantity. To fully discuss the 7,614 artifacts recovered from this strata (41.8% of the overall artifact count), this deposit will be discussed by artifact function.

Buried Plowed A Dating

From the first time it was encountered, this deposit clearly dated to a time well before the building of the Malcolm X House. Previous research on the site, namely the Boston Landmarks Commission report on the home, described the area as being undeveloped farmland prior to the construction of the home, and this was the presumption prior to the commencement of archaeology. When the buried plowed A (APZ) was encountered, the quantity and age of the artifacts being revealed indicated a much more significant event happening at the site than just farmland. Further research after the survey completed (see background section, above), revealed this more-complex nature of the properties history, but the exact individuals and families the deposits being recovered related to was not immediately clear. To better determine the date of these deposits, the ceramics from the site were examined in their entirety. A table of the 5,321 ceramics from this deposit organized by ceramic types recovered from the buried plow zone, their Terminus Post Quem (TPQ) or the time after which they are known to begin production, and their average production date is provided below (Table 1). A Mean Ceramic Date (MCD) of 1784.99 was revealed by this analysis. While the TPQ indicated that the overall deposit dated to after 1840, there were only 12 ceramic artifacts total (.2% of the ceramics) that dated to after 1795 indicating that these later ceramics were likely brought into the site by disturbance or accidental mixing during excavation. With a TPQ of the 95th percentile of the ceramics, a 1795 TPQ was revealed.

Ceramic type	Count in APZ	TPQ	MCD	Count x MCD
borderware	4	1600	1650	6600
Iberian storage jar	5	1600	1690	8450
Tinglazed earthenware	77	1600	1701	130977
Rhenish Brown	5	1650	1712	8560
Westerwald	23	1650	1712	39376
Chinese overglaze enamel	1	1660	1735	1735
Chinese underglaze blue	40	1660	1760	70400
Unidentified early porcelain	50	1660	1760	88000
Staffordshire, slipped	33	1670	1732	57156
British brown stoneware	5	1671	1735.5	8677.5
Manganese Mottled	8	1680	1730	13840
Nottingham-type	12	1683	1746.5	20958
glazed redware	405	1700	1800	729000
Redware, slip decorated	5	1700	1750	8750
Redware, unglazed	510	1700	1800	918000
Coarse agate, buckley ware	5	1720	1747.5	8737.5
white salt-glazed	67	1720	1762.5	118087.5
Astbury ware	5	1725	1750	8750
jackfield type	11	1740	1765	19415
Refined agate ware	1	1740	1757.5	1757.5
Whieldon (clouded or tortoiseshell)	3	1740	1757.5	5272.5
white salt-glazed, scratch blue	4	1744	1759.5	7038
basalt stoneware	1	1750	1785	1785
Cauliflower ware	3	1759	1769.5	5308.5

creamware	1243	1762	1791	2226213
Creamware, transfer printed overglaze	1	1765	1775	1775
Creamware, handpainted, underglaze	2	1775	1795	3590
Pearlware, hand painted blue underglaze	62	1775	1797.5	111445
Pearlware, shell-edge green	122	1775	1797.5	219295
Pearlware, undecorated	1098	1775	1802.5	1979145
Pearlware, factory-made slipware	47	1790	1810	85070
Pearlware, hand painted polychrome	81	1795	1812.5	146812.5
pearlware, transfer printed	535	1795	1812.5	969687.5
Whiteware, hand painted blue	2	1820	1875	3750
Whiteware, molded	1	1820	1910	1910
Whiteware, transfer printed	1	1820	1910	1910
Whiteware, undecorated	1	1820	1910	1910
Rockingham-type	1	1830	1870	1870
Whiteware, hand painted polychrome	1	1830	1875	1875
Yellow ware, plain	3	1830	1885	5655
Ironstone	1	1840	1920	1920
Whiteware, flow blue	1	1840	1870	1870
Totals	**4486**			8052334
			MCD:	**1794.99**
			TPQ	**1840**
			TPQ95	**1795**

Table 1- Ceramic types, TPQ, and MCD for buried APZ strata

To briefly summarize the background history of the property, the 72 Dale Street lot was part of a significantly larger lot of land owned within the Weld-Sumner-Stevens families from the 1630s through 1765. In 1765, the property was purchased by Abijah Seaver, who had already been living on the property. This land stayed in the Seaver family until 1821. In the early 19th century, a property map was drawn possibly indicating the Seaver house to the southwest of the 72 Dale Street property (Figure 4). It appears that the Seaver house was demolished soon after the 1820s sale, and the property was likely rarely if ever used again until the mid 19th century.

Given that the vast majority of the ceramics from the site are concentrated in the creamwares and pearlwares, and given the TPQ and MCD data, it is highly likely that the Seaver estate was the primary, if not exclusive, contributor to the artifacts present within the APZ.

A blue hills rhyolite secondary flake (#103409, Figure 110) was found in close proximity to the house in the buried APZ, and an argillite flake (#105924,Figure 111) was found in unit 1.2, and a a massachusett hornfels stone flake (#104795, Figure 112) was located in unit 1.1. These three lithics representing a Native presence on the site and are concentrated near the center of the 72 Dale Street property. While Native people have been documented, archaeologically, at numerous sites in roxbury, this single flake represents the first archaeological evidence of Massachusett people in the vicinity of 72 Dale street. The site name of this new Native site is the Collins site, named after the current owner of the property.

Figure 110- Blue Hills rhyolite flake from the southern yard of the house, artifact #103409.



Figure 111- Argillite flake from buried APZ, southern yard of the house, Unit 1.2, artifact 105924.



Figure 112- Massachusett Hornfels flake from buried APZ, south yard of house, Unit 1.1, artifact 104795

Architecture

1,181 artifacts were collected under the function of Architecture. These were predominantly bricks, nails, plaster, and window glass. On a typical urban site in Boston, the location of buildings or other structures are either well known or still visible. Here the fact that the source of the 18th century materials is still unknown, the presence/absence of architectural artifacts is significant. Overall, the architectural artifacts appear to be densest in STPS located towards the rear of the property, suggesting the presence of buildings in that general direction and consistent with the Witherton map.

Arms

A single intact musket ball (Artifact #105000) (Figure 113) was recovered from the plowzone. While no evidence has yet been found to suggest any connection between the property and the Revolutionary War, various usages for muskets from self protection to hunting may be the origin of this particular artifact.

Figure 113- Musket ball from buried APZ, Unit 1.1, artifact #105000

Food and Beverage

In total, 5,720 artifacts were cataloged with the function of food and beverage within the APZ. They are divided into sub functions, below

Food Acquisition

709 food acquisition artifacts were recovered, specifically faunal remains related to animals from which food was acquired. Surprisingly, only a single fish bone was found. 148 clam, oyster, or quahog shell fragments, and the remaining 558 faunal artifacts were almost exclusively mammal. Overall, the number of faunal remains suggests that this particular area of the Seaver estate was not the primary area for disposal of organic remains, suggesting the kitchen midden may be in a more-distant location away from 72 Dale street. More-specifically, seafood and fish were relatively small components of the diet, suggesting that even though Roxbury is considered very close to the ocean and downtown Boston by today's standards, the distance from marine resources in the 18th century may have made shellfish and fish a less desirable or

less available food item for the Seaver residences. Other artifacts within the food and beverage component of the site the Seavers were quite wealthy. The preponderance of mammal bones and the presence of 27 mammal teeth (5% of the bones), suggests the Seavers were predominantly mammal eaters and that their farm likely contained sheep, pig, and cow, which were butchered in their entirety due to the presence of teeth.

Alternatively, the presence of bones but in relatively low concentration within the APZ could suggest that 72 Dale Street is located in an area where portions of the Seaver estate refuse disposal were plowed into the landscape and spread widely out from the main concentration near the house. This would account for the overall artifact scatter and would selectively preserve mammal bones better than fish or bird bones, which may have become so broken up and damaged by repeated plowing episodes as to make them disappear from the archaeological record at 72 Dale.

Food Consumption

No artifacts of this category were recovered, which would have included utensils and other artifacts used to aid the eater in consuming the food directly.

Food Preparation

A total of 938 food preparation artifacts were cataloged, the vast majority of which were redware hollow vessels. Only two non-redware food preparation artifacts were documented including a creamware and a white salt glazed stoneware colander fragments. It is interesting that colanders are the only food preparation artifacts documented, but their overall low number is likely insignificant. This continues to support the hypothesis that a concentration of household and food refuse exists near the Seaver Estate, but at 72 Dale Street, these artifacts are appearing as dispersed field scatter in a highly plowed zone near the home.

Food Service

The low numbers of food preparation artifacts suggests distance from a home, but the overall high numbers of food service artifacts suggest the opposite. 3,531 artifacts are cataloged as food service items. These include the vast majority of the ceramic items recovered. While most of the artifacts were highly fragmentary due to plowing and also likely due to the fact that they are located a distance from their primary deposition area, some service forms were identifiable. These include fragments of a Chinese hand-painted bowl (#105574, Figure 114), a guilt-rimmed porcelain mug (#106187, Figure 115), Westerwald Mugs (106166 Figure 116),fragments from at least five different teapots including white salt glazed stoneware, creamware, pearlware, and redware (#103342 Figure 117). Perhaps the most significant service artifact is a large fragment of hand-painted overglaze porcelain depicting a large ship in full sail (104821 FIgure 118 and 119). This was likely part of a custom-painted Chinese export porcelain bowl, perhaps a large punch bowl, and suggests a level of both wealth and group entertaining. As Abijah Seaver does not appear to be a merchant, the origin of the boat is currently unknown. The vast majority of the food service ceramics and glassware were difficult to determine forms from, but hollowware fragments (n=3330) outnumbered flatwares (n=149), significantly.

Figure 114- Rim of porcelain bowl from buried APZ, artifact #105574

Figure 115- Gold decorated porcelain mug rim from buried APZ, 106187

Figure 116- Westerwald mug rim from buried APZ, artifact 106166

Figure 117- Redware teapot lid from buried APZ, artifact #103342

Figure 118- Overglaze enamel porcelain with ship sails from buried APZ, Artifact #104821

Figure 119- Porcelain fragment with painted ship, immediately after being excavated on-site from buried APZ, Artifact # 104821

The food service data suggests several aspects to home life at the Seaver estate, data that would be supported by additional survey closer to the home if it were ever possible. At 2% of the overall assemblage in the APZ, porcelain represents a small but significant amount of porcelain vessels at the site. While creamwares and pearlwares dominate the assemblage, suggesting somewhat modest socioeconomic status, the Seavers were able to afford a not insignificant amount of imported chinese porcelain. Being a relatively rural estate compared to merchant areas along the shore, this house may represent a more refined gentleman farming family. The need for mortgages does suggest financial instability, however.

Food Storage

Food storage artifacts are at relatively high counts (n=495). The majority of these artifacts represent glass bottle fragments (n=478). As this was a farm estate the Seavers would have had poorer access to markets, but also would have been producing far more food themselves than their urban counterparts, requiring the need for additional food storage artifacts. The overall lower numbers in the area suggest that the farm-related and food-storage areas of the site may not be nearby; however, the foundation found behind 72 Dale may very well be a 18th century farm related structure.

Heating, Plumbing, and Lighting

Of the 620 artifacts cataloged with this function from the APZ, 569 were coal, slag, or charcoal. Of the remainder, only four fragments of lighting glass shade are significant.

Industry and Trade

This entire functional category is represented by two straight pins and a flower pot, suggesting that the primary industry at the site was farming, with some sewing and gardening occuring.

Medical

A single, intact 18th century aqua glass free-blown vial (#103286, Figure 120) is the only artifact cataloged as medicinal.



Figure 120- Aqua glass free-blown pharmaceutical bottle from buried APZ, Artifact #103286

Personal

Personal artifacts were relatively few in number, but include a fragment of a Westerwald chamberpot (#103824, Figure 121), wig curler (105166, Figure 122), buckle, and 18th century style button or cufflinks (105171, Figure 123). The remainder were additional buckle and pencil fragments. These artifacts suggest a relatively wealthy family who, despite living in a rural area, required the use of wig curlers for formal engagements or business.



Figure 121 - Westerwald chamberpot rim from from buried APZ, Artifact #103824



Figure 122- Clay wig curler from buried APZ, Artifact #105166.



Figure 123- Copper alloy buttons or cufflinks from buried APZ, Artifact #105171

Recreation and Leisure

312 tobacco smoking related artifacts represent the entirety of the recreation and leisure related goods. All were white ball clay. Sizes of stems include 4/64 (n=10), 5/64 (n=64), 6/64 (n=11), 7/64 (n=2) and 8/64 (n=1). The few large-bore tobacco pipes coupled with a few border ware and other early ceramics suggests a 17th century component to the site, but it appears very faint in the archaeological record, and may be 17th century field scatter. Marks include ER (#104790, Figure 124) and “IE.M” with a lion passant (106182, Figure 125). The ER pipe is likely Edward Randall from between 1699 and 1719 or Edward Reed, early 18th century, and The lion pipe is likely a pre-revolution 18th century armorial pipe with abbreviations for the British royal coat of arms motto “Dieu et mon droit” or “God and my Right” (Davey 1980).



Figure 124- Pipe bowl with “ER” makers mark from buried APZ, artifact #104790



Figure 125- Pipe bowl fragment with British royal crest from buried APZ, artifact #106182

Literacy, Arts, and Education

Two slate stone pencil fragments (105124, Figure 126) and a fragment of Nottingham-type stoneware ink bottle (#106755, Figure 127) were recovered documenting literacy and educational activities at the site.



Figure 126- Slate pencil from buried APZ, artifact #105124



Figure 127- Nottingham ink bottle shoulder from buried APZ, artifact #106755

B1

287 artifacts total were recovered from the B1 soil. This relatively high number is likely due to bioturbation or disturbances caused during early plowing episodes or later excavations of a STP. The artifacts, overall, appear in similar concentrations to the buried APZ strata, with overall lower numbers and include artifacts that date to the 17th-20th centuries.

B2

As expected, far fewer artifacts were identified in this strata than B1 with a total of 37 artifacts in the B2 soil horizon. This strata should be nearly devoid of artifacts that post-date the arrival of Europeans, and the artifacts found likely represent a level of disturbance to the site. These artifacts include coal, charcoal, wire and wrought nails, pearlware, creamware, and whiteware.

C

Only 9 artifacts were found in the C subsoil. These include a cut nail, staffordshire slipware, creamware, pearlware, bone, and flat window glass. All are likely brought in by disturbance, and 8 of the 9 artifacts were found in unit 3.1.

Discussion

In his book, Rodnell Collins describes Ella's struggle with the onslaught of individuals who approached her soon after her brother's assassination. She describes her hesitation to reveal both her knowledge of Malcolm and her personal story of their life together because "[Malcolm's] life was too important and too complex to be done hurriedly" (Collins 1998, 196) and that people would be "presenting an image of Malcolm X, symbolism without substance" (Collins 1998, 197).

This is one of many archaeological reports prepared by or contributed to by the primary author. In each, the best attempt was made to tell the story of the past through a combination of the archaeological, geological, historical, and oral data that could be gathered in preparation for the report. Each was written in good faith and the results were intended to genuinely encapsulate the data that was known about a site. The story of 72 Dale Street, however, is a new experience for the author. The archaeological dig began in 2015, and this report was written beginning in 2017 and ending in early 2018. During these three years, the stories and struggles of the Native, English colonial, Civil War participants, Immigrant, black, female, and muslim residents for equality and recognition, while never gone, have become starkly contemporary. At face value, this report summarizes the data that came from just 9.75 square meters of area excavated by an archaeological team. This is, by area, one of the smallest surveys conducted by the primary author, and yet at around 200 pages, it has become one of the longest phase 1 reports they have written. Still, despite the authors' best efforts, it feels like the data is "too important and too complex to be done hurriedly."

Perhaps it is the issues that this report brings up about civil rights; issues that are still contemporary as hate and bigotry is supported by and justified in the political climate existing while this sentence is being typed. Muslims, black people, women, minorities, and immigrants are still challenging white male supremacy with visibility not seen since the mid 20th century Civil Rights era with many believing this to be a good thing, and many believing the opposite. Perhaps it is the fact that a resident and contributor to the artifacts can be personally asked what the artifacts are and what they mean to them. Perhaps it is the stack of books written by and about the residents of this home sitting next to the computer upon which this paragraph is being written. Perhaps it is the sheer weight of the topics, people, and themes being discussed. Whatever the reason, this report has been a struggle to write. Not because the site itself is complex; it is not. The struggle is the fact that the story of the 20th century occupants feels so immense that no attempt at analysis will ever feel like it is doing justice to these people and their story. What this project has revealed more than anything to the author is the humbling realization that this inadequacy is only due to the quantity and recentness of the data being studied. If enough data was known about others on this or any other site, anywhere in the world, no attempt at analysis or study could *ever* do justice to *any* story revealed through archaeological survey. Regardless, this is our best attempt.

For millennia, Native people, including the Massachusett, have lived at the place we now call Boston. They utilized the many natural resource of the region including its abundant stone resources for tools in a unique concentration around boston, they utilized the fresh, estuary, and marine resources for the flora and fauna they produced, and the climate to grow food and live their lives. The rivers were transportation routes supported by coastal journeys and abundant foot trails. In Roxbury, a coastal and upland environment, resources were abundant and the highlands surrounding 72 Dale Street provided ample locations to process resources protected from elements, and puddingstone outcrops from which the surrounding area could be monitored. Plowing of the area has obscured much of the evidence for Native use at the site, but their stone tool fragments confirm use and presence of the space, now called the Collins Site.

With the arrival of European settlers, the Dudley area of Roxbury became a regional hub as the entranceway into Boston by foot. Early Puritan preachers including the Welds were recognized for their leadership, power, and ability to convert Native people, many of whom left the area to escape disease, physical conflict, and oppression. As Roxbury became increasingly occupied by settlers from elsewhere, the land was divided, cleared, and farmed, either by crops where land was fertile and soils were present, or livestock where outcrops made farming plants impossible. 72 Dale street just happened to be located near Walnut Street, which was likely a foot path created first by Natives, but later appropriated as a travel route by settlers who used it to reach large farm estates near what is today Forest Hills Park.

Sometime in the mid 18th century, perhaps earlier, a home was constructed at a bend on Walnut street, and the land between it and the main highway into and out of Boston from the South became the Seaver estate. Abijah Seaver and his family, according to their artifacts, were a fairly wealthy group who entertained guests, dressed up for public events, and otherwise expressed an heir of urban refinement in the relatively rural backwoods of Roxbury. Historical data suggests that they spent what appears to be an inappropriate amount on luxury goods as they required multiple mortgages to pay for their land, some of which nearly defaulted and were only redeemed by the chaotic aftermath of the Revolutionary War.

In the early 19th century, as Boston grew as a city and Roxbury became a satellite town in support of the larger urban center, Roxbury's population grew dramatically. Also by the mid 19th century, the Industrial Revolution began to spread into the area creating jobs and businesses along Roxbury's waterways. The increase in jobs and opportunities in Roxbury coupled with conditions in Europe and downtown Boston brought many recent immigrants into the town. This population boom converted the value of Roxbury land from agricultural to residential. In response, many of Roxbury's larger farms were broken up and streets were built including Dale Street in the 1840s. As the Seaver home was demolished, speculators bought up the estate and divided it into smaller lots, which were purchased and developed by relatively wealthy individuals and 72 Dale Street was built by Union engineer Nelson Curtis and occupied by a Civil War hero and cartographer, Frederic Dorr. In the late 19th century, the home was

purchased as a private home with rented rooms by a series of first and second generation immigrants from England, Ireland, and Scotland.

With the increase in labor supply, working conditions and pay decrease between the Civil War and Great Depression. This is seen at 72 Dale Street in the historic record as 19th century jobs included physicians, but early 20th century jobs were predominantly laborers. In the archaeological record, 18th century foods were predominantly large mammals including beef and pork, whereas later 19th century food appears to be dominated by much cheaper goose and crustaceans. The great depression having impacted working class people across the US, Ella Little's family moved from the south to Boston to pursue opportunities.

By 1940, 13 people from two families live in 72 Dale Street. Ella would buy 72 Dale Street with money earned from her business and savings savvy. Ella was a strong woman, who impressed her brother, Malcolm who commented that she was "committed to her family; she was resourceful; she was determined (Collins 1998,49). At 72 Dale Street, Ella's farming background and her rural land in Duxbury brought to the site abundant plants and gardens, with many flower pots decorating the landscape as plants were moved between the two properties and cared for. Ella's resourcefulness was reflected in the many older ceramics she collected to decorate her home and use to serve her guests, many of which were recovered from the refuse of others, and the recycled stone fragments from counters and sinks as walkway stones in the rear of her home. She hand-dug stones from glacial deposits in Duxbury and brought them to Roxbury to create a rock garden, and brought rabbits from her family's rabbit farm as pets. Ella created for her entire family a refuge to which her family could find shelter, love, and support.

In 1941, Ella became the legal guardian for her 14-year-old brother, Malcolm. He arrived a teenager who already experienced many personal tragedies and struggles, but possessed great intellect and potential. Coming from Lansing to Boston exposed Malcom to many temptations, which he accepted, resulting in a lifestyle that lead to imprisonment. Ella, never giving up on Malcolm's potential despite her disappointment in his actions, supported Malcolm during his imprisonment and got him into a program where he could get an education and learn debate skills while incarcerated.

Malcolm, already familiar with Islam from family friends, began preaching while in prison, eventually converting upon his release and becoming a national leader of the Nation of Islam. Many of his family members including Ella converted also and became leaders. Through his work preaching for the rights of Black people, his presence and notoriety within the Civil Rights Movement lead to controversy and his eventual denouncement of the Nation. In 1965, Malcolm was assassinated. Ella continued her Civil Rights efforts, but was herself devastated by the loss of her brother. Ella never returned to 72 Dale Street after the death of Malcolm. Ella died in 1996.

At home, Ella was a leader and fought for the rights of her family and of her neighborhood. Decades later, the work of Ella and Malcolm and many others has borne fruit. In 1941, she

fought the owners of 72 Dale street to sell to her. They refused despite their debts strongly suggesting their refusal was on the basis of her race and gender. On March 30, 2015, global news outlets were sharing the ongoing archaeological dig at the Malcolm X house. Jack Hallion, a local construction worker, whose father lived in the home when Ella purchased it, heard of the dig. His family history preserved the story that his family home went to Ella Little in the 1940s. Excited to know his personal connection, Jack came to the dig, met Rodnell Collins, Ella's son, and they had a private conversation in the home (Figure 128). Jack came because he was excited to hear about his family's home being part of a dig, and he was excited that his family's home had become the Malcolm X House.

Figure 128- Jack Hallion (Left) visits dig and speaks with Rodnell Collins (right)

In the 1950's, Ella was angry that Rodnell was not being taught black history in school. She fought the Boston Public School system for their refusal and was told in person by a school board member that it did not belong in Boston curriculum. On April 8, 2015, the Boston Public School Social Studies department organized a day-long open house during the dig (Figure 129) whereby hundreds of BPS students visited the dig, met Rodnell, and heard from him and the archaeologists on site about the story of Malcolm and Ella, their role in black history, and the deep history that was being found during the dig.

Figure 129- Some of the hundreds of BPS Social Studies students visiting the Malcolm X House during the archaeological dig there, April 8, 2015.

As archaeologists, the constant goal is to avoid our analysis becoming "symbolism without substance." When viewed as a whole, the artifacts from the site illustrate broad changes and trends in the occupants, but they fundamentally do not look considerably different from similar sites elsewhere in Boston. Furthermore, the historical documentation from the site appears fairly typical for most of Roxbury, but the nuances of preference and choices made by the occupants in their artifacts provide new insights into the daily lives of each occupant group. Neither data set stands well on its own, but when combined, the history of the site becomes dynamic, real, and original.

The artifacts and the archaeology of 72 Dale Street tell a story that is unique to the US. On a single location, artifacts from Native American, colonial farmer, Civil War, 19th century immigrants, and 20th century black muslim Civil Rights activist tell a near-complete narrative of

not only Roxbury history, but the history of the US. While this story seems grandiose, when examined individually, each story recorded beneath the ground is one of daily existence, normality, and domestic life. What the archaeology of 72 Dale Street revealed is the ordinary lives of extraordinary people.

Conclusions and Recommendations

Significant deposits were documented during this survey spanning many periods of Roxbury history.

The surface deposits cover nearly the entire surface of the property, except for the driveway surface. This deposit is the one most-directly associated with the 20th century occupation of Ella Little-Collins and her family (including Malcolm). This surface deposit is significant.

The 19th century deposit within Feature 6 is significant as it is the deposit most-clearly associated with the earliest occupants of the home, primarily individuals of English and Irish descent.

Feature 6 itself is significant as it is so far the only feature likely directly associated with the use and occupation of the property in the 18th century.

The buried plowed A soil is significant as it is associated with the use and occupation of the 18th century families, priarially Abijah Seaver, and his estate. It is found throughout the property.

The intact B soils are significant as they may possess additional evidence of Native American occupation beyond the scatter of lithic flakes in the plow zone.

All significant deposits should be avoided during modifications of the property. If they can not be avoided, they should be mitigated through additional archaeological survey.

References Cited

Adams, George
1857 *The Massachusetts Register*, Issue 91.

Bache, A. D.
1858 *Report of the Superintendent of the Coast Survey: Showing the Progress of the Survey during the Year 1858*. William A. Harris, Printer

Board of Harbor and Land Commissioners of Massachusetts
1892 H*earings before the Harbor and Land Commissioners in the Matter of the Construction of a Bridge from the City Proper to East Boston.* Rockwell and Churchill

City of Boston Printing Office.
1910 *A Record of the Streets, Alleys, Places, Etc. in the City of Boston*. City of Boston Printing Department

Bremer, Francis J, and Tom Webster.
2005 *Puritans and Puritanism in Europe and America, Volume 1.* ABC-CLIO

Collins, Rodnell with A. Peter Bailey
1998 *Seventh Child: A Family Memoir of Malcolm X*. Birch Lane Press, Carol Publishing Group

Cook, Louis A.
1918 *History of Norfolk County, Massachusetts, 1622-1918.* The S.J. Clarke Publishing Company

Davey, Peter (editor)
1980 "The Archaeology of the Clay Tobacco Pipe III. Britain: the North and West." *BAR British Series 78*

DONN, JOHN W.
2006 "War Record of J.W. Donn Including Reminiscences of Frederic W. Dorr July 1861 To June 1865." NOAA History, www.history.noaa.gov/stories_tales/donn.html.

Federal Bureau of Investigations
1955 "Malcolm Little (Malcolm X) HQ File 01 of 27", United States, Congress, New York.

Fulham, Volney Sewall.
1910 *The Fulham Genealogy: with Index of Names and Blanks for Records*. Free Press Printing Company,

George, E., Massachusetts. Probate Court (Suffolk Co.), .
1895 *Index to the probate records of the County of Suffolk, Massachusetts: from the year 1636 to and including the year 1893.* Rockwell and Churchill, City Printers, Boston, Mass.

Ledger of Mather Withington, 1792-1831. Account Books Collection, Bostonian Society

Middlesex County Probate Records, Massachusetts

Norfolk County Probate Records, Massachusetts

Putnam, Eben
1913 *Lieutenant Joshua Hewes: a New England Pioneer, and Some of His Descendants, with Materials for a Genealogical History of Other Families of the Name, and a Sketch of Joseph Hewes, the Signer. Vol. 1*, J.F. Tapley Company,

Quinn, Thomas J.
1896 *The Bookseller and Newsman. Vol. 13,* The New York Public Library,

Roberts, William H.
2003 *Civil War Ironclads: the U.S. Navy and Industrial Mobilization. illustrated ed.*, Johns Hopkins University Press,

Robinson, Charles Frederick
1938 “Weld collections.” Ann Arbor, Mich.: Priv. print.,

Suffolk County (Massachusetts) Probate Records,

Tuttle, Julius Herbert, editor.
1890 *Dedham Historical Register. Vol. 1*, Dedham Historical Society, Transcript Press,

United States Census
1870
1880
1900
1910
1920
1930
1940

X, Malcolm with Alex Haley 1965. *The Autobiography of Malcolm X*. Grove Press, NYC

This page left blank

Appendix A- Occupancy Documents

City of Boston Tax Records

1868
Dale Street Sw Side
William B Dorr Lawyer
Walter H Dorr Clerk
Frederick W Dorr owner
Total Property value **6,600**
Value of land **1,600**
Value of building **5,000**

1869
Dale Street
William B Dorr Lawyer
Walter H Dorr Clerk
Frederick W Dorr owner
Square feet **7,895**
Total Property value **8,200**
Value of land **3,200**
Value of building **5,000**

1870
72 Dale Street
William B Dorr Lawyer
Walter H Dorr Lawyer
Frederick W Dorr owner
Square feet **7,895**
Total Property value **8,600**
Value of land **3,600**
Value of building **5,000**

1871
72 Dale Street
William B Dorr Lawyer
Walter H Dorr Lawyer
Frederick W Dorr owner
Square feet **7,895**
Total Property value **8,600**

Value of land **3,600**
Value of building **5,000**

1872
72 Dale Street
William B Dorr Councilor
Walter H Dorr Lawyer
Frederick W Dorr owner
Square feet **7,895**
Total Property value **8,900**
Value of land **3,900**
Value of building **5,000**

1873
72 Dale Street
William B Dorr Councilor
Walter H Dorr Lawyer
Frederick W Dorr owner
Square feet **7,895**
Total Property value **8,900**
Value of land **3,900**
Value of building **5,000**

1874
72 Dale Street
House listed as vacant
Caroline P. Nichols
Square feet **7,895**
Total Property value **8,900**
Value of land **3,900**
Value of building **5,000**

1875
72 Dale Street
Daniel P. Nichols Carriages
Caroline P. Nichols Owner
Square feet **7,068**
Total Property value **9,000**
Value of land **3,500**
Value of building **5,500**

1876
72 Dale Street
Daniel P. Nichols Carriages
Caroline P. Nichols Owner
Square feet **7,068**
Total Property value **9,000**
Value of land **3,500**
Value of building **5,500**

1877
72 Dale Street
Daniel P. Nichols Carriages
Caroline P. Nichols Owner
Square feet **7,068**
Total Property value **9,000**
Value of land **3,500**
Value of building **5,500**

1878
72 Dale Street
Daniel P. Nichols Carriages
Caroline P. Nichols Owner
Square feet **7,068**
Total Property value **8,000**
Value of land **3,500**
Value of building **4,500**

1879
72 Dale Street
Daniel P. Nichols Carriages
Caroline P. Nichols Owner
Square feet **7,068**
Total Property value **7,500**
Value of land **3,500**
Value of building **4,000**

1880
72 Dale Street
Daniel P. Nichols Carriages
Caroline P. Nichols Owner
House+stable 1 horse
Square feet **7,068**
Total Property value **7,500**
Value of land **3,500**
Value of building **4,000**

1918
72 Dale Street
Mary M. Murphy Owner
Patrick J. Shannon liquor age 41
Square feet **7,068**
Total Property value **6,000**
Value of land **3,200**
Value of building **2,800**

Census Data

1870
The Dorr Family and one Irish Domestic Servant at least 4 people are in the house at this time
William B. Dorr Age 57, Male, Born in 1813, from Massachusetts, Lawyer, Real Estate value 6000, personal value, 1000
Mary Dorr Wife Age 60, Female, Born in 1810, Massachusetts, Keeping House
Walter H Dorr Son, Age 24, Male, Born in 1846, Massachusetts, Clerk For Lawyer
Bridget Burne Age 25, Male, Born in 1845, Ireland Domestic Servant

1880
72 Dale Street
The Nichols family and a servant are living in the house at least 5 people
Daniel P Nichols age 50, Born in 1830, Massachusetts carriage factory, 118 West Brookline
Caroline Nichols Wife, 43, Born in 1837, Massachusetts Keeping House
Wendell Nichols Son, age 19, Born in 1861, Massachusetts, Bookkeeper carriage factory, 118 West Brookline
Mary Nichols Daughter, age 4, Born in 1876, Massachusetts
Kate Connelley Age 25, Born in 1855, Ireland, Servant

1900
All are from Canada all are white renting all can read write and speak english 3 out of 4 of the Patten children are living in the house at least 5 people are living in the house
72 Dale Street
Alonzo D Patten Head of household, born 1840, age 59, married 32 years, came to America in 1885, Physician, 0 months not employed
Janet C Patten Wife, born 1857, age 49, married 32 years, had 6 children 4 are living, came to America in 1886
Samuel K Patten Son, born 1870, age 30, single, came to America in 1886, Physician, 0 months not employed
Jessie B Patten Daughter, born 1876, age 24, single, came to America in 1886
Ida C Patten Daughter, born 1877, age 22, single, came to America in 1886

1910
72 dale street
Anthony Patten and his two daughters are living in the house as well as his sister.

1 boarder and servant live in the house as well. At least 6 people are living in the house Renting
Anthony D Patten head of household, born in 1840, age 69, Widowed, from Canada, came to America in 1885, Traveling Physician, self employed
Jessie B Patten Daughter, born 1876, age 34, from Canada, came to America in 1885, Typewriter at bank, 0 weeks out of work
Ida S Patten Daughter, born 1877, age 32, from Canada, came to America in 1885
Edna C Patten Sister, age 54, born 1856, from Canada came to America in 1895
Bertha H Wilkinson Border, born 1874, age 36, From Massachusetts, Accountant at bank, 0 weeks out of work
Delia Higgins Servant, born 1881, age 29, From Ireland, came to America in 1902, Servant

1930
72 dale street
None of them attended school all can read and write at least 4 people are in the house at this time the boston city directory listed 2 more
Mary A Linehan Head of household, Owns the home, value of the home 11,500, age 54, born 1876, widowed, From Massachusetts, Parents from Ireland, No occupation
Albert J Gleason Head of Household, Renting, age 55, born 1875, From Massachusetts, Parents from Ireland, Clerk post office
Agnes G Gleason Wife, Renting, age 42, born 1888, From Massachusetts, Parents from Massachusetts, housewife home
Anna T Galvin age 39, born 1891, widowed, From Massachusetts, Parents from Scotland, Nurse

1940
At least 13 people are living in the house at this time and 2 families the Hallion family and Mary J Carrel with her two uncles.
72 dale street
Living in the same house since at least 1935
Mary J Carrel Head of household, age 35, born 1905, completed college, from Massachusetts, employed for pay, Teacher, Public School, income 1900 a year, weeks worked 42,
Charles J Sullivan Uncle, age 65, born 1875, completed high school, from Massachusetts, employed for pay, Shipper, Mill supply, 1200 a year, weeks worked 52
Frank T Sullivan Uncle, age 60, born 1880, completed high school, from Massachusetts, not employed for pay, been unemployed for 5 years, seeking work, Salesman, Shoe-retail
William J Hallion Head of household, from England, Naturalized, age 74, born 1866, completed 8th grade, not employed for pay, unable to work, has income from other sources
Isabella Hallion Wife, From Scotland, Naturalized, age 59, born 1881, completed 6th grade, not employed for pay, housework

Agnes N Hallion Daughter, age 31, born 1909, from Massachusetts, completed 4 years of high school, employed for pay, General Office work, retail Department Store, 780 a year, worked 52 weeks
Isabella Hallion Daughter, age 29, born 1911, from Massachusetts, completed 4 years of high school, employed for pay, General Office work, retail Department Store, 1040 a year, worked 52 weeks
Robert M Hallion Son, age 26, born 1914, from Massachusetts, completed 4 years of high school, employed for pay, Seaman, Shipping Industry, 520 a year, worked 52 weeks
John Hallion Son, age 24, born 1916, from Massachusetts, completed 4 years of high school, not employed for pay, been unemployed for 2 years, seeking work, Laborer, Construction
Frank Hallion Son, age 22, born 1918, from Massachusetts, completed 4 years of high school, not employed for pay, seeking work, Shipper, Wholesale paper distributor, weeks worked in 1939 13, 130 last year
Elisabeth J Hallion Daughter, age 20, born 1920, from Massachusetts, completed 4 years of high school, not employed for pay, seeking work, been unemployed for 76 weeks or almost 1.5 years, New worker
Thomas D Hallion Son, age 19, born 1921, from Massachusetts, completed 4 years of high school, not employed for pay, Public emergency work orderlie's helper, City hospital NYA, been unemployed for 8 weeks ,not seeking work, weeks worked in 1939 6, 60 last year
Henry P Hallion Son, age 17, born 1923, from Massachusetts, completed 3 years of high school, in school, not employed for pay, not seeking work

Boston City Directory 1869-1981

1869
Walter H Dorr student, 717 Federal, bds
William B Dorr counsellor, 717 Federal, h.

1870
Walter H Dorr student, 119 Dorch. Ave b.
William B Dorr counsellor, 119 Dorchester ave. h

Nothing listed for **1871**

Nothing listed for **1872**

Nothing listed for **1873**

Nothing listed for **1874**

Nothing listed for **1875**

1876
Daniel P Nichols & Co. carriage factory, 118 West Brookline, house 72 Dale, ward 21

Nothing listed for **1877**

1878
Daniel P Nichols & Co. carriage factory, 118 West Brookline, house 72 Dale, Roxbury

Nothing listed for **1879**

Nothing listed for **1880**

Nothing listed for **1881**

1882
Wendell L Nichols 118 W. Brookline, bds

1883
Wendell L Nichols 118 W. Brookline, bds

Nothing listed for **1884**

Nothing listed for **1885**

Nothing listed for **1886**

Nothing listed for **1887**

Nothing listed for **1888**

Nothing listed for **1889**

Nothing listed for **1890**

Nothing listed for **1891**

1892
John F Murphy periodicals, etc. Old Colony and providence depots, h

1893
John F Murphy periodicals, etc. Old Colony and providence depots, h

1894
John F Murphy periodicals, etc. Old Colony and providence depots, h

1895
John F Murphy periodicals, etc. Old Colony and providence depots, h

Nothing listed for **1896**

Nothing listed for **1897**

1898
Nathan Myers cigar maker, bds

1899
John F Murphy newsdealer, South station, h

1900
Anthony D Patten physician h
Stephen k Patten physician bds

1901

Anthony D Patten physician h

1902
Anthony D Patten physician h

1903
Anthony D Patten physician h
Stephen k Patten physician, 240 warren, Rox. h. 72 dale

1904
Anthony D Patten physician h
Stephen k Patten physician, 240 warren, Rox. h. 72 dale

1905
Anthony D Patten physician

1906
Anthony D Patten physician h
Stephen k Patten physician, 240 warren, Rox. h. 72 dale

1907
Anthony D Patten physician h

1908
Anthony D Patten physician h

1909
Anthony D Patten physician h

1910
Anthony D Patten physician h
Jessie B Patten stenographer city trust Co bds

1911
Jessie B Patten stenographer O C Trust Co 17 Court bds
Anthony D Patten physician h

1912
Anthony D Patten
Glendora M Clapp Mrs h

1913
Anthony D Patten physician h HLDS

Jessie B Patten clerk h

Nobody listed for **1914**

1915
Kilderry Nora Shannon widow Patrick h
Parker J Shannon manager 30 Avery h

1916
Kilderry Nora Shannon widow Patrick h
Parker J Shannon manager 30 Avery h

1917
Parker J Shannon manager 30 Avery h
Kilderry N Shannon widow Patrick h

Nothing listed for **1918**

Nothing listed for **1919**

Nothing listed for **1920**

1921
John A McDonald carpenter bds
Lewis D McDonald express 164 Dudley Rox bds
Raymond J McDonald police sta 16 bds

1922
Raymond J McDonald police sta 16 res
Daniel G McDonald (McDonald & Imhoff) 164 Dudley Rox h
John A McDonald carpenter res

1923
John A McDonald carpenter res
Raymond J McDonald Salesman res

1924
Mary J McDonald mrs h
John A McDonald carpenter res

1925
John A McDonald carpenter res
Mary J McDonald mrs h

1926
Mary J McDonald mrs h
John A McDonald carpenter res
Daniel G McDonald (McDonald & Imhoff) 164 Dudley Rox h
Lewis D McDonald chauffeur h

1927
Mary J McDonald mrs h
Lewis D McDonald chauffeur h
John A McDonald contractor res

1928
Mary A Linehan widow Joseph D Linehan h
Mary A White Teacher res
Julia A Grille widow Charles E res
Frederick H Blanchard clerk 358 south station h
Frederick H Blanchard Jr res

1929
Frederick H Blanchard clerk 358 south station h
Frederick H Blanchard Jr res
Alva L Leslie watchmaker and optometrist 7 blue hill av Rox res
Richard Daley Carrier Rox P O res
Mary A White Teacher res
Mary A Linehan widow Joseph D Linehan h

1930
Mary A Linehan widow Joseph D Linehan h
Albert J Gleason Laborer delivery div P O h
Francis M Herlihy weigher res
Mary A White Teacher res

1931
Angus J Owen lineman h
Francis M Herlihy weigher r
Mary A Linehan widow Joseph D Linehan h
Mary A White Teacher r

1932
Francis M Herlihy shipper r
Mary A Linehan widow Joseph D Linehan h

Angus J Owen lineman h

1933
Angus J Owen lineman h (Catherine)
Mary A Linehan widow Joseph D Linehan h
Mary widow william abbott r
Francis M Herlihy Shipper r

1934
Francis M Herlihy Shipper r
Charles J Sullivan shipper 20 linden alls r
Mary J Carroll teacher Dudley school h
Mary A Linehan widow Joseph D Linehan h

1935
Charles J Sullivan shipper 20 linden alls r
Mary J Carroll teacher Dudley school h

1936
Thomas J Gately (Mary) porter City Hospital h
Thomas J Gately Jr clerk 245 state rm 201 r
Helen J Gately telephone operator r
Charles J Sullivan shipper 20 linden alls r
Mary J Carroll teacher Dudley school h

1937
Isabel Hallion r Buyer 25 winter r
Robert M Hallion r
William J Hallion (Isabella) h
Mary J Carroll teacher Dudley school h
Charles J Sullivan shipper 20 linden alls r

1938
Frank J Hallion r
Isabel Hallion r Buyer 25 winter r
John J Hallion r
Robert M Hallion Seaman r
William J Hallion (Isabella) h
Frank D Sullivan salesman r
Charles J Sullivan shipper 20 linden alls r
Mary J Carroll assistant intermediate James P. Timility intermediate sch h

1939
Mary J Carroll assistant intermediate James P. Timility intermediate sch h
Frank J Hallion r
Isabel M Hallion Buyer Conrad's r
John J Hallion r
Robert M r
William J Hallion (Isabella) h
Frank T Sullivan salesman r
Charles J Sullivan Shipper H F Livermore Co r

1940
Frank T Sullivan salesman r
Charles J Sullivan shipper H F Livermore Co r
Frank J Hallion r Shipper Ralph F bass Inc
Isabel Hallion r Buyer Conrad's
John J Hallion r
Robert M Hallion Seaman r
William J Hallion (Isabella) h

1941
Agnes Hallion M r
Elizabeth Hallion r saleswoman
Frank J Hallion r Shipper Ralph F bass Inc
Isabella M Hallion r Buyer Conrad's
John J Hallion r Mach Cambells
Robert M Hallion r Mariner
William J Hallion (Isabella Hallion) h
Charles J Sullivan Shipper H F Livermore Co r
Frank T Sullivan Salesman r
Mary J Carroll assistant intermediate James P. Timility intermediate sch h

1942
William Walker Porter Woolworth's r
Fredrick L Jackson Porter (Sadie L Jackson) h
Kenneth Collins (Helen Collins) mech h

1943
Kenneth Collins (Helen Collins) mech h

1944
Kenneth Collins (Helen Collins) mech h

Fredrick L Jackson porter BE r

1945
Kenneth Collins (Helen Collins) Laundry Worker Standard B&A Laundry h

1946
Clara D Chester widow George Chester r
Grace Little r
James C Little h
Sarah Little Mrs r
Mildred Massie helper Tube Deutschmann Corp r
Joseph Massie Laborer r
Kenneth Collins (Helen Collins) h

1947
James C Little (Evelyn M Little) Mattress maker h
Sarah Little Mrs r
Kenneth Collins (Helen Collins) h

1948
Grace Little r
John J Black (Ella H Black) h
Kenneth Collins (Helen Collins) h

1949 is not available from ancestry.com

1950 is not available from ancestry.com

1951
Kenneth Collins (Helen Collins) Laundry Worker h
Harley Mcnair

1952
John Christians (Carol) h
Sarah Little Mrs r
Harley Mcnair
Kenneth Collins (Helen Collins) h

1953
Sarah Little Mrs r

1954
Grace Bolden r
Randolph Bolder wash mn Stilphen motor Co r
Kenneth J Collins Janitor TracerLab (Ella Collins) h
Malcolm Little

1955
Grace Bolden r
Randolph Bolden washman Stilphen motor Co h
Kenneth J Collins Technician TracerLab (Ella Collins) h
Malcolm X Little

1956
Grace Little r
Malcolm X Little h
Bernice McAdam kitchen worker NE Baptist Hospital r
Grace Bolden r
Randolph Bolden h
Kenneth Collins (Ella Collins) Laundry Worker h

1957
Grace Bolden r
Randolph Bolden h
Malcolm X Little h
Bernice McAdam kitchen worker NE Baptist Hospital r
Kenneth Collins (Ella Collins) Laundry Worker h

1958
Grace Bolden r
Randolph Bolden h
Kenneth Collins (Ella Collins) h
Malcolm X Little h

1959
Grace Bolden r
Randolph Bolden h
Kenneth Collins (Ella Collins) Laundry Worker h
Malcolm X Little h

1960
Grace Bolden r
Randolph Bolden h
Kenneth Collins (Ella Collins) Laundry Worker h
Malcolm X Little h

1961
Mina Rhoden Mrs h
Anderson Little h
Malcolm X Little h

1962
Andrea James waitress h
Mina Rhoden Mrs h
Malcolm X Little Laborer h

1963
Beulah B Harman h
Andrea James h Waitress
Harold Little (Grace Little) h

1964
Harold Little (Grace Little) h
Andrea James h Waitress
Beulah B Harman h
Harold Little h

1965
Harold Little (Grace Little) h (R)
Andrea James h (R) Waitress
Beulah B Harman h (R)

1966
Harold Little h (R)
Beulah B Harman h (R)

1967
Listed as vacant

1968
Trafaglia Eugene J

1969
Listed as vacant

1970
Listed as vacant

1971
Eugene J Trafaglia (Edna T) Driver Chevron Oil h (RS)
Edna T Trafaglia bmo Boston mut Life r (RS)

1972
Eugene J Trafaglia (Edna T) Driver Chevron Oil h (RS)
Edna T Trafaglia bmo Boston mut Life r (RS)

1973
Is not available on Ancestry.com

1974
Eugene J Trafaglia (Edna T) Driver Chevron Oil h (RS)

1975
Is not available on Ancestry.com

1976
Eugene J Trafaglia (Edna T) h

1977
Eugene J Trafaglia & Edna T Driver h (RS)

1978 not available on Ancestry.com
1979 not available on Ancestry.com
1980 not available on Ancestry.com

1981
Eugene J Trafaglia & Edna T Driver h (RS)

Appendix B- Provenience Context Code Guide to Malcolm X Site

Context codes organized by provenience

Context Code	Unit name	Feature	Strata	Level	Depth	Strata Function
MXH091	STP N099 E082		STR04	LEV07	60-70cm	B1
MXH092	STP N099 E082		STR04	LEV08	70-80cm	B2
MXH093	STP N099 E082		STR04	LEV09	80-90cm	B2
MXH088	STP N099 E082		STR03	LEV05	40-50cm	Buried APZ
MXH090	STP N099 E082		STR03	LEV07	60-70cm	Buried APZ
MXH085	STP N099 E082		STR02	LEV03	20-30cm	Gravel Fill
MXH086	STP N099 E082		STR02	LEV04	30-40cm	Gravel Fill
MXH087	STP N099 E082		STR02	LEV05	40-50cm	Gravel Fill
MXH089	STP N099 E082		STR02	LEV06	50-60cm	Gravel Fill
MXH083	STP N099 E082			LEV01	00-10cm	Surface/Developing A
MXH084	STP N099 E082		STR01	LEV02	10-20cm	Surface/Developing A
MXH133	STP N099 E084			LEV08	70-80cm	B1
MXH134	STP N099 E084			LEV09	80-90cm	B1
MXH135	STP N099 E084			LEV10	90-100cm	B2
MXH130	STP N099 E084			LEV05	40-50cm	Buried APZ
MXH131	STP N099 E084			LEV06	50-60cm	Buried APZ
MXH132	STP N099 E084			LEV07	60-70cm	Buried APZ
MXH128	STP N099 E084			LEV03	20-30cm	Fill
MXH129	STP N099 E084			LEV04	30-40cm	Fill
MXH126	STP N099 E084			LEV01	00-10cm	Surface/Developing A
MXH127	STP N099 E084			LEV02	10-20cm	Surface/Developing A
MXH079	STP N103 E095			LEV06	50-60cm	B1
MXH080	STP N103 E095			LEV07	60-70cm	B1
MXH077	STP N103 E095			LEV04	30-40cm	Buried APZ
MXH078	STP N103 E095			LEV05	40-50cm	Buried APZ
MXH076	STP N103 E095			LEV03	20-30cm	Fill
MXH074	STP N103 E095			LEV01	00-10cm	Surface/Developing A

MXH075	STP N103 E095			LEV02	10-20cm	Surface/Developing A
MXH048	STP N106 E087			LEV10	90-100cm	B1
MXH040	STP N106 E087			LEV02	10-20cm	Gravel Fill
MXH042	STP N106 E087			LEV04	30-40cm	Rock fill
MXH041	STP N106 E087			LEV03	20-30cm	Sand Fill
MXH039	STP N106 E087			LEV01	00-10cm	Surface/Developing A
MXH044	STP N106 E087			LEV06	50-60cm	Utility Fill
MXH045	STP N106 E087			LEV07	60-70cm	Utility Fill
MXH046	STP N106 E087			LEV08	70-80cm	Utility Fill
MXH047	STP N106 E087			LEV09	80-90cm	Utility Fill
MXH072	STP N106 E089			LEV02	10-20cm	Fill
MXH073	STP N106 E089		STR01	LEV03	20-30cm	Fill
MXH071	STP N106 E089			LEV01	00-10cm	Surface/Developing A
MXH120	STP N106 E094			LEV10	90-100cm	B1
MXH117	STP N106 E094			LEV07	60-70cm	Buried APZ
MXH118	STP N106 E094			LEV08	70-80cm	Buried APZ
MXH119	STP N106 E094			LEV09	80-90cm	Buried APZ
MXH113	STP N106 E094			LEV03	20-30cm	Fill
MXH114	STP N106 E094			LEV04	30-40cm	Fill
MXH115	STP N106 E094			LEV05	40-50cm	Redeposited B
MXH116	STP N106 E094			LEV06	50-60cm	Redeposited B
MXH111	STP N106 E094			LEV01	00-10cm	Surface/Developing A
MXH112	STP N106 E094		STR01	LEV02	10-20cm	Surface/Developing A
MXH067	STP N108 E086			LEV06	50-60cm	Buried APZ
MXH068	STP N108 E086			LEV07	60-70cm	Buried APZ
MXH069	STP N108 E086			LEV08	70-80cm	Buried APZ
MXH070	STP N108 E086			LEV09	80-90cm	Buried APZ
MXH063	STP N108 E086			LEV02	10-20cm	Cobbles
MXH064	STP N108 E086			LEV03	20-30cm	Cobbles
MXH065	STP N108 E086			LEV04	30-40cm	Fill
MXH066	STP N108 E086			LEV05	40-50cm	Fill
MXH062	STP N108 E086			LEV01	00-10cm	Surface/Developing A
MXH049	STP N108 E087		STR01	LEV01	00-10cm	Surface/Developing A
MXH059	STP N108 E089			LEV10	90-100cm	B1

MXH060	STP N108 E089		STR04B	LEV11	100-110cm	B1
MXH061	STP N108 E089		STR04B	LEV12	110-120cm	B1
MXH055	STP N108 E089		STR03	LEV06	50-60cm	Buried APZ
MXH056	STP N108 E089		STR03	LEV07	60-70cm	Buried APZ
MXH057	STP N108 E089		STR03	LEV08	70-80cm	Buried APZ
MXH058	STP N108 E089		STR03	LEV09	80-90cm	Buried APZ
MXH051	STP N108 E089		STR02	LEV02	10-20cm	Fill
MXH052	STP N108 E089		STR02	LEV03	20-30cm	fill
MXH053	STP N108 E089		STR02	LEV04	30-40cm	fill
MXH054	STP N108 E089		STR02	LEV05	40-50cm	fill
MXH050	STP N108 E089		STR02	LEV01	05-10cm	Surface/Developing A
MXH035	STP N109 E102			LEV09	80-90cm	B1
MXH036	STP N109 E102			LEV10	90-100cm	B1
MXH037	STP N109 E102			LEV11	100-110cm	B1
MXH038	STP N109 E102			LEV12	110-120cm	B1
MXH032	STP N109 E102			LEV06	50-60cm	Buried APZ
MXH033	STP N109 E102			LEV07	60-70cm	Buried APZ
MXH034	STP N109 E102			LEV08	70-80cm	Buried APZ
MXH029	STP N109 E102			LEV03	20-30cm	Fill
MXH030	STP N109 E102			LEV04	30-40cm	Fill
MXH031	STP N109 E102			LEV05	40-50cm	Fill
MXH027	STP N109 E102			LEV01	00-10cm	Surface/Developing A
MXH028	STP N109 E102			LEV02	10-20cm	Surface/Developing A
MXH124	STP N110 E079			LEV03	20-30cm	Fill
MXH125	STP N110 E079			LEV04	30-40cm	fill
MXH123	STP N110 E079			LEV02	10-20cm	Rock fill
MXH122	STP N110 E079			LEV01	00-10cm	Surface/Developing A
MXH022	STP N110 E081			LEV01	00-10cm	Surface/Developing A
MXH023	STP N110 E081			LEV02	10-20cm	Utility Fill
MXH024	STP N110 E081			LEV03	20-30cm	Utility Fill
MXH025	STP N110 E081			LEV04	30-40cm	Utility Fill
MXH259	STP N110 E081			LEV06	50-60cm	Utility Fill
MXH018	STP N110 E084		STR02	LEV02	10-20cm	Fill
MXH019	STP N110 E084		STR02	LEV03	20-30cm	Fill

MXH020	STP N110 E084		STR03	LEV04	30-40cm	Rubble Fill
MXH021	STP N110 E084		STR03	LEV05	40-50cm	Rubble Fill
MXH017	STP N110 E084			LEV01	00-10cm	Surface/Developing A
MXH012	STP N111 E072		STR03	LEV03	20-30cm	B1
MXH013	STP N111 E072		STR03	LEV04	30-40cm	B1
MXH011	STP N111 E072		STR02	LEV02	10-20cm	Buried APZ
MXH010	STP N111 E072		STR01	LEV01	00-10cm	Surface/Developing A
MXH016	STP N111 E072			LEV06	00-60cm	
MXH099	STP N117 E074		STR04	LEV05	40-50cm	B1
MXH100	STP N117 E074		STR04	LEV06	50-60cm	B1
MXH097	STP N117 E074		STR03	LEV03	20-30cm	Buried APZ
MXH098	STP N117 E074		STR03	LEV04	30-40cm	Buried APZ
MXH096	STP N117 E074		STR02	LEV02	12-20cm	Redeposited B
MXH095	STP N117 E074		STR01	LEV01	00-12cm	Surface/Developing A
MXH101	STP N117 E074, Wall Fall					
MXH109	STP N117 E081		STR03	LEV07	65-70cm	Fill
MXH110	STP N117 E081		STR03	LEV08	70-80cm	Fill
MXH103	STP N117 E081		STR02	LEV02	10-20cm	Slag
MXH104	STP N117 E081		STR02	LEV03	20-30cm	Slag
MXH105	STP N117 E081		STR02	LEV04	30-40cm	Slag
MXH106	STP N117 E081		STR02	LEV06	50-60cm	Slag
MXH107	STP N117 E081			LEV06	50-60cm	Slag
MXH108	STP N117 E081		STR02	LEV07	60-70cm	Slag
MXH102	STP N117 E081		STR01	LEV01	00-10cm	Surface/Developing A
MXH006	Surface, Alley on Grid North Side GPR					Surface/Developing A
MXH008	Surface, Barn Below Door on East Side of Addition					Surface/Developing A
MXH005	Surface, Berm in Grid East Corner of Yard GPR					Surface/Developing A
MXH007	Surface, Berm on Eastern					Surface/Developing A

	Foundation of Main Building Grid South					
MXH001	Surface, General					Surface/Developing A
MXH009	Surface, Material from Bulkhead					Surface/Developing A
MXH004	Surface, Rear Yard Scraping for GPR					Surface/Developing A
MXH002	Surface, Rock Garden					Surface/Developing A
MXH003	Surface, Screened Back Dirt Pile					Surface/Developing A
MXH155	Trench 1			LEV12	00-120cm	
MXH153	Unit 1.1		STR05	LEV12	110-120cm	B2
MXH145	Unit 1.1		STR04	LEV06-10	60-100cm	Buried APZ
MXH147	Unit 1.1		STR04	LEV07	60-70cm	Buried APZ
MXH149	Unit 1.1		STR04	LEV08	70-80cm	Buried APZ
MXH150	Unit 1.1		STR04	LEV09	80-90cm	Buried APZ
MXH151	Unit 1.1		STR04	LEV10	90-100cm	Buried APZ
MXH152	Unit 1.1		STR04	LEV11	100-110cm	Buried APZ
MXH139	Unit 1.1	5	STR01	LEV03	20-30cm	Foundation Builder's Trench
MXH140	Unit 1.1		STR02	LEV03	23-30cm	Foundation Builder's Trench
MXH141	Unit 1.1		STR02	LEV04	30-40cm	Foundation Builder's Trench
MXH142	Unit 1.1		STR02	LEV05	40-50cm	Foundation Builder's Trench
MXH144	Unit 1.1		STR02	LEV06	50-60cm	Foundation Builder's Trench
MXH146	Unit 1.1		STR02	LEV07	60-70cm	Foundation Builder's Trench
MXH148	Unit 1.1		STR02	LEV08	70-80cm	Foundation Builder's Trench
MXH143	Unit 1.1		STR03	LEV05	40-50cm	Inverted A
MXH136	Unit 1.1		STR01	LEV01	00-10cm	Surface/Developing A
MXH137	Unit 1.1		STR01	LEV02	10-20cm	Surface/Developing A
MXH138	Unit 1.1		STR01	LEV03	20-30cm	Surface/Developing A
MXH154	Unit 1.1, Wall Clean			LEV01-02	00-20cm	
MXH258	Unit 1.2		STR05	LEV11	102-110cm	B2

MXH162	Unit 1.2		STR04	LEV06	50-60cm	Buried APZ
MXH163	Unit 1.2		STR04	LEV07	60-70cm	Buried APZ
MXH164	Unit 1.2		STR04	LEV08	70-80cm	Buried APZ
MXH165	Unit 1.2		STR04	LEV09	80-90cm	Buried APZ
MXH166	Unit 1.2		STR04	LEV10	90-100cm	Buried APZ
MXH167	Unit 1.2		STR04	LEV11	100-110cm	Buried APZ
MXH168	Unit 1.2		STR04	LEV12	110-120cm	Buried APZ
MXH160	Unit 1.2		STR02	LEV04	30-40cm	Foundation Builder's Trench
MXH161	Unit 1.2		STR03	LEV05	40-50cm	Inverted A
MXH156	Unit 1.2		STR01	LEV01	00-10cm	Surface/Developing A
MXH157	Unit 1.2		STR01	LEV02	10-20cm	Surface/Developing A
MXH158	Unit 1.2		STR01	LEV03	20-30cm	Surface/Developing A
MXH159	Unit 1.2		STR01	LEV04	30-40cm	Surface/Developing A
MXH182	Unit 2.1		STR05	LEV09	80-90cm	B1
MXH183b	Unit 2.1		STR05	LEV10	90-100cm	B1
MXH176	Unit 2.1		STR03	LEV06	50-60cm	Buried APZ
MXH178	Unit 2.1		STR03	LEV08	70-80cm	Buried APZ
MXH180	Unit 2.1		STR03	LEV09	80-90cm	Buried APZ
MXH172	Unit 2.1		STR02	LEV04	30-40cm	Foundation Builder's Trench
MXH174	Unit 2.1		STR02	LEV05	40-50cm	Foundation Builder's Trench
MXH175	Unit 2.1		STR02	LEV06	50-60cm	Foundation Builder's Trench
MXH181	Unit 2.1		STR04	LEV09	80-90cm	Foundation Builder's Trench
MXH183	Unit 2.1		STR04	LEV10	90-100cm	Foundation Builder's Trench
MXH177	Unit 2.1		STR02	LEV07	60-70cm	Gravel Fill
MXH191	Unit 2.1	1	STR02	LEV04	30-40cm	Post Hole A soil fill
MXH192	Unit 2.1	1	STR02	LEV04	30-40cm	Post Hole A soil fill
MXH193	Unit 2.1	1	STR02	LEV05	40-50cm	Post Hole A soil fill
MXH194	Unit 2.1	1	STR02	LEV05	40-50cm	Post Hole A soil fill
MXH195	Unit 2.1	1	STR02	LEV06	50-60cm	Post Hole A soil fill
MXH196	Unit 2.1	1	STR02	LEV06	50-60cm	Post Hole A soil fill
MXH197	Unit 2.1	1	STR02	LEV07	60-70cm	Post Hole A soil fill
MXH198	Unit 2.1	1	STR02	LEV07	60-70cm	Post Hole A soil fill
MXH186	Unit 2.1	1	STR01	LEV04	30-40cm	Post Hole coal ash
MXH187	Unit 2.1	1	STR01	LEV05	40-50cm	Post Hole coal ash

MXH188	Unit 2.1	1	STR01	LEV06	50-60cm	Post Hole coal ash
MXH189	Unit 2.1	1	STR01	LEV06	50-60cm	Post Hole coal ash
MXH169	Unit 2.1		STR01	LEV01	00-10cm	Surface/Developing A
MXH170	Unit 2.1		STR01	LEV02	10-20cm	Surface/Developing A
MXH171	Unit 2.1		STR01	LEV03	20-30cm	Surface/Developing A
MXH190	Unit 2.1		STR01	LEV07	60-70cm	Surface/Developing A
MXH222	Unit 2.1+2.2, Wall Fall					
MXH215	Unit 2.2		STR05	LEV09	80-90cm	B1
MXH216	Unit 2.2		STR05	LEV10	90-100cm	B2
MXH218	Unit 2.2		STR05	LEV11	100-110cm	B2
MXH179	Unit 2.2	7	STR01	LEV09	80-90cm	Brick Vault trench fill
MXH210	Unit 2.2	7	STR01	LEV07	60-70cm	Brick Vault trench fill
MXH212	Unit 2.2	7	STR01	LEV08	70-80cm	Brick Vault trench fill
MXH217	Unit 2.2	7	STR05	LEV10	90-100cm	Brick Vault trench fill
MXH219	Unit 2.2	7	STR01	LEV11	100-110cm	Brick Vault trench fill
MXH221	Unit 2.2	7	STR07	LEV12	110-120cm	Brick Vault trench fill
MXH209	Unit 2.2		STR03	LEV06	50-60cm	Buried APZ
MXH211	Unit 2.2		STR03	LEV07	60-70cm	Buried APZ
MXH213	Unit 2.2		STR03	LEV08	70-80cm	Buried APZ
MXH214	Unit 2.2		STR03	LEV09	80-90cm	Buried APZ
MXH220	Unit 2.2		STR05	LEV12	110-120cm	C
MXH203	Unit 2.2	4	STR01	LEV04	30-40cm	Fill 1 over Cistern
MXH202	Unit 2.2	3	STR01	LEV04	30-40cm	Fill 2 over Cistern
MXH204	Unit 2.2		STR02	LEV04	30-40cm	Foundation Builder's Trench
MXH205	Unit 2.2		STR02	LEV05	40-50cm	Foundation Builder's Trench
MXH208	Unit 2.2		STR02	LEV06	50-60cm	Foundation Builder's Trench
MXH207	Unit 2.2	2	STR02	LEV05	40-50cm	Gravel Fill
MXH199	Unit 2.2		STR01	LEV01	00-10cm	Surface/Developing A
MXH200	Unit 2.2		STR01	LEV02	10-20cm	Surface/Developing A
MXH201	Unit 2.2		STR01	LEV03	20-30cm	Surface/Developing A
MXH206	Unit 2.2, Extension	1	STR02	LEV05	40-50cm	Post Hole A soil fill
MXH231	Unit 3.1		STR04	LEV05	40-50cm	B1
MXH227	Unit 3.1		STR03	LEV04	30-40cm	Buried APZ

MXH228	Unit 3.1		STR03	LEV05	40-50cm	Buried APZ
MXH232	Unit 3.1		STR05	LEV08	70-80cm	C
MXH225	Unit 3.1		STR02	LEV02	10-20cm	Foundation Builder's Trench
MXH226	Unit 3.1		STR02	LEV03	20-30cm	Foundation Builder's Trench
MXH230	Unit 3.1	6		LEV06	50-60cm	Outbuilding Foundation
MXH223	Unit 3.1		STR01	LEV01	00-10cm	Surface/Developing A
MXH224	Unit 3.1		STR01	LEV02	10-20cm	Surface/Developing A
MXH235	Unit 3.1		STR01-02	LEV01-02	00-20cm	
MXH234	Unit 3.1, Wall Clean/Fall Closing					
MXH236	Unit 3.1, Wall Fall			LEV04	00-40cm	
MXH253	Unit 3.2		STR09	LEV10	90-100cm	Feature 6 Ash fill
MXH254	Unit 3.2		STR09	LEV11	100-103cm	Feature 6 Ash fill
MXH247	Unit 3.2		STR06	LEV07	60-70cm	Feature 6 Interior Sand Fill
MXH248	Unit 3.2		STR06	LEV08	70-77cm	Feature 6 Interior Sand Fill
MXH249	Unit 3.2		STR06	LEV08	77-80cm	Feature 6 Interior Sand Fill
MXH250	Unit 3.2		STR08	LEV08	70-80cm	Feature 6 Organic fill
MXH251	Unit 3.2		STR08	LEV09	80-90cm	Feature 6 Organic fill
MXH252	Unit 3.2		STR08	LEV10	90-100cm	Feature 6 Organic fill
MXH241	Unit 3.2		STR02	LEV03	20-30cm	Foundation Builder's Trench
MXH242	Unit 3.2		STR02	LEV04	30-40cm	Foundation Builder's Trench
MXH243	Unit 3.2		STR02	LEV05	40-50cm	Foundation Builder's Trench
MXH245	Unit 3.2		STR02	LEV06	50-60cm	Foundation Builder's Trench
MXH246	Unit 3.2		STR02	LEV07	60-70cm	Foundation Builder's Trench
MXH239	Unit 3.2		STR02	LEV02	10-20cm	Redeposited foundation soils
MXH237	Unit 3.2		STR01	LEV01	00-10cm	Surface/Developing A
MXH238	Unit 3.2		STR01	LEV02	10-20cm	Surface/Developing A
MXH240	Unit 3.2		STR01	LEV03	20-30cm	Surface/Developing A
MXH257	Unit 3.2		STR01	LEV01-03	00-30cm	Surface/Developing A
MXH233	Unit 3.2, Wall Clean/Fall			LEV01-08	00-80cm	
MXH256	Unit 3.2, Wall Clean/Fall			LEV01-11	00-110cm	

MXH255	Unit 3.2, Wall Fall			LEV01-04	00-40cm	

Proveniences listed in order by context code

Context Code	UnitID	Feature	Stratum	Level	Depth	Strata Function
MXH001	Surface, General					Surface/Developing A
MXH002	Surface, Rock Garden					Surface/Developing A
MXH003	Surface, Screened Back Dirt Pile					Surface/Developing A
MXH004	Surface, Rear Yard Scraping for GPR					Surface/Developing A
MXH005	Surface, Berm in Grid East Corner of Yard GPR					Surface/Developing A
MXH006	Surface, Alley on Grid North Side GPR					Surface/Developing A
MXH007	Surface, Berm on Eastern Foundation of Main Building Grid South					Surface/Developing A
MXH008	Surface, Barn Below Door on East Side of Addition					Surface/Developing A
MXH009	Surface, Material from Bulkhead					Surface/Developing A
MXH010	STP N111 E072		STR01	LEV01	00-10cm	Surface/Developing A
MXH011	STP N111 E072		STR02	LEV02	10-20cm	Buried APZ
MXH012	STP N111 E072		STR03	LEV03	20-30cm	B1
MXH013	STP N111 E072		STR03	LEV04	30-40cm	B1
MXH016	STP N111 E072			LEV06	00-60cm	
MXH017	STP N110 E084			LEV01	00-10cm	Surface/Developing A
MXH018	STP N084 E110		STR02	LEV02	10-20cm	Fill
MXH019	STP N110 E084		STR02	LEV03	20-30cm	Fill
MXH020	STP N110 E084		STR03	LEV04	30-40cm	Rubble Fill
MXH021	STP N110 E084		STR03	LEV05	40-50cm	Rubble Fill
MXH022	STP N110 E081			LEV01	00-10cm	Surface/Developing A
MXH023	STP N110 E081			LEV02	10-20cm	Utility Fill

MXH024	STP N110 E081			LEV03	20-30cm	Utility Fill
MXH025	STP N110 E081			LEV04	30-40cm	Utility Fill
MXH027	STP N109 E102			LEV01	00-10cm	Surface/Developing A
MXH028	STP N108 E102			LEV02	10-20cm	Surface/Developing A
MXH029	STP N109 E102			LEV03	20-30cm	Fill
MXH030	STP N109 E102			LEV04	30-40cm	Fill
MXH031	STP N109 E102			LEV05	40-50cm	Fill
MXH032	STP N109 E102			LEV06	50-60cm	Buried APZ
MXH033	STP N108 E102			LEV07	60-70cm	Buried APZ
MXH034	STP N109 E102			LEV08	70-80cm	Buried APZ
MXH035	STP N109 E102			LEV09	80-90cm	B1
MXH036	STP N109 E102			LEV10	90-100cm	B1
MXH037	STP N109 E102			LEV11	100-110cm	B1
MXH038	STP N109 E102			LEV12	110-120cm	B1
MXH039	STP N106 E087			LEV01	00-10cm	Surface/Developing A
MXH040	STP N106 E087			LEV02	10-20cm	Gravel Fill
MXH041	STP N106 E087			LEV03	20-30cm	Sand Fill
MXH042	STP N106 E087			LEV04	30-40cm	Rock fill
MXH044	STP N106 E087			LEV06	50-60cm	Utility Fill
MXH045	STP N106 E087			LEV07	60-70cm	Utility Fill
MXH046	STP N106 E087			LEV08	70-80cm	Utility Fill
MXH047	STP N106 E087			LEV09	80-90cm	Utility Fill
MXH048	STP N106 E087			LEV10	90-100cm	B1
MXH049	STP N108 E084		STR01	LEV01	00-10cm	Surface/Developing A
MXH050	STP N108 E089		STR02	LEV01	05-10cm	Surface/Developing A
MXH051	STP N108 E089		STR02	LEV02	10-20cm	Fill
MXH052	STP N108 E089		STR02	LEV03	20-30cm	fill
MXH053	STP N108 E089		STR02	LEV04	30-40cm	fill
MXH054	STP N108 E089		STR02	LEV05	40-50cm	fill
MXH055	STP N108 E089		STR03	LEV06	50-60cm	Buried APZ
MXH056	STP N108 E089		STR03	LEV07	60-70cm	Buried APZ
MXH057	STP N108 E089		STR03	LEV08	70-80cm	Buried APZ
MXH058	STP N108 E089		STR03	LEV09	80-90cm	Buried APZ

MXH059	STP N108 E089			LEV10	90-100cm	B1
MXH060	STP N108 E089		STR04B	LEV11	100-110cm	B1
MXH061	STP N108 E089		STR04B	LEV12	110-120cm	B1
MXH062	STP N108 E086			LEV01	00-10cm	Surface/Developing A
MXH063	STP N108 E086			LEV02	10-20cm	Cobbles
MXH064	STP N108 E086			LEV03	20-30cm	Cobbles
MXH065	STP N108 E086			LEV04	30-40cm	Fill
MXH066	STP N108 E086			LEV05	40-50cm	Fill
MXH067	STP N108 E086			LEV06	50-60cm	Buried APZ
MXH068	STP N108 E086			LEV07	60-70cm	Buried APZ
MXH069	STP N108 E086			LEV08	70-80cm	Buried APZ
MXH070	STP N108 E086			LEV09	80-90cm	Buried APZ
MXH071	STP N106 E089			LEV01	00-10cm	Surface/Developing A
MXH072	STP N106 E089			LEV02	10-20cm	Fill
MXH073	STP N106 E089		STR01	LEV03	20-30cm	Fill
MXH074	STP N103 E095			LEV01	00-10cm	Surface/Developing A
MXH075	STP N103 E095			LEV02	10-20cm	Surface/Developing A
MXH076	STP N103 E095			LEV03	20-30cm	Fill
MXH077	STP N103 E095			LEV04	30-40cm	Buried APZ
MXH078	STP N103 E095			LEV05	40-50cm	Buried APZ
MXH079	STP N103 E095			LEV06	50-60cm	B1
MXH080	STP N103 E095			LEV07	60-70cm	B1
MXH083	STP N099 E082			LEV01	00-10cm	Surface/Developing A
MXH084	STP N099 E082		STR01	LEV02	10-20cm	Surface/Developing A
MXH085	STP N099 E082		STR02	LEV03	20-30cm	Gravel Fill
MXH086	STP N099 E082		STR02	LEV04	30-40cm	Gravel Fill
MXH087	STP N099 E082		STR02	LEV05	40-50cm	Gravel Fill
MXH088	STP N099 E082		STR03	LEV05	40-50cm	Buried APZ
MXH089	STP N099 E082		STR02	LEV06	50-60cm	Gravel Fill
MXH090	STP N099 E082		STR03	LEV07	60-70cm	Buried APZ
MXH091	STP N099 E082		STR04	LEV07	60-70cm	B1
MXH092	STP N099 E082		STR04	LEV08	70-80cm	B2
MXH093	STP N099 E082		STR04	LEV09	80-90cm	B2

MXH095	STP N117 E074		STR01	LEV01	00-12cm	Surface/Developing A
MXH096	STP N117 E074		STR02	LEV02	12-20cm	Redeposited B
MXH097	STP N117 E074		STR03	LEV03	20-30cm	Buried APZ
MXH098	STP N117 E074		STR03	LEV04	30-40cm	Buried APZ
MXH099	STP N117 E074		STR04	LEV05	40-50cm	B1
MXH100	STP N117 E074		STR04	LEV06	50-60cm	B1
MXH101	STP N117 E074, Wall Fall					
MXH102	STP N117 E081		STR01	LEV01	00-10cm	Surface/Developing A
MXH103	STP N117 E081		STR02	LEV02	10-20cm	Slag
MXH104	STP N117 E081		STR02	LEV03	20-30cm	Slag
MXH105	STP N117 E081		STR02	LEV04	30-40cm	Slag
MXH106	STP N117 E081		STR02	LEV06	50-60cm	Slag
MXH107	STP N117 E081			LEV06	50-60cm	Slag
MXH108	STP N117 E081		STR02	LEV07	60-70cm	Slag
MXH109	STP N117 E081		STR03	LEV07	65-70cm	Fill
MXH110	STP N117 E081		STR03	LEV08	70-80cm	Fill
MXH111	STP N106 E094			LEV01	00-10cm	Surface/Developing A
MXH112	STP N106 E094		STR01	LEV02	10-20cm	Surface/Developing A
MXH113	STP N106 E094			LEV03	20-30cm	Fill
MXH114	STP N106 E094			LEV04	30-40cm	Fill
MXH115	STP N106 E094			LEV05	40-50cm	Redeposited B
MXH116	STP N106 E094			LEV06	50-60cm	Redeposited B
MXH117	STP N106 E094			LEV07	60-70cm	Buried APZ
MXH118	STP N106 E094			LEV08	70-80cm	Buried APZ
MXH119	STP N106 E094			LEV09	80-90cm	Buried APZ
MXH120	STP N106 E094			LEV10	90-100cm	B1
MXH122	STP N110 E079			LEV01	00-10cm	Surface/Developing A
MXH123	STP N110 E079			LEV02	10-20cm	Rock fill
MXH124	STP N110 E079			LEV03	20-30cm	Fill
MXH125	STP N110 E079			LEV04	30-40cm	fill
MXH126	STP N099 E084			LEV01	00-10cm	Surface/Developing A
MXH127	STP N099 E084			LEV02	10-20cm	Surface/Developing A
MXH128	STP N099 E084			LEV03	20-30cm	Fill

MXH129	STP N099 E084			LEV04	30-40cm	Fill
MXH130	STP N099 E084			LEV05	40-50cm	Buried APZ
MXH131	STP N099 E084			LEV06	50-60cm	Buried APZ
MXH132	STP N099 E084			LEV07	60-70cm	Buried APZ
MXH133	STP N099 E084			LEV08	70-80cm	B1
MXH134	STP N099 E084			LEV09	80-90cm	B1
MXH135	STP N099 E084			LEV10	90-100cm	B2
MXH136	Unit 1.1		STR01	LEV01	00-10cm	Surface/Developing A
MXH137	Unit 1.1		STR01	LEV02	10-20cm	Surface/Developing A
MXH138	Unit 1.1		STR01	LEV03	20-30cm	Surface/Developing A
MXH139	Unit 1.1	5	STR01	LEV03	20-30cm	Foundation Builder's Trench
MXH140	Unit 1.1		STR02	LEV03	23-30cm	Foundation Builder's Trench
MXH141	Unit 1.1		STR02	LEV04	30-40cm	Foundation Builder's Trench
MXH142	Unit 1.1		STR02	LEV05	40-50cm	Foundation Builder's Trench
MXH143	Unit 1.1		STR03	LEV05	40-50cm	Inverted A
MXH144	Unit 1.1		STR02	LEV06	50-60cm	Foundation Builder's Trench
MXH145	Unit 1.1		STR04	LEV06-10	60-100cm	Buried APZ
MXH146	Unit 1.1		STR02	LEV07	60-70cm	Foundation Builder's Trench
MXH147	Unit 1.1		STR04	LEV07	60-70cm	Buried APZ
MXH148	Unit 1.1		STR02	LEV08	70-80cm	Foundation Builder's Trench
MXH149	Unit 1.1		STR04	LEV08	70-80cm	Buried APZ
MXH150	Unit 1.1		STR04	LEV09	80-90cm	Buried APZ
MXH151	Unit 1.1		STR04	LEV10	90-100cm	Buried APZ
MXH152	Unit 1.1		STR04	LEV11	100-110cm	Buried APZ
MXH153	Unit 1.1		STR05	LEV12	110-120cm	B2
MXH154	Unit 1.1, Wall Clean			LEV01-02	00-20cm	
MXH155	Trench 1			LEV12	00-120cm	
MXH156	Unit 1.2		STR01	LEV01	00-10cm	Surface/Developing A
MXH157	Unit 1.2		STR01	LEV02	10-20cm	Surface/Developing A
MXH158	Unit 1.2		STR01	LEV03	20-30cm	Surface/Developing A
MXH159	Unit 1.2		STR01	LEV04	30-40cm	Surface/Developing A

MXH160	Unit 1.2		STR02	LEV04	30-40cm	Foundation Builder's Trench
MXH161	Unit 1.2		STR03	LEV05	40-50cm	Inverted A
MXH162	Unit 1.2		STR04	LEV06	50-60cm	Buried APZ
MXH163	Unit 1.2		STR04	LEV07	60-70cm	Buried APZ
MXH164	Unit 1.2		STR04	LEV08	70-80cm	Buried APZ
MXH165	Unit 1.2		STR04	LEV09	80-90cm	Buried APZ
MXH166	Unit 1.2		STR04	LEV10	90-100cm	Buried APZ
MXH167	Unit 1.2		STR04	LEV11	100-110cm	Buried APZ
MXH168	Unit 1.2		STR04	LEV12	110-120cm	Buried APZ
MXH169	Unit 2.1		STR01	LEV01	00-10cm	Surface/Developing A
MXH170	Unit 2.1		STR01	LEV02	10-20cm	Surface/Developing A
MXH171	Unit 2.1		STR01	LEV03	20-30cm	Surface/Developing A
MXH172	Unit 2.1		STR02	LEV04	30-40cm	Foundation Builder's Trench
MXH174	Unit 2.1		STR02	LEV05	40-50cm	Foundation Builder's Trench
MXH175	Unit 2.1		STR02	LEV06	50-60cm	Foundation Builder's Trench
MXH176	Unit 2.1		STR03	LEV06	50-60cm	Buried APZ
MXH177	Unit 2.1		STR02	LEV07	60-70cm	Gravel Fill
MXH178	Unit 2.1		STR03	LEV08	70-80cm	Buried APZ
MXH179	Unit 2.2	7	STR01	LEV09	80-90cm	Brick Vault trench fill
MXH180	Unit 2.1		STR03	LEV09	80-90cm	Buried APZ
MXH181	Unit 2.1		STR04	LEV09	80-90cm	Foundation Builder's Trench
MXH182	Unit 2.1		STR05	LEV09	80-90cm	B1
MXH183	Unit 2.1		STR04	LEV10	90-100cm	Foundation Builder's Trench
MXH183b	Unit 2.1		STR05	LEV10	90-100cm	B1
MXH186	Unit 2.1	1	STR01	LEV04	30-40cm	Post Hole coal ash
MXH187	Unit 2.1	1	STR01	LEV05	40-50cm	Post Hole coal ash
MXH188	Unit 2.1	1	STR01	LEV06	50-60cm	Post Hole coal ash
MXH189	Unit 2.1	1	STR01	LEV06	50-60cm	Post Hole coal ash
MXH190	Unit 2.1		STR01	LEV07	60-70cm	Surface/Developing A
MXH191	Unit 2.1	1	STR02	LEV04	30-40cm	Post Hole A soil fill
MXH192	Unit 2.1	1	STR02	LEV04	30-40cm	Post Hole A soil fill
MXH193	Unit 2.1	1	STR02	LEV05	40-50cm	Post Hole A soil fill
MXH194	Unit 2.1	1	STR02	LEV05	40-50cm	Post Hole A soil fill

MXH195	Unit 2.1	1	STR02	LEV06	50-60cm	Post Hole A soil fill
MXH196	Unit 2.1	1	STR02	LEV06	50-60cm	Post Hole A soil fill
MXH197	Unit 2.1	1	STR02	LEV07	60-70cm	Post Hole A soil fill
MXH198	Unit 2.1	1	STR02	LEV07	60-70cm	Post Hole A soil fill
MXH199	Unit 2.2		STR01	LEV01	00-10cm	Surface/Developing A
MXH200	Unit 2.2		STR01	LEV02	10-20cm	Surface/Developing A
MXH201	Unit 2.2		STR01	LEV03	20-30cm	Surface/Developing A
MXH202	Unit 2.2	3	STR01	LEV04	30-40cm	Fill 2 over Cistern
MXH203	Unit 2.2	4	STR01	LEV04	30-40cm	Fill 1 over Cistern
MXH204	Unit 2.2		STR02	LEV04	30-40cm	Foundation Builder's Trench
MXH205	Unit 2.2		STR02	LEV05	40-50cm	Foundation Builder's Trench
MXH206	Unit 2.2, Extension	1	STR02	LEV05	40-50cm	Post Hole A soil fill
MXH207	Unit 2.2	2	STR02	LEV05	40-50cm	Gravel Fill
MXH208	Unit 2.2		STR02	LEV06	50-60cm	Foundation Builder's Trench
MXH209	Unit 2.2		STR03	LEV06	50-60cm	Buried APZ
MXH210	Unit 2.2	7	STR01	LEV07	60-70cm	Brick Vault trench fill
MXH211	Unit 2.2		STR03	LEV07	60-70cm	Buried APZ
MXH212	Unit 2.2	7	STR01	LEV08	70-80cm	Brick Vault trench fill
MXH213	Unit 2.2		STR03	LEV08	70-80cm	Buried APZ
MXH214	Unit 2.2		STR03	LEV09	80-90cm	Buried APZ
MXH215	Unit 2.2		STR05	LEV09	80-90cm	B1
MXH216	Unit 2.2		STR05	LEV10	90-100cm	B2
MXH217	Unit 2.2	7	STR05	LEV10	90-100cm	Brick Vault trench fill
MXH218	Unit 2.2		STR05	LEV11	100-110cm	B2
MXH219	Unit 2.2	7	STR01	LEV11	100-110cm	Brick Vault trench fill
MXH220	Unit 2.2		STR05	LEV12	110-120cm	C
MXH221	Unit 2.2	7	STR07	LEV12	110-120cm	Brick Vault trench fill
MXH222	Unit 2.1+2.2, Wall Fall					
MXH223	Unit 3.1		STR01	LEV01	00-10cm	Surface/Developing A
MXH224	Unit 3.1		STR01	LEV02	10-20cm	Surface/Developing A
MXH225	Unit 3.1		STR02	LEV02	10-20cm	Foundation Builder's Trench

MXH226	Unit 3.1		STR02	LEV03	20-30cm	Foundation Builder's Trench
MXH227	Unit 3.1		STR03	LEV04	30-40cm	Buried APZ
MXH228	Unit 3.1		STR03	LEV05	40-50cm	Buried APZ
MXH230	Unit 3.1	6		LEV06	50-60cm	Outbuilding Foundation
MXH231	Unit 3.1		STR04	LEV05	40-50cm	B1
MXH232	Unit 3.1		STR05	LEV08	70-80cm	C
MXH233	Unit 3.2, Wall Clean/Fall			LEV01-08	00-80cm	
MXH234	Unit 3.1, Wall Clean/Fall Closing					
MXH235	Unit 3.1		STR01-02	LEV01-02	00-20cm	
MXH236	Unit 3.1, Wall Fall			LEV04	00-40cm	
MXH237	Unit 3.2		STR01	LEV01	00-10cm	Surface/Developing A
MXH238	Unit 3.2		STR01	LEV02	10-20cm	Surface/Developing A
MXH239	Unit 3.2		STR02	LEV02	10-20cm	Redeposited foundation soils
MXH240	Unit 3.2		STR01	LEV03	20-30cm	Surface/Developing A
MXH241	Unit 3.2		STR02	LEV03	20-30cm	Foundation Builder's Trench
MXH242	Unit 3.2		STR02	LEV04	30-40cm	Foundation Builder's Trench
MXH243	Unit 3.2		STR02	LEV05	40-50cm	Foundation Builder's Trench
MXH245	Unit 3.2		STR02	LEV06	50-60cm	Foundation Builder's Trench
MXH246	Unit 3.2		STR02	LEV07	60-70cm	Foundation Builder's Trench
MXH247	Unit 3.2		STR06	LEV07	60-70cm	Feature 6 Interior Sand Fill
MXH248	Unit 3.2		STR06	LEV08	70-77cm	Feature 6 Interior Sand Fill
MXH249	Unit 3.2		STR06	LEV08	77-80cm	Feature 6 Interior Sand Fill
MXH250	Unit 3.2		STR08	LEV08	70-80cm	Feature 6 Organic fill
MXH251	Unit 3.2		STR08	LEV09	80-90cm	Feature 6 Organic fill
MXH252	Unit 3.2		STR08	LEV10	90-100cm	Feature 6 Organic fill
MXH253	Unit 3.2		STR09	LEV10	90-100cm	Feature 6 Ash fill
MXH254	Unit 3.2		STR09	LEV11	100-103cm	Feature 6 Ash fill
MXH255	Unit 3.2, Wall Fall			LEV01-04	00-40cm	
MXH256	Unit 3.2, Wall Clean/Fall			LEV01-11	00-110cm	

MXH257	Unit 3.2		STR01	LEV01-03	00-30cm	Surface/Developing A
MXH258	Unit 1.2		STR05	LEV11	102-110cm	B2
MXH259	STP N110 E081			LEV06	50-60cm	Utility Fill

Appendix C- Artifact Catalog

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
108271	Excavation Unit	FEA 1 EXT Unit 2.2 STR02 LEV05 40-50cm MXH206	1	MXH206	Post Hole A Soil Fill	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
108295	Excavation Unit	FEA 1 EXT Unit 2.2 STR02 LEV05 40-50cm MXH206	1	MXH206	Post Hole A Soil Fill	2	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
108275	Excavation Unit	FEA 1 EXT Unit 2.2 STR02 LEV05 40-50cm MXH206	1	MXH206	Post Hole A Soil Fill	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
108300	Excavation Unit	FEA 1 EXT Unit 2.2 STR02 LEV05 40-50cm MXH206	1	MXH206	Post Hole A Soil Fill	1	vessel, hollow	base	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
108277	Excavation Unit	FEA 1 EXT Unit 2.2 STR02 LEV05 40-50cm MXH206	1	MXH206	Post Hole A Soil Fill	4	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
108290	Excavation Unit	FEA 1 EXT Unit 2.2 STR02 LEV05 40-50cm MXH206	1	MXH206	Post Hole A Soil Fill	1	vessel, hollow	base	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
108288	Excavation Unit	FEA 1 EXT Unit 2.2 STR02 LEV05 40-50cm MXH206	1	MXH206	Post Hole A Soil Fill	4	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
108281	Excavation Unit	FEA 1 EXT Unit 2.2 STR02 LEV05 40-50cm MXH206	1	MXH206	Post Hole A Soil Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
108286	Excavation Unit	FEA 1 EXT Unit 2.2 STR02 LEV05 40-50cm MXH206	1	MXH206	Post Hole A Soil Fill	2	vessel, hollow	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
108289	Excavation Unit	FEA 1 EXT Unit 2.2 STR02 LEV05 40-50cm MXH206	1	MXH206	Post Hole A Soil Fill	20	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
108287	Excavation Unit	FEA 1 EXT Unit 2.2 STR02 LEV05 40-50cm MXH206	1	MXH206	Post Hole A Soil Fill	1	vessel, flat	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-black
108299	Excavation Unit	FEA 1 EXT Unit 2.2 STR02 LEV05 40-50cm MXH206	1	MXH206	Post Hole A Soil Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
108285	Excavation Unit	FEA 1 EXT Unit 2.2 STR02 LEV05 40-50cm MXH206	1	MXH206	Post Hole A Soil Fill	1	vessel, flat	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-orange
108279	Excavation Unit	FEA 1 EXT Unit 2.2 STR02 LEV05 40-50cm MXH206	1	MXH206	Post Hole A Soil Fill	3	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
108298	Excavation Unit	FEA 1 EXT Unit 2.2 STR02 LEV05 40-50cm MXH206	1	MXH206	Post Hole A Soil Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
108274	Excavation Unit	FEA 1 EXT Unit 2.2 STR02 LEV05 40-50cm MXH206	1	MXH206	Post Hole A Soil Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
108278	Excavation Unit	FEA 1 EXT Unit 2.2 STR02 LEV05 40-50cm MXH206	1	MXH206	Post Hole A Soil Fill	9	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
108294	Excavation Unit	FEA 1 EXT Unit 2.2 STR02 LEV05 40-50cm MXH206	1	MXH206	Post Hole A Soil Fill	1	vessel, flat	base	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
108280	Excavation Unit	FEA 1 EXT Unit 2.2 STR02 LEV05 40-50cm MXH206	1	MXH206	Post Hole A Soil Fill	18	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
108292	Excavation Unit	FEA 1 EXT Unit 2.2 STR02 LEV05 40-50cm MXH206	1	MXH206	Post Hole A Soil Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
108283	Excavation Unit	FEA 1 EXT Unit 2.2 STR02 LEV05 40-50cm MXH206	1	MXH206	Post Hole A Soil Fill	1	vessel, flat	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
108296	Excavation Unit	FEA 1 EXT Unit 2.2 STR02 LEV05 40-50cm MXH206	1	MXH206	Post Hole A Soil Fill	1	vessel, flat	rim	Ceramic	Porcelain	Chinese overglaze enamel	food/beverage	service	
108297	Excavation Unit	FEA 1 EXT Unit 2.2 STR02 LEV05 40-50cm MXH206	1	MXH206	Post Hole A Soil Fill	1	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
108273	Excavation Unit	FEA 1 EXT Unit 2.2 STR02 LEV05 40-50cm MXH206	1	MXH206	Post Hole A Soil Fill	11	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
108282	Excavation Unit	FEA 1 EXT Unit 2.2 STR02 LEV05 40-50cm MXH206	1	MXH206	Post Hole A Soil Fill	6	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
108284	Excavation Unit	FEA 1 EXT Unit 2.2 STR02 LEV05 40-50cm MXH206	1	MXH206	Post Hole A Soil Fill	8	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
108293	Excavation Unit	FEA 1 EXT Unit 2.2 STR02 LEV05 40-50cm MXH206	1	MXH206	Post Hole A Soil Fill	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
108276	Excavation Unit	FEA 1 EXT Unit 2.2 STR02 LEV05 40-50cm MXH206	1	MXH206	Post Hole A Soil Fill	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
108272	Excavation Unit	FEA 1 EXT Unit 2.2 STR02 LEV05 40-50cm MXH206	1	MXH206	Post Hole A Soil Fill	4	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
108291	Excavation Unit	FEA 1 EXT Unit 2.2 STR02 LEV05 40-50cm MXH206	1	MXH206	Post Hole A Soil Fill	4	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
106455	Excavation Unit	FEA 1 STR01 LEV06 50-60cm MXH189	1	MXH189	Post Hole Coal Ash	2	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
106088	Excavation Unit	FEA 1 Unit 2.1 STR01 LEV05 40-50cm MXH187	1	MXH187	Post Hole Coal Ash	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
106090	Excavation Unit	FEA 1 Unit 2.1 STR01 LEV05 40-50cm MXH187	1	MXH187	Post Hole Coal Ash	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
106091	Excavation Unit	FEA 1 Unit 2.1 STR01 LEV05 40-50cm MXH187	1	MXH187	Post Hole Coal Ash	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
106460	Excavation Unit	FEA 1 Unit 2.1 STR01 LEV05 50-60cm MXH188	1	MXH188	Post Hole Coal Ash	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
106461	Excavation Unit	FEA 1 Unit 2.1 STR01 LEV05 50-60cm MXH188	1	MXH188	Post Hole Coal Ash	1	nail, wire	fragment	Metal	ferrous	machine made	architecture	general construction	
106465	Excavation Unit	FEA 1 Unit 2.1 STR01 LEV4 30-40cm MXH186	1	MXH186	Post Hole Coal Ash	1	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
106466	Excavation Unit	FEA 1 Unit 2.1 STR01 LEV4 30-40cm MXH186	1	MXH186	Post Hole Coal Ash	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
107087	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH191	1	MXH191	Post Hole A Soil Fill	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
107076	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH191	1	MXH191	Post Hole A Soil Fill	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
107068	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH191	1	MXH191	Post Hole A Soil Fill	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
107085	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH191	1	MXH191	Post Hole A Soil Fill	1	vessel, flat	body	Ceramic	Earthenware, refined	Creamware, handpainted, underglaze	food/beverage	service	Annular-blue
107072	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH191	1	MXH191	Post Hole A Soil Fill	15	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107086	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH191	1	MXH191	Post Hole A Soil Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107084	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH191	1	MXH191	Post Hole A Soil Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, transfer printed overglaze	food/beverage	service	transfer print-blue
107081	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH191	1	MXH191	Post Hole A Soil Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
107074	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH191	1	MXH191	Post Hole A Soil Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
107082	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH191	1	MXH191	Post Hole A Soil Fill	4	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107070	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH191	1	MXH191	Post Hole A Soil Fill	5	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107073	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH191	1	MXH191	Post Hole A Soil Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107077	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH191	1	MXH191	Post Hole A Soil Fill	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
107083	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH191	1	MXH191	Post Hole A Soil Fill	3	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
107080	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH191	1	MXH191	Post Hole A Soil Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
107075	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH191	1	MXH191	Post Hole A Soil Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
107067	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH191	1	MXH191	Post Hole A Soil Fill	1	bottle, indeterminate	base	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
107069	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH191	1	MXH191	Post Hole A Soil Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
107079	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH191	1	MXH191	Post Hole A Soil Fill	2	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
107071	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH191	1	MXH191	Post Hole A Soil Fill	3	mica cutout	fragment	Mineral	mica	Not Assigned	architecture	window	
107078	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH191	1	MXH191	Post Hole A Soil Fill	1	pencil	fragment	Stone	Slate	Not Assigned	personal	other personal possession	
106999	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH192	1	MXH192	Post Hole A Soil Fill	3	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
107005	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH192	1	MXH192	Post Hole A Soil Fill	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
107015	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH192	1	MXH192	Post Hole A Soil Fill	13	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107003	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH192	1	MXH192	Post Hole A Soil Fill	1	vessel, flat	body	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
107004	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH192	1	MXH192	Post Hole A Soil Fill	4	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107012	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH192	1	MXH192	Post Hole A Soil Fill	13	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107002	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH192	1	MXH192	Post Hole A Soil Fill	1	vessel, hollow	body	Ceramic	Stoneware	British brown	food/beverage	Service	
107001	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH192	1	MXH192	Post Hole A Soil Fill	1	vessel, hollow	body	Ceramic	Stoneware	brown, salt-glazed	food/beverage	storage	Albany slip-brown
107008	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH192	1	MXH192	Post Hole A Soil Fill	7	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
107011	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH192	1	MXH192	Post Hole A Soil Fill	3	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
107007	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH192	1	MXH192	Post Hole A Soil Fill	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
107014	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH192	1	MXH192	Post Hole A Soil Fill	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
107016	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH192	1	MXH192	Post Hole A Soil Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
107013	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH192	1	MXH192	Post Hole A Soil Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
107006	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH192	1	MXH192	Post Hole A Soil Fill	1	unidentified	fragment	Metal	ferrous	cast	recreation/leisure	toys	
107010	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH192	1	MXH192	Post Hole A Soil Fill	2	unidentified	fragment	Metal	ferrous	unidentified		Not Assigned	
107009	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH192	1	MXH192	Post Hole A Soil Fill	1	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
107000	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV04 30-40cm MXH192	1	MXH192	Post Hole A Soil Fill	7	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
107064	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV05 40-50cm MXH193	1	MXH193	Post Hole A Soil Fill	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
107055	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV05 40-50cm MXH193	1	MXH193	Post Hole A Soil Fill	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
107062	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV05 40-50cm MXH193	1	MXH193	Post Hole A Soil Fill	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire, slipped	food/beverage	service	
107059	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV05 40-50cm MXH193	1	MXH193	Post Hole A Soil Fill	5	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107058	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV05 40-50cm MXH193	1	MXH193	Post Hole A Soil Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-green
107054	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV05 40-50cm MXH193	1	MXH193	Post Hole A Soil Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107063	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV05 40-50cm MXH193	1	MXH193	Post Hole A Soil Fill	2	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
107057	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV05 40-50cm MXH193	1	MXH193	Post Hole A Soil Fill	2	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
107154	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV05 40-50cm MXH193	1	MXH193	Post Hole A Soil Fill	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
107060	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV05 40-50cm MXH193	1	MXH193	Post Hole A Soil Fill	2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
107065	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV05 40-50cm MXH193	1	MXH193	Post Hole A Soil Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Amethyst/Purple
107061	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV05 40-50cm MXH193	1	MXH193	Post Hole A Soil Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
107056	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV05 40-50cm MXH193	1	MXH193	Post Hole A Soil Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Milk Glass/Blue
107052	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV05 40-50cm MXH193	1	MXH193	Post Hole A Soil Fill	1	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
107053	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV05 40-50cm MXH193	1	MXH193	Post Hole A Soil Fill	2	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
107066	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV05 40-50cm MXH193	1	MXH193	Post Hole A Soil Fill	1	pencil	fragment	Stone	Slate	Not Assigned	personal	other personal possession	
107160	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV05 40-50cm MXH194	1	MXH194	Post Hole A Soil Fill	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
107155	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV05 40-50cm MXH194	1	MXH194	Post Hole A Soil Fill	1	vessel, hollow	foot	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107162	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV05 40-50cm MXH194	1	MXH194	Post Hole A Soil Fill	6	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107168	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV05 40-50cm MXH194	1	MXH194	Post Hole A Soil Fill	3	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107156	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV05 40-50cm MXH194	1	MXH194	Post Hole A Soil Fill	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107165	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV05 40-50cm MXH194	1	MXH194	Post Hole A Soil Fill	1	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	service	
107157	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV05 40-50cm MXH194	1	MXH194	Post Hole A Soil Fill	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
107159	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV05 40-50cm MXH194	1	MXH194	Post Hole A Soil Fill	1	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
107161	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV05 40-50cm MXH194	1	MXH194	Post Hole A Soil Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Amber
107166	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV05 40-50cm MXH194	1	MXH194	Post Hole A Soil Fill	1	bottle, indeterminate	lip	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
107167	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV05 40-50cm MXH194	1	MXH194	Post Hole A Soil Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
107158	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV05 40-50cm MXH194	1	MXH194	Post Hole A Soil Fill	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
107163	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV05 40-50cm MXH194	1	MXH194	Post Hole A Soil Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
107164	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV05 40-50cm MXH194	1	MXH194	Post Hole A Soil Fill	3	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
106432	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV06 50-60cm MXH195	1	MXH195	Post Hole A Soil Fill	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
106437	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV06 50-60cm MXH195	1	MXH195	Post Hole A Soil Fill	6	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106431	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV06 50-60cm MXH195	1	MXH195	Post Hole A Soil Fill	3	vessel, hollow	body	Ceramic	Earthenware, refined	jackfield type	food/beverage	service	
106434	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV06 50-60cm MXH195	1	MXH195	Post Hole A Soil Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
106436	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV06 50-60cm MXH195	1	MXH195	Post Hole A Soil Fill	2	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
106435	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV06 50-60cm MXH195	1	MXH195	Post Hole A Soil Fill	8	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106430	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV06 50-60cm MXH195	1	MXH195	Post Hole A Soil Fill	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
106433	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV06 50-60cm MXH195	1	MXH195	Post Hole A Soil Fill	2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
106438	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV06 50-60cm MXH195	1	MXH195	Post Hole A Soil Fill	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
106441	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV06 50-60cm MXH195	1	MXH195	Post Hole A Soil Fill	1	drinking glass, tumbler	rim	Glass	molded	molded	food/beverage	service	-Clear
106429	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV06 50-60cm MXH195	1	MXH195	Post Hole A Soil Fill	1	rod	fragment	Metal	ferrous	machine made	architecture	hardware	
106440	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV06 50-60cm MXH195	1	MXH195	Post Hole A Soil Fill	2	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
106439	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV06 50-60cm MXH195	1	MXH195	Post Hole A Soil Fill	3	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
107098	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV06 50-60cm MXH196	1	MXH196	Post Hole A Soil Fill	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
107097	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV06 50-60cm MXH196	1	MXH196	Post Hole A Soil Fill	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
107095	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV06 50-60cm MXH196	1	MXH196	Post Hole A Soil Fill	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
107090	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV06 50-60cm MXH196	1	MXH196	Post Hole A Soil Fill	1	bowl, punch	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107100	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV06 50-60cm MXH196	1	MXH196	Post Hole A Soil Fill	4	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
107092	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV06 50-60cm MXH196	1	MXH196	Post Hole A Soil Fill	2	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107094	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV06 50-60cm MXH196	1	MXH196	Post Hole A Soil Fill	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107088	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV06 50-60cm MXH196	1	MXH196	Post Hole A Soil Fill	3	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
107093	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV06 50-60cm MXH196	1	MXH196	Post Hole A Soil Fill	2	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
107089	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV06 50-60cm MXH196	1	MXH196	Post Hole A Soil Fill	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
107099	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV06 50-60cm MXH196	1	MXH196	Post Hole A Soil Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
107096	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV06 50-60cm MXH196	1	MXH196	Post Hole A Soil Fill	3	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
107091	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV06 50-60cm MXH196	1	MXH196	Post Hole A Soil Fill	1	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
107145	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV07 60-70cm MXH197	1	MXH197	Post Hole A Soil Fill	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
107136	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV07 60-70cm MXH197	1	MXH197	Post Hole A Soil Fill	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
107142	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV07 60-70cm MXH197	1	MXH197	Post Hole A Soil Fill	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
107143	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV07 60-70cm MXH197	1	MXH197	Post Hole A Soil Fill	5	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107134	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV07 60-70cm MXH197	1	MXH197	Post Hole A Soil Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-brown
107137	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV07 60-70cm MXH197	1	MXH197	Post Hole A Soil Fill	1	plate	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
107130	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV07 60-70cm MXH197	1	MXH197	Post Hole A Soil Fill	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107133	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV07 60-70cm MXH197	1	MXH197	Post Hole A Soil Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107146	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV07 60-70cm MXH197	1	MXH197	Post Hole A Soil Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
107141	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV07 60-70cm MXH197	1	MXH197	Post Hole A Soil Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Whiteware, transfer printed	food/beverage	service	transfer print-blue
107140	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV07 60-70cm MXH197	1	MXH197	Post Hole A Soil Fill	1	vessel, flat	rim	Ceramic	Porcelain	Decorated	food/beverage	service	Annular-gray
107139	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV07 60-70cm MXH197	1	MXH197	Post Hole A Soil Fill	5	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
107132	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV07 60-70cm MXH197	1	MXH197	Post Hole A Soil Fill	1	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
107138	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV07 60-70cm MXH197	1	MXH197	Post Hole A Soil Fill	3	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
107144	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV07 60-70cm MXH197	1	MXH197	Post Hole A Soil Fill	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
107135	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV07 60-70cm MXH197	1	MXH197	Post Hole A Soil Fill	1	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
107129	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV07 60-70cm MXH197	1	MXH197	Post Hole A Soil Fill	2	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
107131	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV07 60-70cm MXH197	1	MXH197	Post Hole A Soil Fill	1	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
107120	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV07 60-70cm MXH198	1	MXH198	Post Hole A Soil Fill	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
107119	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV07 60-70cm MXH198	1	MXH198	Post Hole A Soil Fill	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
107118	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV07 60-70cm MXH198	1	MXH198	Post Hole A Soil Fill	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
107121	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV07 60-70cm MXH198	1	MXH198	Post Hole A Soil Fill	3	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107127	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV07 60-70cm MXH198	1	MXH198	Post Hole A Soil Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-green
107128	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV07 60-70cm MXH198	1	MXH198	Post Hole A Soil Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
107125	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV07 60-70cm MXH198	1	MXH198	Post Hole A Soil Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	Annular-blue
107122	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV07 60-70cm MXH198	1	MXH198	Post Hole A Soil Fill	6	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107123	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV07 60-70cm MXH198	1	MXH198	Post Hole A Soil Fill	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
107126	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV07 60-70cm MXH198	1	MXH198	Post Hole A Soil Fill	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
107124	Excavation Unit	FEA 1 Unit 2.1 STR02 LEV07 60-70cm MXH198	1	MXH198	Post Hole A Soil Fill	1	nail, indeterminate	fragment	Metal	ferrous	cut	architecture	general construction	
108323	Excavation Unit	FEA 2 Unit 2.2 STR02 LEV05 40-50cm MXH207		MXH207	Gravel Fill	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
108322	Excavation Unit	FEA 2 Unit 2.2 STR02 LEV05 40-50cm MXH207		MXH207	Gravel Fill	3	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
108321	Excavation Unit	FEA 2 Unit 2.2 STR02 LEV05 40-50cm MXH207		MXH207	Gravel Fill	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
107902	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	2	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
107906	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	7	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
107913	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
107877	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	4	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
107881	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
107874	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	1	chamber pot	base	Ceramic	Earthenware, coarse	Redware, lead glazed	personal	toiletry/hygiene	
107911	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	10	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
107882	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	1	vessel, hollow	body	Ceramic	Earthenware, coarse	unidentified	0	Not Assigned	
107887	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	1	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, handpainted, underglaze	food/beverage	service	painted-brown
107865	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	38	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107883	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	1	vessel, flat	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107904	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	1	vessel, hollow	foot	Ceramic	Earthenware, refined	Ironstone	food/beverage	service	
107909	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	slip-black
107884	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
107910	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
107864	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	3	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
107870	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	16	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107892	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	2	vessel, flat	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107869	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107875	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	2	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107880	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	3	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107893	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	1	vessel, hollow	foot	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107901	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	37	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107886	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	Annular-brown
107891	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	4	vessel, flat	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
107888	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	1	vessel, flat	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	painted-green
107897	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	1	vessel, hollow	body	Ceramic	Porcelain	Decorated	food/beverage	service	painted-blue
107889	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	1	vessel, flat	body	Ceramic	Porcelain	Decorated	food/beverage	service	painted-red
107885	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	1	vessel, hollow	base	Ceramic	Stoneware	buff salt glazed	food/beverage	service	
107900	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	2	vessel, hollow	body	Ceramic	Stoneware	Westerwald	food/beverage	service	
107872	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	3	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
107873	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	1	vessel, flat	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
107867	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	1	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
107899	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	1	vessel, indeterminate	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
107871	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	2	bone	fragment	Fauna	bone	bird	food/beverage	acquisition	
107866	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	22	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
107903	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	2	tooth	fragment	Fauna	enamel/bone	tooth	food/beverage	acquisition	
107876	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	3	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
107879	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	14	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
107878	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	4	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
107894	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	4	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
107908	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
107896	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	4	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green*
107905	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	1	vessel, indeterminate	fragment	Glass	mold blown	Not Assigned	0	Not Assigned	-Clear
107898	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	3	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
107912	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	9	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
107868	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	1	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
107895	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	6	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
107890	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	4	unidentified	fragment	Synthetic	synthetic	indeterminate	architecture	window	
107907	Excavation Unit	FEA 3 Unit 2.2 STR01 LEV04 30-40cm MXH202	3	MXH202	Fill 2 Over Cistern	1	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
108324	Excavation Unit	FEA 4 Unit 2.2 STR01 LEV04 30-40cm MXH203	4	MXH203	Fill 1 Over Cistern	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-yellow
108325	Excavation Unit	FEA 4 Unit 2.2 STR01 LEV04 30-40cm MXH203	4	MXH203	Fill 1 Over Cistern	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105534	Excavation Unit	FEA 5 Unit 1.1 STR01 LEV03 20-30cm MXH139	5	MXH139	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105545	Excavation Unit	FEA 5 Unit 1.1 STR01 LEV03 20-30cm MXH139	5	MXH139	Foundation Builder's Trench	1	vessel, hollow	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105530	Excavation Unit	FEA 5 Unit 1.1 STR01 LEV03 20-30cm MXH139	5	MXH139	Foundation Builder's Trench	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105543	Excavation Unit	FEA 5 Unit 1.1 STR01 LEV03 20-30cm MXH139	5	MXH139	Foundation Builder's Trench	2	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	service	
105539	Excavation Unit	FEA 5 Unit 1.1 STR01 LEV03 20-30cm MXH139	5	MXH139	Foundation Builder's Trench	1	charcoal	fragment	Flora	wood	charcoal	heating, plumbing, electric	fuel	
105547	Excavation Unit	FEA 5 Unit 1.1 STR01 LEV03 20-30cm MXH139	5	MXH139	Foundation Builder's Trench	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
105532	Excavation Unit	FEA 5 Unit 1.1 STR01 LEV03 20-30cm MXH139	5	MXH139	Foundation Builder's Trench	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Amber
105525	Excavation Unit	FEA 5 Unit 1.1 STR01 LEV03 20-30cm MXH139	5	MXH139	Foundation Builder's Trench	10	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
105531	Excavation Unit	FEA 5 Unit 1.1 STR01 LEV03 20-30cm MXH139	5	MXH139	Foundation Builder's Trench	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear-manganese ti+nt
105536	Excavation Unit	FEA 5 Unit 1.1 STR01 LEV03 20-30cm MXH139	5	MXH139	Foundation Builder's Trench	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
105538	Excavation Unit	FEA 5 Unit 1.1 STR01 LEV03 20-30cm MXH139	5	MXH139	Foundation Builder's Trench	6	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Milk glass/Opaque white
105527	Excavation Unit	FEA 5 Unit 1.1 STR01 LEV03 20-30cm MXH139	5	MXH139	Foundation Builder's Trench	1	bottle, indeterminate	base	Glass	Machine made	machine made	food/beverage	storage	-Clear-ovoid-machine made (1903)
105529	Excavation Unit	FEA 5 Unit 1.1 STR01 LEV03 20-30cm MXH139	5	MXH139	Foundation Builder's Trench	1	bead	whole/intact	Glass	molded	molded	personal	adornment	-Milk Glass/Blue
105533	Excavation Unit	FEA 5 Unit 1.1 STR01 LEV03 20-30cm MXH139	5	MXH139	Foundation Builder's Trench	1	unidentified	fragment	Metal	ferrous	unidentified	0	Not Assigned	
105528	Excavation Unit	FEA 5 Unit 1.1 STR01 LEV03 20-30cm MXH139	5	MXH139	Foundation Builder's Trench	3	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
105526	Excavation Unit	FEA 5 Unit 1.1 STR01 LEV03 20-30cm MXH139	5	MXH139	Foundation Builder's Trench	1	comb, hair	fragment	Synthetic	synthetic	plastic	personal	toiletry/hygiene	
104630	Excavation Unit	FEA 6 Unit 3.1 LEV06 50-60cm MXH230	6	MXH230	Outbuilding Foundation	1	vessel, flat	body	Ceramic	Earthenware, coarse	unidentified	0	Not Assigned	
104629	Excavation Unit	FEA 6 Unit 3.1 LEV06 50-60cm MXH230	6	MXH230	Outbuilding Foundation	1	vessel, hollow	foot	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104632	Excavation Unit	FEA 6 Unit 3.1 LEV06 50-60cm MXH230	6	MXH230	Outbuilding Foundation	2	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104637	Excavation Unit	FEA 6 Unit 3.1 LEV06 50-60cm MXH230	6	MXH230	Outbuilding Foundation	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-brown
104634	Excavation Unit	FEA 6 Unit 3.1 LEV06 50-60cm MXH230	6	MXH230	Outbuilding Foundation	2	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104631	Excavation Unit	FEA 6 Unit 3.1 LEV06 50-60cm MXH230	6	MXH230	Outbuilding Foundation	5	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104635	Excavation Unit	FEA 6 Unit 3.1 LEV06 50-60cm MXH230	6	MXH230	Outbuilding Foundation	1	bone	fragment	Fauna	bone	bird	food/beverage	acquisition	
104633	Excavation Unit	FEA 6 Unit 3.1 LEV06 50-60cm MXH230	6	MXH230	Outbuilding Foundation	3	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
104638	Excavation Unit	FEA 6 Unit 3.1 LEV06 50-60cm MXH230	6	MXH230	Outbuilding Foundation	1	stemware	body	Glass	indeterminate	indeterminate	food/beverage	service	-Clear
104636	Excavation Unit	FEA 6 Unit 3.1 LEV06 50-60cm MXH230	6	MXH230	Outbuilding Foundation	2	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
104628	Excavation Unit	FEA 6 Unit 3.1 LEV06 50-60cm MXH230	6	MXH230	Outbuilding Foundation	2	mortar	fragment	Mineral	composite	mortar	architecture	general construction	
107992	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
108002	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
107986	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	2	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
107980	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
107985	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	4	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
107993	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined		food/beverage	service	painted-green

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
107995	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	18	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107999	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107996	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-orange
107994	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-orange
107976	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	1	vessel, flat	body	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
107977	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	10	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107987	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107991	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107974	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107979	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107989	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	16	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107998	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	2	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
107973	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	food/beverage	service	engine turned-green
107990	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	1	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	service	
107981	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	1	vessel, hollow	body	Ceramic	Stoneware	British brown	food/beverage	Service	
108003	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	1	vessel, hollow	body	Ceramic	Tin Glazed	unidentified	food/beverage	service	
107982	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
107988	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	6	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
108006	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	3	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
108005	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
108001	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	4	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
108004	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	1	bottle, indeterminate	lip	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
107997	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
108007	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
107978	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	1	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
107984	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	4	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
107983	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	1	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
108008	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	2	mortar	fragment	Mineral	composite	mortar	architecture	general construction	
108000	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV07 60-70cm MXH210	7	MXH210	Brick Cistern Vault Trench Fill	1	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
108239	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV08 70-80cm MXH212	7	MXH212	Brick Cistern Vault Trench Fill	1	wig curler	fragment	Ceramic	Ball clay	molded	personal	other personal possession	
108222	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV08 70-80cm MXH212	7	MXH212	Brick Cistern Vault Trench Fill	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
108235	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV08 70-80cm MXH212	7	MXH212	Brick Cistern Vault Trench Fill	2	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
108217	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV08 70-80cm MXH212	7	MXH212	Brick Cistern Vault Trench Fill	10	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
108231	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV08 70-80cm MXH212	7	MXH212	Brick Cistern Vault Trench Fill	4	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
108236	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV08 70-80cm MXH212	7	MXH212	Brick Cistern Vault Trench Fill	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
108227	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV08 70-80cm MXH212	7	MXH212	Brick Cistern Vault Trench Fill	21	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
108225	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV08 70-80cm MXH212	7	MXH212	Brick Cistern Vault Trench Fill	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
108230	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV08 70-80cm MXH212	7	MXH212	Brick Cistern Vault Trench Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-orange
108224	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV08 70-80cm MXH212	7	MXH212	Brick Cistern Vault Trench Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
108228	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV08 70-80cm MXH212	7	MXH212	Brick Cistern Vault Trench Fill	13	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	
108238	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV08 70-80cm MXH212	7	MXH212	Brick Cistern Vault Trench Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
108229	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV08 70-80cm MXH212	7	MXH212	Brick Cistern Vault Trench Fill	26	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
108233	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV08 70-80cm MXH212	7	MXH212	Brick Cistern Vault Trench Fill	1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
108232	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV08 70-80cm MXH212	7	MXH212	Brick Cistern Vault Trench Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
108234	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV08 70-80cm MXH212	7	MXH212	Brick Cistern Vault Trench Fill	1	vessel, hollow	rim	Ceramic	Porcelain	Decorated	food/beverage	service	painted-blue
108218	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV08 70-80cm MXH212	7	MXH212	Brick Cistern Vault Trench Fill	1	bottle, ink	body	Ceramic	Stoneware	Nottingham-type	medical/chemical	storage	
108221	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV08 70-80cm MXH212	7	MXH212	Brick Cistern Vault Trench Fill	1	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	painted-blue
108237	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV08 70-80cm MXH212	7	MXH212	Brick Cistern Vault Trench Fill	31	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
108219	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV08 70-80cm MXH212	7	MXH212	Brick Cistern Vault Trench Fill	4	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
108220	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV08 70-80cm MXH212	7	MXH212	Brick Cistern Vault Trench Fill	6	charcoal	fragment	Flora	wood	charcoal	heating, plumbing, electric	fuel	
108226	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV08 70-80cm MXH212	7	MXH212	Brick Cistern Vault Trench Fill	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
108223	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV08 70-80cm MXH212	7	MXH212	Brick Cistern Vault Trench Fill	1	unidentified	fragment	Metal	ferrous	unidentified	0	Not Assigned	
108301	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV09 80-90cm MXH179	7	MXH179	Brick Cistern Vault Trench Fill	9	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
108303	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV09 80-90cm MXH179	7	MXH179	Brick Cistern Vault Trench Fill	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
108309	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV09 80-90cm MXH179	7	MXH179	Brick Cistern Vault Trench Fill	1	vessel, flat	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
108305	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV09 80-90cm MXH179	7	MXH179	Brick Cistern Vault Trench Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
108306	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV09 80-90cm MXH179	7	MXH179	Brick Cistern Vault Trench Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
108307	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV09 80-90cm MXH179	7	MXH179	Brick Cistern Vault Trench Fill	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
108308	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV09 80-90cm MXH179	7	MXH179	Brick Cistern Vault Trench Fill	1	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
108304	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV09 80-90cm MXH179	7	MXH179	Brick Cistern Vault Trench Fill	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
108302	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV09 80-90cm MXH179	7	MXH179	Brick Cistern Vault Trench Fill	1	nail, cut	whole/intact	Metal	copper alloy	copper alloy	architecture	general construction	
106456	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV11 100-110cm MXH219	7	MXH219	Brick Cistern Vault Trench Fill	5	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
106457	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV11 100-110cm MXH219	7	MXH219	Brick Cistern Vault Trench Fill	2	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106458	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV11 100-110cm MXH219	7	MXH219	Brick Cistern Vault Trench Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
106459	Excavation Unit	FEA 7 Unit 2.2 STR01 LEV11 100-110cm MXH219	7	MXH219	Brick Cistern Vault Trench Fill	1	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
108329	Excavation Unit	FEA 7 Unit 2.2 STR05 LEV10 90-100cm MXH217	7	MXH217	Brick Cistern Vault Trench Fill	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
108334	Excavation Unit	FEA 7 Unit 2.2 STR05 LEV10 90-100cm MXH217	7	MXH217	Brick Cistern Vault Trench Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
108332	Excavation Unit	FEA 7 Unit 2.2 STR05 LEV10 90-100cm MXH217	7	MXH217	Brick Cistern Vault Trench Fill	1	vessel, flat	body	Ceramic	Earthenware, refined	Whiteware, undecorated	food/beverage	service	
108326	Excavation Unit	FEA 7 Unit 2.2 STR05 LEV10 90-100cm MXH217	7	MXH217	Brick Cistern Vault Trench Fill	1	vessel, flat	rim	Ceramic	Porcelain	Chinese overglaze enamel	food/beverage	service	
108327	Excavation Unit	FEA 7 Unit 2.2 STR05 LEV10 90-100cm MXH217	7	MXH217	Brick Cistern Vault Trench Fill	2	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
108330	Excavation Unit	FEA 7 Unit 2.2 STR05 LEV10 90-100cm MXH217	7	MXH217	Brick Cistern Vault Trench Fill	3	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
108333	Excavation Unit	FEA 7 Unit 2.2 STR05 LEV10 90-100cm MXH217	7	MXH217	Brick Cistern Vault Trench Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green^
108328	Excavation Unit	FEA 7 Unit 2.2 STR05 LEV10 90-100cm MXH217	7	MXH217	Brick Cistern Vault Trench Fill	2	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
108331	Excavation Unit	FEA 7 Unit 2.2 STR05 LEV10 90-100cm MXH217	7	MXH217	Brick Cistern Vault Trench Fill	2	plaster, plain	fragment	Mineral	composite	plaster	architecture	general construction	
108310	Excavation Unit	FEA 7 Unit 2.2 STR07 LEV12 110-120cm MXH221	7	MXH221	Brick Cistern Vault Trench Fill	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
108312	Excavation Unit	FEA 7 Unit 2.2 STR07 LEV12 110-120cm MXH221	7	MXH221	Brick Cistern Vault Trench Fill	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
108315	Excavation Unit	FEA 7 Unit 2.2 STR07 LEV12 110-120cm MXH221	7	MXH221	Brick Cistern Vault Trench Fill	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
108311	Excavation Unit	FEA 7 Unit 2.2 STR07 LEV12 110-120cm MXH221	7	MXH221	Brick Cistern Vault Trench Fill	2	vessel, flat	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
108313	Excavation Unit	FEA 7 Unit 2.2 STR07 LEV12 110-120cm MXH221	7	MXH221	Brick Cistern Vault Trench Fill	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
108314	Excavation Unit	FEA 7 Unit 2.2 STR07 LEV12 110-120cm MXH221	7	MXH221	Brick Cistern Vault Trench Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
102705	Shovel test pit	STP E082 N099 STR02 LEV03 20-30cm MXH085		MXH085	Gravel Fill	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
102706	Shovel test pit	STP E082 N099 STR02 LEV03 20-30cm MXH085		MXH085	Gravel Fill	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
102707	Shovel test pit	STP E082 N099 STR02 LEV03 20-30cm MXH085		MXH085	Gravel Fill	5	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
102691	Shovel test pit	STP E082 N099 STR02 LEV03 20-30cm MXH085		MXH085	Gravel Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
102704	Shovel test pit	STP E082 N099 STR02 LEV03 20-30cm MXH085		MXH085	Gravel Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Whiteware, undecorated	food/beverage	service	
102711	Shovel test pit	STP E082 N099 STR02 LEV03 20-30cm MXH085		MXH085	Gravel Fill	1	vessel, flat	body	Ceramic	Earthenware, refined	Whiteware, undecorated	food/beverage	service	
102710	Shovel test pit	STP E082 N099 STR02 LEV03 20-30cm MXH085		MXH085	Gravel Fill	1	vessel, flat	rim	Ceramic	Porcelain	Chinese overglaze enamel	food/beverage	service	
102703	Shovel test pit	STP E082 N099 STR02 LEV03 20-30cm MXH085		MXH085	Gravel Fill	1	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
102701	Shovel test pit	STP E082 N099 STR02 LEV03 20-30cm MXH085		MXH085	Gravel Fill	1	vessel, hollow	rim	Ceramic	Porcelain	Plain	food/beverage	service	
102692	Shovel test pit	STP E082 N099 STR02 LEV03 20-30cm MXH085		MXH085	Gravel Fill	2	vessel, hollow	body	Ceramic	unidentified	unidentified	0	Not Assigned	
102698	Shovel test pit	STP E082 N099 STR02 LEV03 20-30cm MXH085		MXH085	Gravel Fill	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
102702	Shovel test pit	STP E082 N099 STR02 LEV03 20-30cm MXH085		MXH085	Gravel Fill	1	bottle, indeterminate	body	Glass	embossed	embossed	food/beverage	storage	-Aqua
102699	Shovel test pit	STP E082 N099 STR02 LEV03 20-30cm MXH085		MXH085	Gravel Fill	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
102709	Shovel test pit	STP E082 N099 STR02 LEV03 20-30cm MXH085		MXH085	Gravel Fill	2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
102697	Shovel test pit	STP E082 N099 STR02 LEV03 20-30cm MXH085		MXH085	Gravel Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Amber
102708	Shovel test pit	STP E082 N099 STR02 LEV03 20-30cm MXH085		MXH085	Gravel Fill	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
102696	Shovel test pit	STP E082 N099 STR02 LEV03 20-30cm MXH085		MXH085	Gravel Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
102688	Shovel test pit	STP E082 N099 STR02 LEV03 20-30cm MXH085		MXH085	Gravel Fill	1	bottle, wine/liquor/beer	body	Glass	Machine made	machine made	food/beverage	storage	-Clear
102694	Shovel test pit	STP E082 N099 STR02 LEV03 20-30cm MXH085		MXH085	Gravel Fill	1	bottle, indeterminate	lip/neck	Glass	mold blown	Not Assigned	food/beverage	storage	-Aqua-Oil
102689	Shovel test pit	STP E082 N099 STR02 LEV03 20-30cm MXH085		MXH085	Gravel Fill	2	bottle, indeterminate	base	Glass	molded	molded	food/beverage	storage	-Clear
102695	Shovel test pit	STP E082 N099 STR02 LEV03 20-30cm MXH085		MXH085	Gravel Fill	7	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
102693	Shovel test pit	STP E082 N099 STR02 LEV03 20-30cm MXH085		MXH085	Gravel Fill	8	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
102690	Shovel test pit	STP E082 N099 STR02 LEV03 20-30cm MXH085		MXH085	Gravel Fill	5	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
102700	Shovel test pit	STP E082 N099 STR02 LEV03 20-30cm MXH085		MXH085	Gravel Fill	1	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
103260	Shovel test pit	STP LE104 30-40cm MXH042		MXH042	Rock Fill	3	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
103261	Shovel test pit	STP LE104 30-40cm MXH042		MXH042	Rock Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103262	Shovel test pit	STP LE104 30-40cm MXH042		MXH042	Rock Fill	1	charcoal	fragment	Flora	wood	charcoal	heating, plumbing, electric	fuel	
103258	Shovel test pit	STP LE104 30-40cm MXH042		MXH042	Rock Fill	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
103256	Shovel test pit	STP LE104 30-40cm MXH042		MXH042	Rock Fill	1	nail, wire	whole/intact	Metal	ferrous	machine made	architecture	general construction	
103257	Shovel test pit	STP LE104 30-40cm MXH042		MXH042	Rock Fill	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
102978	Shovel test pit	STP N091 E082 STR03 LEV05 40-50cm MXH088		MXH088	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
102965	Shovel test pit	STP N091 E082 STR03 LEV05 40-50cm MXH088		MXH088	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	creamware, hand painted overglaze	food/beverage	service	Annular-green
102966	Shovel test pit	STP N091 E082 STR03 LEV05 40-50cm MXH088		MXH088	Buried APZ	4	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
102976	Shovel test pit	STP N091 E082 STR03 LEV05 40-50cm MXH088		MXH088	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
102971	Shovel test pit	STP N091 E082 STR03 LEV05 40-50cm MXH088		MXH088	Buried APZ	1	vessel, flat	body	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
102969	Shovel test pit	STP N091 E082 STR03 LEV05 40-50cm MXH088		MXH088	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
102974	Shovel test pit	STP N091 E082 STR03 LEV05 40-50cm MXH088		MXH088	Buried APZ	4	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
102968	Shovel test pit	STP N091 E082 STR03 LEV05 40-50cm MXH088		MXH088	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
102967	Shovel test pit	STP N091 E082 STR03 LEV05 40-50cm MXH088		MXH088	Buried APZ	1	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
102977	Shovel test pit	STP N091 E082 STR03 LEV05 40-50cm MXH088		MXH088	Buried APZ	3	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
102972	Shovel test pit	STP N091 E082 STR03 LEV05 40-50cm MXH088		MXH088	Buried APZ	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
102970	Shovel test pit	STP N091 E082 STR03 LEV05 40-50cm MXH088		MXH088	Buried APZ	2	lamp, glass fragment	fragment	Glass	indeterminate	indeterminate	heating, plumbing, electric	fuel	-Clear
102975	Shovel test pit	STP N091 E082 STR03 LEV05 40-50cm MXH088		MXH088	Buried APZ	1	wire	fragment	Metal	copper alloy	copper alloy	heating, plumbing, electric	device	
102964	Shovel test pit	STP N091 E082 STR03 LEV05 40-50cm MXH088		MXH088	Buried APZ	5	sheet metal	fragment	Metal	ferrous	unidentified	0	Not Assigned	
102973	Shovel test pit	STP N091 E082 STR03 LEV05 40-50cm MXH088		MXH088	Buried APZ	2	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
102963	Shovel test pit	STP N091 E082 STR03 LEV05 40-50cm MXH088		MXH088	Buried APZ	4	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
102730	Shovel test pit	STP N099 E082 LEV01 00-10cm MXH083		MXH083	Surface/Developing A	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
102736	Shovel test pit	STP N099 E082 LEV01 00-10cm MXH083		MXH083	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-orange
102731	Shovel test pit	STP N099 E082 LEV01 00-10cm MXH083		MXH083	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	
102737	Shovel test pit	STP N099 E082 LEV01 00-10cm MXH083		MXH083	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
102727	Shovel test pit	STP N099 E082 LEV01 00-10cm MXH083		MXH083	Surface/Developing A	1	pencil	fragment	Composite Artifact	composite artifact	composite artifact	personal	other personal possession	
102733	Shovel test pit	STP N099 E082 LEV01 00-10cm MXH083		MXH083	Surface/Developing A	1	button, four hole	whole/intact	Fauna	shell	mollosk	personal	fastener	
102734	Shovel test pit	STP N099 E082 LEV01 00-10cm MXH083		MXH083	Surface/Developing A	1	button, two hole	whole/intact	Fauna	shell	mollosk	personal	fastener	
102735	Shovel test pit	STP N099 E082 LEV01 00-10cm MXH083		MXH083	Surface/Developing A	1	bottle, indeterminate	body	Glass	embossed	embossed	food/beverage	storage	-Clear
102741	Shovel test pit	STP N099 E082 LEV01 00-10cm MXH083		MXH083	Surface/Developing A	17	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
102748	Shovel test pit	STP N099 E082 LEV01 00-10cm MXH083		MXH083	Surface/Developing A	2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
102746	Shovel test pit	STP N099 E082 LEV01 00-10cm MXH083		MXH083	Surface/Developing A	5	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
102740	Shovel test pit	STP N099 E082 LEV01 00-10cm MXH083		MXH083	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (bright 7-up)
102739	Shovel test pit	STP N099 E082 LEV01 00-10cm MXH083		MXH083	Surface/Developing A	6	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Milk glass/Opaque white
102745	Shovel test pit	STP N099 E082 LEV01 00-10cm MXH083		MXH083	Surface/Developing A	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Milk glass/Opaque white
102750	Shovel test pit	STP N099 E082 LEV01 00-10cm MXH083		MXH083	Surface/Developing A	1	bottle, indeterminate	base	Glass	indeterminate	indeterminate	food/beverage	storage	-Milk glass/Opaque white
102728	Shovel test pit	STP N099 E082 LEV01 00-10cm MXH083		MXH083	Surface/Developing A	1	coin	whole/intact	Metal	copper alloy	copper alloy	commerce	coin	
102743	Shovel test pit	STP N099 E082 LEV01 00-10cm MXH083		MXH083	Surface/Developing A	1	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
102726	Shovel test pit	STP N099 E082 LEV01 00-10cm MXH083		MXH083	Surface/Developing A	1	nail, wire	whole/intact	Metal	ferrous	machine made	architecture	general construction	
102747	Shovel test pit	STP N099 E082 LEV01 00-10cm MXH083		MXH083	Surface/Developing A	3	unidentified	fragment	Metal	ferrous	unidentified	architecture	0	Not Assigned
102749	Shovel test pit	STP N099 E082 LEV01 00-10cm MXH083		MXH083	Surface/Developing A	1	Tube	whole/intact	Metal	lead	Not Assigned	0	Not Assigned	
102729	Shovel test pit	STP N099 E082 LEV01 00-10cm MXH083		MXH083	Surface/Developing A	1	cap, crown bottle	whole/intact	Metal	steel	steel	food/beverage	storage	
102751	Shovel test pit	STP N099 E082 LEV01 00-10cm MXH083		MXH083	Surface/Developing A	1	rivet	whole/intact	Metal	steel	steel	furniture/household equip.	hardware	
102744	Shovel test pit	STP N099 E082 LEV01 00-10cm MXH083		MXH083	Surface/Developing A	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
102742	Shovel test pit	STP N099 E082 LEV01 00-10cm MXH083		MXH083	Surface/Developing A	1	plaster, plain	fragment	Mineral	composite	plaster	architecture	general construction	
102738	Shovel test pit	STP N099 E082 LEV01 00-10cm MXH083		MXH083	Surface/Developing A	2	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
102753	Shovel test pit	STP N099 E082 LEV01 00-10cm MXH083		MXH083	Surface/Developing A	1	vessel, flat	base	Synthetic	synthetic	plastic	food/beverage	service	
102732	Shovel test pit	STP N099 E082 LEV01 00-10cm MXH083		MXH083	Surface/Developing A	1	button, two hole	whole/intact	Synthetic	synthetic	plastic	personal	fastener	
102752	Shovel test pit	STP N099 E082 LEV01 00-10cm MXH083		MXH083	Surface/Developing A	2	unidentified	fragment	Synthetic	synthetic	styrofoam	0	Not Assigned	
102818	Shovel test pit	STP N099 E082 STR01 LEV02 10-20cm MXH084		MXH084	Surface/Developing A	2	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
102828	Shovel test pit	STP N099 E082 STR01 LEV02 10-20cm MXH084		MXH084	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware unidentified	food/beverage	preparation	
102833	Shovel test pit	STP N099 E082 STR01 LEV02 10-20cm MXH084		MXH084	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware unidentified	food/beverage	preparation	
102834	Shovel test pit	STP N099 E082 STR01 LEV02 10-20cm MXH084		MXH084	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
102844	Shovel test pit	STP N099 E082 STR01 LEV02 10-20cm MXH084		MXH084	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
102841	Shovel test pit	STP N099 E082 STR01 LEV02 10-20cm MXH084		MXH084	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
102820	Shovel test pit	STP N099 E082 STR01 LEV02 10-20cm MXH084		MXH084	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
102824	Shovel test pit	STP N099 E082 STR01 LEV02 10-20cm MXH084		MXH084	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
102826	Shovel test pit	STP N099 E082 STR01 LEV02 10-20cm MXH084		MXH084	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-brown
102822	Shovel test pit	STP N099 E082 STR01 LEV02 10-20cm MXH084		MXH084	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
102837	Shovel test pit	STP N099 E082 STR01 LEV02 10-20cm MXH084		MXH084	Surface/Developing A	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
102829	Shovel test pit	STP N099 E082 STR01 LEV02 10-20cm MXH084		MXH084	Surface/Developing A	1	vessel, hollow	handle	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
102842	Shovel test pit	STP N099 E082 STR01 LEV02 10-20cm MXH084		MXH084	Surface/Developing A	2	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
102819	Shovel test pit	STP N099 E082 STR01 LEV02 10-20cm MXH084		MXH084	Surface/Developing A	2	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
102835	Shovel test pit	STP N099 E082 STR01 LEV02 10-20cm MXH084		MXH084	Surface/Developing A	4	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
102840	Shovel test pit	STP N099 E082 STR01 LEV02 10-20cm MXH084		MXH084	Surface/Developing A	5	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Amber
102830	Shovel test pit	STP N099 E082 STR01 LEV02 10-20cm MXH084		MXH084	Surface/Developing A	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
102836	Shovel test pit	STP N099 E082 STR01 LEV02 10-20cm MXH084		MXH084	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
102838	Shovel test pit	STP N099 E082 STR01 LEV02 10-20cm MXH084		MXH084	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
102815	Shovel test pit	STP N099 E082 STR01 LEV02 10-20cm MXH084		MXH084	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Milk glass/Opaque white
102813	Shovel test pit	STP N099 E082 STR01 LEV02 10-20cm MXH084		MXH084	Surface/Developing A	1	bottle, indeterminate	lip	Glass	mold blown	Not Assigned	food/beverage	storage	-Clear
102832	Shovel test pit	STP N099 E082 STR01 LEV02 10-20cm MXH084		MXH084	Surface/Developing A	1	rod	body	Glass	molded	molded		Not Assigned	
102823	Shovel test pit	STP N099 E082 STR01 LEV02 10-20cm MXH084		MXH084	Surface/Developing A	1	cap, crown bottle	whole/intact	Metal	Aluminum	aluminum	food/beverage	storage	
102821	Shovel test pit	STP N099 E082 STR01 LEV02 10-20cm MXH084		MXH084	Surface/Developing A	1	wire	fragment	Metal	copper alloy	copper alloy	0	Not Assigned	
102812	Shovel test pit	STP N099 E082 STR01 LEV02 10-20cm MXH084		MXH084	Surface/Developing A	1	coin	whole/intact	Metal	copper alloy	copper alloy	commerce	coin	
102825	Shovel test pit	STP N099 E082 STR01 LEV02 10-20cm MXH084		MXH084	Surface/Developing A	1	nail, wire	whole/intact	Metal	ferrous	machine made	architecture	general construction	
102827	Shovel test pit	STP N099 E082 STR01 LEV02 10-20cm MXH084		MXH084	Surface/Developing A	2	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
102814	Shovel test pit	STP N099 E082 STR01 LEV02 10-20cm MXH084		MXH084	Surface/Developing A	6	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
102811	Shovel test pit	STP N099 E082 STR01 LEV02 10-20cm MXH084		MXH084	Surface/Developing A	3	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
102816	Shovel test pit	STP N099 E082 STR01 LEV02 10-20cm MXH084		MXH084	Surface/Developing A	1	rod	fragment	Mineral	graphite	worked	heating, plumbing, electric	fuel	
102843	Shovel test pit	STP N099 E082 STR01 LEV02 10-20cm MXH084		MXH084	Surface/Developing A	1	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
102817	Shovel test pit	STP N099 E082 STR01 LEV02 10-20cm MXH084		MXH084	Surface/Developing A	2	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
102831	Shovel test pit	STP N099 E082 STR01 LEV02 10-20cm MXH084		MXH084	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
102839	Shovel test pit	STP N099 E082 STR01 LEV02 10-20cm MXH084		MXH084	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	styrofoam	0	Not Assigned	
102846	Shovel test pit	STP N099 E082 STR02 LEV05 40-50cm MXH087		MXH087	Gravel Fill	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
102850	Shovel test pit	STP N099 E082 STR02 LEV05 40-50cm MXH087		MXH087	Gravel Fill	3	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
102847	Shovel test pit	STP N099 E082 STR02 LEV05 40-50cm MXH087		MXH087	Gravel Fill	4	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
102849	Shovel test pit	STP N099 E082 STR02 LEV05 40-50cm MXH087		MXH087	Gravel Fill	3	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
102848	Shovel test pit	STP N099 E082 STR02 LEV05 40-50cm MXH087		MXH087	Gravel Fill	1	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
102851	Shovel test pit	STP N099 E082 STR02 LEV05 40-50cm MXH087		MXH087	Gravel Fill	2	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
102845	Shovel test pit	STP N099 E082 STR02 LEV05 40-50cm MXH087		MXH087	Gravel Fill	1	asphalt	fragment	Synthetic	synthetic	asphalt	architecture	foundation	
102778	Shovel test pit	STP N099 E082 STR02 LEV06 50-60cm MXH089		MXH089	Gravel Fill	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
102760	Shovel test pit	STP N099 E082 STR02 LEV06 50-60cm MXH089		MXH089	Gravel Fill	5	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
102768	Shovel test pit	STP N099 E082 STR02 LEV06 50-60cm MXH089		MXH089	Gravel Fill	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware unidentified	food/beverage	preparation	
102755	Shovel test pit	STP N099 E082 STR02 LEV06 50-60cm MXH089		MXH089	Gravel Fill	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
102777	Shovel test pit	STP N099 E082 STR02 LEV06 50-60cm MXH089		MXH089	Gravel Fill	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire plain	food/beverage	service	
102766	Shovel test pit	STP N099 E082 STR02 LEV06 50-60cm MXH089		MXH089	Gravel Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
102769	Shovel test pit	STP N099 E082 STR02 LEV06 50-60cm MXH089		MXH089	Gravel Fill	1	vessel, hollow	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
102773	Shovel test pit	STP N099 E082 STR02 LEV06 50-60cm MXH089		MXH089	Gravel Fill	10	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
102774	Shovel test pit	STP N099 E082 STR02 LEV06 50-60cm MXH089		MXH089	Gravel Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Ironstone	food/beverage	service	transfer print-green
102784	Shovel test pit	STP N099 E082 STR02 LEV06 50-60cm MXH089		MXH089	Gravel Fill	1	vessel, hollow	handle	Ceramic	Earthenware, refined	jackfield type	food/beverage	service	
102776	Shovel test pit	STP N099 E082 STR02 LEV06 50-60cm MXH089		MXH089	Gravel Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
102775	Shovel test pit	STP N099 E082 STR02 LEV06 50-60cm MXH089		MXH089	Gravel Fill	7	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
102780	Shovel test pit	STP N099 E082 STR02 LEV06 50-60cm MXH089		MXH089	Gravel Fill	2	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
102783	Shovel test pit	STP N099 E082 STR02 LEV06 50-60cm MXH089		MXH089	Gravel Fill	1	vessel, hollow	base	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
102764	Shovel test pit	STP N099 E082 STR02 LEV06 50-60cm MXH089		MXH089	Gravel Fill	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
102765	Shovel test pit	STP N099 E082 STR02 LEV06 50-60cm MXH089		MXH089	Gravel Fill	1	vessel, hollow	foot	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
102779	Shovel test pit	STP N099 E082 STR02 LEV06 50-60cm MXH089		MXH089	Gravel Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
102762	Shovel test pit	STP N099 E082 STR02 LEV06 50-60cm MXH089		MXH089	Gravel Fill	1	bone	fragment	Fauna	bone	fish	food/beverage	acquisition	
102759	Shovel test pit	STP N099 E082 STR02 LEV06 50-60cm MXH089		MXH089	Gravel Fill	15	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
102754	Shovel test pit	STP N099 E082 STR02 LEV06 50-60cm MXH089		MXH089	Gravel Fill	1	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
102772	Shovel test pit	STP N099 E082 STR02 LEV06 50-60cm MXH089		MXH089	Gravel Fill	5	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
102771	Shovel test pit	STP N099 E082 STR02 LEV06 50-60cm MXH089		MXH089	Gravel Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
102770	Shovel test pit	STP N099 E082 STR02 LEV06 50-60cm MXH089		MXH089	Gravel Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
102767	Shovel test pit	STP N099 E082 STR02 LEV06 50-60cm MXH089		MXH089	Gravel Fill	2	drinking glass, tumbler	rim	Glass	molded	molded	food/beverage	service	-Clear
102781	Shovel test pit	STP N099 E082 STR02 LEV06 50-60cm MXH089		MXH089	Gravel Fill	6	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
102757	Shovel test pit	STP N099 E082 STR02 LEV06 50-60cm MXH089		MXH089	Gravel Fill	1	nail, wire	whole/intact	Metal	ferrous	machine made	architecture	general construction	
102758	Shovel test pit	STP N099 E082 STR02 LEV06 50-60cm MXH089		MXH089	Gravel Fill	3	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
102756	Shovel test pit	STP N099 E082 STR02 LEV06 50-60cm MXH089		MXH089	Gravel Fill	1	nail wrought	whole/intact	Metal	ferrous	wrought	architecture	general construction	
102763	Shovel test pit	STP N099 E082 STR02 LEV06 50-60cm MXH089		MXH089	Gravel Fill	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
102761	Shovel test pit	STP N099 E082 STR02 LEV06 50-60cm MXH089		MXH089	Gravel Fill	1	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
102782	Shovel test pit	STP N099 E082 STR02 LEV06 50-60cm MXH089		MXH089	Gravel Fill	1	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
103009	Shovel test pit	STP N099 E082 STR03 LEV07 60-70cm MXH090		MXH090	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
103018	Shovel test pit	STP N099 E082 STR03 LEV07 60-70cm MXH090		MXH090	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
103014	Shovel test pit	STP N099 E082 STR03 LEV07 60-70cm MXH090		MXH090	Buried APZ	6	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103017	Shovel test pit	STP N099 E082 STR03 LEV07 60-70cm MXH090		MXH090	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103006	Shovel test pit	STP N099 E082 STR03 LEV07 60-70cm MXH090		MXH090	Buried APZ	5	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103016	Shovel test pit	STP N099 E082 STR03 LEV07 60-70cm MXH090		MXH090	Buried APZ	1	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	service	
103015	Shovel test pit	STP N099 E082 STR03 LEV07 60-70cm MXH090		MXH090	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	Westerwald	food/beverage	service	
103012	Shovel test pit	STP N099 E082 STR03 LEV07 60-70cm MXH090		MXH090	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed, scratch blue	food/beverage	service	
103010	Shovel test pit	STP N099 E082 STR03 LEV07 60-70cm MXH090		MXH090	Buried APZ	2	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103008	Shovel test pit	STP N099 E082 STR03 LEV07 60-70cm MXH090		MXH090	Buried APZ	3	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103007	Shovel test pit	STP N099 E082 STR03 LEV07 60-70cm MXH090		MXH090	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
103019	Shovel test pit	STP N099 E082 STR03 LEV07 60-70cm MXH090		MXH090	Buried APZ	1	nail, wire	fragment	Metal	ferrous	machine made	architecture	general construction	
103013	Shovel test pit	STP N099 E082 STR03 LEV07 60-70cm MXH090		MXH090	Buried APZ	2	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
103011	Shovel test pit	STP N099 E082 STR03 LEV07 60-70cm MXH090		MXH090	Buried APZ	1	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
103107	Shovel test pit	STP N099 E082 STR04 LEV07 60-70cm MXH091		MXH091	B1	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
103108	Shovel test pit	STP N099 E082 STR04 LEV07 60-70cm MXH091		MXH091	B1	1	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103109	Shovel test pit	STP N099 E082 STR04 LEV07 60-70cm MXH091		MXH091	B1	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
103111	Shovel test pit	STP N099 E082 STR04 LEV07 60-70cm MXH091		MXH091	B1	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
103106	Shovel test pit	STP N099 E082 STR04 LEV07 60-70cm MXH091		MXH091	B1	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
103110	Shovel test pit	STP N099 E082 STR04 LEV07 60-70cm MXH091		MXH091	B1	2	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
103104	Shovel test pit	STP N099 E082 STR04 LEV07 60-70cm MXH091		MXH091	B1	2	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
102983	Shovel test pit	STP N099 E082 STR04 LEV08 70-80cm MXH092		MXH092	B2	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
102981	Shovel test pit	STP N099 E082 STR04 LEV08 70-80cm MXH092		MXH092	B2	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
102980	Shovel test pit	STP N099 E082 STR04 LEV08 70-80cm MXH092		MXH092	B2	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
102979	Shovel test pit	STP N099 E082 STR04 LEV08 70-80cm MXH092		MXH092	B2	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
102982	Shovel test pit	STP N099 E082 STR04 LEV08 70-80cm MXH092		MXH092	B2	2	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
103053	Shovel test pit	STP N099 E082 STR04 LEV09 80-90cm MXH093		MXH093	B2	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103054	Shovel test pit	STP N099 E082 STR04 LEV09 80-90cm MXH093		MXH093	B2	2	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
102674	Shovel test pit	STP N099 E084 LEV01 00-10cm MXH126		MXH126	Surface/Developing A	1	vessel, hollow	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
102668	Shovel test pit	STP N099 E084 LEV01 00-10cm MXH126		MXH126	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
102680	Shovel test pit	STP N099 E084 LEV01 00-10cm MXH126		MXH126	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
102682	Shovel test pit	STP N099 E084 LEV01 00-10cm MXH126		MXH126	Surface/Developing A	5	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
102669	Shovel test pit	STP N099 E084 LEV01 00-10cm MXH126		MXH126	Surface/Developing A	1	vessel, flat	body	Ceramic	Earthenware, refined	Whiteware, transfer printed	food/beverage	service	transfer print-purple/manganese
102664	Shovel test pit	STP N099 E084 LEV01 00-10cm MXH126		MXH126	Surface/Developing A	1	lightbulb	fragment	Composite Artifact	composite artifact	composite artifact	lighting	device	
102673	Shovel test pit	STP N099 E084 LEV01 00-10cm MXH126		MXH126	Surface/Developing A	4	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
102666	Shovel test pit	STP N099 E084 LEV01 00-10cm MXH126		MXH126	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
102671	Shovel test pit	STP N099 E084 LEV01 00-10cm MXH126		MXH126	Surface/Developing A	7	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
102672	Shovel test pit	STP N099 E084 LEV01 00-10cm MXH126		MXH126	Surface/Developing A	2	bottle, indeterminate	base	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
102678	Shovel test pit	STP N099 E084 LEV01 00-10cm MXH126		MXH126	Surface/Developing A	2	bottle, indeterminate	base	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
102681	Shovel test pit	STP N099 E084 LEV01 00-10cm MXH126		MXH126	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear-manganese ti+nt
102677	Shovel test pit	STP N099 E084 LEV01 00-10cm MXH126		MXH126	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (bright 7-up)
102675	Shovel test pit	STP N099 E084 LEV01 00-10cm MXH126		MXH126	Surface/Developing A	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Milk glass/Opaque white
102679	Shovel test pit	STP N099 E084 LEV01 00-10cm MXH126		MXH126	Surface/Developing A	1	bottle, indeterminate	base	Glass	Machine made	machine made	food/beverage	storage	-Aqua-circular
102685	Shovel test pit	STP N099 E084 LEV01 00-10cm MXH126		MXH126	Surface/Developing A	2	drinking glass, tumbler	body	Glass	molded	molded	food/beverage	service	-Clear
102662	Shovel test pit	STP N099 E084 LEV01 00-10cm MXH126		MXH126	Surface/Developing A	1	unidentified	whole/intact	Metal	copper alloy	copper alloy	architecture	window	
102683	Shovel test pit	STP N099 E084 LEV01 00-10cm MXH126		MXH126	Surface/Developing A	1	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
102663	Shovel test pit	STP N099 E084 LEV01 00-10cm MXH126		MXH126	Surface/Developing A	2	nail, wire	fragment	Metal	ferrous	machine made	architecture	general construction	
102665	Shovel test pit	STP N099 E084 LEV01 00-10cm MXH126		MXH126	Surface/Developing A	3	screw	whole/intact	Metal	ferrous	machine made	architecture	general construction	
102686	Shovel test pit	STP N099 E084 LEV01 00-10cm MXH126		MXH126	Surface/Developing A	1	staple	whole/intact	Metal	ferrous	machine made	architecture	general construction	
102659	Shovel test pit	STP N099 E084 LEV01 00-10cm MXH126		MXH126	Surface/Developing A	2	lens (eye glass)	fragment	Metal	ferrous	machine made	personal	other personal possession	
102661	Shovel test pit	STP N099 E084 LEV01 00-10cm MXH126		MXH126	Surface/Developing A	1	pintle	fragment	Metal	ferrous	unidentified	architecture	window	
102667	Shovel test pit	STP N099 E084 LEV01 00-10cm MXH126		MXH126	Surface/Developing A	2	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
102676	Shovel test pit	STP N099 E084 LEV01 00-10cm MXH126		MXH126	Surface/Developing A	1	plaster, painted	fragment	Mineral	composite	plaster	architecture	general construction	
102660	Shovel test pit	STP N099 E084 LEV01 00-10cm MXH126		MXH126	Surface/Developing A	1	unidentified	fragment	Synthetic	0	Not Assigned	0	Not Assigned	
102670	Shovel test pit	STP N099 E084 LEV01 00-10cm MXH126		MXH126	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
102684	Shovel test pit	STP N099 E084 LEV01 00-10cm MXH126		MXH126	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
102687	Shovel test pit	STP N099 E084 LEV01 00-10cm MXH126		MXH126	Surface/Developing A	1	tool	whole/intact	Synthetic	synthetic	plastic	personal	other personal possession	
102962	Shovel test pit	STP N099 E084 LEV02 10-20cm MXH127		MXH127	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
102960	Shovel test pit	STP N099 E084 LEV02 10-20cm MXH127		MXH127	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
102948	Shovel test pit	STP N099 E084 LEV02 10-20cm MXH127		MXH127	Surface/Developing A	3	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
102943	Shovel test pit	STP N099 E084 LEV02 10-20cm MXH127		MXH127	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
102955	Shovel test pit	STP N099 E084 LEV02 10-20cm MXH127		MXH127	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
102961	Shovel test pit	STP N099 E084 LEV02 10-20cm MXH127		MXH127	Surface/Developing A	4	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
102946	Shovel test pit	STP N099 E084 LEV02 10-20cm MXH127		MXH127	Surface/Developing A	4	vessel, hollow	body	Ceramic	Earthenware, refined	Whiteware, undecorated	food/beverage	service	
102952	Shovel test pit	STP N099 E084 LEV02 10-20cm MXH127		MXH127	Surface/Developing A	2	vessel, flat	rim	Ceramic	Porcelain	Decorated	food/beverage	service	painted-blue
102953	Shovel test pit	STP N099 E084 LEV02 10-20cm MXH127		MXH127	Surface/Developing A	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
102945	Shovel test pit	STP N099 E084 LEV02 10-20cm MXH127		MXH127	Surface/Developing A	1	bottle, indeterminate	fragment	Glass	indeterminate	indeterminate	0	Not Assigned	-Amber
102944	Shovel test pit	STP N099 E084 LEV02 10-20cm MXH127		MXH127	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Blue-cobalt
102956	Shovel test pit	STP N099 E084 LEV02 10-20cm MXH127		MXH127	Surface/Developing A	4	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
102958	Shovel test pit	STP N099 E084 LEV02 10-20cm MXH127		MXH127	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
102959	Shovel test pit	STP N099 E084 LEV02 10-20cm MXH127		MXH127	Surface/Developing A	1	bottle, indeterminate	base	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
102957	Shovel test pit	STP N099 E084 LEV02 10-20cm MXH127		MXH127	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear-manganese ti+nt
102949	Shovel test pit	STP N099 E084 LEV02 10-20cm MXH127		MXH127	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
102951	Shovel test pit	STP N099 E084 LEV02 10-20cm MXH127		MXH127	Surface/Developing A	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Milk glass/Opaque white
102940	Shovel test pit	STP N099 E084 LEV02 10-20cm MXH127		MXH127	Surface/Developing A	7	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
102941	Shovel test pit	STP N099 E084 LEV02 10-20cm MXH127		MXH127	Surface/Developing A	6	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
102947	Shovel test pit	STP N099 E084 LEV02 10-20cm MXH127		MXH127	Surface/Developing A	2	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
102942	Shovel test pit	STP N099 E084 LEV02 10-20cm MXH127		MXH127	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
102939	Shovel test pit	STP N099 E084 LEV02 10-20cm MXH127		MXH127	Surface/Developing A	1	tool	whole/intact	Synthetic	synthetic	plastic	personal	other personal possession	
102954	Shovel test pit	STP N099 E084 LEV02 10-20cm MXH127		MXH127	Surface/Developing A	1	token	whole/intact	Synthetic	synthetic	plastic	recreation/leisure	gaming	
102880	Shovel test pit	STP N099 E084 LEV03 20-30cm MXH128		MXH128	Fill	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
102890	Shovel test pit	STP N099 E084 LEV03 20-30cm MXH128		MXH128	Fill	1	pipe, mouth piece	tip	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
102891	Shovel test pit	STP N099 E084 LEV03 20-30cm MXH128		MXH128	Fill	6	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
102887	Shovel test pit	STP N099 E084 LEV03 20-30cm MXH128		MXH128	Fill	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
102883	Shovel test pit	STP N099 E084 LEV03 20-30cm MXH128		MXH128	Fill	4	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
102893	Shovel test pit	STP N099 E084 LEV03 20-30cm MXH128		MXH128	Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, transfer printed overglaze	food/beverage	service	transfer print-brown
102894	Shovel test pit	STP N099 E084 LEV03 20-30cm MXH128		MXH128	Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-brown
102892	Shovel test pit	STP N099 E084 LEV03 20-30cm MXH128		MXH128	Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
102882	Shovel test pit	STP N099 E084 LEV03 20-30cm MXH128		MXH128	Fill	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
102885	Shovel test pit	STP N099 E084 LEV03 20-30cm MXH128		MXH128	Fill	1	vessel, hollow	base	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
102888	Shovel test pit	STP N099 E084 LEV03 20-30cm MXH128		MXH128	Fill	1	vessel, hollow	base	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
102879	Shovel test pit	STP N099 E084 LEV03 20-30cm MXH128		MXH128	Fill	1	knife	whole/intact	Metal	ferrous	cast	food/beverage	service	
102889	Shovel test pit	STP N099 E084 LEV03 20-30cm MXH128		MXH128	Fill	4	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
102884	Shovel test pit	STP N099 E084 LEV03 20-30cm MXH128		MXH128	Fill	1	screw	whole/intact	Metal	steel	steel	architecture	general construction	
102881	Shovel test pit	STP N099 E084 LEV03 20-30cm MXH128		MXH128	Fill	2	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
103220	Shovel test pit	STP N099 E084 LEV04 30-40cm MXH129		MXH129	Fill	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
103217	Shovel test pit	STP N099 E084 LEV04 30-40cm MXH129		MXH129	Fill	1	vessel, flat	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103222	Shovel test pit	STP N099 E084 LEV04 30-40cm MXH129		MXH129	Fill	5	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103216	Shovel test pit	STP N099 E084 LEV04 30-40cm MXH129		MXH129	Fill	4	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103215	Shovel test pit	STP N099 E084 LEV04 30-40cm MXH129		MXH129	Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103223	Shovel test pit	STP N099 E084 LEV04 30-40cm MXH129		MXH129	Fill	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103218	Shovel test pit	STP N099 E084 LEV04 30-40cm MXH129		MXH129	Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
103214	Shovel test pit	STP N099 E084 LEV04 30-40cm MXH129		MXH129	Fill	7	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
103219	Shovel test pit	STP N099 E084 LEV04 30-40cm MXH129		MXH129	Fill	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
103221	Shovel test pit	STP N099 E084 LEV04 30-40cm MXH129		MXH129	Fill	2	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
103195	Shovel test pit	STP N099 E084 LEV05 40-50cm MXH130		MXH130	Buried APZ	3	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
103207	Shovel test pit	STP N099 E084 LEV05 40-50cm MXH130		MXH130	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103196	Shovel test pit	STP N099 E084 LEV05 40-50cm MXH130		MXH130	Buried APZ	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103198	Shovel test pit	STP N099 E084 LEV05 40-50cm MXH130		MXH130	Buried APZ	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103208	Shovel test pit	STP N099 E084 LEV05 40-50cm MXH130		MXH130	Buried APZ	11	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103213	Shovel test pit	STP N099 E084 LEV05 40-50cm MXH130		MXH130	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103200	Shovel test pit	STP N099 E084 LEV05 40-50cm MXH130		MXH130	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	slip-orange
103209	Shovel test pit	STP N099 E084 LEV05 40-50cm MXH130		MXH130	Buried APZ	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
103206	Shovel test pit	STP N099 E084 LEV05 40-50cm MXH130		MXH130	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
103205	Shovel test pit	STP N099 E084 LEV05 40-50cm MXH130		MXH130	Buried APZ	3	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103211	Shovel test pit	STP N099 E084 LEV05 40-50cm MXH130		MXH130	Buried APZ	8	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103197	Shovel test pit	STP N099 E084 LEV05 40-50cm MXH130		MXH130	Buried APZ	1	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
103201	Shovel test pit	STP N099 E084 LEV05 40-50cm MXH130		MXH130	Buried APZ	6	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103212	Shovel test pit	STP N099 E084 LEV05 40-50cm MXH130		MXH130	Buried APZ	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103210	Shovel test pit	STP N099 E084 LEV05 40-50cm MXH130		MXH130	Buried APZ	5	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103203	Shovel test pit	STP N099 E084 LEV05 40-50cm MXH130		MXH130	Buried APZ	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
103204	Shovel test pit	STP N099 E084 LEV05 40-50cm MXH130		MXH130	Buried APZ	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
103202	Shovel test pit	STP N099 E084 LEV05 40-50cm MXH130		MXH130	Buried APZ	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
103199	Shovel test pit	STP N099 E084 LEV05 40-50cm MXH130		MXH130	Buried APZ	5	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
103023	Shovel test pit	STP N099 E084 LEV06 50-60cm MXH131		MXH131	Buried APZ	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
103042	Shovel test pit	STP N099 E084 LEV06 50-60cm MXH131		MXH131	Buried APZ	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103031	Shovel test pit	STP N099 E084 LEV06 50-60cm MXH131		MXH131	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, slip decorated	food/beverage	preparation	
103025	Shovel test pit	STP N099 E084 LEV06 50-60cm MXH131		MXH131	Buried APZ	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103032	Shovel test pit	STP N099 E084 LEV06 50-60cm MXH131		MXH131	Buried APZ	2	vessel, hollow	handle	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103043	Shovel test pit	STP N099 E084 LEV06 50-60cm MXH131		MXH131	Buried APZ	6	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103030	Shovel test pit	STP N099 E084 LEV06 50-60cm MXH131		MXH131	Buried APZ	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
103022	Shovel test pit	STP N099 E084 LEV06 50-60cm MXH131		MXH131	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103034	Shovel test pit	STP N099 E084 LEV06 50-60cm MXH131		MXH131	Buried APZ	7	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103035	Shovel test pit	STP N099 E084 LEV06 50-60cm MXH131		MXH131	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103027	Shovel test pit	STP N099 E084 LEV06 50-60cm MXH131		MXH131	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Rockingham-type	food/beverage	service	
103029	Shovel test pit	STP N099 E084 LEV06 50-60cm MXH131		MXH131	Buried APZ	3	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	food/beverage	service	
103044	Shovel test pit	STP N099 E084 LEV06 50-60cm MXH131		MXH131	Buried APZ	1	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	service	
103040	Shovel test pit	STP N099 E084 LEV06 50-60cm MXH131		MXH131	Buried APZ	5	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103039	Shovel test pit	STP N099 E084 LEV06 50-60cm MXH131		MXH131	Buried APZ	2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103036	Shovel test pit	STP N099 E084 LEV06 50-60cm MXH131		MXH131	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
103033	Shovel test pit	STP N099 E084 LEV06 50-60cm MXH131		MXH131	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
103037	Shovel test pit	STP N099 E084 LEV06 50-60cm MXH131		MXH131	Buried APZ	1	unidentified	fragment	Metal	ferrous	unidentified	0	Not Assigned	
103038	Shovel test pit	STP N099 E084 LEV06 50-60cm MXH131		MXH131	Buried APZ	2	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
103051	Shovel test pit	STP N099 E084 LEV07 60-70cm MXH132		MXH132	Buried APZ	6	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103045	Shovel test pit	STP N099 E084 LEV07 60-70cm MXH132		MXH132	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103046	Shovel test pit	STP N099 E084 LEV07 60-70cm MXH132		MXH132	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103047	Shovel test pit	STP N099 E084 LEV07 60-70cm MXH132		MXH132	Buried APZ	2	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103049	Shovel test pit	STP N099 E084 LEV07 60-70cm MXH132		MXH132	Buried APZ	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103050	Shovel test pit	STP N099 E084 LEV07 60-70cm MXH132		MXH132	Buried APZ	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
103048	Shovel test pit	STP N099 E084 LEV07 60-70cm MXH132		MXH132	Buried APZ	4	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
102724	Shovel test pit	STP N099 E084 LEV08 70-80cm MXH133		MXH133	B1	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
102723	Shovel test pit	STP N099 E084 LEV08 70-80cm MXH133		MXH133	B1	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
102717	Shovel test pit	STP N099 E084 LEV08 70-80cm MXH133		MXH133	B1	10	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
102714	Shovel test pit	STP N099 E084 LEV08 70-80cm MXH133		MXH133	B1	4	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
102719	Shovel test pit	STP N099 E084 LEV08 70-80cm MXH133		MXH133	B1	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-blue
102725	Shovel test pit	STP N099 E084 LEV08 70-80cm MXH133		MXH133	B1	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-purple/manganese
102713	Shovel test pit	STP N099 E084 LEV08 70-80cm MXH133		MXH133	B1	9	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
102716	Shovel test pit	STP N099 E084 LEV08 70-80cm MXH133		MXH133	B1	1	vessel, hollow	body	Ceramic	Stoneware	Westerwald	food/beverage	service	
102712	Shovel test pit	STP N099 E084 LEV08 70-80cm MXH133		MXH133	B1	1	vessel, hollow	body	Ceramic	Tin Glazed	French (Faience)	food/beverage	service	
102722	Shovel test pit	STP N099 E084 LEV08 70-80cm MXH133		MXH133	B1	3	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
102715	Shovel test pit	STP N099 E084 LEV08 70-80cm MXH133		MXH133	B1	2	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
102721	Shovel test pit	STP N099 E084 LEV08 70-80cm MXH133		MXH133	B1	2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
102720	Shovel test pit	STP N099 E084 LEV08 70-80cm MXH133		MXH133	B1	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
102718	Shovel test pit	STP N099 E084 LEV08 70-80cm MXH133		MXH133	B1	3	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
102864	Shovel test pit	STP N099 E084 LEV09 80-90cm MXH134		MXH134	B1	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
102870	Shovel test pit	STP N099 E084 LEV09 80-90cm MXH134		MXH134	B1	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
102872	Shovel test pit	STP N099 E084 LEV09 80-90cm MXH134		MXH134	B1	6	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
102873	Shovel test pit	STP N099 E084 LEV09 80-90cm MXH134		MXH134	B1	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
102871	Shovel test pit	STP N099 E084 LEV09 80-90cm MXH134		MXH134	B1	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	engine turned-brown
102876	Shovel test pit	STP N099 E084 LEV09 80-90cm MXH134		MXH134	B1	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-brown
102877	Shovel test pit	STP N099 E084 LEV09 80-90cm MXH134		MXH134	B1	3	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
102875	Shovel test pit	STP N099 E084 LEV09 80-90cm MXH134		MXH134	B1	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
102866	Shovel test pit	STP N099 E084 LEV09 80-90cm MXH134		MXH134	B1	1	vessel, hollow	body	Ceramic	Stoneware	brown, salt-glazed	food/beverage	storage	
102869	Shovel test pit	STP N099 E084 LEV09 80-90cm MXH134		MXH134	B1	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
102874	Shovel test pit	STP N099 E084 LEV09 80-90cm MXH134		MXH134	B1	2	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
102862	Shovel test pit	STP N099 E084 LEV09 80-90cm MXH134		MXH134	B1	4	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
102863	Shovel test pit	STP N099 E084 LEV09 80-90cm MXH134		MXH134	B1	1	tooth	whole/intact	Fauna	enamel/bone	tooth	food/beverage	acquisition	
102878	Shovel test pit	STP N099 E084 LEV09 80-90cm MXH134		MXH134	B1	1	charcoal	fragment	Flora	wood	charcoal	heating, plumbing, electric	fuel	
102868	Shovel test pit	STP N099 E084 LEV09 80-90cm MXH134		MXH134	B1	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
102867	Shovel test pit	STP N099 E084 LEV09 80-90cm MXH134		MXH134	B1	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
102865	Shovel test pit	STP N099 E084 LEV09 80-90cm MXH134		MXH134	B1	1	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
102854	Shovel test pit	STP N099 E087 STR02 LEV04 30-40cm MXH086		MXH086	Gravel Fill	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
102860	Shovel test pit	STP N099 E087 STR02 LEV04 30-40cm MXH086		MXH086	Gravel Fill	2	vessel, hollow	base	Ceramic	Earthenware, coarse	Redware unidentified	food/beverage	preparation	
102861	Shovel test pit	STP N099 E087 STR02 LEV04 30-40cm MXH086		MXH086	Gravel Fill	8	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
102859	Shovel test pit	STP N099 E087 STR02 LEV04 30-40cm MXH086		MXH086	Gravel Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Whiteware, undecorated	food/beverage	service	
102855	Shovel test pit	STP N099 E087 STR02 LEV04 30-40cm MXH086		MXH086	Gravel Fill	1	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	service	
102853	Shovel test pit	STP N099 E087 STR02 LEV04 30-40cm MXH086		MXH086	Gravel Fill	2	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
102856	Shovel test pit	STP N099 E087 STR02 LEV04 30-40cm MXH086		MXH086	Gravel Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Amber
102857	Shovel test pit	STP N099 E087 STR02 LEV04 30-40cm MXH086		MXH086	Gravel Fill	2	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
102858	Shovel test pit	STP N099 E087 STR02 LEV04 30-40cm MXH086		MXH086	Gravel Fill	3	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
103282	Shovel test pit	STP N099 E089 LEV 10 90-100cm MXH135		MXH135	B2	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103281	Shovel test pit	STP N099 E089 LEV 10 90-100cm MXH135		MXH135	B2	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103137	Shovel test pit	STP N103 E095 LEV01 00-10cm MXH074		MXH074	Surface/Developing A	1	pipe, bowl	bowl	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
103140	Shovel test pit	STP N103 E095 LEV01 00-10cm MXH074		MXH074	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
103156	Shovel test pit	STP N103 E095 LEV01 00-10cm MXH074		MXH074	Surface/Developing A	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103157	Shovel test pit	STP N103 E095 LEV01 00-10cm MXH074		MXH074	Surface/Developing A	10	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103153	Shovel test pit	STP N103 E095 LEV01 00-10cm MXH074		MXH074	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103139	Shovel test pit	STP N103 E095 LEV01 00-10cm MXH074		MXH074	Surface/Developing A	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, unidentified	food/beverage	service	
103138	Shovel test pit	STP N103 E095 LEV01 00-10cm MXH074		MXH074	Surface/Developing A	1	sewer pipe	fragment	Ceramic	Stoneware	Unidentified	heating, plumbing, electric	device	
103142	Shovel test pit	STP N103 E095 LEV01 00-10cm MXH074		MXH074	Surface/Developing A	1	bottle, indeterminate	body	Glass	embossed	embossed	food/beverage	storage	-Clear
103143	Shovel test pit	STP N103 E095 LEV01 00-10cm MXH074		MXH074	Surface/Developing A	5	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103154	Shovel test pit	STP N103 E095 LEV01 00-10cm MXH074		MXH074	Surface/Developing A	7	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
103155	Shovel test pit	STP N103 E095 LEV01 00-10cm MXH074		MXH074	Surface/Developing A	2	bottle, indeterminate	fragment	Glass	indeterminate	indeterminate	0	Not Assigned	-Blue-cobalt
103147	Shovel test pit	STP N103 E095 LEV01 00-10cm MXH074		MXH074	Surface/Developing A	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
103152	Shovel test pit	STP N103 E095 LEV01 00-10cm MXH074		MXH074	Surface/Developing A	4	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
103141	Shovel test pit	STP N103 E095 LEV01 00-10cm MXH074		MXH074	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (bright 7-up)
103145	Shovel test pit	STP N103 E095 LEV01 00-10cm MXH074		MXH074	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
103149	Shovel test pit	STP N103 E095 LEV01 00-10cm MXH074		MXH074	Surface/Developing A	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
103150	Shovel test pit	STP N103 E095 LEV01 00-10cm MXH074		MXH074	Surface/Developing A	1	screw	whole/intact	Metal	copper alloy	copper alloy	architecture	general construction	
103146	Shovel test pit	STP N103 E095 LEV01 00-10cm MXH074		MXH074	Surface/Developing A	1	nail, wire	whole/intact	Metal	ferrous	machine made	architecture	general construction	
103148	Shovel test pit	STP N103 E095 LEV01 00-10cm MXH074		MXH074	Surface/Developing A	1	screw	whole/intact	Metal	ferrous	machine made	architecture	general construction	
103151	Shovel test pit	STP N103 E095 LEV01 00-10cm MXH074		MXH074	Surface/Developing A	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
103144	Shovel test pit	STP N103 E095 LEV01 00-10cm MXH074		MXH074	Surface/Developing A	1	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
102922	Shovel test pit	STP N103 E095 LEV01 30-40cm MXH077		MXH077	Buried APZ	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-8/64
102927	Shovel test pit	STP N103 E095 LEV01 30-40cm MXH077		MXH077	Buried APZ	1	pipe, heel/spur	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
102936	Shovel test pit	STP N103 E095 LEV01 30-40cm MXH077		MXH077	Buried APZ	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
102933	Shovel test pit	STP N103 E095 LEV01 30-40cm MXH077		MXH077	Buried APZ	4	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
102924	Shovel test pit	STP N103 E095 LEV01 30-40cm MXH077		MXH077	Buried APZ	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
102932	Shovel test pit	STP N103 E095 LEV01 30-40cm MXH077		MXH077	Buried APZ	6	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
102930	Shovel test pit	STP N103 E095 LEV01 30-40cm MXH077		MXH077	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	jackfield type	food/beverage	service	
102935	Shovel test pit	STP N103 E095 LEV01 30-40cm MXH077		MXH077	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	slip-blue
102931	Shovel test pit	STP N103 E095 LEV01 30-40cm MXH077		MXH077	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
102929	Shovel test pit	STP N103 E095 LEV01 30-40cm MXH077		MXH077	Buried APZ	5	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
102926	Shovel test pit	STP N103 E095 LEV01 30-40cm MXH077		MXH077	Buried APZ	6	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
102923	Shovel test pit	STP N103 E095 LEV01 30-40cm MXH077		MXH077	Buried APZ	13	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
102925	Shovel test pit	STP N103 E095 LEV01 30-40cm MXH077		MXH077	Buried APZ	1	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
102937	Shovel test pit	STP N103 E095 LEV01 30-40cm MXH077		MXH077	Buried APZ	3	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
102934	Shovel test pit	STP N103 E095 LEV01 30-40cm MXH077		MXH077	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
102928	Shovel test pit	STP N103 E095 LEV01 30-40cm MXH077		MXH077	Buried APZ	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
103162	Shovel test pit	STP N103 E095 LEV02 10-20cm MXH075		MXH075	Surface/Developing A	1	pipe, bowl	bowl	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
103166	Shovel test pit	STP N103 E095 LEV02 10-20cm MXH075		MXH075	Surface/Developing A	1	pipe, bowl	bowl	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
103158	Shovel test pit	STP N103 E095 LEV02 10-20cm MXH075		MXH075	Surface/Developing A	2	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
103172	Shovel test pit	STP N103 E095 LEV02 10-20cm MXH075		MXH075	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
103170	Shovel test pit	STP N103 E095 LEV02 10-20cm MXH075		MXH075	Surface/Developing A	3	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103160	Shovel test pit	STP N103 E095 LEV02 10-20cm MXH075		MXH075	Surface/Developing A	3	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103163	Shovel test pit	STP N103 E095 LEV02 10-20cm MXH075		MXH075	Surface/Developing A	1	vessel, hollow	foot	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103167	Shovel test pit	STP N103 E095 LEV02 10-20cm MXH075		MXH075	Surface/Developing A	6	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103169	Shovel test pit	STP N103 E095 LEV02 10-20cm MXH075		MXH075	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	food/beverage	service	
103171	Shovel test pit	STP N103 E095 LEV02 10-20cm MXH075		MXH075	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Whiteware, hand painted polychrome	food/beverage	service	painted-green
103164	Shovel test pit	STP N103 E095 LEV02 10-20cm MXH075		MXH075	Surface/Developing A	1	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
103165	Shovel test pit	STP N103 E095 LEV02 10-20cm MXH075		MXH075	Surface/Developing A	2	vessel, hollow	base	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
103161	Shovel test pit	STP N103 E095 LEV02 10-20cm MXH075		MXH075	Surface/Developing A	1	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
103159	Shovel test pit	STP N103 E095 LEV02 10-20cm MXH075		MXH075	Surface/Developing A	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103168	Shovel test pit	STP N103 E095 LEV02 10-20cm MXH075		MXH075	Surface/Developing A	1	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
103117	Shovel test pit	STP N103 E095 Lev03 20-30cm MXH076		MXH076	Fill	2	brick	fragment	Ceramic	Ball clay	molded	architecture	general construction	
103115	Shovel test pit	STP N103 E095 Lev03 20-30cm MXH076		MXH076	Fill	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
103126	Shovel test pit	STP N103 E095 Lev03 20-30cm MXH076		MXH076	Fill	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
103113	Shovel test pit	STP N103 E095 Lev03 20-30cm MXH076		MXH076	Fill	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware unidentified	food/beverage	preparation	
103125	Shovel test pit	STP N103 E095 Lev03 20-30cm MXH076		MXH076	Fill	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103132	Shovel test pit	STP N103 E095 Lev03 20-30cm MXH076		MXH076	Fill	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103112	Shovel test pit	STP N103 E095 Lev03 20-30cm MXH076		MXH076	Fill	5	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
103116	Shovel test pit	STP N103 E095 Lev03 20-30cm MXH076		MXH076	Fill	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
103133	Shovel test pit	STP N103 E095 Lev03 20-30cm MXH076		MXH076	Fill	3	vessel, hollow	base	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
103127	Shovel test pit	STP N103 E095 Lev03 20-30cm MXH076		MXH076	Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, factory-made slipware	food/beverage	service	mottled-orange
103118	Shovel test pit	STP N103 E095 Lev03 20-30cm MXH076		MXH076	Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103124	Shovel test pit	STP N103 E095 Lev03 20-30cm MXH076		MXH076	Fill	7	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103122	Shovel test pit	STP N103 E095 Lev03 20-30cm MXH076		MXH076	Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
103136	Shovel test pit	STP N103 E095 Lev03 20-30cm MXH076		MXH076	Fill	2	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103119	Shovel test pit	STP N103 E095 Lev03 20-30cm MXH076		MXH076	Fill	10	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103123	Shovel test pit	STP N103 E095 Lev03 20-30cm MXH076		MXH076	Fill	2	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
103130	Shovel test pit	STP N103 E095 Lev03 20-30cm MXH076		MXH076	Fill	1	vessel, hollow	rim	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
103135	Shovel test pit	STP N103 E095 Lev03 20-30cm MXH076		MXH076	Fill	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103129	Shovel test pit	STP N103 E095 Lev03 20-30cm MXH076		MXH076	Fill	2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103120	Shovel test pit	STP N103 E095 Lev03 20-30cm MXH076		MXH076	Fill	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
103134	Shovel test pit	STP N103 E095 Lev03 20-30cm MXH076		MXH076	Fill	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Green (light)
103121	Shovel test pit	STP N103 E095 Lev03 20-30cm MXH076		MXH076	Fill	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
103131	Shovel test pit	STP N103 E095 Lev03 20-30cm MXH076		MXH076	Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
103114	Shovel test pit	STP N103 E095 Lev03 20-30cm MXH076		MXH076	Fill	4	unidentified	fragment	Metal	ferrous	unidentified	0	Not Assigned	
103128	Shovel test pit	STP N103 E095 Lev03 20-30cm MXH076		MXH076	Fill	1	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
103193	Shovel test pit	STP N103 E095 LEV05 40-50cm MXH078		MXH078	Buried APZ	0	0	0	0	0	0	0	Not Assigned	
103191	Shovel test pit	STP N103 E095 LEV05 40-50cm MXH078		MXH078	Buried APZ	1	pipe, bowl	bowl	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
103190	Shovel test pit	STP N103 E095 LEV05 40-50cm MXH078		MXH078	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103175	Shovel test pit	STP N103 E095 LEV05 40-50cm MXH078		MXH078	Buried APZ	6	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
103180	Shovel test pit	STP N103 E095 LEV05 40-50cm MXH078		MXH078	Buried APZ	5	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
103194	Shovel test pit	STP N103 E095 LEV05 40-50cm MXH078		MXH078	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	jackfield type	food/beverage	service	
103185	Shovel test pit	STP N103 E095 LEV05 40-50cm MXH078		MXH078	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	
103179	Shovel test pit	STP N103 E095 LEV05 40-50cm MXH078		MXH078	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
103174	Shovel test pit	STP N103 E095 LEV05 40-50cm MXH078		MXH078	Buried APZ	5	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103182	Shovel test pit	STP N103 E095 LEV05 40-50cm MXH078		MXH078	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103184	Shovel test pit	STP N103 E095 LEV05 40-50cm MXH078		MXH078	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	Annular-brown
103173	Shovel test pit	STP N103 E095 LEV05 40-50cm MXH078		MXH078	Buried APZ	8	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103188	Shovel test pit	STP N103 E095 LEV05 40-50cm MXH078		MXH078	Buried APZ	9	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103178	Shovel test pit	STP N103 E095 LEV05 40-50cm MXH078		MXH078	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	Whiteware, hand painted blue	food/beverage	service	
103186	Shovel test pit	STP N103 E095 LEV05 40-50cm MXH078		MXH078	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	British brown	food/beverage	Service	
103176	Shovel test pit	STP N103 E095 LEV05 40-50cm MXH078		MXH078	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	British brown	food/beverage	Service	Albany slip-brown
103189	Shovel test pit	STP N103 E095 LEV05 40-50cm MXH078		MXH078	Buried APZ	1	vessel, flat	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
103181	Shovel test pit	STP N103 E095 LEV05 40-50cm MXH078		MXH078	Buried APZ	6	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103177	Shovel test pit	STP N103 E095 LEV05 40-50cm MXH078		MXH078	Buried APZ	5	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103187	Shovel test pit	STP N103 E095 LEV05 40-50cm MXH078		MXH078	Buried APZ	3	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
103192	Shovel test pit	STP N103 E095 LEV05 40-50cm MXH078		MXH078	Buried APZ	1	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
103230	Shovel test pit	STP N103 E095 LEV06 50-60cm MXH079		MXH079	B1	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
103233	Shovel test pit	STP N103 E095 LEV06 50-60cm MXH079		MXH079	B1	1	vessel, hollow	base	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103226	Shovel test pit	STP N103 E095 LEV06 50-60cm MXH079		MXH079	B1	5	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103231	Shovel test pit	STP N103 E095 LEV06 50-60cm MXH079		MXH079	B1	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103232	Shovel test pit	STP N103 E095 LEV06 50-60cm MXH079		MXH079	B1	1	vessel, hollow	body	Ceramic	Stoneware	Westerwald	food/beverage	service	
103234	Shovel test pit	STP N103 E095 LEV06 50-60cm MXH079		MXH079	B1	1	vessel, hollow	base	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
103229	Shovel test pit	STP N103 E095 LEV06 50-60cm MXH079		MXH079	B1	1	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
103225	Shovel test pit	STP N103 E095 LEV06 50-60cm MXH079		MXH079	B1	2	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103227	Shovel test pit	STP N103 E095 LEV06 50-60cm MXH079		MXH079	B1	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
103224	Shovel test pit	STP N103 E095 LEV06 50-60cm MXH079		MXH079	B1	2	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
103228	Shovel test pit	STP N103 E095 LEV06 50-60cm MXH079		MXH079	B1	1	stone, worked	fragment	Mineral	Quartzite	tan	0	Not Assigned	
103283	Shovel test pit	STP N103 E095 LEV07 60-70cm MXH080		MXH080	B1	1	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
102643	Shovel test pit	STP N106 E087 LEV01 00-10cm MXH039		MXH039	Surface/Developing A	8	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
102654	Shovel test pit	STP N106 E087 LEV01 00-10cm MXH039		MXH039	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
102657	Shovel test pit	STP N106 E087 LEV01 00-10cm MXH039		MXH039	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
102652	Shovel test pit	STP N106 E087 LEV01 00-10cm MXH039		MXH039	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
102658	Shovel test pit	STP N106 E087 LEV01 00-10cm MXH039		MXH039	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
102655	Shovel test pit	STP N106 E087 LEV01 00-10cm MXH039		MXH039	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
102646	Shovel test pit	STP N106 E087 LEV01 00-10cm MXH039		MXH039	Surface/Developing A	24	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
102650	Shovel test pit	STP N106 E087 LEV01 00-10cm MXH039		MXH039	Surface/Developing A	4	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
102649	Shovel test pit	STP N106 E087 LEV01 00-10cm MXH039		MXH039	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
102653	Shovel test pit	STP N106 E087 LEV01 00-10cm MXH039		MXH039	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
102648	Shovel test pit	STP N106 E087 LEV01 00-10cm MXH039		MXH039	Surface/Developing A	1	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
102645	Shovel test pit	STP N106 E087 LEV01 00-10cm MXH039		MXH039	Surface/Developing A	1	ring	whole/intact	Metal	ferrous	machine made	food/beverage	storage	
102642	Shovel test pit	STP N106 E087 LEV01 00-10cm MXH039		MXH039	Surface/Developing A	4	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
102651	Shovel test pit	STP N106 E087 LEV01 00-10cm MXH039		MXH039	Surface/Developing A	1	sheet metal	fragment	Metal	lead	cast	0	Not Assigned	
102647	Shovel test pit	STP N106 E087 LEV01 00-10cm MXH039		MXH039	Surface/Developing A	2	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
102656	Shovel test pit	STP N106 E087 LEV01 00-10cm MXH039		MXH039	Surface/Developing A	1	plaster, plain	fragment	Mineral	composite	plaster	architecture	general construction	
102644	Shovel test pit	STP N106 E087 LEV01 00-10cm MXH039		MXH039	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
102791	Shovel test pit	STP N106 E087 LEV02 10-20cm MXH040		MXH040	Gravel Fill	3	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
102790	Shovel test pit	STP N106 E087 LEV02 10-20cm MXH040		MXH040	Gravel Fill	4	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
102788	Shovel test pit	STP N106 E087 LEV02 10-20cm MXH040		MXH040	Gravel Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Whiteware, hand painted polychrome	food/beverage	service	painted-red
102794	Shovel test pit	STP N106 E087 LEV02 10-20cm MXH040		MXH040	Gravel Fill	3	shell	fragment	Fauna	shell	mollusk	food/beverage	acquisition	
102797	Shovel test pit	STP N106 E087 LEV02 10-20cm MXH040		MXH040	Gravel Fill	5	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
102805	Shovel test pit	STP N106 E087 LEV02 10-20cm MXH040		MXH040	Gravel Fill	3	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
102795	Shovel test pit	STP N106 E087 LEV02 10-20cm MXH040		MXH040	Gravel Fill	5	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Amber
102804	Shovel test pit	STP N106 E087 LEV02 10-20cm MXH040		MXH040	Gravel Fill	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
102792	Shovel test pit	STP N106 E087 LEV02 10-20cm MXH040		MXH040	Gravel Fill	1	bottle, indeterminate	base	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
102801	Shovel test pit	STP N106 E087 LEV02 10-20cm MXH040		MXH040	Gravel Fill	2	bottle, indeterminate	base	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
102809	Shovel test pit	STP N106 E087 LEV02 10-20cm MXH040		MXH040	Gravel Fill	8	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
102800	Shovel test pit	STP N106 E087 LEV02 10-20cm MXH040		MXH040	Gravel Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
102799	Shovel test pit	STP N106 E087 LEV02 10-20cm MXH040		MXH040	Gravel Fill	1	bottle, indeterminate	base	Glass	Machine made	machine made	food/beverage	storage	-Clear
102806	Shovel test pit	STP N106 E087 LEV02 10-20cm MXH040		MXH040	Gravel Fill	1	lightbulb	whole/intact	Glass	Machine made	machine made	lighting	device	-Clear
102810	Shovel test pit	STP N106 E087 LEV02 10-20cm MXH040		MXH040	Gravel Fill	1	bottle, indeterminate	body	Glass	molded	molded	food/beverage	storage	-Clear
102785	Shovel test pit	STP N106 E087 LEV02 10-20cm MXH040		MXH040	Gravel Fill	1	sheet metal	fragment	Metal	Aluminium	aluminum	0	Not Assigned	
102798	Shovel test pit	STP N106 E087 LEV02 10-20cm MXH040		MXH040	Gravel Fill	1	sheet metal	fragment	Metal	Aluminium	aluminum	0	Not Assigned	
102793	Shovel test pit	STP N106 E087 LEV02 10-20cm MXH040		MXH040	Gravel Fill	1	nail, wire	whole/intact	Metal	copper alloy	copper alloy	architecture	general construction	
102803	Shovel test pit	STP N106 E087 LEV02 10-20cm MXH040		MXH040	Gravel Fill	3	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
102786	Shovel test pit	STP N106 E087 LEV02 10-20cm MXH040		MXH040	Gravel Fill	2	wire	fragment	Metal	ferrous	machine made	0	Not Assigned	
102789	Shovel test pit	STP N106 E087 LEV02 10-20cm MXH040		MXH040	Gravel Fill	3	nail, wire	fragment	Metal	ferrous	machine made	architecture	general construction	
102802	Shovel test pit	STP N106 E087 LEV02 10-20cm MXH040		MXH040	Gravel Fill	1	sheet metal	fragment	Metal	lead	Not Assigned	0	Not Assigned	
102807	Shovel test pit	STP N106 E087 LEV02 10-20cm MXH040		MXH040	Gravel Fill	2	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
102787	Shovel test pit	STP N106 E087 LEV02 10-20cm MXH040		MXH040	Gravel Fill	1	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
102796	Shovel test pit	STP N106 E087 LEV02 10-20cm MXH040		MXH040	Gravel Fill	1	handle, cutlery	whole/intact	Synthetic	synthetic	plastic	food/beverage	service	
102808	Shovel test pit	STP N106 E087 LEV02 10-20cm MXH040		MXH040	Gravel Fill	1	cap, screw top	fragment	Synthetic	synthetic	plastic	food/beverage	storage	
103278	Shovel test pit	STP N106 E087 LEV03 20-30cm MXH041		MXH041	Sand Fill	3	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
103279	Shovel test pit	STP N106 E087 LEV03 20-30cm MXH041		MXH041	Sand Fill	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Amber
103280	Shovel test pit	STP N106 E087 LEV03 20-30cm MXH041		MXH041	Sand Fill	1	bottle, indeterminate	lip	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear-External threads
103285	Shovel test pit	STP N106 E087 LEV06 50-60cm MXH044		MXH044	Utility Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103284	Shovel test pit	STP N106 E087 LEV06 50-60cm MXH044		MXH044	Utility Fill	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
103277	Shovel test pit	STP N106 E087 LEV07 60-70cm MXH045		MXH045	Utility Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103276	Shovel test pit	STP N106 E087 LEV07 60-70cm MXH045		MXH045	Utility Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Milk glass/Opaque white
103263	Shovel test pit	STP N106 E087 LEV08 70-80cm MXH046		MXH046	Utility Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103265	Shovel test pit	STP N106 E087 LEV08 70-80cm MXH046		MXH046	Utility Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103264	Shovel test pit	STP N106 E087 LEV08 70-80cm MXH046		MXH046	Utility Fill	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103237	Shovel test pit	STP N106 E087 LEV09 80-90cm MXH047		MXH047	Utility Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	
103236	Shovel test pit	STP N106 E087 LEV09 80-90cm MXH047		MXH047	Utility Fill	2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
103235	Shovel test pit	STP N106 E087 LEV09 80-90cm MXH047		MXH047	Utility Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Amber
103238	Shovel test pit	STP N106 E087 LEV09 80-90cm MXH047		MXH047	Utility Fill	3	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
103268	Shovel test pit	STP N106 E087 LEV10 90-100cm MXH048		MXH048	B1	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
103272	Shovel test pit	STP N106 E087 LEV10 90-100cm MXH048		MXH048	B1	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103271	Shovel test pit	STP N106 E087 LEV10 90-100cm MXH048		MXH048	B1	2	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103269	Shovel test pit	STP N106 E087 LEV10 90-100cm MXH048		MXH048	B1	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103270	Shovel test pit	STP N106 E087 LEV10 90-100cm MXH048		MXH048	B1	2	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103267	Shovel test pit	STP N106 E087 LEV10 90-100cm MXH048		MXH048	B1	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-red
103266	Shovel test pit	STP N106 E087 LEV10 90-100cm MXH048		MXH048	B1	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103274	Shovel test pit	STP N106 E087 LEV10 90-100cm MXH048		MXH048	B1	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103273	Shovel test pit	STP N106 E087 LEV10 90-100cm MXH048		MXH048	B1	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
102895	Shovel test pit	STP N106 E089 LEV01 00-10cm MXH071		MXH071	Surface/Developing A	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
102910	Shovel test pit	STP N106 E089 LEV01 00-10cm MXH071		MXH071	Surface/Developing A	14	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
102913	Shovel test pit	STP N106 E089 LEV01 00-10cm MXH071		MXH071	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
102908	Shovel test pit	STP N106 E089 LEV01 00-10cm MXH071		MXH071	Surface/Developing A	6	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	
102911	Shovel test pit	STP N106 E089 LEV01 00-10cm MXH071		MXH071	Surface/Developing A	12	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
102905	Shovel test pit	STP N106 E089 LEV01 00-10cm MXH071		MXH071	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Whiteware, molded	food/beverage	service	gilded-gold
102900	Shovel test pit	STP N106 E089 LEV01 00-10cm MXH071		MXH071	Surface/Developing A	2	wood, indeterminate	fragment	Flora	wood	unidentified	0	Not Assigned	
102912	Shovel test pit	STP N106 E089 LEV01 00-10cm MXH071		MXH071	Surface/Developing A	12	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
102901	Shovel test pit	STP N106 E089 LEV01 00-10cm MXH071		MXH071	Surface/Developing A	5	window glass, flat	body	Glass	indeterminate	indeterminate	food/beverage	service	-Clear
102909	Shovel test pit	STP N106 E089 LEV01 00-10cm MXH071		MXH071	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	service	-Milk glass/Opaque white
102914	Shovel test pit	STP N106 E089 LEV01 00-10cm MXH071		MXH071	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Amber
102896	Shovel test pit	STP N106 E089 LEV01 00-10cm MXH071		MXH071	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
102915	Shovel test pit	STP N106 E089 LEV01 00-10cm MXH071		MXH071	Surface/Developing A	5	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
102898	Shovel test pit	STP N106 E089 LEV01 00-10cm MXH071		MXH071	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (bright 7-up)
102899	Shovel test pit	STP N106 E089 LEV01 00-10cm MXH071		MXH071	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Milk glass/Opaque white
102906	Shovel test pit	STP N106 E089 LEV01 00-10cm MXH071		MXH071	Surface/Developing A	2	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
102904	Shovel test pit	STP N106 E089 LEV01 00-10cm MXH071		MXH071	Surface/Developing A	1	tool	whole/intact	Metal	ferrous	machine made	0	Not Assigned	
102902	Shovel test pit	STP N106 E089 LEV01 00-10cm MXH071		MXH071	Surface/Developing A	1	nail, wire	whole/intact	Metal	ferrous	machine made	architecture	general construction	
102897	Shovel test pit	STP N106 E089 LEV01 00-10cm MXH071		MXH071	Surface/Developing A	8	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
102907	Shovel test pit	STP N106 E089 LEV01 00-10cm MXH071		MXH071	Surface/Developing A	1	plaster, plain	fragment	Mineral	composite	plaster	architecture	general construction	
102903	Shovel test pit	STP N106 E089 LEV01 00-10cm MXH071		MXH071	Surface/Developing A	3	unidentified	fragment	Synthetic	synthetic	styrofoam	0	Not Assigned	
102984	Shovel test pit	STP N106 E089 LEV01 10-20cm MXH072		MXH072	Fill	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
103003	Shovel test pit	STP N106 E089 LEV01 10-20cm MXH072		MXH072	Fill	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
102999	Shovel test pit	STP N106 E089 LEV01 10-20cm MXH072		MXH072	Fill	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
102988	Shovel test pit	STP N106 E089 LEV01 10-20cm MXH072		MXH072	Fill	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
102991	Shovel test pit	STP N106 E089 LEV01 10-20cm MXH072		MXH072	Fill	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103005	Shovel test pit	STP N106 E089 LEV01 10-20cm MXH072		MXH072	Fill	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, slip decorated	food/beverage	preparation	
102992	Shovel test pit	STP N106 E089 LEV01 10-20cm MXH072		MXH072	Fill	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
103002	Shovel test pit	STP N106 E089 LEV01 10-20cm MXH072		MXH072	Fill	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
102990	Shovel test pit	STP N106 E089 LEV01 10-20cm MXH072		MXH072	Fill	7	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103001	Shovel test pit	STP N106 E089 LEV01 10-20cm MXH072		MXH072	Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
102993	Shovel test pit	STP N106 E089 LEV01 10-20cm MXH072		MXH072	Fill	2	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	storage	painted-blue
103000	Shovel test pit	STP N106 E089 LEV01 10-20cm MXH072		MXH072	Fill	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
102987	Shovel test pit	STP N106 E089 LEV01 10-20cm MXH072		MXH072	Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
102995	Shovel test pit	STP N106 E089 LEV01 10-20cm MXH072		MXH072	Fill	1	vessel, hollow	body	Ceramic	Porcelain	Decorated	food/beverage	service	painted-blue
103004	Shovel test pit	STP N106 E089 LEV01 10-20cm MXH072		MXH072	Fill	1	vessel, hollow	body	Ceramic	Porcelain	Decorated	food/beverage	service	painted-blue
102997	Shovel test pit	STP N106 E089 LEV01 10-20cm MXH072		MXH072	Fill	2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua marine*
102998	Shovel test pit	STP N106 E089 LEV01 10-20cm MXH072		MXH072	Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
102986	Shovel test pit	STP N106 E089 LEV01 10-20cm MXH072		MXH072	Fill	1	nail, wire	whole/intact	Metal	ferrous	machine made	architecture	roofing	
102985	Shovel test pit	STP N106 E089 LEV01 10-20cm MXH072		MXH072	Fill	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
102996	Shovel test pit	STP N106 E089 LEV01 10-20cm MXH072		MXH072	Fill	2	plaster, plain	fragment	Mineral	composite	plaster	architecture	general construction	
103251	Shovel test pit	STP N106 E089 STR01 LEV03 20-30cm MXH073		MXH073	Fill	2	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
103254	Shovel test pit	STP N106 E089 STR01 LEV03 20-30cm MXH073		MXH073	Fill	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
103240	Shovel test pit	STP N106 E089 STR01 LEV03 20-30cm MXH073		MXH073	Fill	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
103252	Shovel test pit	STP N106 E089 STR01 LEV03 20-30cm MXH073		MXH073	Fill	11	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103248	Shovel test pit	STP N106 E089 STR01 LEV03 20-30cm MXH073		MXH073	Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	slip-orange
103247	Shovel test pit	STP N106 E089 STR01 LEV03 20-30cm MXH073		MXH073	Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
103245	Shovel test pit	STP N106 E089 STR01 LEV03 20-30cm MXH073		MXH073	Fill	5	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	
103242	Shovel test pit	STP N106 E089 STR01 LEV03 20-30cm MXH073		MXH073	Fill	2	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103250	Shovel test pit	STP N106 E089 STR01 LEV03 20-30cm MXH073		MXH073	Fill	5	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103246	Shovel test pit	STP N106 E089 STR01 LEV03 20-30cm MXH073		MXH073	Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Yellow ware, plain	food/beverage	service	
103243	Shovel test pit	STP N106 E089 STR01 LEV03 20-30cm MXH073		MXH073	Fill	1	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
103239	Shovel test pit	STP N106 E089 STR01 LEV03 20-30cm MXH073		MXH073	Fill	5	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103249	Shovel test pit	STP N106 E089 STR01 LEV03 20-30cm MXH073		MXH073	Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
103255	Shovel test pit	STP N106 E089 STR01 LEV03 20-30cm MXH073		MXH073	Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
103241	Shovel test pit	STP N106 E089 STR01 LEV03 20-30cm MXH073		MXH073	Fill	1	staple	whole/intact	Metal	ferrous	machine made	furniture/household equip.	hardware	
103244	Shovel test pit	STP N106 E089 STR01 LEV03 20-30cm MXH073		MXH073	Fill	1	buckle	fragment	Metal	lead	cast	personal	fastener	
103253	Shovel test pit	STP N106 E089 STR01 LEV03 20-30cm MXH073		MXH073	Fill	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
103471	Shovel test pit	STP N106 E094 LEV01 00-10cm MXH111		MXH111	Surface/Developing A	10	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
103472	Shovel test pit	STP N106 E094 LEV01 00-10cm MXH111		MXH111	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103469	Shovel test pit	STP N106 E094 LEV01 00-10cm MXH111		MXH111	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire plain	food/beverage	service	
103462	Shovel test pit	STP N106 E094 LEV01 00-10cm MXH111		MXH111	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Ironstone, molded	food/beverage	service	
103467	Shovel test pit	STP N106 E094 LEV01 00-10cm MXH111		MXH111	Surface/Developing A	5	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103464	Shovel test pit	STP N106 E094 LEV01 00-10cm MXH111		MXH111	Surface/Developing A	15	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103475	Shovel test pit	STP N106 E094 LEV01 00-10cm MXH111		MXH111	Surface/Developing A	1	vessel, hollow	foot	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103479	Shovel test pit	STP N106 E094 LEV01 00-10cm MXH111		MXH111	Surface/Developing A	1	vessel, hollow	body	Ceramic	Porcelain	Imari	food/beverage	service	
103458	Shovel test pit	STP N106 E094 LEV01 00-10cm MXH111		MXH111	Surface/Developing A	1	vessel, hollow	body	Ceramic	Stoneware	brown, salt-glazed	0	Not Assigned	
103459	Shovel test pit	STP N106 E094 LEV01 00-10cm MXH111		MXH111	Surface/Developing A	1	vessel, hollow	body	Ceramic	Stoneware	Westerwald	food/beverage	service	
103477	Shovel test pit	STP N106 E094 LEV01 00-10cm MXH111		MXH111	Surface/Developing A	2	bottle, indeterminate	body	Glass	embossed	embossed	food/beverage	storage	-Clear
103476	Shovel test pit	STP N106 E094 LEV01 00-10cm MXH111		MXH111	Surface/Developing A	3	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103470	Shovel test pit	STP N106 E094 LEV01 00-10cm MXH111		MXH111	Surface/Developing A	5	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
103461	Shovel test pit	STP N106 E094 LEV01 00-10cm MXH111		MXH111	Surface/Developing A	1	vessel, hollow	rim	Glass	indeterminate	indeterminate	0	Not Assigned	-Green*
103473	Shovel test pit	STP N106 E094 LEV01 00-10cm MXH111		MXH111	Surface/Developing A	5	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
103463	Shovel test pit	STP N106 E094 LEV01 00-10cm MXH111		MXH111	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
103460	Shovel test pit	STP N106 E094 LEV01 00-10cm MXH111		MXH111	Surface/Developing A	4	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
103478	Shovel test pit	STP N106 E094 LEV01 00-10cm MXH111		MXH111	Surface/Developing A	2	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
103466	Shovel test pit	STP N106 E094 LEV01 00-10cm MXH111		MXH111	Surface/Developing A	1	nail, wire	whole/intact	Metal	steel	steel	architecture	roofing	
103465	Shovel test pit	STP N106 E094 LEV01 00-10cm MXH111		MXH111	Surface/Developing A	3	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
103457	Shovel test pit	STP N106 E094 LEV01 00-10cm MXH111		MXH111	Surface/Developing A	1	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
103468	Shovel test pit	STP N106 E094 LEV01 00-10cm MXH111		MXH111	Surface/Developing A	1	tag	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
103572	Shovel test pit	STP N106 E094 LEV03 20-30cm MXH113		MXH113	Fill	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
103569	Shovel test pit	STP N106 E094 LEV03 20-30cm MXH113		MXH113	Fill	3	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
103562	Shovel test pit	STP N106 E094 LEV03 20-30cm MXH113		MXH113	Fill	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
103564	Shovel test pit	STP N106 E094 LEV03 20-30cm MXH113		MXH113	Fill	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103560	Shovel test pit	STP N106 E094 LEV03 20-30cm MXH113		MXH113	Fill	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
103558	Shovel test pit	STP N106 E094 LEV03 20-30cm MXH113		MXH113	Fill	8	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103571	Shovel test pit	STP N106 E094 LEV03 20-30cm MXH113		MXH113	Fill	1	vessel, hollow	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103574	Shovel test pit	STP N106 E094 LEV03 20-30cm MXH113		MXH113	Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	other-black
103578	Shovel test pit	STP N106 E094 LEV03 20-30cm MXH113		MXH113	Fill	1	vessel, flat	neck	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	Annular-green
103576	Shovel test pit	STP N106 E094 LEV03 20-30cm MXH113		MXH113	Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-green
103566	Shovel test pit	STP N106 E094 LEV03 20-30cm MXH113		MXH113	Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103573	Shovel test pit	STP N106 E094 LEV03 20-30cm MXH113		MXH113	Fill	3	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103559	Shovel test pit	STP N106 E094 LEV03 20-30cm MXH113		MXH113	Fill	8	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103575	Shovel test pit	STP N106 E094 LEV03 20-30cm MXH113		MXH113	Fill	1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103561	Shovel test pit	STP N106 E094 LEV03 20-30cm MXH113		MXH113	Fill	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103565	Shovel test pit	STP N106 E094 LEV03 20-30cm MXH113		MXH113	Fill	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
103567	Shovel test pit	STP N106 E094 LEV03 20-30cm MXH113		MXH113	Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
103570	Shovel test pit	STP N106 E094 LEV03 20-30cm MXH113		MXH113	Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
103563	Shovel test pit	STP N106 E094 LEV03 20-30cm MXH113		MXH113	Fill	6	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
103568	Shovel test pit	STP N106 E094 LEV03 20-30cm MXH113		MXH113	Fill	5	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
103577	Shovel test pit	STP N106 E094 LEV03 20-30cm MXH113		MXH113	Fill	3	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
103840	Shovel test pit	STP N106 E094 LEV04 30-40cm MXH114		MXH114	Fill	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
103842	Shovel test pit	STP N106 E094 LEV04 30-40cm MXH114		MXH114	Fill	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
103843	Shovel test pit	STP N106 E094 LEV04 30-40cm MXH114		MXH114	Fill	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
103844	Shovel test pit	STP N106 E094 LEV04 30-40cm MXH114		MXH114	Fill	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
103847	Shovel test pit	STP N106 E094 LEV04 30-40cm MXH114		MXH114	Fill	3	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103846	Shovel test pit	STP N106 E094 LEV04 30-40cm MXH114		MXH114	Fill	7	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103845	Shovel test pit	STP N106 E094 LEV04 30-40cm MXH114		MXH114	Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
103839	Shovel test pit	STP N106 E094 LEV04 30-40cm MXH114		MXH114	Fill	1	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
103848	Shovel test pit	STP N106 E094 LEV04 30-40cm MXH114		MXH114	Fill	6	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
103841	Shovel test pit	STP N106 E094 LEV04 30-40cm MXH114		MXH114	Fill	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
103968	Shovel test pit	STP N106 E094 LEV05 40-50cm MXH115		MXH115	Redeposited B	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
103955	Shovel test pit	STP N106 E094 LEV05 40-50cm MXH115		MXH115	Redeposited B	4	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103966	Shovel test pit	STP N106 E094 LEV05 40-50cm MXH115		MXH115	Redeposited B	1	vessel, hollow	base	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103967	Shovel test pit	STP N106 E094 LEV05 40-50cm MXH115		MXH115	Redeposited B	2	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103960	Shovel test pit	STP N106 E094 LEV05 40-50cm MXH115		MXH115	Redeposited B	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103965	Shovel test pit	STP N106 E094 LEV05 40-50cm MXH115		MXH115	Redeposited B	1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103961	Shovel test pit	STP N106 E094 LEV05 40-50cm MXH115		MXH115	Redeposited B	7	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103954	Shovel test pit	STP N106 E094 LEV05 40-50cm MXH115		MXH115	Redeposited B	1	vessel, hollow	rim	Ceramic	Stoneware	brown, salt-glazed	food/beverage	service	
103962	Shovel test pit	STP N106 E094 LEV05 40-50cm MXH115		MXH115	Redeposited B	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
103964	Shovel test pit	STP N106 E094 LEV05 40-50cm MXH115		MXH115	Redeposited B	3	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
103957	Shovel test pit	STP N106 E094 LEV05 40-50cm MXH115		MXH115	Redeposited B	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
103958	Shovel test pit	STP N106 E094 LEV05 40-50cm MXH115		MXH115	Redeposited B	1	bottle, indeterminate	lip/neck	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)-Stacked Ring
103963	Shovel test pit	STP N106 E094 LEV05 40-50cm MXH115		MXH115	Redeposited B	3	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
103956	Shovel test pit	STP N106 E094 LEV05 40-50cm MXH115		MXH115	Redeposited B	2	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
103959	Shovel test pit	STP N106 E094 LEV05 40-50cm MXH115		MXH115	Redeposited B	1	ballast	fragment	Stone	flint	butterscotch	architecture	foundation	
103896	Shovel test pit	STP N106 E094 LEV06 50-60cm MXH116		MXH116	Redeposited B	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
103902	Shovel test pit	STP N106 E094 LEV06 50-60cm MXH116		MXH116	Redeposited B	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-6/64
103895	Shovel test pit	STP N106 E094 LEV06 50-60cm MXH116		MXH116	Redeposited B	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103903	Shovel test pit	STP N106 E094 LEV06 50-60cm MXH116		MXH116	Redeposited B	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103899	Shovel test pit	STP N106 E094 LEV06 50-60cm MXH116		MXH116	Redeposited B	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, slip decorated	food/beverage	preparation	
103907	Shovel test pit	STP N106 E094 LEV06 50-60cm MXH116		MXH116	Redeposited B	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
103901	Shovel test pit	STP N106 E094 LEV06 50-60cm MXH116		MXH116	Redeposited B	1	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103894	Shovel test pit	STP N106 E094 LEV06 50-60cm MXH116		MXH116	Redeposited B	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
103905	Shovel test pit	STP N106 E094 LEV06 50-60cm MXH116		MXH116	Redeposited B	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
103904	Shovel test pit	STP N106 E094 LEV06 50-60cm MXH116		MXH116	Redeposited B	1	vessel, flat	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103893	Shovel test pit	STP N106 E094 LEV06 50-60cm MXH116		MXH116	Redeposited B	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103900	Shovel test pit	STP N106 E094 LEV06 50-60cm MXH116		MXH116	Redeposited B	1	vessel, hollow	foot	Ceramic	Earthenware, refined	Whiteware, undecorated	food/beverage	service	
103897	Shovel test pit	STP N106 E094 LEV06 50-60cm MXH116		MXH116	Redeposited B	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
103906	Shovel test pit	STP N106 E094 LEV06 50-60cm MXH116		MXH116	Redeposited B	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
103898	Shovel test pit	STP N106 E094 LEV06 50-60cm MXH116		MXH116	Redeposited B	1	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
103829	Shovel test pit	STP N106 E094 LEV07 60-70cm MXH117		MXH117	Buried APZ	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
103821	Shovel test pit	STP N106 E094 LEV07 60-70cm MXH117		MXH117	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Iberian storage jar	food/beverage	storage	
103833	Shovel test pit	STP N106 E094 LEV07 60-70cm MXH117		MXH117	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103826	Shovel test pit	STP N106 E094 LEV07 60-70cm MXH117		MXH117	Buried APZ	4	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
103822	Shovel test pit	STP N106 E094 LEV07 60-70cm MXH117		MXH117	Buried APZ	6	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103834	Shovel test pit	STP N106 E094 LEV07 60-70cm MXH117		MXH117	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
103823	Shovel test pit	STP N106 E094 LEV07 60-70cm MXH117		MXH117	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
103828	Shovel test pit	STP N106 E094 LEV07 60-70cm MXH117		MXH117	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
103837	Shovel test pit	STP N106 E094 LEV07 60-70cm MXH117		MXH117	Buried APZ	3	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103838	Shovel test pit	STP N106 E094 LEV07 60-70cm MXH117		MXH117	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
103824	Shovel test pit	STP N106 E094 LEV07 60-70cm MXH117		MXH117	Buried APZ	1	chamber pot	rim	Ceramic	Stoneware	Westerwald	personal	toiletry/hygiene	
103836	Shovel test pit	STP N106 E094 LEV07 60-70cm MXH117		MXH117	Buried APZ	1	vessel, hollow	body	Ceramic	Tin Glazed	unidentified	food/beverage	service	
103827	Shovel test pit	STP N106 E094 LEV07 60-70cm MXH117		MXH117	Buried APZ	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103831	Shovel test pit	STP N106 E094 LEV07 60-70cm MXH117		MXH117	Buried APZ	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103835	Shovel test pit	STP N106 E094 LEV07 60-70cm MXH117		MXH117	Buried APZ	1	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
103832	Shovel test pit	STP N106 E094 LEV07 60-70cm MXH117		MXH117	Buried APZ	2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103830	Shovel test pit	STP N106 E094 LEV07 60-70cm MXH117		MXH117	Buried APZ	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
103825	Shovel test pit	STP N106 E094 LEV07 60-70cm MXH117		MXH117	Buried APZ	3	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
103377	Shovel test pit	STP N106 E094 LEV08 70-80cm MXH118		MXH118	Buried APZ	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
103372	Shovel test pit	STP N106 E094 LEV08 70-80cm MXH118		MXH118	Buried APZ	3	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
103374	Shovel test pit	STP N106 E094 LEV08 70-80cm MXH118		MXH118	Buried APZ	5	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
103351	Shovel test pit	STP N106 E094 LEV08 70-80cm MXH118		MXH118	Buried APZ	1	vessel, hollow	handle	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103364	Shovel test pit	STP N106 E094 LEV08 70-80cm MXH118		MXH118	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103373	Shovel test pit	STP N106 E094 LEV08 70-80cm MXH118		MXH118	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103366	Shovel test pit	STP N106 E094 LEV08 70-80cm MXH118		MXH118	Buried APZ	5	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
103371	Shovel test pit	STP N106 E094 LEV08 70-80cm MXH118		MXH118	Buried APZ	10	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103361	Shovel test pit	STP N106 E094 LEV08 70-80cm MXH118		MXH118	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Not Assigned	food/beverage	service	
103357	Shovel test pit	STP N106 E094 LEV08 70-80cm MXH118		MXH118	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
103362	Shovel test pit	STP N106 E094 LEV08 70-80cm MXH118		MXH118	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103368	Shovel test pit	STP N106 E094 LEV08 70-80cm MXH118		MXH118	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103356	Shovel test pit	STP N106 E094 LEV08 70-80cm MXH118		MXH118	Buried APZ	9	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103375	Shovel test pit	STP N106 E094 LEV08 70-80cm MXH118		MXH118	Buried APZ	3	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	food/beverage	service	
103358	Shovel test pit	STP N106 E094 LEV08 70-80cm MXH118		MXH118	Buried APZ	1	vessel, hollow	body	Ceramic	Porcelain	Decorated	food/beverage	service	painted-blue
103365	Shovel test pit	STP N106 E094 LEV08 70-80cm MXH118		MXH118	Buried APZ	1	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
103354	Shovel test pit	STP N106 E094 LEV08 70-80cm MXH118		MXH118	Buried APZ	2	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103367	Shovel test pit	STP N106 E094 LEV08 70-80cm MXH118		MXH118	Buried APZ	3	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103360	Shovel test pit	STP N106 E094 LEV08 70-80cm MXH118		MXH118	Buried APZ	1	tooth	fragment	Fauna	enamel/bone	tooth	food/beverage	acquisition	
103359	Shovel test pit	STP N106 E094 LEV08 70-80cm MXH118		MXH118	Buried APZ	2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103370	Shovel test pit	STP N106 E094 LEV08 70-80cm MXH118		MXH118	Buried APZ	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
103369	Shovel test pit	STP N106 E094 LEV08 70-80cm MXH118		MXH118	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
103352	Shovel test pit	STP N106 E094 LEV08 70-80cm MXH118		MXH118	Buried APZ	1	bottle, indeterminate	lip	Glass	mold blown	Not Assigned	food/beverage	storage	-Green (v. dark/black)-Oil
103363	Shovel test pit	STP N106 E094 LEV08 70-80cm MXH118		MXH118	Buried APZ	3	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
103355	Shovel test pit	STP N106 E094 LEV08 70-80cm MXH118		MXH118	Buried APZ	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
103784	Shovel test pit	STP N106 E094 LEV09 80-90cm MXH119		MXH119	Buried APZ	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
103788	Shovel test pit	STP N106 E094 LEV09 80-90cm MXH119		MXH119	Buried APZ	3	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
103795	Shovel test pit	STP N106 E094 LEV09 80-90cm MXH119		MXH119	Buried APZ	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
103797	Shovel test pit	STP N106 E094 LEV09 80-90cm MXH119		MXH119	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
103783	Shovel test pit	STP N106 E094 LEV09 80-90cm MXH119		MXH119	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103794	Shovel test pit	STP N106 E094 LEV09 80-90cm MXH119		MXH119	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103791	Shovel test pit	STP N106 E094 LEV09 80-90cm MXH119		MXH119	Buried APZ	7	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
103786	Shovel test pit	STP N106 E094 LEV09 80-90cm MXH119		MXH119	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103796	Shovel test pit	STP N106 E094 LEV09 80-90cm MXH119		MXH119	Buried APZ	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103800	Shovel test pit	STP N106 E094 LEV09 80-90cm MXH119		MXH119	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
103793	Shovel test pit	STP N106 E094 LEV09 80-90cm MXH119		MXH119	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
103792	Shovel test pit	STP N106 E094 LEV09 80-90cm MXH119		MXH119	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103789	Shovel test pit	STP N106 E094 LEV09 80-90cm MXH119		MXH119	Buried APZ	10	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103785	Shovel test pit	STP N106 E094 LEV09 80-90cm MXH119		MXH119	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
103781	Shovel test pit	STP N106 E094 LEV09 80-90cm MXH119		MXH119	Buried APZ	1	vessel, hollow	rim	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
103782	Shovel test pit	STP N106 E094 LEV09 80-90cm MXH119		MXH119	Buried APZ	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103798	Shovel test pit	STP N106 E094 LEV09 80-90cm MXH119		MXH119	Buried APZ	5	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103799	Shovel test pit	STP N106 E094 LEV09 80-90cm MXH119		MXH119	Buried APZ	2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
103780	Shovel test pit	STP N106 E094 LEV09 80-90cm MXH119		MXH119	Buried APZ	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	
103787	Shovel test pit	STP N106 E094 LEV09 80-90cm MXH119		MXH119	Buried APZ	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
103779	Shovel test pit	STP N106 E094 LEV09 80-90cm MXH119		MXH119	Buried APZ	2	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
103790	Shovel test pit	STP N106 E094 LEV09 80-90cm MXH119		MXH119	Buried APZ	1	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
104053	Shovel test pit	STP N106 E094 LEV10 90-100cm MXH120		MXH120	B1	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
104054	Shovel test pit	STP N106 E094 LEV10 90-100cm MXH120		MXH120	B1	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
104052	Shovel test pit	STP N106 E094 LEV10 90-100cm MXH120		MXH120	B1	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104055	Shovel test pit	STP N106 E094 LEV10 90-100cm MXH120		MXH120	B1	1	unidentified	fragment	Metal	copper alloy	copper alloy	0	Not Assigned	
103928	Shovel test pit	STP N106 E094 STR01 LEV02 10-20cm MXH112		MXH112	Surface/Developing A	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
103937	Shovel test pit	STP N106 E094 STR01 LEV02 10-20cm MXH112		MXH112	Surface/Developing A	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
103926	Shovel test pit	STP N106 E094 STR01 LEV02 10-20cm MXH112		MXH112	Surface/Developing A	1	flower pot	rim	Ceramic	Earthenware, coarse	Redware, flowerpot	industry, manufacture, trades	gardening/farming	
103923	Shovel test pit	STP N106 E094 STR01 LEV02 10-20cm MXH112		MXH112	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103932	Shovel test pit	STP N106 E094 STR01 LEV02 10-20cm MXH112		MXH112	Surface/Developing A	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
103921	Shovel test pit	STP N106 E094 STR01 LEV02 10-20cm MXH112		MXH112	Surface/Developing A	5	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103924	Shovel test pit	STP N106 E094 STR01 LEV02 10-20cm MXH112		MXH112	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103930	Shovel test pit	STP N106 E094 STR01 LEV02 10-20cm MXH112		MXH112	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103936	Shovel test pit	STP N106 E094 STR01 LEV02 10-20cm MXH112		MXH112	Surface/Developing A	7	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103922	Shovel test pit	STP N106 E094 STR01 LEV02 10-20cm MXH112		MXH112	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	food/beverage	service	
103931	Shovel test pit	STP N106 E094 STR01 LEV02 10-20cm MXH112		MXH112	Surface/Developing A	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
103927	Shovel test pit	STP N106 E094 STR01 LEV02 10-20cm MXH112		MXH112	Surface/Developing A	2	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103929	Shovel test pit	STP N106 E094 STR01 LEV02 10-20cm MXH112		MXH112	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
103933	Shovel test pit	STP N106 E094 STR01 LEV02 10-20cm MXH112		MXH112	Surface/Developing A	1	sheet metal	fragment	Metal	Aluminum	aluminum	0	Not Assigned	
103938	Shovel test pit	STP N106 E094 STR01 LEV02 10-20cm MXH112		MXH112	Surface/Developing A	1	nail, wire	whole/intact	Metal	ferrous	machine made	architecture	general construction	
103925	Shovel test pit	STP N106 E094 STR01 LEV02 10-20cm MXH112		MXH112	Surface/Developing A	1	nail wrought	fragment	Metal	ferrous	wrought	architecture	general construction	
103934	Shovel test pit	STP N106 E094 STR01 LEV02 10-20cm MXH112		MXH112	Surface/Developing A	2	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
103935	Shovel test pit	STP N106 E094 STR01 LEV02 10-20cm MXH112		MXH112	Surface/Developing A	1	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
103312	Shovel test pit	STP N108 E084 STR01 LEV01 00-10cm MXH049		MXH049	Surface/Developing A	1	flower pot	base	Ceramic	Earthenware, coarse	Redware, flowerpot	industry, manufacture, trades	gardening/farming	
103313	Shovel test pit	STP N108 E084 STR01 LEV01 00-10cm MXH049		MXH049	Surface/Developing A	3	flower pot	body	Ceramic	Earthenware, coarse	Redware, flowerpot	industry, manufacture, trades	gardening/farming	
103320	Shovel test pit	STP N108 E084 STR01 LEV01 00-10cm MXH049		MXH049	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103324	Shovel test pit	STP N108 E084 STR01 LEV01 00-10cm MXH049		MXH049	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103317	Shovel test pit	STP N108 E084 STR01 LEV01 00-10cm MXH049		MXH049	Surface/Developing A	1	vessel, hollow	foot	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103318	Shovel test pit	STP N108 E084 STR01 LEV01 00-10cm MXH049		MXH049	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103315	Shovel test pit	STP N108 E084 STR01 LEV01 00-10cm MXH049		MXH049	Surface/Developing A	1	spark plug	whole/intact	Composite Artifact	composite artifact	composite artifact	heating, plumbing, electric	device	
103316	Shovel test pit	STP N108 E084 STR01 LEV01 00-10cm MXH049		MXH049	Surface/Developing A	4	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103325	Shovel test pit	STP N108 E084 STR01 LEV01 00-10cm MXH049		MXH049	Surface/Developing A	3	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
103326	Shovel test pit	STP N108 E084 STR01 LEV01 00-10cm MXH049		MXH049	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Blue-cobalt
103319	Shovel test pit	STP N108 E084 STR01 LEV01 00-10cm MXH049		MXH049	Surface/Developing A	2	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
103323	Shovel test pit	STP N108 E084 STR01 LEV01 00-10cm MXH049		MXH049	Surface/Developing A	2	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
103321	Shovel test pit	STP N108 E084 STR01 LEV01 00-10cm MXH049		MXH049	Surface/Developing A	1	nail, wire	whole/intact	Metal	ferrous	machine made	architecture	general construction	
103322	Shovel test pit	STP N108 E084 STR01 LEV01 00-10cm MXH049		MXH049	Surface/Developing A	2	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
103314	Shovel test pit	STP N108 E084 STR01 LEV01 00-10cm MXH049		MXH049	Surface/Developing A	1	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
103654	Shovel test pit	STP N108 E086 LEV01 00-10cm MXH062		MXH062	Surface/Developing A	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-6/64
103656	Shovel test pit	STP N108 E086 LEV01 00-10cm MXH062		MXH062	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103657	Shovel test pit	STP N108 E086 LEV01 00-10cm MXH062		MXH062	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	unidentified	food/beverage	service	painted-blue
103655	Shovel test pit	STP N108 E086 LEV01 00-10cm MXH062		MXH062	Surface/Developing A	1	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	service	
103658	Shovel test pit	STP N108 E086 LEV01 00-10cm MXH062		MXH062	Surface/Developing A	3	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103653	Shovel test pit	STP N108 E086 LEV01 00-10cm MXH062		MXH062	Surface/Developing A	1	tool	fragment	Metal	ferrous	machine made	0	Not Assigned	
103748	Shovel test pit	STP N108 E086 LEV02 10-20cm MXH063		MXH063	Cobbles	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103747	Shovel test pit	STP N108 E086 LEV02 10-20cm MXH063		MXH063	Cobbles	1	stone	whole/intact	Stone	Felsite	blue-grey	architecture	foundation	
103723	Shovel test pit	STP N108 E086 LEV03 20-30cm MXH064		MXH064	Cobbles	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103724	Shovel test pit	STP N108 E086 LEV03 20-30cm MXH064		MXH064	Cobbles	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103725	Shovel test pit	STP N108 E086 LEV03 20-30cm MXH064		MXH064	Cobbles	1	brick	fragment	Composite Artifact	composite artifact	composite artifact	architecture	general construction	
104077	Shovel test pit	STP N108 E086 LEV04 30-40cm MXH065		MXH065	Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104078	Shovel test pit	STP N108 E086 LEV04 30-40cm MXH065		MXH065	Fill	2	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104079	Shovel test pit	STP N108 E086 LEV04 30-40cm MXH065		MXH065	Fill	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104076	Shovel test pit	STP N108 E086 LEV04 30-40cm MXH065		MXH065	Fill	1	nail, cut	head	Metal	ferrous	cut	architecture	general construction	
103971	Shovel test pit	STP N108 E086 LEV05 40-50cm MXH066		MXH066	Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
103970	Shovel test pit	STP N108 E086 LEV05 40-50cm MXH066		MXH066	Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	
103973	Shovel test pit	STP N108 E086 LEV05 40-50cm MXH066		MXH066	Fill	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103969	Shovel test pit	STP N108 E086 LEV05 40-50cm MXH066		MXH066	Fill	1	vessel, flat	rim	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
103972	Shovel test pit	STP N108 E086 LEV05 40-50cm MXH066		MXH066	Fill	1	vessel, hollow	base	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
103598	Shovel test pit	STP N108 E086 LEV06 50-60cm MXH067		MXH067	Buried APZ	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
103594	Shovel test pit	STP N108 E086 LEV06 50-60cm MXH067		MXH067	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware unidentified	food/beverage	preparation	
103589	Shovel test pit	STP N108 E086 LEV06 50-60cm MXH067		MXH067	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
103591	Shovel test pit	STP N108 E086 LEV06 50-60cm MXH067		MXH067	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Staffordshire plain	food/beverage	service	
103599	Shovel test pit	STP N108 E086 LEV06 50-60cm MXH067		MXH067	Buried APZ	8	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103601	Shovel test pit	STP N108 E086 LEV06 50-60cm MXH067		MXH067	Buried APZ	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
103600	Shovel test pit	STP N108 E086 LEV06 50-60cm MXH067		MXH067	Buried APZ	3	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103590	Shovel test pit	STP N108 E086 LEV06 50-60cm MXH067		MXH067	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103602	Shovel test pit	STP N108 E086 LEV06 50-60cm MXH067		MXH067	Buried APZ	6	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103593	Shovel test pit	STP N108 E086 LEV06 50-60cm MXH067		MXH067	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	Westerwald	food/beverage	service	
103597	Shovel test pit	STP N108 E086 LEV06 50-60cm MXH067		MXH067	Buried APZ	1	vessel, flat	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
103592	Shovel test pit	STP N108 E086 LEV06 50-60cm MXH067		MXH067	Buried APZ	1	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
103596	Shovel test pit	STP N108 E086 LEV06 50-60cm MXH067		MXH067	Buried APZ	1	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
103595	Shovel test pit	STP N108 E086 LEV06 50-60cm MXH067		MXH067	Buried APZ	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
103998	Shovel test pit	STP N108 E086 LEV07 60-70cm MXH068		MXH068	Buried APZ	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
104005	Shovel test pit	STP N108 E086 LEV07 60-70cm MXH068		MXH068	Buried APZ	1	vessel, flat	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103999	Shovel test pit	STP N108 E086 LEV07 60-70cm MXH068		MXH068	Buried APZ	13	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104006	Shovel test pit	STP N108 E086 LEV07 60-70cm MXH068		MXH068	Buried APZ	1	vessel, hollow	handle	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
103992	Shovel test pit	STP N108 E086 LEV07 60-70cm MXH068		MXH068	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
104004	Shovel test pit	STP N108 E086 LEV07 60-70cm MXH068		MXH068	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
103996	Shovel test pit	STP N108 E086 LEV07 60-70cm MXH068		MXH068	Buried APZ	3	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103991	Shovel test pit	STP N108 E086 LEV07 60-70cm MXH068		MXH068	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103993	Shovel test pit	STP N108 E086 LEV07 60-70cm MXH068		MXH068	Buried APZ	13	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104003	Shovel test pit	STP N108 E086 LEV07 60-70cm MXH068		MXH068	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103997	Shovel test pit	STP N108 E086 LEV07 60-70cm MXH068		MXH068	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified		Not Assigned	
103994	Shovel test pit	STP N108 E086 LEV07 60-70cm MXH068		MXH068	Buried APZ	1	vessel, flat	rim	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
104002	Shovel test pit	STP N108 E086 LEV07 60-70cm MXH068		MXH068	Buried APZ	1	vessel, hollow	rim	Ceramic	Porcelain	Plain	food/beverage	service	
104007	Shovel test pit	STP N108 E086 LEV07 60-70cm MXH068		MXH068	Buried APZ	1	vessel, hollow	base	Ceramic	Porcelain	Plain	food/beverage	service	
104001	Shovel test pit	STP N108 E086 LEV07 60-70cm MXH068		MXH068	Buried APZ	1	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
103995	Shovel test pit	STP N108 E086 LEV07 60-70cm MXH068		MXH068	Buried APZ	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
104000	Shovel test pit	STP N108 E086 LEV07 60-70cm MXH068		MXH068	Buried APZ	1	tack, furniture	head	Metal	copper alloy	copper alloy	furniture/household equip.	hardware	
103336	Shovel test pit	STP N108 E086 LEV08 70-80cm MXH069		MXH069	Buried APZ	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
103330	Shovel test pit	STP N108 E086 LEV08 70-80cm MXH069		MXH069	Buried APZ	4	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
103342	Shovel test pit	STP N108 E086 LEV08 70-80cm MXH069		MXH069	Buried APZ	1	teapot	lid	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
103337	Shovel test pit	STP N108 E086 LEV08 70-80cm MXH069		MXH069	Buried APZ	4	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
103350	Shovel test pit	STP N108 E086 LEV08 70-80cm MXH069		MXH069	Buried APZ	1	teapot	spout	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103338	Shovel test pit	STP N108 E086 LEV08 70-80cm MXH069		MXH069	Buried APZ	15	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103343	Shovel test pit	STP N108 E086 LEV08 70-80cm MXH069		MXH069	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103340	Shovel test pit	STP N108 E086 LEV08 70-80cm MXH069		MXH069	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
103345	Shovel test pit	STP N108 E086 LEV08 70-80cm MXH069		MXH069	Buried APZ	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
103348	Shovel test pit	STP N108 E086 LEV08 70-80cm MXH069		MXH069	Buried APZ	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
103328	Shovel test pit	STP N108 E086 LEV08 70-80cm MXH069		MXH069	Buried APZ	7	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103332	Shovel test pit	STP N108 E086 LEV08 70-80cm MXH069		MXH069	Buried APZ	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103339	Shovel test pit	STP N108 E086 LEV08 70-80cm MXH069		MXH069	Buried APZ	14	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103346	Shovel test pit	STP N108 E086 LEV08 70-80cm MXH069		MXH069	Buried APZ	1	vessel, hollow	foot	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103347	Shovel test pit	STP N108 E086 LEV08 70-80cm MXH069		MXH069	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	Nottingham-type		service	
103333	Shovel test pit	STP N108 E086 LEV08 70-80cm MXH069		MXH069	Buried APZ	1	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
103341	Shovel test pit	STP N108 E086 LEV08 70-80cm MXH069		MXH069	Buried APZ	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103334	Shovel test pit	STP N108 E086 LEV08 70-80cm MXH069		MXH069	Buried APZ	3	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103349	Shovel test pit	STP N108 E086 LEV08 70-80cm MXH069		MXH069	Buried APZ	2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
103329	Shovel test pit	STP N108 E086 LEV08 70-80cm MXH069		MXH069	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
103344	Shovel test pit	STP N108 E086 LEV08 70-80cm MXH069		MXH069	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
103327	Shovel test pit	STP N108 E086 LEV08 70-80cm MXH069		MXH069	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
103335	Shovel test pit	STP N108 E086 LEV08 70-80cm MXH069		MXH069	Buried APZ	1	unidentified	fragment	Metal	ferrous	unidentified		0	Not Assigned
103331	Shovel test pit	STP N108 E086 LEV08 70-80cm MXH069		MXH069	Buried APZ	5	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
103295	Shovel test pit	STP N108 E086 LEV09 80-90cm MXH070		MXH070	Buried APZ	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
103299	Shovel test pit	STP N108 E086 LEV09 80-90cm MXH070		MXH070	Buried APZ	1	pipe, bowl	bowl	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
103306	Shovel test pit	STP N108 E086 LEV09 80-90cm MXH070		MXH070	Buried APZ	3	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
103291	Shovel test pit	STP N108 E086 LEV09 80-90cm MXH070		MXH070	Buried APZ	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
103296	Shovel test pit	STP N108 E086 LEV09 80-90cm MXH070		MXH070	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware unidentified	food/beverage	preparation	
103297	Shovel test pit	STP N108 E086 LEV09 80-90cm MXH070		MXH070	Buried APZ	2	vessel, hollow	base	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103298	Shovel test pit	STP N108 E086 LEV09 80-90cm MXH070		MXH070	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103304	Shovel test pit	STP N108 E086 LEV09 80-90cm MXH070		MXH070	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103300	Shovel test pit	STP N108 E086 LEV09 80-90cm MXH070		MXH070	Buried APZ	3	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103288	Shovel test pit	STP N108 E086 LEV09 80-90cm MXH070		MXH070	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
103305	Shovel test pit	STP N108 E086 LEV09 80-90cm MXH070		MXH070	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
103309	Shovel test pit	STP N108 E086 LEV09 80-90cm MXH070		MXH070	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	Annular-black
103310	Shovel test pit	STP N108 E086 LEV09 80-90cm MXH070		MXH070	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-green
103289	Shovel test pit	STP N108 E086 LEV09 80-90cm MXH070		MXH070	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-orange
103294	Shovel test pit	STP N108 E086 LEV09 80-90cm MXH070		MXH070	Buried APZ	4	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103311	Shovel test pit	STP N108 E086 LEV09 80-90cm MXH070		MXH070	Buried APZ	1	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	service	
103292	Shovel test pit	STP N108 E086 LEV09 80-90cm MXH070		MXH070	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	Nottingham-type	food/beverage	service	
103308	Shovel test pit	STP N108 E086 LEV09 80-90cm MXH070		MXH070	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
103301	Shovel test pit	STP N108 E086 LEV09 80-90cm MXH070		MXH070	Buried APZ	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103307	Shovel test pit	STP N108 E086 LEV09 80-90cm MXH070		MXH070	Buried APZ	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103303	Shovel test pit	STP N108 E086 LEV09 80-90cm MXH070		MXH070	Buried APZ	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
103293	Shovel test pit	STP N108 E086 LEV09 80-90cm MXH070		MXH070	Buried APZ	4	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
103286	Shovel test pit	STP N108 E086 LEV09 80-90cm MXH070		MXH070	Buried APZ	1	bottle, vial	whole/intact	Glass	mold blown	contact, 2+ with separate base	medical/chemical	storage	-Aqua-circular-patent
103302	Shovel test pit	STP N108 E086 LEV09 80-90cm MXH070		MXH070	Buried APZ	1	nail, wire	whole/intact	Metal	ferrous	machine made	architecture	general construction	
103287	Shovel test pit	STP N108 E086 LEV09 80-90cm MXH070		MXH070	Buried APZ	2	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
103290	Shovel test pit	STP N108 E086 LEV09 80-90cm MXH070		MXH070	Buried APZ	2	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
103944	Shovel test pit	STP N108 E089 LEV10 90-100cm MXH059		MXH059	B1	1	pipe, bowl	bowl	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
103951	Shovel test pit	STP N108 E089 LEV10 90-100cm MXH059		MXH059	B1	3	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
103948	Shovel test pit	STP N108 E089 LEV10 90-100cm MXH059		MXH059	B1	1	teapot	spout	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103949	Shovel test pit	STP N108 E089 LEV10 90-100cm MXH059		MXH059	B1	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103950	Shovel test pit	STP N108 E089 LEV10 90-100cm MXH059		MXH059	B1	1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103947	Shovel test pit	STP N108 E089 LEV10 90-100cm MXH059		MXH059	B1	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103945	Shovel test pit	STP N108 E089 LEV10 90-100cm MXH059		MXH059	B1	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
103952	Shovel test pit	STP N108 E089 LEV10 90-100cm MXH059		MXH059	B1	2	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
103953	Shovel test pit	STP N108 E089 LEV10 90-100cm MXH059		MXH059	B1	3	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
103946	Shovel test pit	STP N108 E089 LEV10 90-100cm MXH059		MXH059	B1	1	unidentified	fragment	Metal	lead	Not Assigned		0	Not Assigned
103582	Shovel test pit	STP N108 E089 STR02 LEV01 05-10cm MXH050		MXH050	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
103580	Shovel test pit	STP N108 E089 STR02 LEV01 05-10cm MXH050		MXH050	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103585	Shovel test pit	STP N108 E089 STR02 LEV01 05-10cm MXH050		MXH050	Surface/Developing A	3	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103583	Shovel test pit	STP N108 E089 STR02 LEV01 05-10cm MXH050		MXH050	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103584	Shovel test pit	STP N108 E089 STR02 LEV01 05-10cm MXH050		MXH050	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103579	Shovel test pit	STP N108 E089 STR02 LEV01 05-10cm MXH050		MXH050	Surface/Developing A	1	button, four hole	whole/intact	Ceramic	Porcelain	Plain	personal	fastener	
103586	Shovel test pit	STP N108 E089 STR02 LEV01 05-10cm MXH050		MXH050	Surface/Developing A	2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103581	Shovel test pit	STP N108 E089 STR02 LEV01 05-10cm MXH050		MXH050	Surface/Developing A	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
103587	Shovel test pit	STP N108 E089 STR02 LEV01 05-10cm MXH050		MXH050	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
103588	Shovel test pit	STP N108 E089 STR02 LEV01 05-10cm MXH050		MXH050	Surface/Developing A	1	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
103939	Shovel test pit	STP N108 E089 STR02 LEV02 10-20cm MXH051		MXH051	Fill	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
103943	Shovel test pit	STP N108 E089 STR02 LEV02 10-20cm MXH051		MXH051	Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	slip-red
103942	Shovel test pit	STP N108 E089 STR02 LEV02 10-20cm MXH051		MXH051	Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	
103941	Shovel test pit	STP N108 E089 STR02 LEV02 10-20cm MXH051		MXH051	Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103940	Shovel test pit	STP N108 E089 STR02 LEV02 10-20cm MXH051		MXH051	Fill	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
104024	Shovel test pit	STP N108 E089 STR02 LEV03 20-30cm MXH052		MXH052	Fill	2	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104021	Shovel test pit	STP N108 E089 STR02 LEV03 20-30cm MXH052		MXH052	Fill	1	teapot	spout	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104025	Shovel test pit	STP N108 E089 STR02 LEV03 20-30cm MXH052		MXH052	Fill	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
104023	Shovel test pit	STP N108 E089 STR02 LEV03 20-30cm MXH052		MXH052	Fill	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
104022	Shovel test pit	STP N108 E089 STR02 LEV03 20-30cm MXH052		MXH052	Fill	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
104026	Shovel test pit	STP N108 E089 STR02 LEV03 20-30cm MXH052		MXH052	Fill	3	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
104027	Shovel test pit	STP N108 E089 STR02 LEV03 20-30cm MXH052		MXH052	Fill	1	nail wrought	whole/intact	Metal	ferrous	wrought	architecture	general construction	
103647	Shovel test pit	STP N108 E089 STR02 LEV04 30-40cm MXH053		MXH053	Fill	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
103648	Shovel test pit	STP N108 E089 STR02 LEV04 30-40cm MXH053		MXH053	Fill	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
103649	Shovel test pit	STP N108 E089 STR02 LEV04 30-40cm MXH053		MXH053	Fill	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103643	Shovel test pit	STP N108 E089 STR02 LEV04 30-40cm MXH053		MXH053	Fill	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
103642	Shovel test pit	STP N108 E089 STR02 LEV04 30-40cm MXH053		MXH053	Fill	4	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103650	Shovel test pit	STP N108 E089 STR02 LEV04 30-40cm MXH053		MXH053	Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	Annular-green
103641	Shovel test pit	STP N108 E089 STR02 LEV04 30-40cm MXH053		MXH053	Fill	1	vessel, flat	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103645	Shovel test pit	STP N108 E089 STR02 LEV04 30-40cm MXH053		MXH053	Fill	4	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103652	Shovel test pit	STP N108 E089 STR02 LEV04 30-40cm MXH053		MXH053	Fill	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103651	Shovel test pit	STP N108 E089 STR02 LEV04 30-40cm MXH053		MXH053	Fill	1	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
103640	Shovel test pit	STP N108 E089 STR02 LEV04 30-40cm MXH053		MXH053	Fill	1	vessel, hollow	body	Ceramic	Porcelain	English porcelain	food/beverage	service	painted-red
103639	Shovel test pit	STP N108 E089 STR02 LEV04 30-40cm MXH053		MXH053	Fill	1	wood, indeterminate	fragment	Flora	wood	unidentified		0	Not Assigned
103638	Shovel test pit	STP N108 E089 STR02 LEV04 30-40cm MXH053		MXH053	Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (light olive)
103644	Shovel test pit	STP N108 E089 STR02 LEV04 30-40cm MXH053		MXH053	Fill	10	unidentified	fragment	Metal	ferrous	unidentified		0	Not Assigned
103646	Shovel test pit	STP N108 E089 STR02 LEV04 30-40cm MXH053		MXH053	Fill	4	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
103727	Shovel test pit	STP N108 E089 STR02 LEV05 40-50cm MXH054		MXH054	Fill	3	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103728	Shovel test pit	STP N108 E089 STR02 LEV05 40-50cm MXH054		MXH054	Fill	1	vessel, flat	body	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
103730	Shovel test pit	STP N108 E089 STR02 LEV05 40-50cm MXH054		MXH054	Fill	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103729	Shovel test pit	STP N108 E089 STR02 LEV05 40-50cm MXH054		MXH054	Fill	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103726	Shovel test pit	STP N108 E089 STR02 LEV05 40-50cm MXH054		MXH054	Fill	2	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
103755	Shovel test pit	STP N108 E089 STR03 LEV06 50-60cm MXH055		MXH055	Buried APZ	5	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
103759	Shovel test pit	STP N108 E089 STR03 LEV06 50-60cm MXH055		MXH055	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
103757	Shovel test pit	STP N108 E089 STR03 LEV06 50-60cm MXH055		MXH055	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103764	Shovel test pit	STP N108 E089 STR03 LEV06 50-60cm MXH055		MXH055	Buried APZ	1	vessel, flat	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103750	Shovel test pit	STP N108 E089 STR03 LEV06 50-60cm MXH055		MXH055	Buried APZ	14	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103765	Shovel test pit	STP N108 E089 STR03 LEV06 50-60cm MXH055		MXH055	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	Annular-brown
103753	Shovel test pit	STP N108 E089 STR03 LEV06 50-60cm MXH055		MXH055	Buried APZ	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
103754	Shovel test pit	STP N108 E089 STR03 LEV06 50-60cm MXH055		MXH055	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
103751	Shovel test pit	STP N108 E089 STR03 LEV06 50-60cm MXH055		MXH055	Buried APZ	4	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103757	Shovel test pit	STP N108 E089 STR03 LEV06 50-60cm MXH055		MXH055	Buried APZ	15	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
103758	Shovel test pit	STP N108 E089 STR03 LEV06 50-60cm MXH055		MXH055	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103749	Shovel test pit	STP N108 E089 STR03 LEV06 50-60cm MXH055		MXH055	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	American blue and gray	food/beverage	storage	slip-orange
103760	Shovel test pit	STP N108 E089 STR03 LEV06 50-60cm MXH055		MXH055	Buried APZ	1	vessel, flat	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
103763	Shovel test pit	STP N108 E089 STR03 LEV06 50-60cm MXH055		MXH055	Buried APZ	1	vessel, hollow	body	Ceramic	Tin Glazed	unidentified	food/beverage	service	
103768	Shovel test pit	STP N108 E089 STR03 LEV06 50-60cm MXH055		MXH055	Buried APZ	2	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103762	Shovel test pit	STP N108 E089 STR03 LEV06 50-60cm MXH055		MXH055	Buried APZ	1	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
103766	Shovel test pit	STP N108 E089 STR03 LEV06 50-60cm MXH055		MXH055	Buried APZ	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
103752	Shovel test pit	STP N108 E089 STR03 LEV06 50-60cm MXH055		MXH055	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
103761	Shovel test pit	STP N108 E089 STR03 LEV06 50-60cm MXH055		MXH055	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Milk glass/Opaque white
103756	Shovel test pit	STP N108 E089 STR03 LEV06 50-60cm MXH055		MXH055	Buried APZ	2	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
103889	Shovel test pit	STP N108 E089 STR03 LEV07 60-70cm MXH056		MXH056	Buried APZ	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
103877	Shovel test pit	STP N108 E089 STR03 LEV07 60-70cm MXH056		MXH056	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103882	Shovel test pit	STP N108 E089 STR03 LEV07 60-70cm MXH056		MXH056	Buried APZ	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103876	Shovel test pit	STP N108 E089 STR03 LEV07 60-70cm MXH056		MXH056	Buried APZ	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
103891	Shovel test pit	STP N108 E089 STR03 LEV07 60-70cm MXH056		MXH056	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire, slipped	food/beverage	service	
103888	Shovel test pit	STP N108 E089 STR03 LEV07 60-70cm MXH056		MXH056	Buried APZ	10	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103890	Shovel test pit	STP N108 E089 STR03 LEV07 60-70cm MXH056		MXH056	Buried APZ	2	vessel, hollow	handle	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103883	Shovel test pit	STP N108 E089 STR03 LEV07 60-70cm MXH056		MXH056	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	slip-orange
103881	Shovel test pit	STP N108 E089 STR03 LEV07 60-70cm MXH056		MXH056	Buried APZ	7	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103892	Shovel test pit	STP N108 E089 STR03 LEV07 60-70cm MXH056		MXH056	Buried APZ	2	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103875	Shovel test pit	STP N108 E089 STR03 LEV07 60-70cm MXH056		MXH056	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-brown
103878	Shovel test pit	STP N108 E089 STR03 LEV07 60-70cm MXH056		MXH056	Buried APZ	14	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103884	Shovel test pit	STP N108 E089 STR03 LEV07 60-70cm MXH056		MXH056	Buried APZ	1	vessel, flat	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
103874	Shovel test pit	STP N108 E089 STR03 LEV07 60-70cm MXH056		MXH056	Buried APZ	1	vessel, flat	rim	Ceramic	Tin Glazed	unidentified	food/beverage	service	
103885	Shovel test pit	STP N108 E089 STR03 LEV07 60-70cm MXH056		MXH056	Buried APZ	4	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103879	Shovel test pit	STP N108 E089 STR03 LEV07 60-70cm MXH056		MXH056	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
103880	Shovel test pit	STP N108 E089 STR03 LEV07 60-70cm MXH056		MXH056	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
103887	Shovel test pit	STP N108 E089 STR03 LEV07 60-70cm MXH056		MXH056	Buried APZ	3	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
103886	Shovel test pit	STP N108 E089 STR03 LEV07 60-70cm MXH056		MXH056	Buried APZ	1	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
103381	Shovel test pit	STP N108 E089 STR03 LEV08 70-80cm MXH057		MXH057	Buried APZ	2	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
103405	Shovel test pit	STP N108 E089 STR03 LEV08 70-80cm MXH057		MXH057	Buried APZ	2	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
103407	Shovel test pit	STP N108 E089 STR03 LEV08 70-80cm MXH057		MXH057	Buried APZ	3	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
103402	Shovel test pit	STP N108 E089 STR03 LEV08 70-80cm MXH057		MXH057	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
103397	Shovel test pit	STP N108 E089 STR03 LEV08 70-80cm MXH057		MXH057	Buried APZ	3	vessel, hollow	base	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103406	Shovel test pit	STP N108 E089 STR03 LEV08 70-80cm MXH057		MXH057	Buried APZ	12	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
103388	Shovel test pit	STP N108 E089 STR03 LEV08 70-80cm MXH057		MXH057	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire, slipped	food/beverage	service	
103391	Shovel test pit	STP N108 E089 STR03 LEV08 70-80cm MXH057		MXH057	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103400	Shovel test pit	STP N108 E089 STR03 LEV08 70-80cm MXH057		MXH057	Buried APZ	19	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103396	Shovel test pit	STP N108 E089 STR03 LEV08 70-80cm MXH057		MXH057	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-yellow
103393	Shovel test pit	STP N108 E089 STR03 LEV08 70-80cm MXH057		MXH057	Buried APZ	4	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103385	Shovel test pit	STP N108 E089 STR03 LEV08 70-80cm MXH057		MXH057	Buried APZ	1	vessel, flat	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103382	Shovel test pit	STP N108 E089 STR03 LEV08 70-80cm MXH057		MXH057	Buried APZ	10	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103399	Shovel test pit	STP N108 E089 STR03 LEV08 70-80cm MXH057		MXH057	Buried APZ	1	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
103389	Shovel test pit	STP N108 E089 STR03 LEV08 70-80cm MXH057		MXH057	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	buff salt glazed	food/beverage	storage	
103383	Shovel test pit	STP N108 E089 STR03 LEV08 70-80cm MXH057		MXH057	Buried APZ	1	vessel, flat	base	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
103394	Shovel test pit	STP N108 E089 STR03 LEV08 70-80cm MXH057		MXH057	Buried APZ	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103387	Shovel test pit	STP N108 E089 STR03 LEV08 70-80cm MXH057		MXH057	Buried APZ	1	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
103392	Shovel test pit	STP N108 E089 STR03 LEV08 70-80cm MXH057		MXH057	Buried APZ	1	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
103403	Shovel test pit	STP N108 E089 STR03 LEV08 70-80cm MXH057		MXH057	Buried APZ	3	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103390	Shovel test pit	STP N108 E089 STR03 LEV08 70-80cm MXH057		MXH057	Buried APZ	1	drinking glass, stemmed	rim	Glass	indeterminate	indeterminate	food/beverage	service	-Clear
103398	Shovel test pit	STP N108 E089 STR03 LEV08 70-80cm MXH057		MXH057	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Amber
103386	Shovel test pit	STP N108 E089 STR03 LEV08 70-80cm MXH057		MXH057	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
103384	Shovel test pit	STP N108 E089 STR03 LEV08 70-80cm MXH057		MXH057	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
103408	Shovel test pit	STP N108 E089 STR03 LEV08 70-80cm MXH057		MXH057	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
103404	Shovel test pit	STP N108 E089 STR03 LEV08 70-80cm MXH057		MXH057	Buried APZ	1	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
103401	Shovel test pit	STP N108 E089 STR03 LEV08 70-80cm MXH057		MXH057	Buried APZ	3	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
103409	Shovel test pit	STP N108 E089 STR03 LEV08 70-80cm MXH057		MXH057	Buried APZ	1	stone, worked	fragment	Stone	Felsite	blue-grey	personal	other personal possession	
103395	Shovel test pit	STP N108 E089 STR03 LEV08 70-80cm MXH057		MXH057	Buried APZ	1	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
103442	Shovel test pit	STP N108 E089 STR03 LEV09 80-90cm MXH058		MXH058	Buried APZ	3	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
103444	Shovel test pit	STP N108 E089 STR03 LEV09 80-90cm MXH058		MXH058	Buried APZ	5	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
103437	Shovel test pit	STP N108 E089 STR03 LEV09 80-90cm MXH058		MXH058	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103449	Shovel test pit	STP N108 E089 STR03 LEV09 80-90cm MXH058		MXH058	Buried APZ	6	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103448	Shovel test pit	STP N108 E089 STR03 LEV09 80-90cm MXH058		MXH058	Buried APZ	8	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
103443	Shovel test pit	STP N108 E089 STR03 LEV09 80-90cm MXH058		MXH058	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire, slipped	food/beverage	service	
103440	Shovel test pit	STP N108 E089 STR03 LEV09 80-90cm MXH058		MXH058	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103450	Shovel test pit	STP N108 E089 STR03 LEV09 80-90cm MXH058		MXH058	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103452	Shovel test pit	STP N108 E089 STR03 LEV09 80-90cm MXH058		MXH058	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103439	Shovel test pit	STP N108 E089 STR03 LEV09 80-90cm MXH058		MXH058	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103453	Shovel test pit	STP N108 E089 STR03 LEV09 80-90cm MXH058		MXH058	Buried APZ	13	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103455	Shovel test pit	STP N108 E089 STR03 LEV09 80-90cm MXH058		MXH058	Buried APZ	1	vessel, hollow	body	Ceramic	Tin Glazed	unidentified	food/beverage	service	
103451	Shovel test pit	STP N108 E089 STR03 LEV09 80-90cm MXH058		MXH058	Buried APZ	2	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103454	Shovel test pit	STP N108 E089 STR03 LEV09 80-90cm MXH058		MXH058	Buried APZ	1	tooth	fragment	Fauna	enamel/bone	tooth	food/beverage	acquisition	
103445	Shovel test pit	STP N108 E089 STR03 LEV09 80-90cm MXH058		MXH058	Buried APZ	2	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
103447	Shovel test pit	STP N108 E089 STR03 LEV09 80-90cm MXH058		MXH058	Buried APZ	4	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103446	Shovel test pit	STP N108 E089 STR03 LEV09 80-90cm MXH058		MXH058	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
103456	Shovel test pit	STP N108 E089 STR03 LEV09 80-90cm MXH058		MXH058	Buried APZ	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
103438	Shovel test pit	STP N108 E089 STR03 LEV09 80-90cm MXH058		MXH058	Buried APZ	11	nail, indeterminate	fragment	Metal	ferrous	slag	architecture	general construction	
103441	Shovel test pit	STP N108 E089 STR03 LEV09 80-90cm MXH058		MXH058	Buried APZ	1	unidentified	fragment	Metal	lead	Not Assigned	0	Not Assigned	
104082	Shovel test pit	STP N108 E089 STR04-B LEV11 100-110cm MXH060		MXH060	B1	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
104086	Shovel test pit	STP N108 E089 STR04-B LEV11 100-110cm MXH060		MXH060	B1	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104089	Shovel test pit	STP N108 E089 STR04-B LEV11 100-110cm MXH060		MXH060	B1	1	vessel, hollow	body	Ceramic	Earthenware, refined	Whiteware, undecorated	food/beverage	service	
104084	Shovel test pit	STP N108 E089 STR04-B LEV11 100-110cm MXH060		MXH060	B1	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
104092	Shovel test pit	STP N108 E089 STR04-B LEV11 100-110cm MXH060		MXH060	B1	2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
104083	Shovel test pit	STP N108 E089 STR04-B LEV11 100-110cm MXH060		MXH060	B1	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
104088	Shovel test pit	STP N108 E089 STR04-B LEV11 100-110cm MXH060		MXH060	B1	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104087	Shovel test pit	STP N108 E089 STR04-B LEV11 100-110cm MXH060		MXH060	B1	1	nail wrought	whole/intact	Metal	ferrous	wrought	architecture	general construction	
104091	Shovel test pit	STP N108 E089 STR04-B LEV11 100-110cm MXH060		MXH060	B1	1	unidentified	fragment	Metal	lead	Not Assigned	0	Not Assigned	
104090	Shovel test pit	STP N108 E089 STR04-B LEV11 100-110cm MXH060		MXH060	B1	1	paint	fragment	Synthetic	synthetic	Not Assigned	architecture	hardware	
104085	Shovel test pit	STP N108 E089 STR04-B LEV11 100-110cm MXH060		MXH060	B1	1	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
104017	Shovel test pit	STP N108 E089 STR04-B LEV12 110-120cm MXH061		MXH061	B1	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
104016	Shovel test pit	STP N108 E089 STR04-B LEV12 110-120cm MXH061		MXH061	B1	2	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104012	Shovel test pit	STP N108 E089 STR04-B LEV12 110-120cm MXH061		MXH061	B1	1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104013	Shovel test pit	STP N108 E089 STR04-B LEV12 110-120cm MXH061		MXH061	B1	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104011	Shovel test pit	STP N108 E089 STR04-B LEV12 110-120cm MXH061		MXH061	B1	1	vessel, hollow	body	Ceramic	Earthenware, refined	Whiteware, transfer printed	food/beverage	service	transfer print-brown
104009	Shovel test pit	STP N108 E089 STR04-B LEV12 110-120cm MXH061		MXH061	B1	1	button, one piece	near intact	Composite Artifact	composite artifact	composite artifact	personal	fastener	
104015	Shovel test pit	STP N108 E089 STR04-B LEV12 110-120cm MXH061		MXH061	B1	1	bone	fragment	Fauna	bone	bird	food/beverage	acquisition	
104008	Shovel test pit	STP N108 E089 STR04-B LEV12 110-120cm MXH061		MXH061	B1	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
104019	Shovel test pit	STP N108 E089 STR04-B LEV12 110-120cm MXH061		MXH061	B1	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
104018	Shovel test pit	STP N108 E089 STR04-B LEV12 110-120cm MXH061		MXH061	B1	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
104014	Shovel test pit	STP N108 E089 STR04-B LEV12 110-120cm MXH061		MXH061	B1	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (bright 7-up)
104010	Shovel test pit	STP N108 E089 STR04-B LEV12 110-120cm MXH061		MXH061	B1	8	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
103676	Shovel test pit	STP N108 E102 LEV07 60-70cm MXH033		MXH033	Buried APZ	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
103691	Shovel test pit	STP N108 E102 LEV07 60-70cm MXH033		MXH033	Buried APZ	2	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
103679	Shovel test pit	STP N108 E102 LEV07 60-70cm MXH033		MXH033	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103683	Shovel test pit	STP N108 E102 LEV07 60-70cm MXH033		MXH033	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
103693	Shovel test pit	STP N108 E102 LEV07 60-70cm MXH033		MXH033	Buried APZ	2	vessel, hollow	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103698	Shovel test pit	STP N108 E102 LEV07 60-70cm MXH033		MXH033	Buried APZ	9	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103685	Shovel test pit	STP N108 E102 LEV07 60-70cm MXH033		MXH033	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	Annular-brown
103690	Shovel test pit	STP N108 E102 LEV07 60-70cm MXH033		MXH033	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-green
103695	Shovel test pit	STP N108 E102 LEV07 60-70cm MXH033		MXH033	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
103682	Shovel test pit	STP N108 E102 LEV07 60-70cm MXH033		MXH033	Buried APZ	2	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103684	Shovel test pit	STP N108 E102 LEV07 60-70cm MXH033		MXH033	Buried APZ	5	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103692	Shovel test pit	STP N108 E102 LEV07 60-70cm MXH033		MXH033	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103680	Shovel test pit	STP N108 E102 LEV07 60-70cm MXH033		MXH033	Buried APZ	9	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103696	Shovel test pit	STP N108 E102 LEV07 60-70cm MXH033		MXH033	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103694	Shovel test pit	STP N108 E102 LEV07 60-70cm MXH033		MXH033	Buried APZ	1	vessel, hollow	rim	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
103678	Shovel test pit	STP N108 E102 LEV07 60-70cm MXH033		MXH033	Buried APZ	1	vessel, hollow	body	Ceramic	Porcelain	Decorated	food/beverage	service	painted-orange
103681	Shovel test pit	STP N108 E102 LEV07 60-70cm MXH033		MXH033	Buried APZ	1	vessel, hollow	handle	Ceramic	Porcelain	Plain	food/beverage	service	
103689	Shovel test pit	STP N108 E102 LEV07 60-70cm MXH033		MXH033	Buried APZ	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103687	Shovel test pit	STP N108 E102 LEV07 60-70cm MXH033		MXH033	Buried APZ	4	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103686	Shovel test pit	STP N108 E102 LEV07 60-70cm MXH033		MXH033	Buried APZ	1	drinking glass, tumbler	rim	Glass	indeterminate	indeterminate	food/beverage	service	-Clear
103677	Shovel test pit	STP N108 E102 LEV07 60-70cm MXH033		MXH033	Buried APZ	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
103697	Shovel test pit	STP N108 E102 LEV07 60-70cm MXH033		MXH033	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
103688	Shovel test pit	STP N108 E102 LEV07 60-70cm MXH033		MXH033	Buried APZ	1	lamp, glass fragment	fragment	Glass	indeterminate	indeterminate	heating, plumbing, electric	device	-Clear
103675	Shovel test pit	STP N108 E102 LEV07 60-70cm MXH033		MXH033	Buried APZ	2	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
103556	Shovel test pit	STP N109 E102 LEV01 00-10cm MXH027		MXH027	Surface/Developing A	3	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
103554	Shovel test pit	STP N109 E102 LEV01 00-10cm MXH027		MXH027	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
103549	Shovel test pit	STP N109 E102 LEV01 00-10cm MXH027		MXH027	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103550	Shovel test pit	STP N109 E102 LEV01 00-10cm MXH027		MXH027	Surface/Developing A	1	bottle, indeterminate	base	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
103553	Shovel test pit	STP N109 E102 LEV01 00-10cm MXH027		MXH027	Surface/Developing A	1	bottle, indeterminate	lip	Glass	Machine made	machine made	food/beverage	storage	-Clear-External threads
103557	Shovel test pit	STP N109 E102 LEV01 00-10cm MXH027		MXH027	Surface/Developing A	1	bottle, indeterminate	base	Glass	mold blown	Not Assigned	food/beverage	storage	-Clear
103551	Shovel test pit	STP N109 E102 LEV01 00-10cm MXH027		MXH027	Surface/Developing A	1	marble	whole/intact	Glass	molded	molded	recreation/leisure	toys	-Blue-cobalt
103544	Shovel test pit	STP N109 E102 LEV01 00-10cm MXH027		MXH027	Surface/Developing A	1	cap, screw top	whole/intact	Metal	Aluminium	aluminium		Not Assigned	
103545	Shovel test pit	STP N109 E102 LEV01 00-10cm MXH027		MXH027	Surface/Developing A	1	unidentified	fragment	Metal	copper alloy	copper alloy	0	Not Assigned	
103542	Shovel test pit	STP N109 E102 LEV01 00-10cm MXH027		MXH027	Surface/Developing A	1	key, door	whole/intact	Metal	ferrous	cast	architecture	hardware	
103543	Shovel test pit	STP N109 E102 LEV01 00-10cm MXH027		MXH027	Surface/Developing A	1	nail, wire	whole/intact	Metal	ferrous	machine made	architecture	general construction	
103555	Shovel test pit	STP N109 E102 LEV01 00-10cm MXH027		MXH027	Surface/Developing A	2	plaster, plain	fragment	Mineral	composite	plaster	architecture	general construction	
103552	Shovel test pit	STP N109 E102 LEV01 00-10cm MXH027		MXH027	Surface/Developing A	1	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
103547	Shovel test pit	STP N109 E102 LEV01 00-10cm MXH027		MXH027	Surface/Developing A	1	cap, screw top	fragment	Synthetic	synthetic	plastic	food/beverage	storage	
103548	Shovel test pit	STP N109 E102 LEV01 00-10cm MXH027		MXH027	Surface/Developing A	1	pipe, plumbing/gas	fragment	Synthetic	synthetic	plastic	heating, plumbing, electric	device	
103546	Shovel test pit	STP N109 E102 LEV01 00-10cm MXH027		MXH027	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	styrofoam	0	Not Assigned	
104064	Shovel test pit	STP N109 E102 LEV02 10-20cm MXH028		MXH028	Surface/Developing A	2	vessel, flat	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104056	Shovel test pit	STP N109 E102 LEV02 10-20cm MXH028		MXH028	Surface/Developing A	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
104058	Shovel test pit	STP N109 E102 LEV02 10-20cm MXH028		MXH028	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
104057	Shovel test pit	STP N109 E102 LEV02 10-20cm MXH028		MXH028	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
104060	Shovel test pit	STP N109 E102 LEV02 10-20cm MXH028		MXH028	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104061	Shovel test pit	STP N109 E102 LEV02 10-20cm MXH028		MXH028	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (bright 7-up)
104059	Shovel test pit	STP N109 E102 LEV02 10-20cm MXH028		MXH028	Surface/Developing A	1	bottle, indeterminate	base	Glass	Machine made	machine made	food/beverage	storage	-Clear-circular-machine made (1903)
104062	Shovel test pit	STP N109 E102 LEV02 10-20cm MXH028		MXH028	Surface/Developing A	2	nail, wire	whole/intact	Metal	ferrous	machine made	architecture	general construction	
104063	Shovel test pit	STP N109 E102 LEV02 10-20cm MXH028		MXH028	Surface/Developing A	1	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
103869	Shovel test pit	STP N109 E102 LEV03 20-30cm MXH029		MXH029	Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
103871	Shovel test pit	STP N109 E102 LEV03 20-30cm MXH029		MXH029	Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103870	Shovel test pit	STP N109 E102 LEV03 20-30cm MXH029		MXH029	Fill	8	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103873	Shovel test pit	STP N109 E102 LEV03 20-30cm MXH029		MXH029	Fill	1	vessel, flat	rim	Ceramic	Earthenware, refined	Whiteware, unidentified	food/beverage	service	
103858	Shovel test pit	STP N109 E102 LEV03 20-30cm MXH029		MXH029	Fill	1	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
103866	Shovel test pit	STP N109 E102 LEV03 20-30cm MXH029		MXH029	Fill	1	button, four hole	whole/intact	Ceramic	Porcelain	Plain	personal	fastener	
103865	Shovel test pit	STP N109 E102 LEV03 20-30cm MXH029		MXH029	Fill	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103859	Shovel test pit	STP N109 E102 LEV03 20-30cm MXH029		MXH029	Fill	1	charcoal	fragment	Flora	wood	charcoal	heating, plumbing, electric	fuel	
103862	Shovel test pit	STP N109 E102 LEV03 20-30cm MXH029		MXH029	Fill	3	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103863	Shovel test pit	STP N109 E102 LEV03 20-30cm MXH029		MXH029	Fill	3	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103864	Shovel test pit	STP N109 E102 LEV03 20-30cm MXH029		MXH029	Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Amber
103868	Shovel test pit	STP N109 E102 LEV03 20-30cm MXH029		MXH029	Fill	1	bottle, indeterminate	lip	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
103861	Shovel test pit	STP N109 E102 LEV03 20-30cm MXH029		MXH029	Fill	1	bottle, indeterminate	body	Glass	molded	molded	food/beverage	storage	-Clear
103867	Shovel test pit	STP N109 E102 LEV03 20-30cm MXH029		MXH029	Fill	2	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
103872	Shovel test pit	STP N109 E102 LEV03 20-30cm MXH029		MXH029	Fill	4	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
103860	Shovel test pit	STP N109 E102 LEV03 20-30cm MXH029		MXH029	Fill	1	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
103817	Shovel test pit	STP N109 E102 LEV04 30-40cm MXH030		MXH030	Fill	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
103819	Shovel test pit	STP N109 E102 LEV04 30-40cm MXH030		MXH030	Fill	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
103811	Shovel test pit	STP N109 E102 LEV04 30-40cm MXH030		MXH030	Fill	1	vessel, hollow	base	Ceramic	Earthenware, coarse	Manganese Mottled	food/beverage	service	
103815	Shovel test pit	STP N109 E102 LEV04 30-40cm MXH030		MXH030	Fill	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Manganese Mottled	food/beverage	service	
103804	Shovel test pit	STP N109 E102 LEV04 30-40cm MXH030		MXH030	Fill	1	vessel, hollow	foot	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103805	Shovel test pit	STP N109 E102 LEV04 30-40cm MXH030		MXH030	Fill	1	vessel, flat	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103816	Shovel test pit	STP N109 E102 LEV04 30-40cm MXH030		MXH030	Fill	3	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103814	Shovel test pit	STP N109 E102 LEV04 30-40cm MXH030		MXH030	Fill	2	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103803	Shovel test pit	STP N109 E102 LEV04 30-40cm MXH030		MXH030	Fill	4	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103806	Shovel test pit	STP N109 E102 LEV04 30-40cm MXH030		MXH030	Fill	1	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
103813	Shovel test pit	STP N109 E102 LEV04 30-40cm MXH030		MXH030	Fill	2	vessel, hollow	body	Ceramic	Stoneware	Westerwald	food/beverage	service	
103812	Shovel test pit	STP N109 E102 LEV04 30-40cm MXH030		MXH030	Fill	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
103818	Shovel test pit	STP N109 E102 LEV04 30-40cm MXH030		MXH030	Fill	2	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103809	Shovel test pit	STP N109 E102 LEV04 30-40cm MXH030		MXH030	Fill	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
103808	Shovel test pit	STP N109 E102 LEV04 30-40cm MXH030		MXH030	Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
103820	Shovel test pit	STP N109 E102 LEV04 30-40cm MXH030		MXH030	Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (bright 7-up)
103801	Shovel test pit	STP N109 E102 LEV04 30-40cm MXH030		MXH030	Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Milk Glass/Blue
103807	Shovel test pit	STP N109 E102 LEV04 30-40cm MXH030		MXH030	Fill	1	lamp, glass fragment	fragment	Glass	indeterminate	indeterminate	heating, plumbing, electric	device	-Clear
103810	Shovel test pit	STP N109 E102 LEV04 30-40cm MXH030		MXH030	Fill	2	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
103802	Shovel test pit	STP N109 E102 LEV04 30-40cm MXH030		MXH030	Fill	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
103665	Shovel test pit	STP N109 E102 LEV05 40-50cm MXH031		MXH031	Fill	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-6/64
103672	Shovel test pit	STP N109 E102 LEV05 40-50cm MXH031		MXH031	Fill	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
103673	Shovel test pit	STP N109 E102 LEV05 40-50cm MXH031		MXH031	Fill	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103667	Shovel test pit	STP N109 E102 LEV05 40-50cm MXH031		MXH031	Fill	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
103659	Shovel test pit	STP N109 E102 LEV05 40-50cm MXH031		MXH031	Fill	13	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103661	Shovel test pit	STP N109 E102 LEV05 40-50cm MXH031		MXH031	Fill	2	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, transfer printed overglaze	food/beverage	service	transfer print-blue
103668	Shovel test pit	STP N109 E102 LEV05 40-50cm MXH031		MXH031	Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
103664	Shovel test pit	STP N109 E102 LEV05 40-50cm MXH031		MXH031	Fill	6	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103660	Shovel test pit	STP N109 E102 LEV05 40-50cm MXH031		MXH031	Fill	2	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
103674	Shovel test pit	STP N109 E102 LEV05 40-50cm MXH031		MXH031	Fill	1	vessel, hollow	rim	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
103662	Shovel test pit	STP N109 E102 LEV05 40-50cm MXH031		MXH031	Fill	2	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103670	Shovel test pit	STP N109 E102 LEV05 40-50cm MXH031		MXH031	Fill	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103669	Shovel test pit	STP N109 E102 LEV05 40-50cm MXH031		MXH031	Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
103666	Shovel test pit	STP N109 E102 LEV05 40-50cm MXH031		MXH031	Fill	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
103671	Shovel test pit	STP N109 E102 LEV05 40-50cm MXH031		MXH031	Fill	1	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
103663	Shovel test pit	STP N109 E102 LEV05 40-50cm MXH031		MXH031	Fill	1	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
103701	Shovel test pit	STP N109 E102 LEV06 50-60cm MXH032		MXH032	Buried APZ	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
103699	Shovel test pit	STP N109 E102 LEV06 50-60cm MXH032		MXH032	Buried APZ	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
103705	Shovel test pit	STP N109 E102 LEV06 50-60cm MXH032		MXH032	Buried APZ	5	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103721	Shovel test pit	STP N109 E102 LEV06 50-60cm MXH032		MXH032	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103711	Shovel test pit	STP N109 E102 LEV06 50-60cm MXH032		MXH032	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
103706	Shovel test pit	STP N109 E102 LEV06 50-60cm MXH032		MXH032	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103709	Shovel test pit	STP N109 E102 LEV06 50-60cm MXH032		MXH032	Buried APZ	7	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103717	Shovel test pit	STP N109 E102 LEV06 50-60cm MXH032		MXH032	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
103703	Shovel test pit	STP N109 E102 LEV06 50-60cm MXH032		MXH032	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-brown
103712	Shovel test pit	STP N109 E102 LEV06 50-60cm MXH032		MXH032	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103713	Shovel test pit	STP N109 E102 LEV06 50-60cm MXH032		MXH032	Buried APZ	3	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103702	Shovel test pit	STP N109 E102 LEV06 50-60cm MXH032		MXH032	Buried APZ	1	vessel, hollow	foot	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103704	Shovel test pit	STP N109 E102 LEV06 50-60cm MXH032		MXH032	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103714	Shovel test pit	STP N109 E102 LEV06 50-60cm MXH032		MXH032	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103715	Shovel test pit	STP N109 E102 LEV06 50-60cm MXH032		MXH032	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103700	Shovel test pit	STP N109 E102 LEV06 50-60cm MXH032		MXH032	Buried APZ	2	vessel, indeterminate	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
103719	Shovel test pit	STP N109 E102 LEV06 50-60cm MXH032		MXH032	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
103707	Shovel test pit	STP N109 E102 LEV06 50-60cm MXH032		MXH032	Buried APZ	2	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103722	Shovel test pit	STP N109 E102 LEV06 50-60cm MXH032		MXH032	Buried APZ	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103718	Shovel test pit	STP N109 E102 LEV06 50-60cm MXH032		MXH032	Buried APZ	3	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103708	Shovel test pit	STP N109 E102 LEV06 50-60cm MXH032		MXH032	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
103710	Shovel test pit	STP N109 E102 LEV06 50-60cm MXH032		MXH032	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
103720	Shovel test pit	STP N109 E102 LEV06 50-60cm MXH032		MXH032	Buried APZ	1	unidentified	fragment	Metal	ferrous	unidentified	0	Not Assigned	
103716	Shovel test pit	STP N109 E102 LEV06 50-60cm MXH032		MXH032	Buried APZ	4	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
103909	Shovel test pit	STP N109 E102 LEV08 70-80cm MXH034		MXH034	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
103916	Shovel test pit	STP N109 E102 LEV08 70-80cm MXH034		MXH034	Buried APZ	4	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103910	Shovel test pit	STP N109 E102 LEV08 70-80cm MXH034		MXH034	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	Annular-blue
103911	Shovel test pit	STP N109 E102 LEV08 70-80cm MXH034		MXH034	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	Annular-green
103917	Shovel test pit	STP N109 E102 LEV08 70-80cm MXH034		MXH034	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103915	Shovel test pit	STP N109 E102 LEV08 70-80cm MXH034		MXH034	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103919	Shovel test pit	STP N109 E102 LEV08 70-80cm MXH034		MXH034	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	Westerwald	food/beverage	service	
103914	Shovel test pit	STP N109 E102 LEV08 70-80cm MXH034		MXH034	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
103908	Shovel test pit	STP N109 E102 LEV08 70-80cm MXH034		MXH034	Buried APZ	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103918	Shovel test pit	STP N109 E102 LEV08 70-80cm MXH034		MXH034	Buried APZ	7	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103920	Shovel test pit	STP N109 E102 LEV08 70-80cm MXH034		MXH034	Buried APZ	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
103912	Shovel test pit	STP N109 E102 LEV08 70-80cm MXH034		MXH034	Buried APZ	3	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
103913	Shovel test pit	STP N109 E102 LEV08 70-80cm MXH034		MXH034	Buried APZ	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
103850	Shovel test pit	STP N109 E102 LEV09 80-90cm MXH035		MXH035	B1	3	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103854	Shovel test pit	STP N109 E102 LEV09 80-90cm MXH035		MXH035	B1	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
103857	Shovel test pit	STP N109 E102 LEV09 80-90cm MXH035		MXH035	B1	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103851	Shovel test pit	STP N109 E102 LEV09 80-90cm MXH035		MXH035	B1	7	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103856	Shovel test pit	STP N109 E102 LEV09 80-90cm MXH035		MXH035	B1	1	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	food/beverage	Not Assigned	
103853	Shovel test pit	STP N109 E102 LEV09 80-90cm MXH035		MXH035	B1	2	vessel, flat	body	Ceramic	Earthenware, refined	Whieldon (clouded or tortoiseshell)	food/beverage	service	
103849	Shovel test pit	STP N109 E102 LEV09 80-90cm MXH035		MXH035	B1	1	vessel, hollow	body	Ceramic	Stoneware	Westerwald	food/beverage	service	
103852	Shovel test pit	STP N109 E102 LEV09 80-90cm MXH035		MXH035	B1	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103855	Shovel test pit	STP N109 E102 LEV09 80-90cm MXH035		MXH035	B1	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
104103	Shovel test pit	STP N109 E102 LEV10 90-100cm MXH036		MXH036	B1	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
104108	Shovel test pit	STP N109 E102 LEV10 90-100cm MXH036		MXH036	B1	1	pipe, mouth piece	tip	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
104102	Shovel test pit	STP N109 E102 LEV10 90-100cm MXH036		MXH036	B1	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
104101	Shovel test pit	STP N109 E102 LEV10 90-100cm MXH036		MXH036	B1	4	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104099	Shovel test pit	STP N109 E102 LEV10 90-100cm MXH036		MXH036	B1	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104100	Shovel test pit	STP N109 E102 LEV10 90-100cm MXH036		MXH036	B1	1	vessel, flat	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
104105	Shovel test pit	STP N109 E102 LEV10 90-100cm MXH036		MXH036	B1	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
104104	Shovel test pit	STP N109 E102 LEV10 90-100cm MXH036		MXH036	B1	3	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
104106	Shovel test pit	STP N109 E102 LEV10 90-100cm MXH036		MXH036	B1	1	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
104107	Shovel test pit	STP N109 E102 LEV10 90-100cm MXH036		MXH036	B1	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
104081	Shovel test pit	STP N109 E102 LEV11 100-110cm MXH037		MXH037	B1	1	vessel, hollow	handle	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
104080	Shovel test pit	STP N109 E102 LEV11 100-110cm MXH037		MXH037	B1	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
104093	Shovel test pit	STP N109 E102 LEV12 110-120cm MXH038		MXH038	B1	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
103522	Shovel test pit	STP N110 E079 LEV01 00-10cm MXH122		MXH122	Surface/Developing A	11	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
103523	Shovel test pit	STP N110 E079 LEV01 00-10cm MXH122		MXH122	Surface/Developing A	4	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
103516	Shovel test pit	STP N110 E079 LEV01 00-10cm MXH122		MXH122	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103507	Shovel test pit	STP N110 E079 LEV01 00-10cm MXH122		MXH122	Surface/Developing A	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103515	Shovel test pit	STP N110 E079 LEV01 00-10cm MXH122		MXH122	Surface/Developing A	1	vessel, flat	body	Ceramic	Porcelain	Plain	food/beverage	service	
103517	Shovel test pit	STP N110 E079 LEV01 00-10cm MXH122		MXH122	Surface/Developing A	1	seed	fragment	Flora	seed/pit/nut	Not Assigned	food/beverage	acquisition	
103512	Shovel test pit	STP N110 E079 LEV01 00-10cm MXH122		MXH122	Surface/Developing A	6	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103509	Shovel test pit	STP N110 E079 LEV01 00-10cm MXH122		MXH122	Surface/Developing A	4	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
103514	Shovel test pit	STP N110 E079 LEV01 00-10cm MXH122		MXH122	Surface/Developing A	1	bottle, indeterminate	base	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
103521	Shovel test pit	STP N110 E079 LEV01 00-10cm MXH122		MXH122	Surface/Developing A	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
103513	Shovel test pit	STP N110 E079 LEV01 00-10cm MXH122		MXH122	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Milk glass/Opaque white
103506	Shovel test pit	STP N110 E079 LEV01 00-10cm MXH122		MXH122	Surface/Developing A	1	vessel, hollow	body	Glass	molded	molded	0	Not Assigned	-Clear
103519	Shovel test pit	STP N110 E079 LEV01 00-10cm MXH122		MXH122	Surface/Developing A	1	earring	fragment	Glass	molded	molded	personal	adornment	-Red
103505	Shovel test pit	STP N110 E079 LEV01 00-10cm MXH122		MXH122	Surface/Developing A	2	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
103503	Shovel test pit	STP N110 E079 LEV01 00-10cm MXH122		MXH122	Surface/Developing A	1	screw	whole/intact	Metal	ferrous	machine made	architecture	general construction	
103504	Shovel test pit	STP N110 E079 LEV01 00-10cm MXH122		MXH122	Surface/Developing A	1	nail, wire	whole/intact	Metal	ferrous	machine made	architecture	general construction	
103510	Shovel test pit	STP N110 E079 LEV01 00-10cm MXH122		MXH122	Surface/Developing A	1	cap, crown bottle	fragment	Metal	ferrous	machine made	food/beverage	storage	
103508	Shovel test pit	STP N110 E079 LEV01 00-10cm MXH122		MXH122	Surface/Developing A	2	button, one piece	near intact	Metal	ferrous	unidentified	personal	fastener	
103518	Shovel test pit	STP N110 E079 LEV01 00-10cm MXH122		MXH122	Surface/Developing A	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
103524	Shovel test pit	STP N110 E079 LEV01 00-10cm MXH122		MXH122	Surface/Developing A	1	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
103520	Shovel test pit	STP N110 E079 LEV01 00-10cm MXH122		MXH122	Surface/Developing A	1	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
103511	Shovel test pit	STP N110 E079 LEV01 00-10cm MXH122		MXH122	Surface/Developing A	1	unidentified	whole/intact	Synthetic	synthetic	plastic	personal	other personal possession	
103978	Shovel test pit	STP N110 E079 LEV02 10-20cm MXH123		MXH123	Rock Fill	6	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
103974	Shovel test pit	STP N110 E079 LEV02 10-20cm MXH123		MXH123	Rock Fill	2	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103975	Shovel test pit	STP N110 E079 LEV02 10-20cm MXH123		MXH123	Rock Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103981	Shovel test pit	STP N110 E079 LEV02 10-20cm MXH123		MXH123	Rock Fill	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103977	Shovel test pit	STP N110 E079 LEV02 10-20cm MXH123		MXH123	Rock Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Amber
103982	Shovel test pit	STP N110 E079 LEV02 10-20cm MXH123		MXH123	Rock Fill	3	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
103976	Shovel test pit	STP N110 E079 LEV02 10-20cm MXH123		MXH123	Rock Fill	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
103979	Shovel test pit	STP N110 E079 LEV02 10-20cm MXH123		MXH123	Rock Fill	1	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
103980	Shovel test pit	STP N110 E079 LEV02 10-20cm MXH123		MXH123	Rock Fill	1	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
103769	Shovel test pit	STP N110 E079 LEV03 20-30cm MXH124		MXH124	Fill	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
103770	Shovel test pit	STP N110 E079 LEV03 20-30cm MXH124		MXH124	Fill	2	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
103771	Shovel test pit	STP N110 E079 LEV03 20-30cm MXH124		MXH124	Fill	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
103775	Shovel test pit	STP N110 E079 LEV03 20-30cm MXH124		MXH124	Fill	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103774	Shovel test pit	STP N110 E079 LEV03 20-30cm MXH124		MXH124	Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103776	Shovel test pit	STP N110 E079 LEV03 20-30cm MXH124		MXH124	Fill	1	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
103773	Shovel test pit	STP N110 E079 LEV03 20-30cm MXH124		MXH124	Fill	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103777	Shovel test pit	STP N110 E079 LEV03 20-30cm MXH124		MXH124	Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
103772	Shovel test pit	STP N110 E079 LEV03 20-30cm MXH124		MXH124	Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
103778	Shovel test pit	STP N110 E079 LEV03 20-30cm MXH124		MXH124	Fill	1	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
104044	Shovel test pit	STP N110 E079 LEV04 30-40cm MXH125		MXH125	Fill	1	vessel, hollow	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104045	Shovel test pit	STP N110 E079 LEV04 30-40cm MXH125		MXH125	Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104047	Shovel test pit	STP N110 E079 LEV04 30-40cm MXH125		MXH125	Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104042	Shovel test pit	STP N110 E079 LEV04 30-40cm MXH125		MXH125	Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-blue
104046	Shovel test pit	STP N110 E079 LEV04 30-40cm MXH125		MXH125	Fill	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
104049	Shovel test pit	STP N110 E079 LEV04 30-40cm MXH125		MXH125	Fill	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104051	Shovel test pit	STP N110 E079 LEV04 30-40cm MXH125		MXH125	Fill	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
104043	Shovel test pit	STP N110 E079 LEV04 30-40cm MXH125		MXH125	Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104050	Shovel test pit	STP N110 E079 LEV04 30-40cm MXH125		MXH125	Fill	3	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
104048	Shovel test pit	STP N110 E079 LEV04 30-40cm MXH125		MXH125	Fill	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
104074	Shovel test pit	STP N110 E081 LEV01 00-10cm MXH022		MXH022	Surface/Developing A	1	vessel, flat	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	decal-purple/manganese
104069	Shovel test pit	STP N110 E081 LEV01 00-10cm MXH022		MXH022	Surface/Developing A	4	vessel, hollow	body	Ceramic	unidentified	Not Assigned	0	Not Assigned	
104072	Shovel test pit	STP N110 E081 LEV01 00-10cm MXH022		MXH022	Surface/Developing A	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
104075	Shovel test pit	STP N110 E081 LEV01 00-10cm MXH022		MXH022	Surface/Developing A	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
104073	Shovel test pit	STP N110 E081 LEV01 00-10cm MXH022		MXH022	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104070	Shovel test pit	STP N110 E081 LEV01 00-10cm MXH022		MXH022	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (bright 7-up)
104065	Shovel test pit	STP N110 E081 LEV01 00-10cm MXH022		MXH022	Surface/Developing A	1	token	whole/intact	Metal	copper alloy	copper alloy	religion/magic	religion/magic	
104066	Shovel test pit	STP N110 E081 LEV01 00-10cm MXH022		MXH022	Surface/Developing A	1	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
104068	Shovel test pit	STP N110 E081 LEV01 00-10cm MXH022		MXH022	Surface/Developing A	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
104067	Shovel test pit	STP N110 E081 LEV01 00-10cm MXH022		MXH022	Surface/Developing A	1	vessel, indeterminate	rim	Synthetic	synthetic	plastic	0	Not Assigned	
104071	Shovel test pit	STP N110 E081 LEV01 00-10cm MXH022		MXH022	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
103627	Shovel test pit	STP N110 E081 LEV02 10-20cm MXH023		MXH023	Utility Fill	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
103630	Shovel test pit	STP N110 E081 LEV02 10-20cm MXH023		MXH023	Utility Fill	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-6/64
103635	Shovel test pit	STP N110 E081 LEV02 10-20cm MXH023		MXH023	Utility Fill	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103634	Shovel test pit	STP N110 E081 LEV02 10-20cm MXH023		MXH023	Utility Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103631	Shovel test pit	STP N110 E081 LEV02 10-20cm MXH023		MXH023	Utility Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103629	Shovel test pit	STP N110 E081 LEV02 10-20cm MXH023		MXH023	Utility Fill	4	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103636	Shovel test pit	STP N110 E081 LEV02 10-20cm MXH023		MXH023	Utility Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103628	Shovel test pit	STP N110 E081 LEV02 10-20cm MXH023		MXH023	Utility Fill	2	vessel, hollow	base	Ceramic	Porcelain	Plain	food/beverage	service	
103637	Shovel test pit	STP N110 E081 LEV02 10-20cm MXH023		MXH023	Utility Fill	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103633	Shovel test pit	STP N110 E081 LEV02 10-20cm MXH023		MXH023	Utility Fill	1	ring	whole/intact	Metal	copper alloy	copper alloy	furniture/household equip.	hardware	
103632	Shovel test pit	STP N110 E081 LEV02 10-20cm MXH023		MXH023	Utility Fill	2	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
104096	Shovel test pit	STP N110 E081 LEV03 20-30cm MXH024		MXH024	Utility Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104098	Shovel test pit	STP N110 E081 LEV03 20-30cm MXH024		MXH024	Utility Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104097	Shovel test pit	STP N110 E081 LEV03 20-30cm MXH024		MXH024	Utility Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104094	Shovel test pit	STP N110 E081 LEV03 20-30cm MXH024		MXH024	Utility Fill	1	vessel, hollow	body	Ceramic	unidentified	unidentified		Not Assigned	
104095	Shovel test pit	STP N110 E081 LEV03 20-30cm MXH024		MXH024	Utility Fill	1	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
103985	Shovel test pit	STP N110 E081 LEV04 30-40cm MXH025		MXH025	Utility Fill	2	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103986	Shovel test pit	STP N110 E081 LEV04 30-40cm MXH025		MXH025	Utility Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-black
103990	Shovel test pit	STP N110 E081 LEV04 30-40cm MXH025		MXH025	Utility Fill	4	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103984	Shovel test pit	STP N110 E081 LEV04 30-40cm MXH025		MXH025	Utility Fill	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103988	Shovel test pit	STP N110 E081 LEV04 30-40cm MXH025		MXH025	Utility Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
103987	Shovel test pit	STP N110 E081 LEV04 30-40cm MXH025		MXH025	Utility Fill	1	vessel, hollow	body	Ceramic	Porcelain	Decorated	food/beverage	service	painted-orange
103983	Shovel test pit	STP N110 E081 LEV04 30-40cm MXH025		MXH025	Utility Fill	2	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103989	Shovel test pit	STP N110 E081 LEV04 30-40cm MXH025		MXH025	Utility Fill	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
103486	Shovel test pit	STP N110 E081 LEV06 50-60cm MXH259		MXH259	Utility Fill	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
103487	Shovel test pit	STP N110 E081 LEV06 50-60cm MXH259		MXH259	Utility Fill	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
103489	Shovel test pit	STP N110 E081 LEV06 50-60cm MXH259		MXH259	Utility Fill	2	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
103501	Shovel test pit	STP N110 E081 LEV06 50-60cm MXH259		MXH259	Utility Fill	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103499	Shovel test pit	STP N110 E081 LEV06 50-60cm MXH259		MXH259	Utility Fill	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire plain	food/beverage	service	
103485	Shovel test pit	STP N110 E081 LEV06 50-60cm MXH259		MXH259	Utility Fill	12	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103490	Shovel test pit	STP N110 E081 LEV06 50-60cm MXH259		MXH259	Utility Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103495	Shovel test pit	STP N110 E081 LEV06 50-60cm MXH259		MXH259	Utility Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-orange
103493	Shovel test pit	STP N110 E081 LEV06 50-60cm MXH259		MXH259	Utility Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-green
103488	Shovel test pit	STP N110 E081 LEV06 50-60cm MXH259		MXH259	Utility Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103498	Shovel test pit	STP N110 E081 LEV06 50-60cm MXH259		MXH259	Utility Fill	4	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103492	Shovel test pit	STP N110 E081 LEV06 50-60cm MXH259		MXH259	Utility Fill	6	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103494	Shovel test pit	STP N110 E081 LEV06 50-60cm MXH259		MXH259	Utility Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103496	Shovel test pit	STP N110 E081 LEV06 50-60cm MXH259		MXH259	Utility Fill	1	vessel, flat	rim	Ceramic	Porcelain	Plain	food/beverage	service	
103497	Shovel test pit	STP N110 E081 LEV06 50-60cm MXH259		MXH259	Utility Fill	1	vessel, flat	body	Ceramic	Porcelain	Plain	food/beverage	service	
103482	Shovel test pit	STP N110 E081 LEV06 50-60cm MXH259		MXH259	Utility Fill	21	sewer pipe	fragment	Ceramic	Stoneware	Unidentified	heating, plumbing, electric	device	
103480	Shovel test pit	STP N110 E081 LEV06 50-60cm MXH259		MXH259	Utility Fill	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
103502	Shovel test pit	STP N110 E081 LEV06 50-60cm MXH259		MXH259	Utility Fill	5	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103483	Shovel test pit	STP N110 E081 LEV06 50-60cm MXH259		MXH259	Utility Fill	5	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
103500	Shovel test pit	STP N110 E081 LEV06 50-60cm MXH259		MXH259	Utility Fill	1	bottle, indeterminate	lip	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
103484	Shovel test pit	STP N110 E081 LEV06 50-60cm MXH259		MXH259	Utility Fill	3	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
103491	Shovel test pit	STP N110 E081 LEV06 50-60cm MXH259		MXH259	Utility Fill	1	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
103481	Shovel test pit	STP N110 E081 LEV06 50-60cm MXH259		MXH259	Utility Fill	1	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
103532	Shovel test pit	STP N110 E084 LEV01 00-10cm MXH017		MXH017	Surface/Developing A	4	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
103541	Shovel test pit	STP N110 E084 LEV01 00-10cm MXH017		MXH017	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103540	Shovel test pit	STP N110 E084 LEV01 00-10cm MXH017		MXH017	Surface/Developing A	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
103529	Shovel test pit	STP N110 E084 LEV01 00-10cm MXH017		MXH017	Surface/Developing A	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103536	Shovel test pit	STP N110 E084 LEV01 00-10cm MXH017		MXH017	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
103525	Shovel test pit	STP N110 E084 LEV01 00-10cm MXH017		MXH017	Surface/Developing A	1	hardware, other	whole/intact	Glass	Machine made	machine made	architecture	hardware	
103538	Shovel test pit	STP N110 E084 LEV01 00-10cm MXH017		MXH017	Surface/Developing A	1	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
103535	Shovel test pit	STP N110 E084 LEV01 00-10cm MXH017		MXH017	Surface/Developing A	1	screw	whole/intact	Metal	ferrous	machine made	architecture	general construction	
103527	Shovel test pit	STP N110 E084 LEV01 00-10cm MXH017		MXH017	Surface/Developing A	1	sheet metal	fragment	Metal	lead	cast	0	Not Assigned	
103530	Shovel test pit	STP N110 E084 LEV01 00-10cm MXH017		MXH017	Surface/Developing A	2	mortar	fragment	Mineral	composite	mortar	architecture	general construction	
103531	Shovel test pit	STP N110 E084 LEV01 00-10cm MXH017		MXH017	Surface/Developing A	3	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
103533	Shovel test pit	STP N110 E084 LEV01 00-10cm MXH017		MXH017	Surface/Developing A	2	unidentified	fragment	Synthetic	synthetic	indeterminate	0	Not Assigned	
103526	Shovel test pit	STP N110 E084 LEV01 00-10cm MXH017		MXH017	Surface/Developing A	3	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
103534	Shovel test pit	STP N110 E084 LEV01 00-10cm MXH017		MXH017	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	plastic	food/beverage	storage	
103539	Shovel test pit	STP N110 E084 LEV01 00-10cm MXH017		MXH017	Surface/Developing A	2	unidentified	fragment	Synthetic	synthetic	styrofoam	0	Not Assigned	
103528	Shovel test pit	STP N110 E084 LEV01 00-10cm MXH017		MXH017	Surface/Developing A	3	vessel, indeterminate	fragment	Synthetic	synthetic	styrofoam	food/beverage	storage	
103424	Shovel test pit	STP N110 E084 STR02 LEV02 10-20cm MXH018		MXH018	Fill	1	pipe, bowl	bowl	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
103419	Shovel test pit	STP N110 E084 STR02 LEV02 10-20cm MXH018		MXH018	Fill	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
103415	Shovel test pit	STP N110 E084 STR02 LEV02 10-20cm MXH018		MXH018	Fill	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103423	Shovel test pit	STP N110 E084 STR02 LEV02 10-20cm MXH018		MXH018	Fill	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103426	Shovel test pit	STP N110 E084 STR02 LEV02 10-20cm MXH018		MXH018	Fill	4	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
103427	Shovel test pit	STP N110 E084 STR02 LEV02 10-20cm MXH018		MXH018	Fill	1	vessel, hollow	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103428	Shovel test pit	STP N110 E084 STR02 LEV02 10-20cm MXH018		MXH018	Fill	1	vessel, hollow	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103434	Shovel test pit	STP N110 E084 STR02 LEV02 10-20cm MXH018		MXH018	Fill	13	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103430	Shovel test pit	STP N110 E084 STR02 LEV02 10-20cm MXH018		MXH018	Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
103418	Shovel test pit	STP N110 E084 STR02 LEV02 10-20cm MXH018		MXH018	Fill	1	vessel, hollow	base	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103422	Shovel test pit	STP N110 E084 STR02 LEV02 10-20cm MXH018		MXH018	Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103431	Shovel test pit	STP N110 E084 STR02 LEV02 10-20cm MXH018		MXH018	Fill	7	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103436	Shovel test pit	STP N110 E084 STR02 LEV02 10-20cm MXH018		MXH018	Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103413	Shovel test pit	STP N110 E084 STR02 LEV02 10-20cm MXH018		MXH018	Fill	1	vessel, hollow	body	Ceramic	Stoneware	brown, salt-glazed	food/beverage	service	
103412	Shovel test pit	STP N110 E084 STR02 LEV02 10-20cm MXH018		MXH018	Fill	1	vessel, flat	rim	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
103420	Shovel test pit	STP N110 E084 STR02 LEV02 10-20cm MXH018		MXH018	Fill	1	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
103421	Shovel test pit	STP N110 E084 STR02 LEV02 10-20cm MXH018		MXH018	Fill	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103414	Shovel test pit	STP N110 E084 STR02 LEV02 10-20cm MXH018		MXH018	Fill	1	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
103433	Shovel test pit	STP N110 E084 STR02 LEV02 10-20cm MXH018		MXH018	Fill	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua marine*
103429	Shovel test pit	STP N110 E084 STR02 LEV02 10-20cm MXH018		MXH018	Fill	7	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
103435	Shovel test pit	STP N110 E084 STR02 LEV02 10-20cm MXH018		MXH018	Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
103432	Shovel test pit	STP N110 E084 STR02 LEV02 10-20cm MXH018		MXH018	Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
103416	Shovel test pit	STP N110 E084 STR02 LEV02 10-20cm MXH018		MXH018	Fill	1	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
103425	Shovel test pit	STP N110 E084 STR02 LEV02 10-20cm MXH018		MXH018	Fill	2	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
103417	Shovel test pit	STP N110 E084 STR02 LEV02 10-20cm MXH018		MXH018	Fill	2	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
103410	Shovel test pit	STP N110 E084 STR02 LEV02 10-20cm MXH018		MXH018	Fill	2	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
103411	Shovel test pit	STP N110 E084 STR02 LEV02 10-20cm MXH018		MXH018	Fill	1	unidentified	fragment	Synthetic	synthetic	indeterminate	0	Not Assigned	
103745	Shovel test pit	STP N110 E084 STR02 LEV03 20-30cm MXH019		MXH019	Fill	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
103734	Shovel test pit	STP N110 E084 STR02 LEV03 20-30cm MXH019		MXH019	Fill	5	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
103735	Shovel test pit	STP N110 E084 STR02 LEV03 20-30cm MXH019		MXH019	Fill	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103746	Shovel test pit	STP N110 E084 STR02 LEV03 20-30cm MXH019		MXH019	Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103736	Shovel test pit	STP N110 E084 STR02 LEV03 20-30cm MXH019		MXH019	Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Not Assigned	food/beverage	service	
103732	Shovel test pit	STP N110 E084 STR02 LEV03 20-30cm MXH019		MXH019	Fill	3	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103743	Shovel test pit	STP N110 E084 STR02 LEV03 20-30cm MXH019		MXH019	Fill	2	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103738	Shovel test pit	STP N110 E084 STR02 LEV03 20-30cm MXH019		MXH019	Fill	1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103741	Shovel test pit	STP N110 E084 STR02 LEV03 20-30cm MXH019		MXH019	Fill	1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103742	Shovel test pit	STP N110 E084 STR02 LEV03 20-30cm MXH019		MXH019	Fill	17	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103733	Shovel test pit	STP N110 E084 STR02 LEV03 20-30cm MXH019		MXH019	Fill	1	vessel, hollow	body	Ceramic	Stoneware	Buff smooth-glazed	food/beverage	storage	Albany slip-brown
103740	Shovel test pit	STP N110 E084 STR02 LEV03 20-30cm MXH019		MXH019	Fill	1	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
103737	Shovel test pit	STP N110 E084 STR02 LEV03 20-30cm MXH019		MXH019	Fill	2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103739	Shovel test pit	STP N110 E084 STR02 LEV03 20-30cm MXH019		MXH019	Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
103744	Shovel test pit	STP N110 E084 STR02 LEV03 20-30cm MXH019		MXH019	Fill	3	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
103731	Shovel test pit	STP N110 E084 STR02 LEV03 20-30cm MXH019		MXH019	Fill	1	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
103606	Shovel test pit	STP N110 E084 STR03 LEV04 30-40cm MXH020		MXH020	Rubble Fill	1	pipe, bowl/stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
103618	Shovel test pit	STP N110 E084 STR03 LEV04 30-40cm MXH020		MXH020	Rubble Fill	4	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
103615	Shovel test pit	STP N110 E084 STR03 LEV04 30-40cm MXH020		MXH020	Rubble Fill	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103623	Shovel test pit	STP N110 E084 STR03 LEV04 30-40cm MXH020		MXH020	Rubble Fill	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
103617	Shovel test pit	STP N110 E084 STR03 LEV04 30-40cm MXH020		MXH020	Rubble Fill	4	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
103611	Shovel test pit	STP N110 E084 STR03 LEV04 30-40cm MXH020		MXH020	Rubble Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-blue
103622	Shovel test pit	STP N110 E084 STR03 LEV04 30-40cm MXH020		MXH020	Rubble Fill	1	vessel, indeterminate	body	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
103608	Shovel test pit	STP N110 E084 STR03 LEV04 30-40cm MXH020		MXH020	Rubble Fill	2	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
103607	Shovel test pit	STP N110 E084 STR03 LEV04 30-40cm MXH020		MXH020	Rubble Fill	2	vessel, flat	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103613	Shovel test pit	STP N110 E084 STR03 LEV04 30-40cm MXH020		MXH020	Rubble Fill	6	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
103626	Shovel test pit	STP N110 E084 STR03 LEV04 30-40cm MXH020		MXH020	Rubble Fill	2	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
103621	Shovel test pit	STP N110 E084 STR03 LEV04 30-40cm MXH020		MXH020	Rubble Fill	2	vessel, hollow	body	Ceramic	unidentified	Not Assigned	0	Not Assigned	
103609	Shovel test pit	STP N110 E084 STR03 LEV04 30-40cm MXH020		MXH020	Rubble Fill	2	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
103620	Shovel test pit	STP N110 E084 STR03 LEV04 30-40cm MXH020		MXH020	Rubble Fill	1	tooth	fragment	Fauna	enamel/bone	tooth	food/beverage	acquisition	
103616	Shovel test pit	STP N110 E084 STR03 LEV04 30-40cm MXH020		MXH020	Rubble Fill	1	shell	fragment	Fauna	shell	mollosk	food/beverage	acquisition	
103612	Shovel test pit	STP N110 E084 STR03 LEV04 30-40cm MXH020		MXH020	Rubble Fill	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
103619	Shovel test pit	STP N110 E084 STR03 LEV04 30-40cm MXH020		MXH020	Rubble Fill	2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
103603	Shovel test pit	STP N110 E084 STR03 LEV04 30-40cm MXH020		MXH020	Rubble Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
103610	Shovel test pit	STP N110 E084 STR03 LEV04 30-40cm MXH020		MXH020	Rubble Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
103625	Shovel test pit	STP N110 E084 STR03 LEV04 30-40cm MXH020		MXH020	Rubble Fill	1	unidentified	fragment	Metal	copper alloy	copper alloy	0	Not Assigned	
103624	Shovel test pit	STP N110 E084 STR03 LEV04 30-40cm MXH020		MXH020	Rubble Fill	1	unidentified	fragment	Metal	ferrous	unidentified	0	Not Assigned	
103604	Shovel test pit	STP N110 E084 STR03 LEV04 30-40cm MXH020		MXH020	Rubble Fill	4	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
103605	Shovel test pit	STP N110 E084 STR03 LEV04 30-40cm MXH020		MXH020	Rubble Fill	1	mortar	fragment	Mineral	composite	mortar	architecture	general construction	
103614	Shovel test pit	STP N110 E084 STR03 LEV04 30-40cm MXH020		MXH020	Rubble Fill	1	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
104028	Shovel test pit	STP N110 E084 STR03 LEV05 40-50cm MXH021		MXH021	Rubble Fill	2	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
104030	Shovel test pit	STP N110 E084 STR03 LEV05 40-50cm MXH021		MXH021	Rubble Fill	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
104035	Shovel test pit	STP N110 E084 STR03 LEV05 40-50cm MXH021		MXH021	Rubble Fill	4	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104036	Shovel test pit	STP N110 E084 STR03 LEV05 40-50cm MXH021		MXH021	Rubble Fill	1	vessel, flat	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104032	Shovel test pit	STP N110 E084 STR03 LEV05 40-50cm MXH021		MXH021	Rubble Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	Annular-black
104031	Shovel test pit	STP N110 E084 STR03 LEV05 40-50cm MXH021		MXH021	Rubble Fill	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
104040	Shovel test pit	STP N110 E084 STR03 LEV05 40-50cm MXH021		MXH021	Rubble Fill	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104039	Shovel test pit	STP N110 E084 STR03 LEV05 40-50cm MXH021		MXH021	Rubble Fill	1	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
104029	Shovel test pit	STP N110 E084 STR03 LEV05 40-50cm MXH021		MXH021	Rubble Fill	5	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
104033	Shovel test pit	STP N110 E084 STR03 LEV05 40-50cm MXH021		MXH021	Rubble Fill	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
104037	Shovel test pit	STP N110 E084 STR03 LEV05 40-50cm MXH021		MXH021	Rubble Fill	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
104041	Shovel test pit	STP N110 E084 STR03 LEV05 40-50cm MXH021		MXH021	Rubble Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua marine*
104038	Shovel test pit	STP N110 E084 STR03 LEV05 40-50cm MXH021		MXH021	Rubble Fill	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104034	Shovel test pit	STP N110 E084 STR03 LEV05 40-50cm MXH021		MXH021	Rubble Fill	1	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
104415	Shovel test pit	STP N111 E072 LEV06 00-60cm MXH016		MXH016		1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104321	Shovel test pit	STP N111 E072 STR01 LEV01 00-10cm MXH010		MXH010	Surface/Developing A	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
104318	Shovel test pit	STP N111 E072 STR01 LEV01 00-10cm MXH010		MXH010	Surface/Developing A	1	vessel, flat	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104319	Shovel test pit	STP N111 E072 STR01 LEV01 00-10cm MXH010		MXH010	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
104316	Shovel test pit	STP N111 E072 STR01 LEV01 00-10cm MXH010		MXH010	Surface/Developing A	1	vessel, hollow	neck	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104312	Shovel test pit	STP N111 E072 STR01 LEV01 00-10cm MXH010		MXH010	Surface/Developing A	1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104315	Shovel test pit	STP N111 E072 STR01 LEV01 00-10cm MXH010		MXH010	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104322	Shovel test pit	STP N111 E072 STR01 LEV01 00-10cm MXH010		MXH010	Surface/Developing A	1	vessel, hollow	foot	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104317	Shovel test pit	STP N111 E072 STR01 LEV01 00-10cm MXH010		MXH010	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Whiteware, transfer printed	food/beverage	service	transfer print-red
104320	Shovel test pit	STP N111 E072 STR01 LEV01 00-10cm MXH010		MXH010	Surface/Developing A	1	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	service	
104311	Shovel test pit	STP N111 E072 STR01 LEV01 00-10cm MXH010		MXH010	Surface/Developing A	1	vessel, hollow	body	Ceramic	Stoneware	gray salt glazed	food/beverage	storage	Albany slip-black
104323	Shovel test pit	STP N111 E072 STR01 LEV01 00-10cm MXH010		MXH010	Surface/Developing A	1	vessel, hollow	body	Ceramic	unidentified	unidentified	0	Not Assigned	
104310	Shovel test pit	STP N111 E072 STR01 LEV01 00-10cm MXH010		MXH010	Surface/Developing A	3	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
104313	Shovel test pit	STP N111 E072 STR01 LEV01 00-10cm MXH010		MXH010	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Amber
104314	Shovel test pit	STP N111 E072 STR01 LEV01 00-10cm MXH010		MXH010	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
104309	Shovel test pit	STP N111 E072 STR01 LEV01 00-10cm MXH010		MXH010	Surface/Developing A	1	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
104369	Shovel test pit	STP N111 E072 STR03 LEV03 20-30cm MXH012		MXH012	B1	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
104360	Shovel test pit	STP N111 E072 STR03 LEV03 20-30cm MXH012		MXH012	B1	6	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104371	Shovel test pit	STP N111 E072 STR03 LEV03 20-30cm MXH012		MXH012	B1	1	vessel, flat	body	Ceramic	Earthenware, refined	Creamware, transfer printed overglaze	food/beverage	service	transfer print-brown
104367	Shovel test pit	STP N111 E072 STR03 LEV03 20-30cm MXH012		MXH012	B1	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
104361	Shovel test pit	STP N111 E072 STR03 LEV03 20-30cm MXH012		MXH012	B1	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-green
104359	Shovel test pit	STP N111 E072 STR03 LEV03 20-30cm MXH012		MXH012	B1	3	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104358	Shovel test pit	STP N111 E072 STR03 LEV03 20-30cm MXH012		MXH012	B1	4	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, unidentified	food/beverage	service	
104365	Shovel test pit	STP N111 E072 STR03 LEV03 20-30cm MXH012		MXH012	B1	1	charcoal	fragment	Flora	wood	charcoal	heating, plumbing, electric	fuel	
104368	Shovel test pit	STP N111 E072 STR03 LEV03 20-30cm MXH012		MXH012	B1	5	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
104366	Shovel test pit	STP N111 E072 STR03 LEV03 20-30cm MXH012		MXH012	B1	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104363	Shovel test pit	STP N111 E072 STR03 LEV03 20-30cm MXH012		MXH012	B1	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
104370	Shovel test pit	STP N111 E072 STR03 LEV03 20-30cm MXH012		MXH012	B1	1	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
104362	Shovel test pit	STP N111 E072 STR03 LEV03 20-30cm MXH012		MXH012	B1	3	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
104364	Shovel test pit	STP N111 E072 STR03 LEV03 20-30cm MXH012		MXH012	B1	1	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
104307	Shovel test pit	STP N111 E072 STR03 LEV04 30-40cm MXH013		MXH013	B1	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
104303	Shovel test pit	STP N111 E072 STR03 LEV04 30-40cm MXH013		MXH013	B1	2	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104308	Shovel test pit	STP N111 E072 STR03 LEV04 30-40cm MXH013		MXH013	B1	1	vessel, flat	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
104302	Shovel test pit	STP N111 E072 STR03 LEV04 30-40cm MXH013		MXH013	B1	1	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	food/beverage	service	
104305	Shovel test pit	STP N111 E072 STR03 LEV04 30-40cm MXH013		MXH013	B1	1	vessel, hollow	body	Ceramic	Earthenware, refined	Whiteware, transfer printed	food/beverage	service	transfer print-blue
104304	Shovel test pit	STP N111 E072 STR03 LEV04 30-40cm MXH013		MXH013	B1	1	vessel, indeterminate	body	Ceramic	unidentified	unidentified	0	Not Assigned	
104301	Shovel test pit	STP N111 E072 STR03 LEV04 30-40cm MXH013		MXH013	B1	2	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
104300	Shovel test pit	STP N111 E072 STR03 LEV04 30-40cm MXH013		MXH013	B1	1	nail wrought	whole/intact	Metal	ferrous	wrought	architecture	general construction	
104306	Shovel test pit	STP N111 E072 STR03 LEV04 30-40cm MXH013		MXH013	B1	2	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
104124	Shovel test pit	STP N117 E074 STR01 LEV01 00-12cm MXH095		MXH095	Surface/Developing A	25	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
104117	Shovel test pit	STP N117 E074 STR01 LEV01 00-12cm MXH095		MXH095	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
104123	Shovel test pit	STP N117 E074 STR01 LEV01 00-12cm MXH095		MXH095	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
104134	Shovel test pit	STP N117 E074 STR01 LEV01 00-12cm MXH095		MXH095	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	creamware, hand painted overglaze	food/beverage	service	painted-green
104122	Shovel test pit	STP N117 E074 STR01 LEV01 00-12cm MXH095		MXH095	Surface/Developing A	5	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104130	Shovel test pit	STP N117 E074 STR01 LEV01 00-12cm MXH095		MXH095	Surface/Developing A	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104137	Shovel test pit	STP N117 E074 STR01 LEV01 00-12cm MXH095		MXH095	Surface/Developing A	1	vessel, flat	body	Ceramic	Earthenware, refined	Whiteware, transfer printed	food/beverage	service	transfer print-brown
104139	Shovel test pit	STP N117 E074 STR01 LEV01 00-12cm MXH095		MXH095	Surface/Developing A	1	tile, decorative	fragment	Ceramic	Earthenware, refined	Whiteware, undecorated	architecture	foundation	
104131	Shovel test pit	STP N117 E074 STR01 LEV01 00-12cm MXH095		MXH095	Surface/Developing A	1	vessel, hollow	base	Ceramic	Porcelain	Decorated	food/beverage	service	painted-blue
104110	Shovel test pit	STP N117 E074 STR01 LEV01 00-12cm MXH095		MXH095	Surface/Developing A	11	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
104116	Shovel test pit	STP N117 E074 STR01 LEV01 00-12cm MXH095		MXH095	Surface/Developing A	44	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
104129	Shovel test pit	STP N117 E074 STR01 LEV01 00-12cm MXH095		MXH095	Surface/Developing A	1	glass, mirror	fragment	Glass	flat	flat	personal	toiletry/hygiene	-Clear
104126	Shovel test pit	STP N117 E074 STR01 LEV01 00-12cm MXH095		MXH095	Surface/Developing A	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Amber
104118	Shovel test pit	STP N117 E074 STR01 LEV01 00-12cm MXH095		MXH095	Surface/Developing A	1	bottle, indeterminate	base	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
104127	Shovel test pit	STP N117 E074 STR01 LEV01 00-12cm MXH095		MXH095	Surface/Developing A	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
104121	Shovel test pit	STP N117 E074 STR01 LEV01 00-12cm MXH095		MXH095	Surface/Developing A	18	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104140	Shovel test pit	STP N117 E074 STR01 LEV01 00-12cm MXH095		MXH095	Surface/Developing A	12	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104120	Shovel test pit	STP N117 E074 STR01 LEV01 00-12cm MXH095		MXH095	Surface/Developing A	9	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (bright 7-up)
104125	Shovel test pit	STP N117 E074 STR01 LEV01 00-12cm MXH095		MXH095	Surface/Developing A	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
104128	Shovel test pit	STP N117 E074 STR01 LEV01 00-12cm MXH095		MXH095	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Milk glass/Opaque white
104141	Shovel test pit	STP N117 E074 STR01 LEV01 00-12cm MXH095		MXH095	Surface/Developing A	4	bottle, indeterminate	body	Glass	molded	molded	food/beverage	storage	-Clear
104109	Shovel test pit	STP N117 E074 STR01 LEV01 00-12cm MXH095		MXH095	Surface/Developing A	1	rod	fragment	Metal	ferrous	machine made	architecture	general construction	
104111	Shovel test pit	STP N117 E074 STR01 LEV01 00-12cm MXH095		MXH095	Surface/Developing A	1	bolt	whole/intact	Metal	ferrous	machine made	architecture	general construction	
104132	Shovel test pit	STP N117 E074 STR01 LEV01 00-12cm MXH095		MXH095	Surface/Developing A	1	screw	whole/intact	Metal	ferrous	machine made	architecture	general construction	
104113	Shovel test pit	STP N117 E074 STR01 LEV01 00-12cm MXH095		MXH095	Surface/Developing A	1	washer	whole/intact	Metal	ferrous	machine made	architecture	hardware	
104138	Shovel test pit	STP N117 E074 STR01 LEV01 00-12cm MXH095		MXH095	Surface/Developing A	3	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
104112	Shovel test pit	STP N117 E074 STR01 LEV01 00-12cm MXH095		MXH095	Surface/Developing A	9	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
104114	Shovel test pit	STP N117 E074 STR01 LEV01 00-12cm MXH095		MXH095	Surface/Developing A	7	plaster, plain	fragment	Mineral	composite	plaster	architecture	general construction	
104133	Shovel test pit	STP N117 E074 STR01 LEV01 00-12cm MXH095		MXH095	Surface/Developing A	2	tile, floor	fragment	Stone	marble	Not Assigned	architecture	foundation	
104115	Shovel test pit	STP N117 E074 STR01 LEV01 00-12cm MXH095		MXH095	Surface/Developing A	2	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
104136	Shovel test pit	STP N117 E074 STR01 LEV01 00-12cm MXH095		MXH095	Surface/Developing A	6	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
104142	Shovel test pit	STP N117 E074 STR01 LEV01 00-12cm MXH095		MXH095	Surface/Developing A	13	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
104119	Shovel test pit	STP N117 E074 STR01 LEV01 00-12cm MXH095		MXH095	Surface/Developing A	1	washer	whole/intact	Synthetic	synthetic	plastic	architecture	hardware	
104135	Shovel test pit	STP N117 E074 STR01 LEV01 00-12cm MXH095		MXH095	Surface/Developing A	2	unidentified	fragment	Synthetic	synthetic	styrofoam	0	Not Assigned	
104281	Shovel test pit	STP N117 E074 STR02 LEV02 12-22cm MXH096		MXH096	Redeposited B	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
104283	Shovel test pit	STP N117 E074 STR02 LEV02 12-22cm MXH096		MXH096	Redeposited B	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
104293	Shovel test pit	STP N117 E074 STR02 LEV02 12-22cm MXH096		MXH096	Redeposited B	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire plain	food/beverage	service	
104288	Shovel test pit	STP N117 E074 STR02 LEV02 12-22cm MXH096		MXH096	Redeposited B	6	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104284	Shovel test pit	STP N117 E074 STR02 LEV02 12-22cm MXH096		MXH096	Redeposited B	1	vessel, flat	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-black
104292	Shovel test pit	STP N117 E074 STR02 LEV02 12-22cm MXH096		MXH096	Redeposited B	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	engine turned-green
104287	Shovel test pit	STP N117 E074 STR02 LEV02 12-22cm MXH096		MXH096	Redeposited B	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
104289	Shovel test pit	STP N117 E074 STR02 LEV02 12-22cm MXH096		MXH096	Redeposited B	4	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104291	Shovel test pit	STP N117 E074 STR02 LEV02 12-22cm MXH096		MXH096	Redeposited B	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104279	Shovel test pit	STP N117 E074 STR02 LEV02 12-22cm MXH096		MXH096	Redeposited B	1	vessel, hollow	base	Ceramic	Stoneware	Westerwald	food/beverage	service	
104298	Shovel test pit	STP N117 E074 STR02 LEV02 12-22cm MXH096		MXH096	Redeposited B	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
104299	Shovel test pit	STP N117 E074 STR02 LEV02 12-22cm MXH096		MXH096	Redeposited B	6	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
104286	Shovel test pit	STP N117 E074 STR02 LEV02 12-22cm MXH096		MXH096	Redeposited B	2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
104280	Shovel test pit	STP N117 E074 STR02 LEV02 12-22cm MXH096		MXH096	Redeposited B	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Amber
104282	Shovel test pit	STP N117 E074 STR02 LEV02 12-22cm MXH096		MXH096	Redeposited B	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104297	Shovel test pit	STP N117 E074 STR02 LEV02 12-22cm MXH096		MXH096	Redeposited B	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104294	Shovel test pit	STP N117 E074 STR02 LEV02 12-22cm MXH096		MXH096	Redeposited B	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (bright 7-up)
104295	Shovel test pit	STP N117 E074 STR02 LEV02 12-22cm MXH096		MXH096	Redeposited B	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
104277	Shovel test pit	STP N117 E074 STR02 LEV02 12-22cm MXH096		MXH096	Redeposited B	5	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
104290	Shovel test pit	STP N117 E074 STR02 LEV02 12-22cm MXH096		MXH096	Redeposited B	4	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
104296	Shovel test pit	STP N117 E074 STR02 LEV02 12-22cm MXH096		MXH096	Redeposited B	3	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
104285	Shovel test pit	STP N117 E074 STR02 LEV02 12-22cm MXH096		MXH096	Redeposited B	1	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
104278	Shovel test pit	STP N117 E074 STR02 LEV02 12-22cm MXH096		MXH096	Redeposited B	1	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
104180	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
104172	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
104185	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
104178	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	7	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
104177	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	12	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104186	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104193	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	1	bowl, punch	base	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
104206	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
104171	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	1	vessel, flat	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	Annular-brown
104182	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	Annular-brown
104190	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
104174	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	5	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104198	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104199	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104205	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	6	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104175	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	painted-brown
104173	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	1	vessel, hollow	rim	Ceramic	Porcelain	Decorated	food/beverage	service	painted-red
104202	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	1	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	service	
104176	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	1	vessel, flat	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
104201	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
104183	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	6	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
104184	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	1	charcoal	fragment	Flora	wood	charcoal	heating, plumbing, electric	fuel	
104192	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	1	wood, indeterminate	fragment	Flora	wood	Not Assigned	0	Not Assigned	
104188	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	14	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
104189	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	5	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
104191	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua marine*
104196	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	12	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104204	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104181	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (bright 7-up)
104170	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	5	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
104194	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	1	bottle, indeterminate	lip	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)-Stacked Ring
104195	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	1	drinking glass, tumbler	rim	Glass	molded	molded	food/beverage	service	-Clear
104187	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	5	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
104179	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	4	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
104203	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	1	plaster, plain	fragment	Mineral	composite	plaster	architecture	general construction	
104207	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	2	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
104197	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	2	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
104200	Shovel test pit	STP N117 E074 STR03 LEV03 20-30cm MXH097		MXH097	Buried APZ	1	tag	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
104153	Shovel test pit	STP N117 E074 STR03 LEV04 30-40cm MXH098		MXH098	Buried APZ	2	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
104154	Shovel test pit	STP N117 E074 STR03 LEV04 30-40cm MXH098		MXH098	Buried APZ	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
104145	Shovel test pit	STP N117 E074 STR03 LEV04 30-40cm MXH098		MXH098	Buried APZ	7	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
104155	Shovel test pit	STP N117 E074 STR03 LEV04 30-40cm MXH098		MXH098	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
104162	Shovel test pit	STP N117 E074 STR03 LEV04 30-40cm MXH098		MXH098	Buried APZ	1	flower pot	base	Ceramic	Earthenware, coarse	Redware, flowerpot	industry, manufacture, trades	gardening/farming	
104163	Shovel test pit	STP N117 E074 STR03 LEV04 30-40cm MXH098		MXH098	Buried APZ	6	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
104157	Shovel test pit	STP N117 E074 STR03 LEV04 30-40cm MXH098		MXH098	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	unidentified	0	Not Assigned	
104149	Shovel test pit	STP N117 E074 STR03 LEV04 30-40cm MXH098		MXH098	Buried APZ	4	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104151	Shovel test pit	STP N117 E074 STR03 LEV04 30-40cm MXH098		MXH098	Buried APZ	22	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104159	Shovel test pit	STP N117 E074 STR03 LEV04 30-40cm MXH098		MXH098	Buried APZ	1	vessel, flat	body	Ceramic	Earthenware, refined	Not Assigned	food/beverage	service	
104164	Shovel test pit	STP N117 E074 STR03 LEV04 30-40cm MXH098		MXH098	Buried APZ	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	Annular-black
104146	Shovel test pit	STP N117 E074 STR03 LEV04 30-40cm MXH098		MXH098	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
104152	Shovel test pit	STP N117 E074 STR03 LEV04 30-40cm MXH098		MXH098	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
104150	Shovel test pit	STP N117 E074 STR03 LEV04 30-40cm MXH098		MXH098	Buried APZ	13	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104166	Shovel test pit	STP N117 E074 STR03 LEV04 30-40cm MXH098		MXH098	Buried APZ	3	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104156	Shovel test pit	STP N117 E074 STR03 LEV04 30-40cm MXH098		MXH098	Buried APZ	25	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104143	Shovel test pit	STP N117 E074 STR03 LEV04 30-40cm MXH098		MXH098	Buried APZ	9	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
104160	Shovel test pit	STP N117 E074 STR03 LEV04 30-40cm MXH098		MXH098	Buried APZ	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
104148	Shovel test pit	STP N117 E074 STR03 LEV04 30-40cm MXH098		MXH098	Buried APZ	5	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
104158	Shovel test pit	STP N117 E074 STR03 LEV04 30-40cm MXH098		MXH098	Buried APZ	11	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
104168	Shovel test pit	STP N117 E074 STR03 LEV04 30-40cm MXH098		MXH098	Buried APZ	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
104167	Shovel test pit	STP N117 E074 STR03 LEV04 30-40cm MXH098		MXH098	Buried APZ	6	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104147	Shovel test pit	STP N117 E074 STR03 LEV04 30-40cm MXH098		MXH098	Buried APZ	10	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
104161	Shovel test pit	STP N117 E074 STR03 LEV04 30-40cm MXH098		MXH098	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
104144	Shovel test pit	STP N117 E074 STR03 LEV04 30-40cm MXH098		MXH098	Buried APZ	5	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
104169	Shovel test pit	STP N117 E074 STR03 LEV04 30-40cm MXH098		MXH098	Buried APZ	15	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
104165	Shovel test pit	STP N117 E074 STR03 LEV04 30-40cm MXH098		MXH098	Buried APZ	4	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
104259	Shovel test pit	STP N117 E074 STR04 LEV05 40-50cm MXH099		MXH099	B1	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
104261	Shovel test pit	STP N117 E074 STR04 LEV05 40-50cm MXH099		MXH099	B1	2	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104263	Shovel test pit	STP N117 E074 STR04 LEV05 40-50cm MXH099		MXH099	B1	5	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104258	Shovel test pit	STP N117 E074 STR04 LEV05 40-50cm MXH099		MXH099	B1	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
104264	Shovel test pit	STP N117 E074 STR04 LEV05 40-50cm MXH099		MXH099	B1	9	charcoal	fragment	Flora	wood	charcoal	heating, plumbing, electric	fuel	
104262	Shovel test pit	STP N117 E074 STR04 LEV05 40-50cm MXH099		MXH099	B1	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
104260	Shovel test pit	STP N117 E074 STR04 LEV05 40-50cm MXH099		MXH099	B1	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104418	Shovel test pit	STP N117 E074 STR04 LEV06 50-60cm MXH100		MXH100	B1	2	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104416	Shovel test pit	STP N117 E074 STR04 LEV06 50-60cm MXH100		MXH100	B1	1	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
104417	Shovel test pit	STP N117 E074 STR04 LEV06 50-60cm MXH100		MXH100	B1	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104410	Shovel test pit	STP N117 E074 Wall Fall MXH101		MXH101		1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104334	Shovel test pit	STP N117 E081 LEV06 50-60cm MXH107		MXH107	Slag	4	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
104326	Shovel test pit	STP N117 E081 LEV06 50-60cm MXH107		MXH107	Slag	4	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104327	Shovel test pit	STP N117 E081 LEV06 50-60cm MXH107		MXH107	Slag	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	Annular-brown
104333	Shovel test pit	STP N117 E081 LEV06 50-60cm MXH107		MXH107	Slag	4	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104324	Shovel test pit	STP N117 E081 LEV06 50-60cm MXH107		MXH107	Slag	10	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104325	Shovel test pit	STP N117 E081 LEV06 50-60cm MXH107		MXH107	Slag	3	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104331	Shovel test pit	STP N117 E081 LEV06 50-60cm MXH107		MXH107	Slag	1	vessel, flat	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
104329	Shovel test pit	STP N117 E081 LEV06 50-60cm MXH107		MXH107	Slag	6	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
104332	Shovel test pit	STP N117 E081 LEV06 50-60cm MXH107		MXH107	Slag	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Blue-cobalt
104330	Shovel test pit	STP N117 E081 LEV06 50-60cm MXH107		MXH107	Slag	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
104336	Shovel test pit	STP N117 E081 LEV06 50-60cm MXH107		MXH107	Slag	6	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
104335	Shovel test pit	STP N117 E081 LEV06 50-60cm MXH107		MXH107	Slag	2	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
104328	Shovel test pit	STP N117 E081 LEV06 50-60cm MXH107		MXH107	Slag	1	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
104403	Shovel test pit	STP N117 E081 STR01 LEV01 00-10cm MXH102		MXH102	Surface/Developing A	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
104404	Shovel test pit	STP N117 E081 STR01 LEV01 00-10cm MXH102		MXH102	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
104398	Shovel test pit	STP N117 E081 STR01 LEV01 00-10cm MXH102		MXH102	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, factory-made slipware	food/beverage	service	slip-green
104408	Shovel test pit	STP N117 E081 STR01 LEV01 00-10cm MXH102		MXH102	Surface/Developing A	6	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104407	Shovel test pit	STP N117 E081 STR01 LEV01 00-10cm MXH102		MXH102	Surface/Developing A	5	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104396	Shovel test pit	STP N117 E081 STR01 LEV01 00-10cm MXH102		MXH102	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
104399	Shovel test pit	STP N117 E081 STR01 LEV01 00-10cm MXH102		MXH102	Surface/Developing A	1	wood, indeterminate	fragment	Flora	wood	unidentified	0	Not Assigned	
104405	Shovel test pit	STP N117 E081 STR01 LEV01 00-10cm MXH102		MXH102	Surface/Developing A	3	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
104406	Shovel test pit	STP N117 E081 STR01 LEV01 00-10cm MXH102		MXH102	Surface/Developing A	2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
104401	Shovel test pit	STP N117 E081 STR01 LEV01 00-10cm MXH102		MXH102	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
104409	Shovel test pit	STP N117 E081 STR01 LEV01 00-10cm MXH102		MXH102	Surface/Developing A	1	unidentified	fragment	Metal	ferrous	unidentified	0	Not Assigned	
104397	Shovel test pit	STP N117 E081 STR01 LEV01 00-10cm MXH102		MXH102	Surface/Developing A	2	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
104402	Shovel test pit	STP N117 E081 STR01 LEV01 00-10cm MXH102		MXH102	Surface/Developing A	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
104400	Shovel test pit	STP N117 E081 STR01 LEV01 00-10cm MXH102		MXH102	Surface/Developing A	2	asphalt	fragment	Synthetic	synthetic	asphalt	architecture	foundation	
104381	Shovel test pit	STP N117 E081 STR02 LEV02 10-20cm MXH103		MXH103	Slag	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
104387	Shovel test pit	STP N117 E081 STR02 LEV02 10-20cm MXH103		MXH103	Slag	1	flower pot	rim	Ceramic	Earthenware, coarse	Redware, flowerpot	industry, manufacture, trades	gardening/farming	
104383	Shovel test pit	STP N117 E081 STR02 LEV02 10-20cm MXH103		MXH103	Slag	4	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
104390	Shovel test pit	STP N117 E081 STR02 LEV02 10-20cm MXH103		MXH103	Slag	1	vessel, hollow	base	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
104386	Shovel test pit	STP N117 E081 STR02 LEV02 10-20cm MXH103		MXH103	Slag	2	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104388	Shovel test pit	STP N117 E081 STR02 LEV02 10-20cm MXH103		MXH103	Slag	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104392	Shovel test pit	STP N117 E081 STR02 LEV02 10-20cm MXH103		MXH103	Slag	1	vessel, flat	body	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
104389	Shovel test pit	STP N117 E081 STR02 LEV02 10-20cm MXH103		MXH103	Slag	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104382	Shovel test pit	STP N117 E081 STR02 LEV02 10-20cm MXH103		MXH103	Slag	1	vessel, hollow	body	Ceramic	unidentified	unidentified	0	Not Assigned	
104394	Shovel test pit	STP N117 E081 STR02 LEV02 10-20cm MXH103		MXH103	Slag	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
104385	Shovel test pit	STP N117 E081 STR02 LEV02 10-20cm MXH103		MXH103	Slag	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104384	Shovel test pit	STP N117 E081 STR02 LEV02 10-20cm MXH103		MXH103	Slag	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
104393	Shovel test pit	STP N117 E081 STR02 LEV02 10-20cm MXH103		MXH103	Slag	2	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
104391	Shovel test pit	STP N117 E081 STR02 LEV02 10-20cm MXH103		MXH103	Slag	2	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
104395	Shovel test pit	STP N117 E081 STR02 LEV02 10-20cm MXH103		MXH103	Slag	2	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
104375	Shovel test pit	STP N117 E081 STR02 LEV03 20-30cm MXH104		MXH104	Slag	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104374	Shovel test pit	STP N117 E081 STR02 LEV03 20-30cm MXH104		MXH104	Slag	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104377	Shovel test pit	STP N117 E081 STR02 LEV03 20-30cm MXH104		MXH104	Slag	4	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
104373	Shovel test pit	STP N117 E081 STR02 LEV03 20-30cm MXH104		MXH104	Slag	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
104378	Shovel test pit	STP N117 E081 STR02 LEV03 20-30cm MXH104		MXH104	Slag	1	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
104379	Shovel test pit	STP N117 E081 STR02 LEV03 20-30cm MXH104		MXH104	Slag	1	nail, wire	whole/intact	Metal	ferrous	machine made	architecture	general construction	
104376	Shovel test pit	STP N117 E081 STR02 LEV03 20-30cm MXH104		MXH104	Slag	1	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
104372	Shovel test pit	STP N117 E081 STR02 LEV03 20-30cm MXH104		MXH104	Slag	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
104380	Shovel test pit	STP N117 E081 STR02 LEV03 20-30cm MXH104		MXH104	Slag	2	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
104269	Shovel test pit	STP N117 E081 STR02 LEV04 30-40cm MXH105		MXH105	Slag	2	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
104272	Shovel test pit	STP N117 E081 STR02 LEV04 30-40cm MXH105		MXH105	Slag	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104274	Shovel test pit	STP N117 E081 STR02 LEV04 30-40cm MXH105		MXH105	Slag	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
104276	Shovel test pit	STP N117 E081 STR02 LEV04 30-40cm MXH105		MXH105	Slag	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104268	Shovel test pit	STP N117 E081 STR02 LEV04 30-40cm MXH105		MXH105	Slag	1	vessel, indeterminate	body	Ceramic	unidentified	Not Assigned	0	Not Assigned	
104267	Shovel test pit	STP N117 E081 STR02 LEV04 30-40cm MXH105		MXH105	Slag	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
104265	Shovel test pit	STP N117 E081 STR02 LEV04 30-40cm MXH105		MXH105	Slag	1	vessel, hollow	body	Glass	indeterminate	indeterminate		Not Assigned	-Clear
104270	Shovel test pit	STP N117 E081 STR02 LEV04 30-40cm MXH105		MXH105	Slag	4	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Blue-cobalt
104273	Shovel test pit	STP N117 E081 STR02 LEV04 30-40cm MXH105		MXH105	Slag	2	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
104275	Shovel test pit	STP N117 E081 STR02 LEV04 30-40cm MXH105		MXH105	Slag	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
104266	Shovel test pit	STP N117 E081 STR02 LEV04 30-40cm MXH105		MXH105	Slag	2	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
104271	Shovel test pit	STP N117 E081 STR02 LEV04 30-40cm MXH105		MXH105	Slag	3	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
104245	Shovel test pit	STP N117 E081 STR02 LEV06 50-60cm MXH106		MXH106	Slag	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
104248	Shovel test pit	STP N117 E081 STR02 LEV06 50-60cm MXH106		MXH106	Slag	1	flower pot	base	Ceramic	Earthenware, coarse	Redware, flowerpot	industry, manufacture, trades	gardening/farming	
104257	Shovel test pit	STP N117 E081 STR02 LEV06 50-60cm MXH106		MXH106	Slag	2	flower pot	body	Ceramic	Earthenware, coarse	Redware, flowerpot	industry, manufacture, trades	gardening/farming	
104241	Shovel test pit	STP N117 E081 STR02 LEV06 50-60cm MXH106		MXH106	Slag	2	vessel, indeterminate	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze		service	
104242	Shovel test pit	STP N117 E081 STR02 LEV06 50-60cm MXH106		MXH106	Slag	1	mug	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104246	Shovel test pit	STP N117 E081 STR02 LEV06 50-60cm MXH106		MXH106	Slag	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
104251	Shovel test pit	STP N117 E081 STR02 LEV06 50-60cm MXH106		MXH106	Slag	2	vessel, indeterminate	body	Ceramic	Earthenware, refined	Pearlware, undecorated		service	
104243	Shovel test pit	STP N117 E081 STR02 LEV06 50-60cm MXH106		MXH106	Slag	1	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	service	
104252	Shovel test pit	STP N117 E081 STR02 LEV06 50-60cm MXH106		MXH106	Slag	1	vessel, hollow	rim	Ceramic	Porcelain	Plain	food/beverage	service	
104247	Shovel test pit	STP N117 E081 STR02 LEV06 50-60cm MXH106		MXH106	Slag	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Blue-cobalt
104249	Shovel test pit	STP N117 E081 STR02 LEV06 50-60cm MXH106		MXH106	Slag	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
104255	Shovel test pit	STP N117 E081 STR02 LEV06 50-60cm MXH106		MXH106	Slag	2	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
104253	Shovel test pit	STP N117 E081 STR02 LEV06 50-60cm MXH106		MXH106	Slag	1	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
104250	Shovel test pit	STP N117 E081 STR02 LEV06 50-60cm MXH106		MXH106	Slag	3	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
104256	Shovel test pit	STP N117 E081 STR02 LEV06 50-60cm MXH106		MXH106	Slag	1	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
104254	Shovel test pit	STP N117 E081 STR02 LEV06 50-60cm MXH106		MXH106	Slag	1	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
104345	Shovel test pit	STP N117 E081 STR02 LEV07 60-70cm MXH108		MXH108	Slag	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
104342	Shovel test pit	STP N117 E081 STR02 LEV07 60-70cm MXH108		MXH108	Slag	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
104346	Shovel test pit	STP N117 E081 STR02 LEV07 60-70cm MXH108		MXH108	Slag	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, handpainted, underglaze	food/beverage	service	Annular-red
104340	Shovel test pit	STP N117 E081 STR02 LEV07 60-70cm MXH108		MXH108	Slag	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104343	Shovel test pit	STP N117 E081 STR02 LEV07 60-70cm MXH108		MXH108	Slag	1	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104347	Shovel test pit	STP N117 E081 STR02 LEV07 60-70cm MXH108		MXH108	Slag	1	vessel, flat	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104337	Shovel test pit	STP N117 E081 STR02 LEV07 60-70cm MXH108		MXH108	Slag	6	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104339	Shovel test pit	STP N117 E081 STR02 LEV07 60-70cm MXH108		MXH108	Slag	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104348	Shovel test pit	STP N117 E081 STR02 LEV07 60-70cm MXH108		MXH108	Slag	1	vessel, hollow	rim	Ceramic	Stoneware	gray, smooth glazed	food/beverage	storage	
104338	Shovel test pit	STP N117 E081 STR02 LEV07 60-70cm MXH108		MXH108	Slag	1	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
104349	Shovel test pit	STP N117 E081 STR02 LEV07 60-70cm MXH108		MXH108	Slag	1	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
104344	Shovel test pit	STP N117 E081 STR02 LEV07 60-70cm MXH108		MXH108	Slag	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
104341	Shovel test pit	STP N117 E081 STR02 LEV07 60-70cm MXH108		MXH108	Slag	1	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
104412	Shovel test pit	STP N117 E081 STR03 LEV07 65-70cm MXH109		MXH109	Fill	2	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104414	Shovel test pit	STP N117 E081 STR03 LEV07 65-70cm MXH109		MXH109	Fill	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104413	Shovel test pit	STP N117 E081 STR03 LEV07 65-70cm MXH109		MXH109	Fill	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
104411	Shovel test pit	STP N117 E081 STR03 LEV07 65-70cm MXH109		MXH109	Fill	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
104352	Shovel test pit	STP N117 E081 STR03 LEV08 70-80cm MXH110		MXH110	Fill	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
104357	Shovel test pit	STP N117 E081 STR03 LEV08 70-80cm MXH110		MXH110	Fill	3	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104354	Shovel test pit	STP N117 E081 STR03 LEV08 70-80cm MXH110		MXH110	Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
104355	Shovel test pit	STP N117 E081 STR03 LEV08 70-80cm MXH110		MXH110	Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104356	Shovel test pit	STP N117 E081 STR03 LEV08 70-80cm MXH110		MXH110	Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104351	Shovel test pit	STP N117 E081 STR03 LEV08 70-80cm MXH110		MXH110	Fill	1	nail, cut	tip	Metal	ferrous	cut	architecture	general construction	
104350	Shovel test pit	STP N117 E081 STR03 LEV08 70-80cm MXH110		MXH110	Fill	1	can	base	Metal	ferrous	machine made	storage	Not Assigned	
104353	Shovel test pit	STP N117 E081 STR03 LEV08 70-80cm MXH110		MXH110	Fill	3	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
104218	Shovel test pit	STP STR02 LEV02 10-20cm MXH011		MXH011	Buried APZ	7	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
104219	Shovel test pit	STP STR02 LEV02 10-20cm MXH011		MXH011	Buried APZ	5	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
104236	Shovel test pit	STP STR02 LEV02 10-20cm MXH011		MXH011	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	luster-blue
104213	Shovel test pit	STP STR02 LEV02 10-20cm MXH011		MXH011	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
104238	Shovel test pit	STP STR02 LEV02 10-20cm MXH011		MXH011	Buried APZ	4	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
104239	Shovel test pit	STP STR02 LEV02 10-20cm MXH011		MXH011	Buried APZ	5	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
104225	Shovel test pit	STP STR02 LEV02 10-20cm MXH011		MXH011	Buried APZ	1	vessel, hollow	handle	Ceramic	Earthenware, coarse	Staffordshire plain	food/beverage	service	

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
104217	Shovel test pit	STP STR02 LEV02 10-20cm MXH011		MXH011	Buried APZ	24	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104210	Shovel test pit	STP STR02 LEV02 10-20cm MXH011		MXH011	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
104234	Shovel test pit	STP STR02 LEV02 10-20cm MXH011		MXH011	Buried APZ	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	Annular-brown
104231	Shovel test pit	STP STR02 LEV02 10-20cm MXH011		MXH011	Buried APZ	3	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
104212	Shovel test pit	STP STR02 LEV02 10-20cm MXH011		MXH011	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
104214	Shovel test pit	STP STR02 LEV02 10-20cm MXH011		MXH011	Buried APZ	8	vessel, flat	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104211	Shovel test pit	STP STR02 LEV02 10-20cm MXH011		MXH011	Buried APZ	1	vessel, flat	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104226	Shovel test pit	STP STR02 LEV02 10-20cm MXH011		MXH011	Buried APZ	36	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104230	Shovel test pit	STP STR02 LEV02 10-20cm MXH011		MXH011	Buried APZ	1	vessel, hollow	foot	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104235	Shovel test pit	STP STR02 LEV02 10-20cm MXH011		MXH011	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	food/beverage	0	Not Assigned
104237	Shovel test pit	STP STR02 LEV02 10-20cm MXH011		MXH011	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	Westerwald	food/beverage	service	
104229	Shovel test pit	STP STR02 LEV02 10-20cm MXH011		MXH011	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
104224	Shovel test pit	STP STR02 LEV02 10-20cm MXH011		MXH011	Buried APZ	1	vessel, hollow	body	Ceramic	Tin Glazed	unidentified	food/beverage	0	Not Assigned
104220	Shovel test pit	STP STR02 LEV02 10-20cm MXH011		MXH011	Buried APZ	2	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
104233	Shovel test pit	STP STR02 LEV02 10-20cm MXH011		MXH011	Buried APZ	7	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
104228	Shovel test pit	STP STR02 LEV02 10-20cm MXH011		MXH011	Buried APZ	4	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
104209	Shovel test pit	STP STR02 LEV02 10-20cm MXH011		MXH011	Buried APZ	10	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
104215	Shovel test pit	STP STR02 LEV02 10-20cm MXH011		MXH011	Buried APZ	3	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
104216	Shovel test pit	STP STR02 LEV02 10-20cm MXH011		MXH011	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
104221	Shovel test pit	STP STR02 LEV02 10-20cm MXH011		MXH011	Buried APZ	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear*
104240	Shovel test pit	STP STR02 LEV02 10-20cm MXH011		MXH011	Buried APZ	6	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104223	Shovel test pit	STP STR02 LEV02 10-20cm MXH011		MXH011	Buried APZ	4	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
104232	Shovel test pit	STP STR02 LEV02 10-20cm MXH011		MXH011	Buried APZ	5	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
104208	Shovel test pit	STP STR02 LEV02 10-20cm MXH011		MXH011	Buried APZ	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
104227	Shovel test pit	STP STR02 LEV02 10-20cm MXH011		MXH011	Buried APZ	1	unidentified	fragment	Synthetic	synthetic	indeterminate	0	Not Assigned	
104222	Shovel test pit	STP STR02 LEV02 10-20cm MXH011		MXH011	Buried APZ	2	cup	fragment	Synthetic	synthetic	styrofoam	food/beverage	service	
108648	surface collection	Surface Alley on Grid North side GPR MXH006		MXH006	Surface/Developing A	4	flower pot	rim	Ceramic	Earthenware, coarse	Redware, flowerpot	industry, manufacture, trades	gardening/farming	
108649	surface collection	Surface Alley on Grid North side GPR MXH006		MXH006	Surface/Developing A	1	flower pot	base	Ceramic	Earthenware, coarse	Redware, flowerpot	industry, manufacture, trades	gardening/farming	
108631	surface collection	Surface Alley on Grid North side GPR MXH006		MXH006	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
108643	surface collection	Surface Alley on Grid North side GPR MXH006		MXH006	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
108629	surface collection	Surface Alley on Grid North side GPR MXH006		MXH006	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
108636	surface collection	Surface Alley on Grid North side GPR MXH006		MXH006	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
108650	surface collection	Surface Alley on Grid North side GPR MXH006		MXH006	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-orange
108645	surface collection	Surface Alley on Grid North side GPR MXH006		MXH006	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
108655	surface collection	Surface Alley on Grid North side GPR MXH006		MXH006	Surface/Developing A	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
108654	surface collection	Surface Alley on Grid North side GPR MXH006		MXH006	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
108657	surface collection	Surface Alley on Grid North side GPR MXH006		MXH006	Surface/Developing A	1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
108640	surface collection	Surface Alley on Grid North side GPR MXH006		MXH006	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Whiteware, undecorated	food/beverage	service	
108646	surface collection	Surface Alley on Grid North side GPR MXH006		MXH006	Surface/Developing A	5	vessel, hollow	body	Ceramic	Earthenware, refined	Whiteware, undecorated	food/beverage	service	
108651	surface collection	Surface Alley on Grid North side GPR MXH006		MXH006	Surface/Developing A	2	vessel, flat	rim	Ceramic	Porcelain	Chinese overglaze enamel	food/beverage	service	painted-blue
108652	surface collection	Surface Alley on Grid North side GPR MXH006		MXH006	Surface/Developing A	1	vessel, flat	body	Ceramic	Porcelain	Chinese overglaze enamel	food/beverage	service	painted-blue
108647	surface collection	Surface Alley on Grid North side GPR MXH006		MXH006	Surface/Developing A	1	vessel, hollow	body	Ceramic	Porcelain	Decorated	food/beverage	service	glided-gold
108653	surface collection	Surface Alley on Grid North side GPR MXH006		MXH006	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Porcelain	Plain	food/beverage	service	
108641	surface collection	Surface Alley on Grid North side GPR MXH006		MXH006	Surface/Developing A	1	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
108632	surface collection	Surface Alley on Grid North side GPR MXH006		MXH006	Surface/Developing A	1	bottle, indeterminate	lip/neck	Glass	mold blown	Not Assigned	food/beverage	service	-Milk Glass/Blue-External threads
108656	surface collection	Surface Alley on Grid North side GPR MXH006		MXH006	Surface/Developing A	1	bottle, indeterminate	lip/neck	Glass	mold blown	Not Assigned	food/beverage	storage	-Aqua-External threads
108642	surface collection	Surface Alley on Grid North side GPR MXH006		MXH006	Surface/Developing A	1	bottle, indeterminate	base	Glass	molded	molded	food/beverage	storage	-Clear
108638	surface collection	Surface Alley on Grid North side GPR MXH006		MXH006	Surface/Developing A	1	Tube	whole/intact	Metal	Aluminium	aluminum	0	Not Assigned	
108644	surface collection	Surface Alley on Grid North side GPR MXH006		MXH006	Surface/Developing A	1	pull tab	fragment	Metal	Aluminium	aluminum	food/beverage	storage	
108658	surface collection	Surface Alley on Grid North side GPR MXH006		MXH006	Surface/Developing A	1	cap, crown bottle	whole/intact	Metal	Aluminium	aluminum	food/beverage	storage	
108659	surface collection	Surface Alley on Grid North side GPR MXH006		MXH006	Surface/Developing A	1	cap, crown bottle	whole/intact	Metal	Aluminium	aluminum	food/beverage	storage	
108634	surface collection	Surface Alley on Grid North side GPR MXH006		MXH006	Surface/Developing A	1	electrical, misc.	fragment	Metal	copper alloy	copper alloy	heating, plumbing, electric	device	
108630	surface collection	Surface Alley on Grid North side GPR MXH006		MXH006	Surface/Developing A	1	stake	fragment	Metal	ferrous	machine made	0	Not Assigned	
108637	surface collection	Surface Alley on Grid North side GPR MXH006		MXH006	Surface/Developing A	1	screw	whole/intact	Metal	ferrous	machine made	architecture	general construction	
108633	surface collection	Surface Alley on Grid North side GPR MXH006		MXH006	Surface/Developing A	2	washer	whole/intact	Metal	steel	steel	0	Not Assigned	
108635	surface collection	Surface Alley on Grid North side GPR MXH006		MXH006	Surface/Developing A	1	ring	fragment	Synthetic	synthetic	rubber	0	Not Assigned	
108385	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	unidentified	fragment	0	0	0	Not Assigned	Not Assigned	
108360	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	2	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
108377	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
108361	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	flower pot	rim	Ceramic	Earthenware, coarse	Redware, flowerpot	industry, manufacture, trades	gardening/farming	
108382	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	sewer pipe	body	Ceramic	Earthenware, coarse	Redware, lead glazed	heating, plumbing, electric	device	
108351	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
108368	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
108352	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	10	vessel, hollow	body	Ceramic	Earthenware, coarse	unidentified	0	Not Assigned	
108390	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	3	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
108372	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
108379	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
108365	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	painted-pink
108370	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, refined	Whiteware, undecorated	food/beverage	service	
108374	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Whiteware, undecorated	food/beverage	service	
108366	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	vessel, hollow	body	Ceramic	Porcelain	Chinese overglaze enamel	food/beverage	service	
108363	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	figurine	fragment	Ceramic	Porcelain	Not Assigned	personal	other personal possession	
108386	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	2	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
108369	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	wood, structural	fragment	Flora	wood	unidentified	architecture	general construction	
108376	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	
108367	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
108358	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
108371	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Milk glass/Opaque white
108346	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	unidentified	whole/intact	Glass	Machine made	machine made	0	Not Assigned	
108388	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	bottle, indeterminate	base	Glass	Machine made	machine made	food/beverage	storage	-Green (bright 7-up)
108337	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	bottle, food	base	Glass	mold blown	contact, 2+ with separate base	food/beverage	storage	-Clear-ovoid
108339	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	bottle, indeterminate	lip/neck	Glass	mold blown	contact, 2+ with separate base	food/beverage	storage	-Amber-External threads
108357	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	bottle, indeterminate	base	Glass	mold blown	Not Assigned	food/beverage	storage	-Clear
108380	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	bottle, indeterminate	lip	Glass	mold blown	Not Assigned	food/beverage	storage	-Clear-External threads
108347	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	plate	base	Glass	mold/pressed	Not Assigned	food/beverage	service	-Green*
108348	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	2	plate	rim	Glass	mold/pressed	Not Assigned	food/beverage	service	-Green*
108349	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	plate	body	Glass	mold/pressed	Not Assigned	food/beverage	service	-Green*
108350	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	plate	base	Glass	mold/pressed	Not Assigned	food/beverage	service	-Green*
108356	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	nut	whole/intact	Metal	Aluminium	aluminum	0	Not Assigned	
108362	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	ring	fragment	Metal	Aluminium	aluminum	architecture	hardware	
108354	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	coin	whole/intact	Metal	copper alloy	copper alloy	commerce	coin	
108381	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	5	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
108341	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	bar	fragment	Metal	ferrous	machine made	0	Not Assigned	
108345	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	sheet metal	fragment	Metal	ferrous	machine made	0	Not Assigned	
108340	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	screw	whole/intact	Metal	ferrous	machine made	architecture	general construction	
108344	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	4	nail, wire	whole/intact	Metal	ferrous	machine made	architecture	general construction	
108353	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	screw	whole/intact	Metal	ferrous	machine made	architecture	general construction	
108355	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	ring	whole/intact	Metal	steel	steel	0	Not Assigned	
108338	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	cap, screw top	whole/intact	Metal	steel	steel	food/beverage	storage	
108373	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	mortar	fragment	Mineral	composite	mortar	architecture	window	
108342	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
108384	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
108378	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	paint	fragment	Synthetic	synthetic	indeterminate	0	Not Assigned	
108391	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	paint	fragment	Synthetic	synthetic	Not Assigned	0	Not Assigned	
108343	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	vessel, hollow	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
108359	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	tag	whole/intact	Synthetic	synthetic	plastic	0	Not Assigned	
108364	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
108375	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	vessel, indeterminate	rim	Synthetic	synthetic	plastic	0	Not Assigned	
108383	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	handle	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
108389	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
108387	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1	button, two hole	whole/intact	Synthetic	synthetic	plastic	personal	fastener	
108336	surface collection	Surface Barn Below Door on East Side of Addition MXH008		MXH008	Surface/Developing A	1		whole/intact	Synthetic	synthetic	plastic	recreation/leisure	music	
108605	surface collection	Surface Berm in Grid East corner of Yard GPR MXH005		MXH005	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	painted-yellow
108613	surface collection	Surface Berm in Grid East corner of Yard GPR MXH005		MXH005	Surface/Developing A	1	vessel, hollow	base	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
108625	surface collection	Surface Berm in Grid East corner of Yard GPR MXH005		MXH005	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
108608	surface collection	Surface Berm in Grid East corner of Yard GPR MXH005		MXH005	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
108618	surface collection	Surface Berm in Grid East corner of Yard GPR MXH005		MXH005	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
108624	surface collection	Surface Berm in Grid East corner of Yard GPR MXH005		MXH005	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Ironstone	food/beverage	service	
108621	surface collection	Surface Berm in Grid East corner of Yard GPR MXH005		MXH005	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
108607	surface collection	Surface Berm in Grid East corner of Yard GPR MXH005		MXH005	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
108610	surface collection	Surface Berm in Grid East corner of Yard GPR MXH005		MXH005	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Whiteware, undecorated	food/beverage	service	
108626	surface collection	Surface Berm in Grid East corner of Yard GPR MXH005		MXH005	Surface/Developing A	1	doll	fragment	Ceramic	Porcelain	Decorated	recreation/leisure	toys	painted-pink
108612	surface collection	Surface Berm in Grid East corner of Yard GPR MXH005		MXH005	Surface/Developing A	3	bottle, indeterminate	body	Glass	embossed	embossed	food/beverage	storage	-Clear
108616	surface collection	Surface Berm in Grid East corner of Yard GPR MXH005		MXH005	Surface/Developing A	1	bottle, indeterminate	base	Glass	embossed	embossed	food/beverage	storage	-Clear
108619	surface collection	Surface Berm in Grid East corner of Yard GPR MXH005		MXH005	Surface/Developing A	2	bottle, indeterminate	base	Glass	embossed	embossed	food/beverage	storage	-Clear-ovoid with 2 flat sides

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
108617	surface collection	Surface Berm in Grid East corner of Yard GPR MXH005		MXH005	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	0	Not Assigned	-Green (bright 7-up)
108611	surface collection	Surface Berm in Grid East corner of Yard GPR MXH005		MXH005	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
108615	surface collection	Surface Berm in Grid East corner of Yard GPR MXH005		MXH005	Surface/Developing A	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
108623	surface collection	Surface Berm in Grid East corner of Yard GPR MXH005		MXH005	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (bright 7-up)
108627	surface collection	Surface Berm in Grid East corner of Yard GPR MXH005		MXH005	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Milk Glass/Blue
108628	surface collection	Surface Berm in Grid East corner of Yard GPR MXH005		MXH005	Surface/Developing A	1	drinking glass, tumbler	rim	Glass	molded	molded	food/beverage	service	-Green*
108620	surface collection	Surface Berm in Grid East corner of Yard GPR MXH005		MXH005	Surface/Developing A	1	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
108609	surface collection	Surface Berm in Grid East corner of Yard GPR MXH005		MXH005	Surface/Developing A	1	screw	whole/intact	Synthetic	synthetic	plastic	Not Assigned	0	
108622	surface collection	Surface Berm in Grid East corner of Yard GPR MXH005		MXH005	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
108606	surface collection	Surface Berm in Grid East corner of Yard GPR MXH005		MXH005	Surface/Developing A	1	shoe	fragment	Synthetic	synthetic	rubber	personal	clothing	
108430	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	3	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
108497	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
108479	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	painted-blue
108410	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	5	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
108512	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	2	vessel, hollow	base	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
108404	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	unidentified	0	Not Assigned	painted-yellow
108432	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	unidentified	fragment	Ceramic	Earthenware, coarse	unidentified	architecture	general construction	
108518	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	unidentified	food/beverage	storage	
108464	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
108519	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	15	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
108523	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Ironstone	food/beverage	service	
108539	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Ironstone	food/beverage	service	painted-pink
108458	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Ironstone	food/beverage	service	transfer print-pink
108540	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	vessel, hollow	base	Ceramic	Earthenware, refined	Ironstone, molded	food/beverage	service	
108478	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	4	vessel, hollow	body	Ceramic	Earthenware, refined	Not Assigned	food/beverage	service	painted-blue
108453	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-red
108482	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
108557	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-brown
108455	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
108549	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	2	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
108527	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	12	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	painted-blue
108507	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	7	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
108541	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	vessel, hollow	base	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
108542	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
108546	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	17	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
108556	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
108417	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	3	vessel, flat	rim	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	painted-pink
108480	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Whiteware, hand painted polychrome	food/beverage	service	painted-blue
108481	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	vessel, hollow	base	Ceramic	Earthenware, refined	Whiteware, undecorated	food/beverage	service	
108514	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	3	vessel, hollow	body	Ceramic	Earthenware, refined	Whiteware, undecorated	food/beverage	service	
108537	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	3	vessel, flat	body	Ceramic	Earthenware, refined	Whiteware, undecorated	food/beverage	service	
108426	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Yellow ware, banded	food/beverage	service	
108465	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Porcelain	Chinese overglaze enamel	food/beverage	service	
108550	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	vessel, flat	rim	Ceramic	Porcelain	Decorated	food/beverage	service	painted-blue
108487	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	vessel, hollow	body	Ceramic	Porcelain	Decorated	food/beverage	service	transfer print-blue
108530	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	2	vessel, hollow	body	Ceramic	Porcelain	Decorated	food/beverage	service	transfer print-blue
108420	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	plate	e	Ceramic	Porcelain	Decorated	food/beverage	service	gilded-gold
108484	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	vessel, hollow	body	Ceramic	Porcelain	Decorated	food/beverage	service	gilded-gold
108498	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Porcelain	Decorated	food/beverage	service	gilded-gold
108419	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	vessel, hollow	body	Ceramic	Porcelain	Decorated	food/beverage	service	gilded-gray
108495	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	2	vessel, hollow	body	Ceramic	Porcelain	Decorated	food/beverage	service	painted-green
108483	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Porcelain	Decorated	food/beverage	service	painted-red
108402	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	bottle, wine/liquor/beer	near intact	Ceramic	Porcelain	Decorated	food/beverage	storage	
108403	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	cup	handle	Ceramic	Porcelain	Plain	food/beverage	service	
108475	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Porcelain	Plain	food/beverage	service	
108477	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	service	
108522	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	3	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	storage	
108491	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	2	vessel, hollow	base	Ceramic	Stoneware	Buff smooth-glazed	food/beverage	storage	Albany slip-brown
108547	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	2	vessel, hollow	base	Ceramic	Stoneware	Unidentified	food/beverage	storage	
108470	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	vessel, hollow	base	Ceramic	Stoneware	Unidentified	food/beverage	storage	Albany slip-black
108499	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	4	vessel, hollow	body	Ceramic	Stoneware	Unidentified	food/beverage	storage	Albany slip-brown
108405	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	sewer pipe	fragment	Ceramic	Stoneware	Unidentified	heating, plumbing, electric	device	
108413	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
108461	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	3	vessel, hollow	base	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
108533	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	2	vessel, hollow	base	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
108548	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
108503	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	plate	rim	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
108415	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	lightbulb	base	Composite Artifact	composite artifact	composite artifact	lighting	device	
108460	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	lightbulb	whole/intact	Composite Artifact	composite artifact	composite artifact	lighting	device	
108493	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	lightbulb	base	Composite Artifact	composite artifact	composite artifact	lighting	device	
108472	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	9	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
108504	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	13	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
108511	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
108471	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	shell, oyster	whole/intact	Fauna	shell	bivalve	food/beverage	acquisition	
108555	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	10	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
108466	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	3	shell	fragment	Fauna	shell	mollosk	0	Not Assigned	
108489	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	2	charcoal	fragment	Flora	wood	charcoal	heating, plumbing, electric	fuel	
108536	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	lid	fragment	Glass	embossed	embossed	food/beverage	storage	
108454	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	bottle, indeterminate	base	Glass	embossed	embossed	food/beverage	storage	-Amber
108517	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
108505	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
108496	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	0	Not Assigned	-Clear
108526	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua marine*
108448	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	6	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
108486	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	bottle, indeterminate	base	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
108488	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
108506	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	bottle, indeterminate	base	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
108516	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
108520	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
108528	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
108513	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Milk Glass/Blue
108521	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	bottle, indeterminate	lip	Glass	indeterminate	indeterminate	food/beverage	storage	-Milk Glass/Blue
108538	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	vessel, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Milk glass/Opaque white
108545	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Milk glass/Opaque white
108457	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	bottle, indeterminate	base	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear-circular
108446	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	bottle, indeterminate	base	Glass	Machine made	machine made	food/beverage	storage	-Aqua
108395	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	bottle, Soda	base	Glass	Machine made	machine made	food/beverage	storage	-Clear
108400	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	bottle, wine/liquor/beer	base	Glass	Machine made	machine made	food/beverage	storage	-Clear
108502	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	bottle, indeterminate	base	Glass	Machine made	machine made	food/beverage	storage	-Clear
108392	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	bottle, food	base	Glass	mold blown	contact, 2+ with separate base	food/beverage	storage	
108393	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	bottle, indeterminate	base	Glass	mold blown	contact, 2+ with separate base	food/beverage	storage	-Green (bright 7-up)
108456	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	bottle, indeterminate	base	Glass	mold blown	contact, 2+ with separate base	food/beverage	storage	-Aqua-ovoid
108396	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	bottle, perfume	whole/intact	Glass	mold blown	contact, 2+ with separate base	personal	toiletry/hygiene	-Clear-circular-External threads
108414	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	2	bottle, indeterminate	lip/neck	Glass	mold blown	contact, 2-piece mold	food/beverage	storage	-Clear
108447	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	bottle, indeterminate	lip/neck	Glass	mold blown	mold blown	food/beverage	storage	
108532	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	Tube	fragment	Glass	molded	molded	0	Not Assigned	-Clear
108459	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	bottle, indeterminate	base	Glass	molded	molded	food/beverage	storage	-Clear
108544	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	bottle, indeterminate	lip/neck	Glass	molded	molded	food/beverage	storage	-Milk glass/Opaque white-Stacked Ring
108552	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	Thermometer	fragment	Glass	molded	molded	personal	other personal possession	-Clear
108531	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	eye	fragment	Glass	molded	molded	recreation/leisure	toys	-Clear
108409	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	cap, screw top	fragment	Metal	Aluminium	aluminum	food/beverage	storage	
108485	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	ring	fragment	Metal	copper alloy	copper alloy	0	Not Assigned	
108529	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	Tube	fragment	Metal	copper alloy	copper alloy	0	Not Assigned	
108399	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	coin	whole/intact	Metal	copper alloy	copper alloy	commerce	coin	
108436	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	lock, furniture	whole/intact	Metal	copper alloy	copper alloy	furniture/household equip.	hardware	
108408	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	electrical, misc.	fragment	Metal	copper alloy	copper alloy	lighting	device	
108476	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	button	whole/intact	Metal	copper alloy	Not Assigned	personal	fastener	
108445	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	vessel, indeterminate	fragment	Metal	ferrous	cast	0	Not Assigned	
108494	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	cap, crown bottle	fragment	Metal	ferrous	cast	0	Not Assigned	
108501	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	rod	fragment	Metal	ferrous	cast	architecture	general construction	
108427	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	pipe, plumbing/gas	whole/intact	Metal	ferrous	cast	architecture	hardware	
108428	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	finial	whole/intact	Metal	ferrous	cast	architecture	hardware	
108449	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	hardware, other	whole/intact	Metal	ferrous	cast	architecture	hardware	
108473	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	pulley	whole/intact	Metal	ferrous	cast	architecture	hardware	
108525	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	hinge, door	fragment	Metal	ferrous	cast	architecture	hardware	

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
108534	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	4	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
108431	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	tool	fragment	Metal	ferrous	machine made	0	Not Assigned	
108433	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	washer	whole/intact	Metal	ferrous	machine made	0	Not Assigned	
108452	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	spring	fragment	Metal	ferrous	machine made	0	Not Assigned	
108429	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	screw	head	Metal	ferrous	machine made	architecture	general construction	
108451	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	screw	whole/intact	Metal	ferrous	machine made	architecture	general construction	
108500	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	cap, crown bottle	fragment	Metal	ferrous	machine made	food/beverage	storage	
108463	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	Tube	fragment	Metal	ferrous	unidentified	0	Not Assigned	
108510	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	tool	fragment	Metal	ferrous	unidentified	0	Not Assigned	
108524	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	sheet metal	fragment	Metal	ferrous	unidentified	0	Not Assigned	
108434	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	hook	whole/intact	Metal	ferrous	wrought	architecture	hardware	
108435	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	unidentified	fragment	Metal	lead	cast	0	Not Assigned	
108411	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	can	base	Metal	steel	steel	0	Not Assigned	
108407	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	washer	whole/intact	Metal	steel	steel	architecture	general construction	
108467	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	unidentified	fragment	Metal	white metal	white metal	0	Not Assigned	
108543	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	4	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
108406	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	plaster, plain	fragment	Mineral	composite	plaster	architecture	general construction	
108444	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	3	stone	fragment	Stone	0	Not Assigned	architecture	foundation	
108424	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
108462	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	asphalt	fragment	Synthetic	synthetic	asphalt	architecture	foundation	
108425	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	Tube	whole/intact	Synthetic	synthetic	plastic	0	Not Assigned	
108443	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	cap, screw top	whole/intact	Synthetic	synthetic	plastic	0	Not Assigned	
108450	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
108490	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	vessel, indeterminate	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
108515	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
108551	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
108553	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	vessel, indeterminate	rim	Synthetic	synthetic	plastic	0	Not Assigned	
108554	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
108558	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	wire	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
108469	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	handle, cutlery	handle	Synthetic	synthetic	plastic	food/beverage	service	
108509	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	cup	fragment	Synthetic	synthetic	plastic	food/beverage	storage	
108422	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	tag	fragment	Synthetic	synthetic	plastic	personal	clothing	
108412	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	button	whole/intact	Synthetic	synthetic	plastic	personal	fastener	
108468	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	button, four hole	whole/intact	Synthetic	synthetic	plastic	personal	fastener	
108474	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	button	whole/intact	Synthetic	synthetic	plastic	personal	fastener	
108416	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	comb, hair	fragment	Synthetic	synthetic	plastic	personal	toiletry/hygiene	
108508	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	comb, hair	fragment	Synthetic	synthetic	plastic	personal	toiletry/hygiene	
108421	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	plastic	recreation/leisure	toys	
108423	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	Tube	fragment	Synthetic	synthetic	rubber	0	Not Assigned	
108492	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	rubber	0	Not Assigned	
108535	surface collection	Surface Berm on Eastern Foundation of main building grid south MXH007		MXH007	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	rubber	0	Not Assigned	
99624	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	pipe, stem	fragment	Ceramic	Ball clay	Not Assigned	recreation/leisure	smoking/tobacco	
99628	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	pipe, bowl/stem	fragment	Ceramic	Ball clay	Not Assigned	recreation/leisure	smoking/tobacco	-5/64
99631	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	pipe, stem	fragment	Ceramic	Ball clay	Not Assigned	recreation/leisure	smoking/tobacco	-4/64
99538	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	vessel, indeterminate	body	Ceramic	Earthenware, coarse	Redware unidentified	food/beverage	preparation	
99574	surface collection	Surface General MXH001		MXH001	Surface/Developing A	4	flower pot	body	Ceramic	Earthenware, coarse	Redware, flowerpot	industry, manufacture, trades	gardening/farming	
99601	surface collection	Surface General MXH001		MXH001	Surface/Developing A	4	flower pot	rim	Ceramic	Earthenware, coarse	Redware, flowerpot	industry, manufacture, trades	gardening/farming	
99649	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	vessel, indeterminate	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	-brown
99621	surface collection	Surface General MXH001		MXH001	Surface/Developing A	2	vessel, indeterminate	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
99573	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	vessel, indeterminate	base	Ceramic	Earthenware, coarse	Staffordshire, slipped	food/beverage	service	
99619	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	vessel, indeterminate	body	Ceramic	Earthenware, coarse	Staffordshire, slipped	food/beverage	service	molded
99675	surface collection	Surface General MXH001		MXH001	Surface/Developing A	2	vessel, indeterminate	body	Ceramic	Earthenware, coarse	unidentified	0	Not Assigned	molded
99657	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	unidentified	industry, manufacture, trades	gardening/farming	
99602	surface collection	Surface General MXH001		MXH001	Surface/Developing A	9	vessel, indeterminate	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
99626	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	vessel, indeterminate	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
99583	surface collection	Surface General MXH001		MXH001	Surface/Developing A	4	vessel, indeterminate	rim	Ceramic	Earthenware, refined	Ironstone	food/beverage	service	
99603	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	vessel, indeterminate	body	Ceramic	Earthenware, refined	Ironstone	food/beverage	service	
99614	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	vessel, hollow	base	Ceramic	Earthenware, refined	Ironstone	food/beverage	service	
99616	surface collection	Surface General MXH001		MXH001	Surface/Developing A	2	vessel, indeterminate	rim	Ceramic	Earthenware, refined	Ironstone	food/beverage	service	
99647	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	vessel, indeterminate	body	Ceramic	Earthenware, refined	Ironstone	food/beverage	service	
99667	surface collection	Surface General MXH001		MXH001	Surface/Developing A	2	vessel, indeterminate	body	Ceramic	Earthenware, refined	Ironstone, molded	food/beverage	service	
99604	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	vessel, indeterminate	rim	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	Annular-brown
99539	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	vessel, indeterminate	rim	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-green
99612	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	plate	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	molded-blue
99548	surface collection	Surface General MXH001		MXH001	Surface/Developing A	5	vessel, indeterminate	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
99606	surface collection	Surface General MXH001		MXH001	Surface/Developing A	5	vessel, indeterminate	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
99652	surface collection	Surface General MXH001		MXH001	Surface/Developing A	2	vessel, indeterminate	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
99671	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	vessel, indeterminate	body	Ceramic	Earthenware, refined	unidentified	food/beverage	service	-blue
99676	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	vessel, indeterminate	body	Ceramic	Earthenware, refined	unidentified	food/beverage	service	-blue
99541	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	vessel, indeterminate	handle	Ceramic	Earthenware, refined	Whiteware, flow blue	food/beverage	service	flow blue
99553	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	vessel, indeterminate	rim	Ceramic	Earthenware, refined	Whiteware, flow blue	food/beverage	service	flow blue
99660	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	vessel, indeterminate	body	Ceramic	Earthenware, refined	Whiteware, transfer printed	food/beverage	service	transfer print-blue
99559	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	vessel, indeterminate	rim	Ceramic	Earthenware, refined	Whiteware, transfer printed	food/beverage	service	transfer print-pink
99668	surface collection	Surface General MXH001		MXH001	Surface/Developing A	6	vessel, indeterminate	body	Ceramic	Earthenware, refined	Whiteware, undecorated	food/beverage	service	
99542	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	vessel, indeterminate	body	Ceramic	Earthenware, refined	Whiteware, undentified	food/beverage	service	-pink
99611	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	vessel, indeterminate	body	Ceramic	Earthenware, refined	Yellow ware, plain	food/beverage	service	
99672	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	figurine	fragment	Ceramic	Porcelain	unidentified		Not Assigned	
99540	surface collection	Surface General MXH001		MXH001	Surface/Developing A	2	vessel, indeterminate	base	Ceramic	Porcelain	unidentified	food/beverage	service	
99662	surface collection	Surface General MXH001		MXH001	Surface/Developing A	3	vessel, indeterminate	body	Ceramic	Porcelain	unidentified	food/beverage	service	
99664	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	vessel, indeterminate	body	Ceramic	Porcelain	unidentified	food/beverage	service	
99666	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	vessel, indeterminate	body	Ceramic	Porcelain	unidentified	food/beverage	service	gilded
99607	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	lid	lid	Ceramic	Porcelain	unidentified	food/beverage	service	painted-blue
99617	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	vessel, indeterminate	body	Ceramic	Porcelain	unidentified	food/beverage	service	painted-blue
99575	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	vessel, indeterminate	body	Ceramic	Porcelain	unidentified	food/beverage	service	gilded-gold
99608	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	plate	rim	Ceramic	Porcelain	unidentified	food/beverage	service	painted-multi
99632	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	vessel, flat	base	Ceramic	Porcelain	unidentified	food/beverage	service	painted-multi
99651	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	vessel, hollow	body	Ceramic	Stoneware	Westerwald	food/beverage	service	molded-blue
99645	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	vessel, indeterminate	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
99669	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	vessel, indeterminate	base	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
99635	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	bone	fragment	Fauna	bone	indeterminate	food/beverage	acquisition	
99654	surface collection	Surface General MXH001		MXH001	Surface/Developing A	8	bone	fragment	Fauna	bone	indeterminate	food/beverage	acquisition	
99570	surface collection	Surface General MXH001		MXH001	Surface/Developing A	2	shell	near intact	Fauna	shell	mollosk	food/beverage	acquisition	
99572	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	shell, indeterminate	fragment	Fauna	shell	Not Assigned	food/beverage	acquisition	
99587	surface collection	Surface General MXH001		MXH001	Surface/Developing A	2	seed	near intact	Flora	seed/pit/nut	peach	food/beverage	acquisition	
99567	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	bottle, indeterminate	body	Glass	Blown/molded	Blown/molded	food/beverage	storage	-Clear
99579	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	bottle, indeterminate	base	Glass	Blown/molded	Blown/molded	food/beverage	storage	-Milk glass/Opaque white
99561	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	bottle, indeterminate	body	Glass	embossed	embossed	food/beverage	service	-Clear
99554	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	bottle, indeterminate	body	Glass	embossed	embossed	food/beverage	storage	-Clear
99627	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	unidentified	fragment	Glass	flat	flat	0	Not Assigned	-Aqua
99670	surface collection	Surface General MXH001		MXH001	Surface/Developing A	2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
99551	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
99585	surface collection	Surface General MXH001		MXH001	Surface/Developing A	4	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Milk glass/Opaque white
99563	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	marble	whole/intact	Glass	indeterminate	indeterminate	recreation/leisure	toys	-Green*
99564	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	marble	whole/intact	Glass	indeterminate	indeterminate	recreation/leisure	toys	-Yellow
99592	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	bottle, indeterminate	base	Glass	Machine made	machine made	food/beverage	storage	-Clear-circular
99566	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	bottle, indeterminate	base	Glass	Machine made	machine made	food/beverage	storage	-Clear-circular
99593	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	bottle, indeterminate	base	Glass	Machine made	machine made	food/beverage	storage	-Green (bright 7-up)-circular
99686	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	bottle, wine/liquor/beer	whole/intact	Glass	Machine made	machine made	food/beverage	storage	-Amber-ovoid
99543	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	bottle, indeterminate	base	Glass	Machine made	machine made	food/beverage	storage	-Amber-ovoid
99623	surface collection	Surface General MXH001		MXH001	Surface/Developing A	2	bottle, wine/liquor/beer	body	Glass	mold blown	mold blown	food/beverage	storage	-Green (olive)
99547	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	vessel, indeterminate	body	Glass	molded	molded		Not Assigned	-Milk glass/Opaque white
99549	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	vessel, indeterminate	rim	Glass	molded	molded	food/beverage	service	-Green*
99546	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	vessel, indeterminate	body	Glass	molded	molded	food/beverage	storage	-Clear
99676	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	bottle, indeterminate	lip	Glass	molded	molded	food/beverage	storage	-Milk glass/Opaque white
99588	surface collection	Surface General MXH001		MXH001	Surface/Developing A	2	unidentified	whole/intact	Metal	Aluminium	aluminum	recreation/leisure	toys	
99600	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	hardware, other	fragment	Metal	copper alloy	copper alloy	0	Not Assigned	
99678	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	hardware, other	whole/intact	Metal	copper alloy	copper alloy	0	Not Assigned	
99555	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	coin	whole/intact	Metal	copper alloy	copper alloy	commerce	coin	
99580	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	coin	whole/intact	Metal	copper alloy	copper alloy	commerce	coin	
99595	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	electrical, misc.	whole/intact	Metal	ferrous	machine made	heating, plumbing, electric	device	
99633	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	hardware, other	whole/intact	Metal	ferrous	unidentified	0	Not Assigned	
99639	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	spike	near intact	Metal	ferrous	unidentified	0	Not Assigned	
99643	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	bar	fragment	Metal	ferrous	unidentified	0	Not Assigned	
99674	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	Tube	fragment	Metal	ferrous	unidentified	0	Not Assigned	
99681	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	unidentified	fragment	Metal	ferrous	unidentified	0	Not Assigned	

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
99677	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	Wheel	near intact	Metal	ferrous	unidentified		Not Assigned	
99673	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	hardware	
99637	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	file	whole/intact	Metal	ferrous	unidentified	industry, manufacture, trades	Not Assigned	
99685	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	tool	whole/intact	Metal	ferrous	unidentified	industry, manufacture, trades	woodworking	
99599	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	key, door	whole/intact	Metal	ferrous	wrought	furniture/household equip.	Not Assigned	
99683	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	unidentified	near intact	Synthetic	synthetic	indeterminate	0	Not Assigned	
99582	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
99550	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	bead	whole/intact	Synthetic	synthetic	plastic	personal	adornment	
99557	surface collection	Surface General MXH001		MXH001	Surface/Developing A	1	bead	0	Synthetic	synthetic	plastic	personal	adornment	
108571	surface collection	Surface Material from Bulckhead MXH009		MXH009	Surface/Developing A	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
108566	surface collection	Surface Material from Bulckhead MXH009		MXH009	Surface/Developing A	4	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
108567	surface collection	Surface Material from Bulckhead MXH009		MXH009	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
108583	surface collection	Surface Material from Bulckhead MXH009		MXH009	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Ironstone	food/beverage	service	
108572	surface collection	Surface Material from Bulckhead MXH009		MXH009	Surface/Developing A	1	electrical, misc.	fragment	Ceramic	Porcelain	Plain	heating, plumbing, electric	device	
108559	surface collection	Surface Material from Bulckhead MXH009		MXH009	Surface/Developing A	14	toilet	fragment	Ceramic	Porcelain	Plain	personal	toiletry/hygiene	
108560	surface collection	Surface Material from Bulckhead MXH009		MXH009	Surface/Developing A	1	caster	near intact	Composite Artifact	composite artifact	composite artifact	furniture/household equip.	hardware	
108561	surface collection	Surface Material from Bulckhead MXH009		MXH009	Surface/Developing A	2	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
108574	surface collection	Surface Material from Bulckhead MXH009		MXH009	Surface/Developing A	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
108569	surface collection	Surface Material from Bulckhead MXH009		MXH009	Surface/Developing A	1	Tube	fragment	Glass	indeterminate	indeterminate		Not Assigned	-Aqua
108582	surface collection	Surface Material from Bulckhead MXH009		MXH009	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
108570	surface collection	Surface Material from Bulckhead MXH009		MXH009	Surface/Developing A	1	Thermometer	fragment	Glass	indeterminate	indeterminate	medical/chemical	tool	-Clear
108575	surface collection	Surface Material from Bulckhead MXH009		MXH009	Surface/Developing A	1	light fixture, electric	fragment	Metal	copper alloy	copper alloy	lighting	device	
108563	surface collection	Surface Material from Bulckhead MXH009		MXH009	Surface/Developing A	2	washer	fragment	Metal	ferrous	cast	architecture	hardware	
108573	surface collection	Surface Material from Bulckhead MXH009		MXH009	Surface/Developing A	1	hinge, door	fragment	Metal	ferrous	cast	architecture	hardware	
108578	surface collection	Surface Material from Bulckhead MXH009		MXH009	Surface/Developing A	14	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
108580	surface collection	Surface Material from Bulckhead MXH009		MXH009	Surface/Developing A	1	ring	fragment	Metal	ferrous	machine made	0	Not Assigned	
108577	surface collection	Surface Material from Bulckhead MXH009		MXH009	Surface/Developing A	3	nail, wire	whole/intact	Metal	ferrous	machine made	architecture	general construction	
108568	surface collection	Surface Material from Bulckhead MXH009		MXH009	Surface/Developing A	1	lock, pad	whole/intact	Metal	ferrous	machine made	architecture	hardware	
108565	surface collection	Surface Material from Bulckhead MXH009		MXH009	Surface/Developing A	5	sheet metal	fragment	Metal	ferrous	unidentified	0	Not Assigned	
108579	surface collection	Surface Material from Bulckhead MXH009		MXH009	Surface/Developing A	1	hardware, other	fragment	Metal	ferrous	unidentified	0	Not Assigned	
108576	surface collection	Surface Material from Bulckhead MXH009		MXH009	Surface/Developing A	17	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
108564	surface collection	Surface Material from Bulckhead MXH009		MXH009	Surface/Developing A	1	unidentified	fragment	Metal	lead	cast	0	Not Assigned	
108581	surface collection	Surface Material from Bulckhead MXH009		MXH009	Surface/Developing A	3	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
108562	surface collection	Surface Material from Bulckhead MXH009		MXH009	Surface/Developing A	1	tag	fragment	Synthetic	synthetic	plastic	food/beverage	storage	
108588	surface collection	Surface Rear Yard Scraping for GPR MXH004		MXH004	Surface/Developing A	1	flower pot	base	Ceramic	Earthenware, coarse	Redware, flowerpot	industry, manufacture, trades	gardening/farming	
108589	surface collection	Surface Rear Yard Scraping for GPR MXH004		MXH004	Surface/Developing A	1	vessel, flat	body	Ceramic	Earthenware, refined	Whiteware, undecorated	food/beverage	service	
108599	surface collection	Surface Rear Yard Scraping for GPR MXH004		MXH004	Surface/Developing A	8	tile, floor	fragment	Ceramic	Porcelain	Plain	architecture	foundation	
108587	surface collection	Surface Rear Yard Scraping for GPR MXH004		MXH004	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Stoneware	Buff smooth-glazed	food/beverage	storage	
108590	surface collection	Surface Rear Yard Scraping for GPR MXH004		MXH004	Surface/Developing A	2	vessel, hollow	body	Ceramic	Stoneware	Buff smooth-glazed	food/beverage	storage	
108600	surface collection	Surface Rear Yard Scraping for GPR MXH004		MXH004	Surface/Developing A	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
108586	surface collection	Surface Rear Yard Scraping for GPR MXH004		MXH004	Surface/Developing A	1	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
108597	surface collection	Surface Rear Yard Scraping for GPR MXH004		MXH004	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Amber
108594	surface collection	Surface Rear Yard Scraping for GPR MXH004		MXH004	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
108604	surface collection	Surface Rear Yard Scraping for GPR MXH004		MXH004	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (bright 7-up)
108601	surface collection	Surface Rear Yard Scraping for GPR MXH004		MXH004	Surface/Developing A	1	bottle, indeterminate	base	Glass	mold blown	contact, 2+ with separate base	food/beverage	storage	-Clear-circular
108598	surface collection	Surface Rear Yard Scraping for GPR MXH004		MXH004	Surface/Developing A	1	bottle, wine/liquor/beer	near intact	Glass	mold blown	contact, 2+ with separate base	food/beverage	storage	-Clear-circular-machine made (1903)
108593	surface collection	Surface Rear Yard Scraping for GPR MXH004		MXH004	Surface/Developing A	1	bottle, indeterminate	base	Glass	mold blown	indeterminate	food/beverage	storage	-Clear
108603	surface collection	Surface Rear Yard Scraping for GPR MXH004		MXH004	Surface/Developing A	1	bottle, wine/liquor/beer	base	Glass	mold blown	Not Assigned	food/beverage	storage	-Green (bright 7-up)-circular
108592	surface collection	Surface Rear Yard Scraping for GPR MXH004		MXH004	Surface/Developing A	1	bottle, indeterminate	lip/neck	Glass	mold blown	Not Assigned	food/beverage	storage	-Clear-Bead
108595	surface collection	Surface Rear Yard Scraping for GPR MXH004		MXH004	Surface/Developing A	1	vessel, indeterminate	body	Glass	pressed	patterned	0	Not Assigned	-Clear
108596	surface collection	Surface Rear Yard Scraping for GPR MXH004		MXH004	Surface/Developing A	1	handle/pull, furniture	whole/intact	Metal	ferrous	cast	furniture/household equip.	hardware	
108602	surface collection	Surface Rear Yard Scraping for GPR MXH004		MXH004	Surface/Developing A	1	nail, wire	fragment	Metal	ferrous	machine made	architecture	general construction	
108584	surface collection	Surface Rear Yard Scraping for GPR MXH004		MXH004	Surface/Developing A	2	wire	fragment	Metal	ferrous	unidentified	0	Not Assigned	
108591	surface collection	Surface Rear Yard Scraping for GPR MXH004		MXH004	Surface/Developing A	1	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
108585	surface collection	Surface Rear Yard Scraping for GPR MXH004		MXH004	Surface/Developing A	1	Wheel	whole/intact	Synthetic	synthetic	rubber	recreation/leisure	toys	
99715	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	1	vessel, indeterminate	base	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	molded
99704	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	1	pipe, plumbing/gas	rim	Ceramic	Earthenware, coarse	unidentified	heating, plumbing, electric	device	-brown
99722	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	1	vessel, indeterminate	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
99738	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	1	vessel, indeterminate	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	transfer print-black
99724	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	1	vessel, indeterminate	rim	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	molded
99736	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	1	vessel, indeterminate	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	painted-blue
99720	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	2	vessel, indeterminate	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
99737	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	1	vessel, indeterminate	body	Ceramic	Earthenware, refined	Whiteware, hand painted blue	food/beverage	service	painted-blue
99718	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	4	vessel, indeterminate	body	Ceramic	Earthenware, refined	Whiteware, undecorated	food/beverage	service	
99728	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	1	vessel, indeterminate	rim	Ceramic	Porcelain	unidentified	food/beverage	service	
99734	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	1	vessel, indeterminate	body	Ceramic	Porcelain	unidentified	food/beverage	service	painted-multi
99753	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	1	spark plug	whole/intact	Composite Artifact	composite artifact	composite artifact	transportation	automobile	
99739	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	1	shell	fragment	Fauna	shell	Not Assigned	food/beverage	acquisition	
99716	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
99733	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	1	vessel, indeterminate	fragment	Glass	indeterminate	indeterminate	food/beverage	service	-Clear
99725	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	1	bottle, indeterminate	fragment	Glass	indeterminate	indeterminate	food/beverage	storage	
99719	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	1	bottle, indeterminate	fragment	Glass	indeterminate	indeterminate	food/beverage	storage	-Amber
99723	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	1	bottle, wine/liquor/beer	fragment	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
99727	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	18	vessel, indeterminate	fragment	Glass	indeterminate	indeterminate	food/beverage	storage	-Milk glass/Opaque white
99732	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	4	vessel, indeterminate	fragment	Glass	indeterminate	indeterminate	food/beverage	storage	-Milk Glass/yellow
99709	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	4	bottle, indeterminate	base	Glass	Machine made	machine made	food/beverage	storage	-Amber
99711	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	1	unidentified	fragment	Glass	Machine made	machine made	transportation	automobile	-Clear
99710	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	1	bottle, indeterminate	body	Glass	mold blown	mold blown	food/beverage	storage	-Clear
99726	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	9	vessel, indeterminate	fragment	Glass	molded	molded	0	Not Assigned	-Milk glass/Opaque white
99749	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	1	vessel, indeterminate	fragment	Glass	molded	molded	food/beverage	service	
99747	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	2	bottle, indeterminate	fragment	Glass	molded	molded	food/beverage	service	-Clear
99751	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	1	bottle, indeterminate	fragment	Glass	molded	molded	food/beverage	service	-Clear
99713	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	1	sheet metal	fragment	Metal	copper alloy	copper alloy	0	Not Assigned	
99706	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	1	Wheel	whole/intact	Metal	ferrous	unidentified	0	Not Assigned	
99708	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	1	rod	fragment	Metal	ferrous	unidentified	0	Not Assigned	
99740	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	1	spring	fragment	Metal	ferrous	unidentified	0	Not Assigned	
99752	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	1	hardware, other	near intact	Metal	ferrous	unidentified	0	Not Assigned	
99712	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	1	hook	whole/intact	Metal	ferrous	unidentified		Not Assigned	
99714	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	1	bracket	whole/intact	Metal	ferrous	unidentified	furniture/household equip.	hardware	
99748	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	1	coin	whole/intact	Metal	white metal	white metal	recreation/leisure	toys	
99745	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	1	unidentified	whole/intact	Synthetic	synthetic	indeterminate	0	Not Assigned	
99750	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	1	button, two hole	whole/intact	Synthetic	synthetic	indeterminate	personal	fastener	
99729	surface collection	Surface Rock Garden MXH002		MXH002	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
108705	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
108688	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
108691	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	creamware, hand painted overglaze	food/beverage	service	painted-brown
108684	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	4	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
108690	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	vessel, hollow	handle	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
108704	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
108693	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	3	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	painted-blue
108694	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	3	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
108699	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	4	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
108683	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	vessel, flat	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	painted-green
108698	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, refined	Whiteware, undecorated	food/beverage	service	
108681	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	vessel, flat	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
108675	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	tile, floor	whole/intact	Ceramic	Porcelain	Decorated	architecture	foundation	painted-mottled green
108686	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	vessel, hollow	body	Ceramic	Porcelain	Transfer printed	food/beverage	service	transfer print-blue
108676	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	vessel, hollow	base	Ceramic	Stoneware	gray salt glazed	food/beverage	storage	
108682	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	vessel, hollow	base	Ceramic	Stoneware	Unidentified	food/beverage	storage	painted-orange
108680	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
108667	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
108695	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
108662	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	button, two hole	whole/intact	Fauna	bone	mammal	personal	fastener	
108666	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	shoe	fragment	Fauna	leather	leather	personal	clothing	
108685	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
108697	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	glass, mirror	fragment	Glass	flat	flat		Not Assigned	-Clear
108702	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	bottle, indeterminate	lip	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
108703	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
108679	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (bright 7-up)
108674	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Milk Glass/yellow
108677	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	bottle, indeterminate	lip/neck	Glass	indeterminate	indeterminate	food/beverage	storage	-Milk glass/Opaque white-External threads
108660	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	bottle, pharmaceutical	whole/intact	Glass	mold blown	contact, 2+ with separate base	medical/chemical	storage	-Clear-ovoid-External threads
108665	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	bottle, indeterminate	lip	Glass	mold blown	Not Assigned	food/beverage	storage	-Green (olive)-Stacked Ring
108687	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	2	bottle, indeterminate	body	Glass	molded	molded	food/beverage	storage	-Clear
108661	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	bottle, indeterminate	whole/intact	Glass	molded	molded	personal	toiletry/hygiene	-Clear-rectangular, rounded corners-machine made (1903)-External threads

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
108664	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	button, one piece	whole/intact	Metal	copper alloy	copper alloy	personal	fastener	
108663	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	hardware, furniture	handle	Metal	ferrous	cast	furniture/household equip.	hardware	
108692	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	7	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
108678	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	hook	whole/intact	Metal	ferrous	machine made	architecture	hardware	
108673	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	chain, other	fragment	Metal	ferrous	Not Assigned	0	Not Assigned	
108700	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	hinge, furniture	fragment	Metal	ferrous	Not Assigned	furniture/household equip.	hardware	
108670	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	hardware, other	fragment	Metal	ferrous	unidentified	0	Not Assigned	
108669	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	hinge, door	whole/intact	Metal	white metal	white metal	architecture	hardware	
108696	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
108668	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	tile	fragment	Stone	marble	Not Assigned	architecture	foundation	
108671	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
108689	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
108672	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	plastic	medical/chemical	storage	
108701	surface collection	Surface Screened Backed Dirt Pile MXH003		MXH003	Surface/Developing A	1	lightbulb	fragment	Synthetic	synthetic	plastic	recreation/leisure	toys	
104673	Excavation Unit	Trench 1 LEV12 00-120cm MXH155		MXH155		1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
104677	Excavation Unit	Trench 1 LEV12 00-120cm MXH155		MXH155		3	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
104671	Excavation Unit	Trench 1 LEV12 00-120cm MXH155		MXH155		1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
104679	Excavation Unit	Trench 1 LEV12 00-120cm MXH155		MXH155		2	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104667	Excavation Unit	Trench 1 LEV12 00-120cm MXH155		MXH155		1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	slip-brown
104675	Excavation Unit	Trench 1 LEV12 00-120cm MXH155		MXH155		2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104676	Excavation Unit	Trench 1 LEV12 00-120cm MXH155		MXH155		1	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
104666	Excavation Unit	Trench 1 LEV12 00-120cm MXH155		MXH155		1	vessel, hollow	body	Ceramic	Stoneware	Nottingham-type	food/beverage	service	
104670	Excavation Unit	Trench 1 LEV12 00-120cm MXH155		MXH155		3	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
104672	Excavation Unit	Trench 1 LEV12 00-120cm MXH155		MXH155		3	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
104669	Excavation Unit	Trench 1 LEV12 00-120cm MXH155		MXH155		2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
104674	Excavation Unit	Trench 1 LEV12 00-120cm MXH155		MXH155		1	Tube	fragment	Metal	ferrous	machine made	0	Not Assigned	
104678	Excavation Unit	Trench 1 LEV12 00-120cm MXH155		MXH155		10	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
104668	Excavation Unit	Trench 1 LEV12 00-120cm MXH155		MXH155		1	asphalt	fragment	Synthetic	synthetic	asphalt	architecture	foundation	
105557	Excavation Unit	Unit 1.1 Lev02 00-20cm MXH154		MXH154		1	flower pot	rim	Ceramic	Earthenware, coarse	Redware, flowerpot	industry, manufacture, trades	gardening/farming	
105560	Excavation Unit	Unit 1.1 Lev02 00-20cm MXH154		MXH154		1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
105550	Excavation Unit	Unit 1.1 Lev02 00-20cm MXH154		MXH154		2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
105564	Excavation Unit	Unit 1.1 Lev02 00-20cm MXH154		MXH154		3	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105558	Excavation Unit	Unit 1.1 Lev02 00-20cm MXH154		MXH154		1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
105561	Excavation Unit	Unit 1.1 Lev02 00-20cm MXH154		MXH154		3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105562	Excavation Unit	Unit 1.1 Lev02 00-20cm MXH154		MXH154		2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
105563	Excavation Unit	Unit 1.1 Lev02 00-20cm MXH154		MXH154		3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
105551	Excavation Unit	Unit 1.1 Lev02 00-20cm MXH154		MXH154		1	bottle, indeterminate	base	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (bright 7-up)
105553	Excavation Unit	Unit 1.1 Lev02 00-20cm MXH154		MXH154		11	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
105565	Excavation Unit	Unit 1.1 Lev02 00-20cm MXH154		MXH154		5	sheet metal	fragment	Metal	ferrous	unidentified	0	Not Assigned	
104731	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	4	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
104748	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	2	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
104768	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
104769	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	2	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-6/64
104774	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	1	marble	whole/intact	Ceramic	Ball clay	molded	recreation/leisure	toys	
104772	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	12	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
104743	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	1	flower pot	base	Ceramic	Earthenware, coarse	Redware, flowerpot	industry, manufacture, trades	gardening/farming	
104745	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	5	flower pot	rim	Ceramic	Earthenware, coarse	Redware, flowerpot	industry, manufacture, trades	gardening/farming	
104746	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	10	flower pot	body	Ceramic	Earthenware, coarse	Redware, flowerpot	industry, manufacture, trades	gardening/farming	
104740	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	10	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
104754	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	4	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
104762	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	5	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
104780	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
104786	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Staffordshire plain	food/beverage	service	
104759	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	31	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104783	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	1	vessel, flat	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104739	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
104763	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	Annular-brown
104782	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-green
104787	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-green
104756	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	2	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	
104765	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	19	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104734	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	45	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104766	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Whiteware, hand painted polychrome	food/beverage	service	transfer print-purple/manganese
104789	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	1	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
104784	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	2	vessel, hollow	body	Ceramic	Stoneware	Unidentified	0	Not Assigned	
104777	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	1	vessel, hollow	body	Ceramic	Stoneware	Westerwald	food/beverage	service	
104741	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
104738	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	1	vessel, hollow	body	Ceramic	Tin Glazed	unidentified	food/beverage	service	
104744	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	9	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
104753	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	3	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
104755	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	3	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
104779	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
104749	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	3	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
104733	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	2	drinking glass, tumbler	rim	Glass	indeterminate	indeterminate	food/beverage	service	-Clear
104775	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	1	bottle, indeterminate	base	Glass	indeterminate	indeterminate	food/beverage	storage	-Amber
104781	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Amber
104747	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
104767	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
104757	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Blue-cobalt
104736	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	12	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104751	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	1	bottle, indeterminate	base	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104752	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104742	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (bright 7-up)
104785	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	8	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
104770	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	1	nail, cut	whole/intact	Metal	copper alloy	copper alloy	furniture/household equip.	hardware	
104773	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	11	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
104761	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	1	nail, wire	fragment	Metal	ferrous	machine made	architecture	general construction	
104776	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	4	nail, wire	whole/intact	Metal	ferrous	machine made	architecture	general construction	
104788	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	1	button, one piece	whole/intact	Metal	ferrous	machine made	personal	fastener	
104732	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	1	unidentified	fragment	Metal	ferrous	unidentified	0	Not Assigned	
104778	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	17	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
104735	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	1	screw	whole/intact	Metal	steel	steel	architecture	general construction	
104750	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	1	nail, cut	whole/intact	Metal	white metal	white metal	architecture	general construction	
104760	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	2	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
104764	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	1	mortar	fragment	Mineral	composite	mortar	architecture	general construction	
104737	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	1	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
104771	Excavation Unit	Unit 1.1 STR01 LEV01 00-10cm MXH136		MXH136	Surface/Developing A	2	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
104882	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
104874	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	2	brick	fragment	Ceramic	Brick	Standard American	heating, plumbing, electric	device	
104856	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	3	flower pot	rim	Ceramic	Earthenware, coarse	Redware, flowerpot	industry, manufacture, trades	gardening/farming	
104857	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	7	flower pot	body	Ceramic	Earthenware, coarse	Redware, flowerpot	industry, manufacture, trades	gardening/farming	
104883	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
104873	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire plain	food/beverage	service	
104893	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	1	vessel, hollow	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104861	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	1	vessel, hollow	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104872	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104879	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104869	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
104891	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
104865	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	4	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104886	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	4	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104890	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	3	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104892	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	4	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104887	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Whiteware, hand painted polychrome	food/beverage	service	painted-black
104875	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	1	bone		Fauna	bone	mammal		smoking/tobacco	
104877	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	3	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
104878	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	4	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
104868	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	3	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
104884	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
104859	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua marine*
104860	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	5	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104881	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104885	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear-manganese ti+nt
104889	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
104863	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	1	bottle, indeterminate	lip/neck	Glass	mold blown	contact, 2-piece mold	food/beverage	storage	-Clear-Oil

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
104862	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	1	tool	whole/intact	Metal	ferrous	cast	industry, manufacture, trades	gardening/farming	
104870	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	1	buckle	whole/intact	Metal	ferrous	cast	personal	fastener	
104880	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	4	sheet metal	fragment	Metal	ferrous	machine made	0	Not Assigned	
104858	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	23	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
104876	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	1	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
104867	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	1	asphalt	fragment	Synthetic	synthetic	asphalt	architecture	roofing	
104866	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	1	sign	fragment	Synthetic	synthetic	plastic	personal	other personal possession	
104871	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	1	comb, hair	fragment	Synthetic	synthetic	plastic	personal	other personal possession	
104864	Excavation Unit	Unit 1.1 STR01 LEV02 10-20cm MXH137		MXH137	Surface/Developing A	1	comb, hair	fragment	Synthetic	synthetic	rubber	personal	other personal possession	
105520	Excavation Unit	Unit 1.1 STR01 LEV03 20-30cm MXH138		MXH138	Surface/Developing A	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
105522	Excavation Unit	Unit 1.1 STR01 LEV03 20-30cm MXH138		MXH138	Surface/Developing A	1	pipe, bowl	bowl	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
105521	Excavation Unit	Unit 1.1 STR01 LEV03 20-30cm MXH138		MXH138	Surface/Developing A	2	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
105513	Excavation Unit	Unit 1.1 STR01 LEV03 20-30cm MXH138		MXH138	Surface/Developing A	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
105516	Excavation Unit	Unit 1.1 STR01 LEV03 20-30cm MXH138		MXH138	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
105515	Excavation Unit	Unit 1.1 STR01 LEV03 20-30cm MXH138		MXH138	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
105524	Excavation Unit	Unit 1.1 STR01 LEV03 20-30cm MXH138		MXH138	Surface/Developing A	11	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
105508	Excavation Unit	Unit 1.1 STR01 LEV03 20-30cm MXH138		MXH138	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire, slipped	food/beverage	service	
105498	Excavation Unit	Unit 1.1 STR01 LEV03 20-30cm MXH138		MXH138	Surface/Developing A	17	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105507	Excavation Unit	Unit 1.1 STR01 LEV03 20-30cm MXH138		MXH138	Surface/Developing A	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105510	Excavation Unit	Unit 1.1 STR01 LEV03 20-30cm MXH138		MXH138	Surface/Developing A	2	vessel, hollow	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105504	Excavation Unit	Unit 1.1 STR01 LEV03 20-30cm MXH138		MXH138	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	Annular-brown
105500	Excavation Unit	Unit 1.1 STR01 LEV03 20-30cm MXH138		MXH138	Surface/Developing A	1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105503	Excavation Unit	Unit 1.1 STR01 LEV03 20-30cm MXH138		MXH138	Surface/Developing A	12	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105506	Excavation Unit	Unit 1.1 STR01 LEV03 20-30cm MXH138		MXH138	Surface/Developing A	1	vessel, hollow	body	Ceramic	Porcelain	Decorated	food/beverage	service	
105518	Excavation Unit	Unit 1.1 STR01 LEV03 20-30cm MXH138		MXH138	Surface/Developing A	1	vessel, hollow	base	Ceramic	Stoneware	British brown	food/beverage	Service	
105519	Excavation Unit	Unit 1.1 STR01 LEV03 20-30cm MXH138		MXH138	Surface/Developing A	2	vessel, hollow	body	Ceramic	Stoneware	Unidentified	0	Not Assigned	
105514	Excavation Unit	Unit 1.1 STR01 LEV03 20-30cm MXH138		MXH138	Surface/Developing A	1	vessel, hollow	body	Ceramic	Stoneware	Westerwald	food/beverage	service	
105523	Excavation Unit	Unit 1.1 STR01 LEV03 20-30cm MXH138		MXH138	Surface/Developing A	3	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
105502	Excavation Unit	Unit 1.1 STR01 LEV03 20-30cm MXH138		MXH138	Surface/Developing A	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
105505	Excavation Unit	Unit 1.1 STR01 LEV03 20-30cm MXH138		MXH138	Surface/Developing A	2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
105509	Excavation Unit	Unit 1.1 STR01 LEV03 20-30cm MXH138		MXH138	Surface/Developing A	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Amber
105501	Excavation Unit	Unit 1.1 STR01 LEV03 20-30cm MXH138		MXH138	Surface/Developing A	5	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
105511	Excavation Unit	Unit 1.1 STR01 LEV03 20-30cm MXH138		MXH138	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
105499	Excavation Unit	Unit 1.1 STR01 LEV03 20-30cm MXH138		MXH138	Surface/Developing A	10	unidentified	fragment	Metal	ferrous	unidentified	0	Not Assigned	
105496	Excavation Unit	Unit 1.1 STR01 LEV03 20-30cm MXH138		MXH138	Surface/Developing A	21	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
105497	Excavation Unit	Unit 1.1 STR01 LEV03 20-30cm MXH138		MXH138	Surface/Developing A	1	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
105517	Excavation Unit	Unit 1.1 STR01 LEV03 20-30cm MXH138		MXH138	Surface/Developing A	1	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
105512	Excavation Unit	Unit 1.1 STR01 LEV03 20-30cm MXH138		MXH138	Surface/Developing A	1	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
105597	Excavation Unit	Unit 1.1 STR02 LEV03 23-30cm MXH140		MXH140	Foundation Builder's Trench	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
105592	Excavation Unit	Unit 1.1 STR02 LEV03 23-30cm MXH140		MXH140	Foundation Builder's Trench	5	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105590	Excavation Unit	Unit 1.1 STR02 LEV03 23-30cm MXH140		MXH140	Foundation Builder's Trench	4	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
105591	Excavation Unit	Unit 1.1 STR02 LEV03 23-30cm MXH140		MXH140	Foundation Builder's Trench	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	Annular-brown
105594	Excavation Unit	Unit 1.1 STR02 LEV03 23-30cm MXH140		MXH140	Foundation Builder's Trench	4	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105596	Excavation Unit	Unit 1.1 STR02 LEV03 23-30cm MXH140		MXH140	Foundation Builder's Trench	1	vessel, hollow	rim	Ceramic	Earthenware, refined	unidentified	food/beverage	service	painted-blue
105589	Excavation Unit	Unit 1.1 STR02 LEV03 23-30cm MXH140		MXH140	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
105593	Excavation Unit	Unit 1.1 STR02 LEV03 23-30cm MXH140		MXH140	Foundation Builder's Trench	1	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
105595	Excavation Unit	Unit 1.1 STR02 LEV03 23-30cm MXH140		MXH140	Foundation Builder's Trench	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
105599	Excavation Unit	Unit 1.1 STR02 LEV03 23-30cm MXH140		MXH140	Foundation Builder's Trench	1	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
105598	Excavation Unit	Unit 1.1 STR02 LEV03 23-30cm MXH140		MXH140	Foundation Builder's Trench	1	nail, wire	whole/intact	Metal	ferrous	machine made	architecture	general construction	
105600	Excavation Unit	Unit 1.1 STR02 LEV03 23-30cm MXH140		MXH140	Foundation Builder's Trench	1	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
105318	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
105323	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	3	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
105328	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-6/64
105342	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	4	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
105349	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
105338	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	1	vessel, indeterminate	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
105322	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	4	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
105339	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	8	vessel, hollow	base	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
105333	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Staffordshire plain	food/beverage	service	
105313	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire, slipped	food/beverage	service	
105334	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	Astbury ware	food/beverage	service	
105362	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105341	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	1	vessel, hollow	foot	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105346	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	23	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105316	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	jackfield type	food/beverage	service	
105327	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	slip-orange
105361	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
105330	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-brown
105331	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
105326	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	2	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
105336	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	6	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
105351	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	4	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
105314	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	22	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105345	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	6	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105358	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105343	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	1	vessel, flat	rim	Ceramic	Porcelain	Chinese overglaze enamel	food/beverage	service	
105321	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	2	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
105340	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Stoneware	Westerwald	food/beverage	service	
105329	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	1	vessel, hollow	base	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
105335	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	1	vessel, flat	base	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
105332	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	2	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
105324	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	7	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
105356	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	5	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
105337	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
105311	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Red
105344	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
105359	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	5	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
105320	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	4	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
105312	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
105319	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	3	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
105325	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	14	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
105354	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
105317	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	1	ballast	fragment	Stone	flint	butterscotch	architecture	foundation	
105315	Excavation Unit	Unit 1.1 STR02 LEV04 30-40cm MXH141		MXH141	Foundation Builder's Trench	1	pencil	fragment	Stone	Slate	Not Assigned	personal	other personal possession	
105204	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-6/64
105223	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
105228	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
105207	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	3	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
105202	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	1	vessel, hollow	base	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
105216	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
105229	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, slip decorated	food/beverage	preparation	
105219	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	5	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
105210	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, factory-made slipware	food/beverage	service	Annular-brown
105214	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	17	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105215	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	1	vessel, hollow	foot	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105220	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	1	vessel, hollow	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105209	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	1	vessel, flat	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-blue
105222	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
105225	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	Annular-brown
105206	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	6	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
105217	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	1	vessel, hollow	base	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
105224	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	2	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
105226	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	20	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105227	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	2	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105232	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
105213	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	2	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
105203	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	12	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
105218	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
105234	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	1	tooth	fragment	Fauna	enamel/bone	tooth	food/beverage	acquisition	
105201	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	9	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
105231	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	10	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
105235	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
105208	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
105212	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	4	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
105233	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	1	bottle, indeterminate	lip	Glass	Machine made	machine made	food/beverage	storage	-Clear-External threads

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
105205	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	3	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
105230	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	1	tack, furniture	whole/intact	Metal	ferrous	machine made	furniture/household equip.	hardware	
105211	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	11	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
105221	Excavation Unit	Unit 1.1 STR02 LEV05 40-50cm MXH142		MXH142	Foundation Builder's Trench	1	tag	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
105282	Excavation Unit	Unit 1.1 STR02 LEV06 50-60cm MXH144		MXH144	Foundation Builder's Trench	1	pipe, bowl	bowl	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
105283	Excavation Unit	Unit 1.1 STR02 LEV06 50-60cm MXH144		MXH144	Foundation Builder's Trench	1	pipe, bowl	0	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
105290	Excavation Unit	Unit 1.1 STR02 LEV06 50-60cm MXH144		MXH144	Foundation Builder's Trench	2	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
105303	Excavation Unit	Unit 1.1 STR02 LEV06 50-60cm MXH144		MXH144	Foundation Builder's Trench	26	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
105305	Excavation Unit	Unit 1.1 STR02 LEV06 50-60cm MXH144		MXH144	Foundation Builder's Trench	9	vessel, indeterminate	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
105288	Excavation Unit	Unit 1.1 STR02 LEV06 50-60cm MXH144		MXH144	Foundation Builder's Trench	1	vessel, hollow	base	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
105302	Excavation Unit	Unit 1.1 STR02 LEV06 50-60cm MXH144		MXH144	Foundation Builder's Trench	12	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105285	Excavation Unit	Unit 1.1 STR02 LEV06 50-60cm MXH144		MXH144	Foundation Builder's Trench	1	plate	rim	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
105294	Excavation Unit	Unit 1.1 STR02 LEV06 50-60cm MXH144		MXH144	Foundation Builder's Trench	7	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
105307	Excavation Unit	Unit 1.1 STR02 LEV06 50-60cm MXH144		MXH144	Foundation Builder's Trench	1	vessel, hollow	foot	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
105281	Excavation Unit	Unit 1.1 STR02 LEV06 50-60cm MXH144		MXH144	Foundation Builder's Trench	1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105284	Excavation Unit	Unit 1.1 STR02 LEV06 50-60cm MXH144		MXH144	Foundation Builder's Trench	17	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105293	Excavation Unit	Unit 1.1 STR02 LEV06 50-60cm MXH144		MXH144	Foundation Builder's Trench	2	vessel, hollow	body	Ceramic	Earthenware, refined	Yellow ware, plain	food/beverage	service	
105297	Excavation Unit	Unit 1.1 STR02 LEV06 50-60cm MXH144		MXH144	Foundation Builder's Trench	3	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
105278	Excavation Unit	Unit 1.1 STR02 LEV06 50-60cm MXH144		MXH144	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Stoneware	Nottingham-type	food/beverage	service	
105300	Excavation Unit	Unit 1.1 STR02 LEV06 50-60cm MXH144		MXH144	Foundation Builder's Trench	2	vessel, hollow	body	Ceramic	Stoneware	Westerwald	food/beverage	service	
105296	Excavation Unit	Unit 1.1 STR02 LEV06 50-60cm MXH144		MXH144	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
105289	Excavation Unit	Unit 1.1 STR02 LEV06 50-60cm MXH144		MXH144	Foundation Builder's Trench	1	gaming piece	fragment	Ceramic	Tin Glazed	Dutch (delft)	recreation/leisure	gaming	
105306	Excavation Unit	Unit 1.1 STR02 LEV06 50-60cm MXH144		MXH144	Foundation Builder's Trench	5	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
105287	Excavation Unit	Unit 1.1 STR02 LEV06 50-60cm MXH144		MXH144	Foundation Builder's Trench	5	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
105295	Excavation Unit	Unit 1.1 STR02 LEV06 50-60cm MXH144		MXH144	Foundation Builder's Trench	3	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
105304	Excavation Unit	Unit 1.1 STR02 LEV06 50-60cm MXH144		MXH144	Foundation Builder's Trench	1	window glass, flat	body	Glass	flat	flat	architecture	window	-Clear
105299	Excavation Unit	Unit 1.1 STR02 LEV06 50-60cm MXH144		MXH144	Foundation Builder's Trench	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Amber
105279	Excavation Unit	Unit 1.1 STR02 LEV06 50-60cm MXH144		MXH144	Foundation Builder's Trench	2	drinking glass, tumbler	rim	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
105280	Excavation Unit	Unit 1.1 STR02 LEV06 50-60cm MXH144		MXH144	Foundation Builder's Trench	4	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
105291	Excavation Unit	Unit 1.1 STR02 LEV06 50-60cm MXH144		MXH144	Foundation Builder's Trench	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
105286	Excavation Unit	Unit 1.1 STR02 LEV06 50-60cm MXH144		MXH144	Foundation Builder's Trench	4	unidentified	fragment	Metal	ferrous	unidentified	0	Not Assigned	
105301	Excavation Unit	Unit 1.1 STR02 LEV06 50-60cm MXH144		MXH144	Foundation Builder's Trench	14	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
105292	Excavation Unit	Unit 1.1 STR02 LEV06 50-60cm MXH144		MXH144	Foundation Builder's Trench	10	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
105298	Excavation Unit	Unit 1.1 STR02 LEV06 50-60cm MXH144		MXH144	Foundation Builder's Trench	1	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
105453	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	2	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
105418	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	2	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
105451	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	2	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
105452	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
105439	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Coarse agate, buckley ware	food/beverage	service	
105445	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
105450	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
105426	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	14	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
105414	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire plain	food/beverage	service	
105440	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, coarse	unidentified	0	Not Assigned	
105446	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	Astbury ware	food/beverage	service	
105436	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	8	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105420	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	1	teapot	base	Ceramic	Earthenware, refined	jackfield type	food/beverage	service	
105428	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	slip-brown
105409	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	slip-green
105448	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	slip-orange
105412	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	8	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
105442	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
105429	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105431	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105435	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	12	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105443	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	1	vessel, hollow	rim	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
105449	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
105415	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
105438	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	2	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
105422	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Tin Glazed	unidentified	food/beverage	service	
105425	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	10	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
105427	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
105447	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	1	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
105410	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	4	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
105437	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
105441	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
105430	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
105444	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	1	drinking glass, tumbler	rim	Glass	molded	molded	food/beverage	service	-Clear
105424	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	1	button, one piece	whole/intact	Metal	copper alloy	copper alloy	personal	fastener	
105432	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	1	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
105423	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	20	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
105434	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	1	Tube	fragment	Metal	lead	cast	heating, plumbing, electric	device	
105433	Excavation Unit	Unit 1.1 STR02 LEV07 60-70cm MXH146		MXH146	Foundation Builder's Trench	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
105091	Excavation Unit	Unit 1.1 STR02 LEV08 70-80cm MXH148		MXH148	Foundation Builder's Trench	2	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
105075	Excavation Unit	Unit 1.1 STR02 LEV08 70-80cm MXH148		MXH148	Foundation Builder's Trench	1	vessel, flat	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
105085	Excavation Unit	Unit 1.1 STR02 LEV08 70-80cm MXH148		MXH148	Foundation Builder's Trench	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
105086	Excavation Unit	Unit 1.1 STR02 LEV08 70-80cm MXH148		MXH148	Foundation Builder's Trench	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
105070	Excavation Unit	Unit 1.1 STR02 LEV08 70-80cm MXH148		MXH148	Foundation Builder's Trench	1	vessel, hollow	handle	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
105073	Excavation Unit	Unit 1.1 STR02 LEV08 70-80cm MXH148		MXH148	Foundation Builder's Trench	4	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
105074	Excavation Unit	Unit 1.1 STR02 LEV08 70-80cm MXH148		MXH148	Foundation Builder's Trench	1	vessel, hollow	base	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
105083	Excavation Unit	Unit 1.1 STR02 LEV08 70-80cm MXH148		MXH148	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
105068	Excavation Unit	Unit 1.1 STR02 LEV08 70-80cm MXH148		MXH148	Foundation Builder's Trench	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire, slipped	food/beverage	service	
105079	Excavation Unit	Unit 1.1 STR02 LEV08 70-80cm MXH148		MXH148	Foundation Builder's Trench	4	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105081	Excavation Unit	Unit 1.1 STR02 LEV08 70-80cm MXH148		MXH148	Foundation Builder's Trench	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105069	Excavation Unit	Unit 1.1 STR02 LEV08 70-80cm MXH148		MXH148	Foundation Builder's Trench	1	vessel, hollow	handle	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	sprig molded
105090	Excavation Unit	Unit 1.1 STR02 LEV08 70-80cm MXH148		MXH148	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	slip-blue
105093	Excavation Unit	Unit 1.1 STR02 LEV08 70-80cm MXH148		MXH148	Foundation Builder's Trench	1	vessel, flat	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	slip-blue
105067	Excavation Unit	Unit 1.1 STR02 LEV08 70-80cm MXH148		MXH148	Foundation Builder's Trench	1	vessel, flat	base	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
105076	Excavation Unit	Unit 1.1 STR02 LEV08 70-80cm MXH148		MXH148	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
105080	Excavation Unit	Unit 1.1 STR02 LEV08 70-80cm MXH148		MXH148	Foundation Builder's Trench	1	vessel, hollow	handle	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
105077	Excavation Unit	Unit 1.1 STR02 LEV08 70-80cm MXH148		MXH148	Foundation Builder's Trench	6	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
105078	Excavation Unit	Unit 1.1 STR02 LEV08 70-80cm MXH148		MXH148	Foundation Builder's Trench	18	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105088	Excavation Unit	Unit 1.1 STR02 LEV08 70-80cm MXH148		MXH148	Foundation Builder's Trench	1	vessel, hollow	foot	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105082	Excavation Unit	Unit 1.1 STR02 LEV08 70-80cm MXH148		MXH148	Foundation Builder's Trench	2	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
105072	Excavation Unit	Unit 1.1 STR02 LEV08 70-80cm MXH148		MXH148	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Stoneware	gray salt glazed	food/beverage	storage	Albany slip-black
105089	Excavation Unit	Unit 1.1 STR02 LEV08 70-80cm MXH148		MXH148	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
105071	Excavation Unit	Unit 1.1 STR02 LEV08 70-80cm MXH148		MXH148	Foundation Builder's Trench	5	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
105092	Excavation Unit	Unit 1.1 STR02 LEV08 70-80cm MXH148		MXH148	Foundation Builder's Trench	3	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
105084	Excavation Unit	Unit 1.1 STR02 LEV08 70-80cm MXH148		MXH148	Foundation Builder's Trench	1	drinking glass, tumbler	rim	Glass	molded	molded	food/beverage	service	-Clear
105087	Excavation Unit	Unit 1.1 STR02 LEV08 70-80cm MXH148		MXH148	Foundation Builder's Trench	2	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
105373	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
105391	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	3	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
105392	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
105400	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
105370	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Coarse agate, buckley ware	food/beverage	storage	
105381	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	1	vessel, hollow	foot	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
105383	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
105407	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	4	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
105387	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, slip decorated	food/beverage	preparation	
105397	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
105372	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	8	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105390	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105389	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Ironstone	food/beverage	service	
105402	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	luster-purple/manganese
105401	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
105394	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
105380	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	2	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105382	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	9	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105396	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	1	vessel, hollow	foot	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105403	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	1	vessel, hollow	body	Ceramic	Stoneware	British brown	food/beverage	Service	
105399	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	1	vessel, hollow	body	Ceramic	Stoneware	Westerwald	food/beverage	service	
105398	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
105393	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	1	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
105388	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	1	vessel, hollow	body	Ceramic	Tin Glazed	unidentified	food/beverage	service	
105377	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
105405	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
105386	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	1	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
105395	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Amber
105404	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	3	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
105371	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
105406	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
105378	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
105376	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	1	bottle, indeterminate	lip	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
105384	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
105374	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	6	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
105369	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	3	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
105385	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	1	ballast	fragment	Stone	flint	butterscotch	architecture	foundation	
105379	Excavation Unit	Unit 1.1 STR03 LEV05 40-50cm MXH143		MXH143	Inverted A	1	stone	fragment	Stone	marble	Not Assigned	0	Not Assigned	
105566	Excavation Unit	Unit 1.1 STR04 LEV06 60-100cm MXH145		MXH145	Buried APZ	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
105581	Excavation Unit	Unit 1.1 STR04 LEV06 60-100cm MXH145		MXH145	Buried APZ	2	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
105575	Excavation Unit	Unit 1.1 STR04 LEV06 60-100cm MXH145		MXH145	Buried APZ	5	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
105578	Excavation Unit	Unit 1.1 STR04 LEV06 60-100cm MXH145		MXH145	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
105579	Excavation Unit	Unit 1.1 STR04 LEV06 60-100cm MXH145		MXH145	Buried APZ	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
105576	Excavation Unit	Unit 1.1 STR04 LEV06 60-100cm MXH145		MXH145	Buried APZ	10	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105588	Excavation Unit	Unit 1.1 STR04 LEV06 60-100cm MXH145		MXH145	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105570	Excavation Unit	Unit 1.1 STR04 LEV06 60-100cm MXH145		MXH145	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
105568	Excavation Unit	Unit 1.1 STR04 LEV06 60-100cm MXH145		MXH145	Buried APZ	4	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105585	Excavation Unit	Unit 1.1 STR04 LEV06 60-100cm MXH145		MXH145	Buried APZ	6	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105586	Excavation Unit	Unit 1.1 STR04 LEV06 60-100cm MXH145		MXH145	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105574	Excavation Unit	Unit 1.1 STR04 LEV06 60-100cm MXH145		MXH145	Buried APZ	1	bowl	rim	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
105577	Excavation Unit	Unit 1.1 STR04 LEV06 60-100cm MXH145		MXH145	Buried APZ	1	vessel, hollow	rim	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
105571	Excavation Unit	Unit 1.1 STR04 LEV06 60-100cm MXH145		MXH145	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	British brown	food/beverage	Service	
105572	Excavation Unit	Unit 1.1 STR04 LEV06 60-100cm MXH145		MXH145	Buried APZ	2	vessel, hollow	body	Ceramic	Stoneware	Nottingham-type	food/beverage	service	
105569	Excavation Unit	Unit 1.1 STR04 LEV06 60-100cm MXH145		MXH145	Buried APZ	1	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	painted-blue
105580	Excavation Unit	Unit 1.1 STR04 LEV06 60-100cm MXH145		MXH145	Buried APZ	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
105583	Excavation Unit	Unit 1.1 STR04 LEV06 60-100cm MXH145		MXH145	Buried APZ	2	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
105567	Excavation Unit	Unit 1.1 STR04 LEV06 60-100cm MXH145		MXH145	Buried APZ	2	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
105582	Excavation Unit	Unit 1.1 STR04 LEV06 60-100cm MXH145		MXH145	Buried APZ	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
105587	Excavation Unit	Unit 1.1 STR04 LEV06 60-100cm MXH145		MXH145	Buried APZ	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
105584	Excavation Unit	Unit 1.1 STR04 LEV06 60-100cm MXH145		MXH145	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
105573	Excavation Unit	Unit 1.1 STR04 LEV06 60-100cm MXH145		MXH145	Buried APZ	4	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
104931	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	1	pipe, bowl/stem	bowl	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
104954	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
104972	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	7	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
104918	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	5	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
104953	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	4	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
104981	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
104915	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
104950	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	1	vessel, flat	body	Ceramic	Earthenware, coarse	Manganese Mottled	food/beverage	service	
104966	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	5	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
104965	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	11	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
104983	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	1	vessel, hollow	handle	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	luster-gray
104914	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	26	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
104923	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	2	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
104929	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire plain	food/beverage	service	
104925	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	1	colander	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	preparation	
104982	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	1	vessel, flat	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104933	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104937	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	32	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104948	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104924	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Not Assigned	food/beverage	service	
104957	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
104921	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-brown
104980	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-brown
104963	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-yellow
104946	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
104916	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	4	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
104970	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
104976	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
104919	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	1	vessel, hollow	foot	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104922	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	14	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104958	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104936	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104962	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	27	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104964	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	3	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104968	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	1	cup	handle	Ceramic	Porcelain	Decorated	food/beverage	service	gilded-gold
104955	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	British brown	food/beverage	Service	
104960	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	Nottingham-type	food/beverage	storage	
104935	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	Westerwald	food/beverage	service	
104959	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	1	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	painted-blue
104941	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	4	vessel, indeterminate	body	Ceramic	Tin Glazed	unidentified	0	Not Assigned	
104967	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	6	vessel, hollow	body	Ceramic	unidentified	unidentified	0	Not Assigned	
104913	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	8	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
104979	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	5	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
104920	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	1	tooth	fragment	Fauna	enamel/bone	tooth	food/beverage	acquisition	
104978	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	3	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
104973	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	5	charcoal	fragment	Flora	wood	charcoal	heating, plumbing, electric	fuel	
104961	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	23	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
104934	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	5	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104971	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	9	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
104917	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	1	sheet metal	fragment	Metal	copper alloy	copper alloy	0	Not Assigned	
104975	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	6	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
104952	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	3	unidentified	fragment	Metal	ferrous	unidentified	0	Not Assigned	
104939	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	10	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
104932	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	1	nail wrought	whole/intact	Metal	ferrous	wrought	architecture	general construction	
104977	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	5	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
104943	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	10	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
104956	Excavation Unit	Unit 1.1 STR04 LEV07 60-70cm MXH147		MXH147	Buried APZ	1	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
105131	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
105115	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-6/64
105118	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-6/64
105134	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
105142	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
105133	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	borderware	food/beverage	storage	
105105	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	5	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
105121	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
105125	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, slip decorated	food/beverage	preparation	
105114	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
105117	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
105137	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	2	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
105095	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire, slipped	food/beverage	storage	
105099	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	30	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105139	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	2	vessel, hollow	foot	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105135	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-blue
105106	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	4	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
105120	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
105110	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	1	vessel, flat	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
105108	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	11	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
105104	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105113	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	30	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105111	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	3	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
105107	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, refined	Yellow ware, plain	food/beverage	service	
105132	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	2	vessel, hollow	body	Ceramic	Porcelain	Decorated	food/beverage	service	painted-blue
105123	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	buff salt glazed	food/beverage	storage	Albany slip-brown
105116	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	1	coffee pot	spout	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
105130	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	1	vessel, flat	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
105138	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	1	vessel, flat	base	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
105140	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	1	vessel, hollow	rim	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
105112	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	1	vessel, flat	rim	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	Annular-blue
105122	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	1	vessel, flat	body	Ceramic	Tin Glazed	unidentified	0	Not Assigned	

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
105126	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	2	vessel, hollow	body	Ceramic	Tin Glazed	unidentified	food/beverage	service	
105102	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
105128	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	5	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
105096	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	1	tooth	fragment	Fauna	enamel/bone	tooth	food/beverage	acquisition	
105098	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	1	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
105109	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	3	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
105119	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
105097	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	7	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
105100	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
105127	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
105101	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	1	drinking glass, tumbler	rim	Glass	molded	molded	food/beverage	service	-Aqua marine*
105103	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	1	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
105136	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	4	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
105129	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
105094	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	3	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
105124	Excavation Unit	Unit 1.1 STR04 LEV08 70-80cm MXH149		MXH149	Buried APZ	1	pencil	fragment	Stone	Slate	Not Assigned	personal	other personal possession	
104832	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	3	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
104841	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	6	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
104804	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-6/64
104790	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	1	pipe, bowl	0	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
104828	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	4	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
104833	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	2	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
104836	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	22	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
104824	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	3	vessel, hollow	body	Ceramic	Earthenware, coarse	borderware	food/beverage	storage	
104831	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Manganese Mottled	food/beverage	service	
104806	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	6	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
104811	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
104838	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	37	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
104826	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	59	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
104796	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	5	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104812	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	69	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104840	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	10	vessel, hollow	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104845	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104825	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	Annular-black
104854	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	engine turned-brown
104805	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	4	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-brown
104850	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	1	vessel, flat	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
104853	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	Annular-black
104837	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-brown
104797	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-yellow
104803	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	5	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
104823	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
104844	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
104839	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
104794	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	1	vessel, flat	base	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104816	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	26	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104819	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	6	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104801	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	4	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104815	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	47	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104820	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	5	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	food/beverage	service	
104821	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	1	vessel, flat	body	Ceramic	Porcelain	Chinese overglaze enamel	food/beverage	service	
104808	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	2	vessel, hollow	rim	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
104810	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	3	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	service	
104829	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	1	vessel, hollow	rim	Ceramic	Porcelain	Plain	food/beverage	service	
104843	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	Westerwald	food/beverage	service	
104848	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	3	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
104849	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	1	vessel, hollow	rim	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
104800	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	3	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
104813	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	1	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	Annular-blue
104814	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	1	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	painted-green
104809	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	6	vessel, hollow	body	Ceramic	Tin Glazed	unidentified	food/beverage	service	
104791	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	13	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
104793	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	2	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
104834	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	15	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
104817	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	24	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
104827	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	14	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
104835	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	8	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104807	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	6	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (light olive)
104802	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	10	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
104847	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	1	bottle, indeterminate	lip/neck	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
104851	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
104852	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	1	bottle, indeterminate	base	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
104830	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	14	unidentified	fragment	Metal	ferrous	unidentified	0	Not Assigned	
104792	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	26	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
104799	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	2	unidentified	fragment	Metal	lead	cast	0	Not Assigned	
104818	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	10	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
104842	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	1	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
104846	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	2	mortar	fragment	Mineral	composite	mortar	architecture	general construction	
104822	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	1	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
104798	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	2	ballast	fragment	Stone	flint	butterscotch	architecture	foundation	
104795	Excavation Unit	Unit 1.1 STR04 LEV09 80-90cm MXH150		MXH150	Buried APZ	1	stone, worked	fragment	Stone	Hornfels	Not Assigned	personal	other personal possession	
105048	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	6	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
105053	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
105043	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	4	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
105044	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	3	pipe, bowl/stem	bowl	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
105058	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-6/64
105008	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	9	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
105038	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	8	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
105011	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
104996	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	19	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
105033	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	18	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
105054	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire plain	food/beverage	service	
105019	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	3	vessel, flat	rim	Ceramic	Earthenware, coarse	Staffordshire, slipped	food/beverage	service	
105016	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Staffordshire, slipped	food/beverage	service	
105059	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire, slipped	food/beverage	service	
105017	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	1	vessel, flat	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105028	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	50	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105039	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105057	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	jackfield type	food/beverage	service	
105013	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-black
105051	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
105055	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-black
105004	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	7	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
105049	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	4	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
105012	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	3	vessel, flat	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
105031	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	27	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
105050	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	1	teapot	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105015	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	1	vessel, flat	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105010	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	49	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105014	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105062	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	1	vessel, hollow	foot	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105003	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Whiteware, molded	food/beverage	service	
105029	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	1	vessel, flat	base	Ceramic	Earthenware, refined	Whiteware, undecorated	food/beverage	service	
105024	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	2	vessel, hollow	rim	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
105037	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	2	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
105001	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	British brown	food/beverage	Service	
105027	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	1	vessel, hollow	base	Ceramic	Stoneware	buff salt glazed	food/beverage	storage	
105063	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	2	vessel, hollow	body	Ceramic	Stoneware	Unidentified	0	Not Assigned	
105046	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	3	vessel, hollow	body	Ceramic	Stoneware	Westerwald	food/beverage	service	
104994	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	1	colander	body	Ceramic	Stoneware	white salt-glazed	food/beverage	preparation	
105018	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	1	vessel, flat	rim	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
105023	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	1	vessel, flat	rim	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
105060	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	2	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
105061	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	2	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
105056	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	1	vessel, flat	rim	Ceramic	Stoneware	white salt-glazed, scratch blue	food/beverage	service	

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
105026	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	3	vessel, flat	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
105002	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	1	vessel, hollow	rim	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
105034	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	1	vessel, flat	body	Ceramic	Tin Glazed	unidentified	food/beverage	service	
105052	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	5	vessel, hollow	body	Ceramic	unidentified	unidentified	0	Not Assigned	
104993	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	28	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
105041	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	9	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
105009	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	3	tooth	fragment	Fauna	enamel/bone	tooth	food/beverage	acquisition	
104995	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	5	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
105020	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	1	shell, clam	near intact	Fauna	shell	bivalve	food/beverage	acquisition	
105005	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	24	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
105025	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	1	bottle, wine/liquor/beer	base	Glass	Free blown	free blown	food/beverage	storage	-Green (olive)-circular-pushup, large mammalon
105021	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	1	drinking glass, tumbler	rim	Glass	indeterminate	indeterminate	food/beverage	service	-Aqua
105007	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	5	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
105040	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	8	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
105036	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	12	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
105047	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	1	stone, worked	whole/intact	Glass	molded	molded	personal	adornment	-Clear
105035	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	1	buckle	fragment	Metal	copper alloy	copper alloy	personal	fastener	
104998	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	10	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
105006	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	3	sheet metal	fragment	Metal	ferrous	machine made	0	Not Assigned	
105030	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	11	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
104997	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	3	nail wrought	near intact	Metal	ferrous	wrought	architecture	general construction	
105000	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	1	bullet	whole/intact	Metal	lead	cast	arms	guns	
104999	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	1	unidentified	fragment	Metal	lead	Not Assigned	0	Not Assigned	
105022	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
105042	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	2	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
105032	Excavation Unit	Unit 1.1 STR04 LEV10 90-100cm MXH151		MXH151	Buried APZ	4	ballast	fragment	Stone	flint	butterscotch	architecture	foundation	
105189	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	1	vessel, hollow	body	0	0	Not Assigned	0	Not Assigned	
105155	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	1	pipe, mouth piece	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
105163	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	4	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
105197	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	5	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
105170	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	8	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
105147	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	10	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
105153	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	8	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
105156	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	2	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
105191	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	3	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
105176	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	5	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
105169	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	4	vessel, hollow	body	Ceramic	Earthenware, coarse	Coarse agate, buckley ware	food/beverage	storage	
105198	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
105158	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	6	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
105178	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	30	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
105199	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire plain	food/beverage	service	
105173	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	unidentified	food/beverage	storage	
105167	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	6	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105172	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-brown
105146	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-yellow
105151	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	5	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
105159	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105166	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	1	wig curler	fragment	Ceramic	Ball clay	molded	personal	adornment	
105187	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Whieldon (clouded or tortoiseshell)	food/beverage	service	
105162	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	2	vessel, flat	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
105185	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	1	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	service	
105196	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	1	sewer pipe	fragment	Ceramic	Stoneware	Not Assigned	heating, plumbing, electric	device	
105149	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	1	vessel, flat	rim	Ceramic	Stoneware	Nottingham-type	food/beverage	service	
105182	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	1	vessel, hollow	rim	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
105188	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	5	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
105194	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	2	vessel, flat	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
105192	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	1	vessel, flat	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	painted-blue
105150	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	2	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
105164	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	1	vessel, hollow	rim	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	Annular-blue
105183	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	2	vessel, hollow	body	Ceramic	Tin Glazed	unidentified	0	Not Assigned	
105180	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	1	unidentified	fragment	Ceramic	unidentified	Not Assigned	0	Not Assigned	
105143	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	13	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
105184	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	4	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
105144	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	3	tooth	fragment	Fauna	enamel/bone	tooth	food/beverage	acquisition	
105165	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	6	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
105154	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	14	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
105200	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
105179	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	4	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
105160	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	5	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
105161	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	1	bottle, indeterminate	base	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
105157	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	2	bottle, wine/liquor/beer	base	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
105145	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	1	sheet metal	fragment	Metal	copper alloy	copper alloy	0	Not Assigned	
105193	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	1	pin	whole/intact	Metal	copper alloy	copper alloy	industry, manufacture, trades	sewing/tailoring	
105148	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	1	buckle	whole/intact	Metal	copper alloy	copper alloy	personal	fastener	
105171	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	2	button, one piece	whole/intact	Metal	copper alloy	copper alloy	personal	fastener	
105177	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	38	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
105195	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	1	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
105175	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	1	rod	fragment	Metal	ferrous	machine made	0	Not Assigned	
105186	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	2	sheet metal	fragment	Metal	ferrous	machine made	0	Not Assigned	
105181	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	2	unidentified	fragment	Metal	ferrous	unidentified	0	Not Assigned	
105174	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	6	nail wrought	fragment	Metal	ferrous	wrought	architecture	general construction	
105190	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	1	mortar	fragment	Mineral	composite	mortar	architecture	window	
105168	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	1	plaster, plain	fragment	Mineral	composite	plaster	architecture	general construction	
105152	Excavation Unit	Unit 1.1 STR04 LEV11 100-110cm MXH152		MXH152	Buried APZ	2	ballast	whole/intact	Stone	flint	butterscotch	architecture	foundation	
105602	Excavation Unit	Unit 1.1 STR05 LEV12 110-120cm MXH153		MXH153	B2	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
105606	Excavation Unit	Unit 1.1 STR05 LEV12 110-120cm MXH153		MXH153	B2	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
105601	Excavation Unit	Unit 1.1 STR05 LEV12 110-120cm MXH153		MXH153	B2	1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105604	Excavation Unit	Unit 1.1 STR05 LEV12 110-120cm MXH153		MXH153	B2	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105607	Excavation Unit	Unit 1.1 STR05 LEV12 110-120cm MXH153		MXH153	B2	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Green (light)
105603	Excavation Unit	Unit 1.1 STR05 LEV12 110-120cm MXH153		MXH153	B2	1	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
105605	Excavation Unit	Unit 1.1 STR05 LEV12 110-120cm MXH153		MXH153	B2	2	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
106358	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
106360	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
106339	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Manganese Mottled	food/beverage	service	
106364	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
106355	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	9	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
106335	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	1	vessel, flat	body	Ceramic	Earthenware, coarse	Staffordshire, slipped	food/beverage	service	
106356	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	27	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106363	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	1	vessel, flat	body	Ceramic	Earthenware, refined	Creamware, transfer printed overglaze	food/beverage	service	transfer print-brown
106352	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
106343	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	1	vessel, flat	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
106365	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	13	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
106336	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106340	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	28	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106354	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	1	vessel, flat	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106373	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	1	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
106344	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Porcelain	Decorated	food/beverage	service	painted-blue
106351	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	1	sewer pipe	fragment	Ceramic	Stoneware	Unidentified	heating, plumbing, electric	device	
106357	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	2	vessel, flat	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
106370	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	2	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
106362	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	3	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
106346	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
106366	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	2	drinking glass, tumbler	rim	Glass	indeterminate	indeterminate	food/beverage	service	-Clear
106350	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	6	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Amber
106338	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	4	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
106353	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
106368	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	5	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
106372	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
106369	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (bright 7-up)
106371	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (bright 7-up)
106359	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
106337	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	1	slag, metallic	fragment	Metal	ferrous	slag	0	Not Assigned	
106349	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	1	ring	fragment	Metal	ferrous	unidentified	0	Not Assigned	
106348	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	13	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
106361	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	3	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
106345	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	1	ballast	fragment	Stone	flint	butterscotch	architecture	foundation	
106341	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	1	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
106367	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
106334	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	1	token	fragment	Synthetic	synthetic	plastic	commerce	token	
106342	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	1	button, four hole	fragment	Synthetic	synthetic	plastic	personal	fastener	
106347	Excavation Unit	Unit 1.2 STR01 LEV01 00-10cm MXH156		MXH156	Surface/Developing A	1	Tube	fragment	Synthetic	synthetic	rubber	0	Not Assigned	
107027	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	2	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
107042	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	1	pipe, bowl	bowl	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
107017	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	1	marble	whole/intact	Ceramic	Ball clay	molded	recreation/leisure	toys	
107018	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
107021	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	1	vessel, hollow	handle	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
107043	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
107044	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
107023	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	4	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
107020	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107040	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	1	vessel, hollow	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107051	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	19	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107029	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	Annular-green
107038	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-green
107031	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-orange
107030	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
107039	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-green
107024	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-orange
107034	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	2	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
107022	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107028	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	12	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107033	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	2	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107041	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	22	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107050	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	3	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107049	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	3	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
107046	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	2	vessel, hollow	body	Ceramic	Stoneware	Westerwald	food/beverage	service	
107047	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	1	vessel, hollow	body	Ceramic	Stoneware	Westerwald	food/beverage	service	
107045	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
107048	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	1	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
107035	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
107036	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	6	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
107032	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	6	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
107025	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	1	bottle, indeterminate	base	Glass	Machine made	machine made	food/beverage	storage	-Green (bright 7-up)-machine made (1903)
107019	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	1	pintle	whole/intact	Metal	ferrous	machine made	architecture	window	
107026	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	11	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
107037	Excavation Unit	Unit 1.2 STR01 LEV02 10-20cm MXH157		MXH157	Surface/Developing A	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
106271	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	3	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
106289	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	3	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
106282	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	8	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
106295	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
106263	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	14	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
106293	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, slip decorated	food/beverage	preparation	
106260	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	4	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire plain	food/beverage	service	
106309	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire, slipped	food/beverage	service	
106270	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	39	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106278	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	1	vessel, hollow	handle	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106307	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	5	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106296	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	slip-black
106269	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	6	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
106298	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	6	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
106268	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-blue
106274	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-green
106277	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
106287	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
106264	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106266	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	2	chamber pot	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106279	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	28	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106261	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
106303	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	1	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	service	
106302	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	1	vessel, hollow	body	Ceramic	Stoneware	British brown	food/beverage	Service	
106281	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	1	vessel, hollow	body	Ceramic	Stoneware	gray salt glazed	food/beverage	service	
106292	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	5	vessel, hollow	body	Ceramic	Stoneware	Unidentified	0	Not Assigned	
106285	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	1	vessel, flat	body	Ceramic	Stoneware	Westerwald	food/beverage	service	
106265	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	2	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
106297	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
106267	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	1	vessel, flat	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
106308	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	3	vessel, flat	body	Ceramic	Tin Glazed	unidentified	0	Not Assigned	
106259	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	10	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
106305	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	1	tooth	fragment	Fauna	enamel/bone	tooth	food/beverage	acquisition	
106275	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	4	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
106304	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	13	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
106301	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	4	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
106310	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
106306	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	8	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
106300	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	8	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
106284	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	1	tack, furniture	fragment	Metal	copper alloy	copper alloy	furniture/household equip.	hardware	
106262	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	3	unidentified	fragment	Metal	ferrous	unidentified	0	Not Assigned	
106276	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	21	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
106272	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	1	sewer pipe	fragment	Metal	lead	Not Assigned	heating, plumbing, electric	device	
106299	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	9	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
106294	Excavation Unit	Unit 1.2 STR01 LEV03 20-30cm MXH158		MXH158	Surface/Developing A	1	ballast	fragment	Stone	flint	gray	architecture	foundation	
106376	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-7/64
106377	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	2	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
106380	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
106383	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	2	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
106400	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-6/64
106409	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
106381	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	1	vessel, hollow	handle	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	luster-gray
106390	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
106389	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	6	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106404	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106401	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	jackfield type	food/beverage	service	
106374	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
106384	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
106391	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-green
106407	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	3	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
106408	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	7	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
106395	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	1	vessel, hollow	base	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-brown
106396	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-brown
106394	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106397	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	6	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106405	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	2	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106392	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	1	vessel, indeterminate	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
106379	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	1	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
106393	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	1	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
106403	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	3	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	painted-blue
106406	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	2	vessel, hollow	body	Ceramic	Tin Glazed	unidentified	0	Not Assigned	
106385	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
106410	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	4	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
106398	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	5	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
106375	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
106402	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
106382	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	4	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
106399	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
106378	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	9	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
106386	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	1	nail wrought	whole/intact	Metal	ferrous	wrought	architecture	general construction	
106388	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	1	unidentified	fragment	Metal	lead	cast	0	Not Assigned	
106387	Excavation Unit	Unit 1.2 STR01 LEV04 30-40cm MXH159		MXH159	Surface/Developing A	1	stone	fragment	Mineral	quartz	milky	0	Not Assigned	
106029	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	6	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
106042	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	3	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
106044	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	3	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-6/64
106078	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	2	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
106052	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
106069	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	5	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
106021	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	9	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
106049	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
106062	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	luster-black
106064	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	3	vessel, hollow	handle	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	luster-black
106076	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	2	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
106082	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	6	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
106033	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire plain	food/beverage	service	
106072	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Staffordshire plain	food/beverage	service	
106028	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire, slipped	food/beverage	service	
106054	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	2	vessel, hollow	body	Ceramic	Earthenware, coarse	unidentified	0	Not Assigned	
106077	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	1	vessel, flat	body	Ceramic	Earthenware, refined	creamware, hand painted overglaze	food/beverage	service	painted-yellow
106079	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	4	vessel, hollow	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106083	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	12	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106023	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
106074	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
106026	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
106073	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	6	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
106084	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	2	vessel, flat	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106063	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	12	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106038	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified		Not Assigned	painted-blue
106016	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	1	vessel, hollow	foot	Ceramic	Earthenware, refined	unidentified	food/beverage	service	slip-green
106075	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	Whiteware, undecorated	food/beverage	service	
106034	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	1	vessel, indeterminate	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
106081	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	3	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
106080	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	2	vessel, hollow	body	Ceramic	unidentified	Not Assigned	0	Not Assigned	
106031	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	5	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
106030	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	2	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
106019	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	4	charcoal	fragment	Flora	wood	charcoal	heating, plumbing, electric	fuel	
106032	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	8	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
106024	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	1	drinking glass, tumbler	rim	Glass	indeterminate	indeterminate	food/beverage	service	-Clear
106018	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
106015	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	3	vessel, hollow	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
106045	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	1	bottle, indeterminate	neck	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
106067	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	6	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
106035	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	1	bottle, indeterminate	body	Glass	mold blown	Not Assigned	food/beverage	storage	-Clear
106070	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	1	hardware, decorative	whole/intact	Metal	copper alloy	copper alloy	furniture/household equip.	hardware	
106020	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	3	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
106025	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	15	unidentified	fragment	Metal	ferrous	unidentified	0	Not Assigned	
106027	Excavation Unit	Unit 1.2 STR02 LEV04 30-40cm MXH160		MXH160	Foundation Builder's Trench	18	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
105852	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	5	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
105874	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	5	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
105885	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	3	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-6/64
105901	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	14	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
105890	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	10	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
105865	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	9	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
105853	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
105872	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	1	vessel, hollow	base	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
105884	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	5	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
105870	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	luster-gray
105882	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
105876	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire plain	food/beverage	service	
105900	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Staffordshire plain	food/beverage	service	
105873	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Astbury ware	food/beverage	service	
105866	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, factory-made slipware	food/beverage	service	painted-black
105862	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	34	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105889	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105895	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	3	vessel, hollow	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105896	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	6	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105887	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	5	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
105908	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	19	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
105911	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	Annular-blue
105906	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-brown
105860	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-green
105875	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	4	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
105877	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
105888	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
105878	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	4	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
105854	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105871	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	1	vessel, hollow	handle	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105894	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	34	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105898	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	2	vessel, hollow	foot	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105864	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	1	vessel, hollow	foot	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
105899	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	1	vessel, hollow	rim	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
105902	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	1	vessel, hollow	foot	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
105861	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	2	vessel, hollow	body	Ceramic	Porcelain	Imari	food/beverage	service	
105859	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	4	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	service	
105869	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	1	vessel, hollow	body	Ceramic	Stoneware	buff salt glazed	food/beverage	storage	
105856	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	1	vessel, hollow	body	Ceramic	Stoneware	Nottingham-type	food/beverage	service	
105897	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	2	vessel, hollow	body	Ceramic	Stoneware	Rhenish Brown	food/beverage	storage	
105858	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	1	vessel, hollow	body	Ceramic	Stoneware	Westerwald	food/beverage	service	
105868	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	2	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
105851	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	2	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
105903	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	2	vessel, hollow	body	Ceramic	Tin Glazed	unidentified	food/beverage	service	
105855	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	8	vessel, hollow	body	Ceramic	unidentified	unidentified	0	Not Assigned	
105893	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	28	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
105880	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	7	tooth	fragment	Fauna	enamel/bone	tooth	food/beverage	acquisition	
105863	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	13	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
105883	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	17	charcoal	fragment	Flora	wood	charcoal	heating, plumbing, electric	fuel	
105910	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	21	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
105857	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	6	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
105879	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	1	drinking glass, tumbler	rim	Glass	indeterminate	indeterminate	food/beverage	service	-Clear
105907	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
105905	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	7	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
105886	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	13	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
105881	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	1	unidentified	fragment	Metal	copper alloy	copper alloy	0	Not Assigned	
105904	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	15	unidentified	fragment	Metal	ferrous	unidentified	0	Not Assigned	
105867	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	27	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
105891	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	2	stone, worked	fragment	Stone	Felsite	blue-grey	personal	other personal possession	
105892	Excavation Unit	Unit 1.2 STR03 LEV05 40-50cm MXH161		MXH161	Inverted A	3	stone, worked	fragment	Stone	flint	butterscotch	personal	other personal possession	
105838	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	2	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
105832	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	1	pipe, bowl/stem	bowl	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
105846	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
105824	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-6/64
105826	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-7/64
105845	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	2	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
105848	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	2	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
105850	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	3	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
105829	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Iberian storage jar	food/beverage	storage	
105843	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	7	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
105798	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
105799	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	15	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
105816	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	38	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
105796	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	1	vessel, hollow	handle	Ceramic	Earthenware, coarse	Staffordshire plain	food/beverage	service	
105803	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	50	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105806	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	3	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105811	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	1	tea bowl	base	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-orange
105801	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	Annular-brown
105818	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-green
105842	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-orange
105809	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	3	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
105822	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	3	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
105794	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	21	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
105823	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
105836	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	2	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
105793	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	47	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105795	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105844	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	6	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105833	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	1	vessel, hollow	rim	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
105837	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	2	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
105813	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	1	vessel, flat	rim	Ceramic	Porcelain	Decorated	food/beverage	service	painted-blue
105802	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	1	vessel, hollow	base	Ceramic	Stoneware	buff salt glazed	food/beverage	storage	
105828	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	Nottingham-type	food/beverage	service	
105839	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	Rhenish Brown	food/beverage	storage	
105819	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	Unidentified	0	Not Assigned	
105831	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	Westerwald	food/beverage	service	
105834	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
105947	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	3	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
105821	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	2	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	storage	
105804	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	3	vessel, indeterminate	body	Ceramic	unidentified	unidentified	0	Not Assigned	
105817	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	14	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
105820	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	3	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
105812	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	5	tooth	fragment	Fauna	enamel/bone	tooth	food/beverage	acquisition	
105792	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	16	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
105835	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	1	seed	whole/intact	Flora	seed/pit/nut	cherry	food/beverage	acquisition	
105814	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	28	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
105807	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	1	vessel, hollow	rim	Glass	indeterminate	indeterminate		Not Assigned	-Clear
105825	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	2	drinking glass, unid.	body	Glass	indeterminate	indeterminate	food/beverage	service	-Clear
105797	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
105830	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	7	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
105841	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	1	bottle, indeterminate	lip	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
105808	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
105827	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	1	bottle, indeterminate	lip	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)-Oil
105815	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	1	drinking glass, tumbler	rim	Glass	molded	molded	food/beverage	service	-Clear
105840	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	6	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
105800	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	39	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
105810	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	1	unidentified	fragment	Metal	lead	Not Assigned	0	Not Assigned	
105805	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	5	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
105949	Excavation Unit	Unit 1.2 STR04 LEV06 50-60cm MXH162		MXH162	Buried APZ	3	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
105974	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
105983	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	7	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
105985	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
105921	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
105980	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	8	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
106004	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	2	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
105917	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	19	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
105990	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
105977	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	25	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
105971	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	1	tile, roof	fragment	Ceramic	Earthenware, coarse	Redware, unglazed	architecture	roofing	
105978	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	26	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
106005	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
105984	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	4	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire plain	food/beverage	service	
105920	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	49	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106006	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105968	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	
106000	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-blue
105938	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	2	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
105926	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	3	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
105967	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	1	vessel, flat	body	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
105927	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	31	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
105991	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
105918	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	60	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105999	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	1	vessel, flat	rim	Ceramic	Earthenware, refined	Refined agate ware	food/beverage	service	
105976	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	1	vessel, flat	base	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
106001	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	1	vessel, flat	rim	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
105998	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	1	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
105992	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	1	vessel, flat	base	Ceramic	Porcelain	Decorated	food/beverage	service	painted-blue
105979	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	1	vessel, flat	rim	Ceramic	Porcelain	Decorated	food/beverage	service	painted-brown
105981	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	3	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	service	
105931	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	gray salt glazed	food/beverage	storage	Albany slip-black
105997	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	Rhenish Brown	food/beverage	storage	
105995	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	1	teapot	rim	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
105994	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
105972	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed, scratch blue	food/beverage	service	
106003	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	13	vessel, hollow	body	Ceramic	unidentified	Redware, unglazed	food/beverage	storage	
105916	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	21	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
105969	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	3	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
105988	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	1	tooth	fragment	Fauna	enamel/bone	tooth	food/beverage	acquisition	
105993	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	1	tooth	fragment	Fauna	enamel/bone	tooth	food/beverage	acquisition	
105989	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	8	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
105935	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	1	charcoal	fragment	Flora	wood	charcoal	heating, plumbing, electric	fuel	
105975	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	27	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
105982	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
105970	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	1	vessel, tableware	base	Glass	indeterminate	indeterminate	food/beverage	service	-Clear
106007	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	9	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
105923	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	11	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
105996	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	1	bottle, pharmaceutical	lip/neck	Glass	indeterminate	indeterminate	medical/chemical	storage	-Aqua marine*-prescription
105987	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	3	unidentified	fragment	Metal	copper alloy	copper alloy	0	Not Assigned	
106002	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	4	unidentified	fragment	Metal	ferrous	unidentified	0	Not Assigned	
105973	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	27	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
105934	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	6	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
105928	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	4	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
105937	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	2	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
105924	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	1	stone, worked	fragment	Stone	Argillite	gray	personal	other personal possession	
105986	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	2	ballast	fragment	Stone	flint	gray	architecture	foundation	
105925	Excavation Unit	Unit 1.2 STR04 LEV07 60-70cm MXH163		MXH163	Buried APZ	7	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
105637	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	pipe, mouth piece	head	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
105642	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	2	pipe, mouth piece	head	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
105655	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	5	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
105674	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	3	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
105615	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	pipe, bowl/stem	bowl	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
105659	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
105682	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	10	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
105684	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	4	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
105635	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	22	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
105652	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Coarse agate, buckley ware	food/beverage	storage	
105681	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Manganese Mottled	food/beverage	service	
105622	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
105648	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
105649	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	12	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
105689	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, hollow	handle	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
105631	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	21	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
105664	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	2	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
105685	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
105663	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, slip decorated	food/beverage	preparation	
105630	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	68	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
105645	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	3	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
105644	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire plain	food/beverage	service	
105672	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire, slipped	food/beverage	service	
105636	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, indeterminate	body	Ceramic	Earthenware, coarse	unidentified	0	Not Assigned	
105658	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	4	vessel, hollow	body	Ceramic	Earthenware, refined	Astbury ware	food/beverage	service	
105688	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Astbury ware	food/beverage	service	
105638	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Cauliflower ware	food/beverage	service	
105678	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	creamware, hand painted overglaze	food/beverage	service	painted-brown
105623	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	5	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105629	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	90	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105632	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, hollow	handle	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
105633	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	5	vessel, hollow	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105711	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
105680	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, refined	Creamware, transfer printed overglaze	food/beverage	service	transfer print-black
105617	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, flat	body	Ceramic	Earthenware, refined	Ironstone	food/beverage	service	
105692	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, flat	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-brown
105639	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-brown
105709	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
105694	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	flow blue-blue
105625	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-brown
105701	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-brown
105650	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-green
105624	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	4	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
105712	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, flat	body	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
105691	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	6	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
105613	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	42	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
105686	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	4	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
105618	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	96	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105620	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105657	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	6	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
105698	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Whiteldon (clouded or tortoiseshell)	food/beverage	service	
105640	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Whiteware, transfer printed	food/beverage	service	transfer print-blue
105621	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	Yellow ware, plain	food/beverage	service	
105634	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
105670	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, hollow	rim	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
105643	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, hollow	base	Ceramic	Porcelain	Decorated	food/beverage	service	
105665	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, hollow	rim	Ceramic	Porcelain	Decorated	food/beverage	service	painted-brown
105704	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, hollow	body	Ceramic	Porcelain	Decorated	food/beverage	service	painted-orange
105690	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	3	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	service	
105666	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	brown, salt-glazed	food/beverage	storage	
105696	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, hollow	base	Ceramic	Stoneware	gray salt glazed	food/beverage	service	
105641	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, hollow	rim	Ceramic	Stoneware	Westerwald	food/beverage	service	
105660	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	Westerwald	food/beverage	service	
105661	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	Westerwald	food/beverage	service	
105654	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	5	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
105699	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, hollow	rim	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
105626	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
105677	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	2	vessel, hollow	body	Ceramic	Tin Glazed	unidentified	food/beverage	service	
105619	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	12	vessel, hollow	body	Ceramic	unidentified	Not Assigned	0	Not Assigned	
105628	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	19	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
105667	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	7	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
105668	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	tooth	fragment	Fauna	enamel/bone	tooth	food/beverage	acquisition	
105695	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
105697	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	5	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
105646	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	8	charcoal	fragment	Flora	wood	charcoal	heating, plumbing, electric	fuel	
105614	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	35	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
105653	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	5	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
105671	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	7	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
105647	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	10	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
105656	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	16	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
105693	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	bottle, wine/liquor/beer	body	Glass	molded	molded	food/beverage	storage	-Green (olive)
105669	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	nail, cut	whole/intact	Metal	copper alloy	copper alloy	architecture	general construction	
105687	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	1	pin	whole/intact	Metal	copper alloy	copper alloy	industry, manufacture, trades	sewing/tailoring	
105627	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	4	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
105676	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	4	tack, furniture	fragment	Metal	ferrous	cut	furniture/household equip.	hardware	
105612	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	42	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
105683	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	15	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
105651	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	3	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
105611	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	4	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
105662	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	3	ballast	fragment	Stone	flint	gray	architecture	foundation	
105616	Excavation Unit	Unit 1.2 STR04 LEV08 70-80cm MXH164		MXH164	Buried APZ	6	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
106211	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
106194	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	2	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
106191	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	9	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
106197	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
106235	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	8	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
106237	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Manganese Mottled	food/beverage	service	
106192	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
106222	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
106202	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	8	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
106206	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	12	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
106226	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	luster-black
106188	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	20	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
106224	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire, slipped	food/beverage	service	
106200	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106209	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	4	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106231	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	55	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106255	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106252	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	jackfield type	food/beverage	service	
106205	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	2	vessel, flat	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-blue
106229	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	2	vessel, flat	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	slip-yellow
106239	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	4	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-brown
106195	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
106236	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
106214	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-green
106196	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	2	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
106227	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	3	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
106199	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	5	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
106201	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	2	vessel, hollow	base	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
106215	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	12	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
106233	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	1	vessel, flat	foot	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106234	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	2	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106203	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106232	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	42	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106254	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106221	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	1	vessel, flat	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
106187	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	1	mug	rim	Ceramic	Porcelain	Decorated	food/beverage	service	gilded-gold
106243	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	1	vessel, hollow	foot	Ceramic	Porcelain	Plain	food/beverage	service	
106253	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	1	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	service	
106198	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	Nottingham-type	food/beverage	storage	
106225	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	Rhenish Brown	food/beverage	storage	
106249	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	Rhenish Brown	food/beverage	storage	
106193	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	1	vessel, hollow	rim	Ceramic	Stoneware	Westerwald	food/beverage	service	
106220	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	1	vessel, hollow	foot	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
106247	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	3	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
106241	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	3	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
106240	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	1	vessel, hollow	body	Ceramic	Tin Glazed	unidentified	food/beverage	service	
106219	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	2	vessel, indeterminate	body	Ceramic	unidentified	Not Assigned	0	Not Assigned	
106207	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	5	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
106238	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	4	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
106228	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	3	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
106204	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	17	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
106248	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
106251	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	1	drinking glass, tumbler	body	Glass	indeterminate	indeterminate	food/beverage	service	-Clear
106242	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	4	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
106230	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	6	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
106244	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	5	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
106212	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	9	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
106213	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	1	tack, furniture	fragment	Metal	copper alloy	copper alloy	furniture/household equip.	hardware	
106189	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	1	unidentified	fragment	Metal	ferrous	unidentified	0	Not Assigned	
106208	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	14	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
106245	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	1	sheet metal	fragment	Metal	lead	Not Assigned	0	Not Assigned	
106223	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
106190	Excavation Unit	Unit 1.2 STR04 LEV09 80-90cm MXH165		MXH165	Buried APZ	1	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
106148	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	4	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
106127	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	8	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
106180	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-6/64
106183	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-6/64
106147	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-7/64
106182	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
106141	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	2	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
106142	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	4	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
106168	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	3	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
106179	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
106174	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	10	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
106173	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Manganese Mottled	food/beverage	service	
106153	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Manganese Mottled	food/beverage	service	
106175	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	23	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
106177	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
106149	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	1	pot	rim	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
106172	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	10	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
106178	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Staffordshire plain	food/beverage	service	
106185	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire, slipped	food/beverage	service	
106130	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	7	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106133	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106140	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-brown
106135	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
106161	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
106163	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
106171	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
106132	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	14	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106151	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	2	vessel, hollow	foot	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106154	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106162	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	2	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
106129	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	Rhenish Brown	food/beverage	storage	
106160	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	Unidentified	food/beverage	service	
106152	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	1	vessel, hollow	base	Ceramic	Stoneware	Unidentified	food/beverage	storage	Albany slip-brown
106166	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	1	vessel, hollow	rim	Ceramic	Stoneware	Westerwald	food/beverage	service	
106170	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	4	vessel, hollow	body	Ceramic	Stoneware	Westerwald	food/beverage	service	
106186	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	1	vessel, flat	rim	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
106137	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	1	vessel, hollow	rim	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
106138	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	1	vessel, hollow	handle	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
106159	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	6	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
106158	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	1	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	painted-blue
106184	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	1	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	painted-blue
106144	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	7	vessel, hollow	body	Ceramic	Tin Glazed	unidentified	food/beverage	service	
106169	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	1	bone	fragment	Fauna	bone	fish	food/beverage	acquisition	
106125	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	17	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
106167	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	11	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
106136	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	4	tooth	fragment	Fauna	enamel/bone	tooth	food/beverage	acquisition	
106134	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	9	shell, quahog	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
106164	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	2	charcoal	fragment	Flora	wood	charcoal	heating, plumbing, electric	fuel	
106181	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	9	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
106157	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
106176	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	1	bottle, indeterminate	lip/neck	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
106139	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua marine*
106128	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
106146	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
106126	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	6	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
106150	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	1	bottle, indeterminate	base	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
106156	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	1	stemware	stem	Glass	molded	molded	food/beverage	service	-Clear
106165	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	20	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
106145	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	1	chain, link	fragment	Metal	ferrous	machine made	0	Not Assigned	
106143	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	1	unidentified	fragment	Metal	ferrous	unidentified	0	Not Assigned	
106131	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	1	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
106155	Excavation Unit	Unit 1.2 STR04 LEV10 90-100cm MXH166		MXH166	Buried APZ	5	ballast	fragment	Stone	flint	buttes:cotch	architecture	foundation	
106101	Excavation Unit	Unit 1.2 STR04 LEV11 100-110cm MXH167		MXH167	Buried APZ	2	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-6/64
106114	Excavation Unit	Unit 1.2 STR04 LEV11 100-110cm MXH167		MXH167	Buried APZ	2	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
106119	Excavation Unit	Unit 1.2 STR04 LEV11 100-110cm MXH167		MXH167	Buried APZ	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
106120	Excavation Unit	Unit 1.2 STR04 LEV11 100-110cm MXH167		MXH167	Buried APZ	2	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
106104	Excavation Unit	Unit 1.2 STR04 LEV11 100-110cm MXH167		MXH167	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
106102	Excavation Unit	Unit 1.2 STR04 LEV11 100-110cm MXH167		MXH167	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
106118	Excavation Unit	Unit 1.2 STR04 LEV11 100-110cm MXH167		MXH167	Buried APZ	8	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
106098	Excavation Unit	Unit 1.2 STR04 LEV11 100-110cm MXH167		MXH167	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire plain	food/beverage	service	
106100	Excavation Unit	Unit 1.2 STR04 LEV11 100-110cm MXH167		MXH167	Buried APZ	1	vessel, hollow	body	Ceramic	Porcelain	Decorated	food/beverage	service	gilded-gold
106113	Excavation Unit	Unit 1.2 STR04 LEV11 100-110cm MXH167		MXH167	Buried APZ	2	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	painted-blue
106097	Excavation Unit	Unit 1.2 STR04 LEV11 100-110cm MXH167		MXH167	Buried APZ	16	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
106105	Excavation Unit	Unit 1.2 STR04 LEV11 100-110cm MXH167		MXH167	Buried APZ	1	tooth	fragment	Fauna	enamel/bone	tooth	food/beverage	acquisition	
106111	Excavation Unit	Unit 1.2 STR04 LEV11 100-110cm MXH167		MXH167	Buried APZ	5	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
106099	Excavation Unit	Unit 1.2 STR04 LEV11 100-110cm MXH167		MXH167	Buried APZ	3	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
106095	Excavation Unit	Unit 1.2 STR04 LEV11 100-110cm MXH167		MXH167	Buried APZ	2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
106115	Excavation Unit	Unit 1.2 STR04 LEV11 100-110cm MXH167		MXH167	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
106106	Excavation Unit	Unit 1.2 STR04 LEV11 100-110cm MXH167		MXH167	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
106109	Excavation Unit	Unit 1.2 STR04 LEV11 100-110cm MXH167		MXH167	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
106107	Excavation Unit	Unit 1.2 STR04 LEV11 100-110cm MXH167		MXH167	Buried APZ	2	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
106103	Excavation Unit	Unit 1.2 STR04 LEV11 100-110cm MXH167		MXH167	Buried APZ	2	nail, wire	near intact	Metal	ferrous	machine made	architecture	general construction	
106096	Excavation Unit	Unit 1.2 STR04 LEV11 100-110cm MXH167		MXH167	Buried APZ	6	unidentified	fragment	Metal	ferrous	unidentified	0	Not Assigned	
106110	Excavation Unit	Unit 1.2 STR04 LEV11 100-110cm MXH167		MXH167	Buried APZ	5	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
106108	Excavation Unit	Unit 1.2 STR04 LEV11 100-110cm MXH167		MXH167	Buried APZ	2	unidentified	fragment	Metal	lead	Not Assigned	0	Not Assigned	
106117	Excavation Unit	Unit 1.2 STR04 LEV11 100-110cm MXH167		MXH167	Buried APZ	1	ballast	fragment	Stone	flint	buttes:cotch	architecture	foundation	
107153	Excavation Unit	Unit 1.2 STR04 LEV12 110-120cm MXH168		MXH168	Buried APZ	1	charcoal	fragment	Flora	wood	charcoal	heating, plumbing, electric	fuel	
106453	Excavation Unit	Unit 1.2 STR05 LEV11 102-110cm MXH258		MXH258	B2	1	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106450	Excavation Unit	Unit 1.2 STR05 LEV11 102-110cm MXH258		MXH258	B2	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
106452	Excavation Unit	Unit 1.2 STR05 LEV11 102-110cm MXH258		MXH258	B2	1	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
106451	Excavation Unit	Unit 1.2 STR05 LEV11 102-110cm MXH258		MXH258	B2	4	charcoal	fragment	Flora	wood	charcoal	heating, plumbing, electric	fuel	
106449	Excavation Unit	Unit 1.2 STR05 LEV11 102-110cm MXH258		MXH258	B2	1	nail wrought	fragment	Metal	ferrous	wrought	architecture	general construction	
106331	Excavation Unit	Unit 2.1 STR01 LEV01 00-10cm MXH169		MXH169	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
106330	Excavation Unit	Unit 2.1 STR01 LEV01 00-10cm MXH169		MXH169	Surface/Developing A	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
106322	Excavation Unit	Unit 2.1 STR01 LEV01 00-10cm MXH169		MXH169	Surface/Developing A	3	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
106332	Excavation Unit	Unit 2.1 STR01 LEV01 00-10cm MXH169		MXH169	Surface/Developing A	2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
106323	Excavation Unit	Unit 2.1 STR01 LEV01 00-10cm MXH169		MXH169	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
106327	Excavation Unit	Unit 2.1 STR01 LEV01 00-10cm MXH169		MXH169	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
106325	Excavation Unit	Unit 2.1 STR01 LEV01 00-10cm MXH169		MXH169	Surface/Developing A	2	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
106333	Excavation Unit	Unit 2.1 STR01 LEV01 00-10cm MXH169		MXH169	Surface/Developing A	1	unidentified	fragment	Metal	ferrous	machine made	0	Not Assigned	
106324	Excavation Unit	Unit 2.1 STR01 LEV01 00-10cm MXH169		MXH169	Surface/Developing A	2	nail, wire	whole/intact	Metal	ferrous	machine made	architecture	general construction	
106326	Excavation Unit	Unit 2.1 STR01 LEV01 00-10cm MXH169		MXH169	Surface/Developing A	1	bolt	whole/intact	Metal	ferrous	machine made	architecture	general construction	
106328	Excavation Unit	Unit 2.1 STR01 LEV01 00-10cm MXH169		MXH169	Surface/Developing A	3	nail, wire	whole/intact	Metal	ferrous	machine made	architecture	general construction	
106329	Excavation Unit	Unit 2.1 STR01 LEV01 00-10cm MXH169		MXH169	Surface/Developing A	1	cap, screw top	whole/intact	Synthetic	synthetic	plastic	0	Not Assigned	
106977	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
106982	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
106976	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	8	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106979	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106985	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	1	vessel, flat	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106990	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	sponge-blue
106996	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	Annular-brown
106988	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	4	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
106993	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
106989	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	6	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106973	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	unidentified	food/beverage	service	
106994	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Porcelain	Chinese overglaze enamel	food/beverage	service	painted-brown
106997	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	1	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
106974	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	1	vessel, hollow	body	Ceramic	Porcelain	Decorated	food/beverage	service	painted-red
106970	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	2	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
106971	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	2	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
106992	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
106981	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	1	button, two hole	whole/intact	Fauna	shell	bivalve	personal	fastener	
106967	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	1	paper	whole/intact	Flora	wood	paper	food/beverage	storage	
106972	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	3	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
106980	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Amber
106978	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	4	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
106995	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
106983	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	1	bottle, indeterminate	base	Glass	indeterminate	indeterminate	food/beverage	storage	-Amber-circular
106991	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	1	bead	whole/intact	Glass	molded	molded	personal	adornment	-Amethyst/Purple
106964	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	1	coin	whole/intact	Metal	copper alloy	copper alloy	commerce	coin	
106984	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	1	hinge, furniture	whole/intact	Metal	copper alloy	copper alloy	furniture/household equip.	hardware	
106968	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	6	nail, wire	whole/intact	Metal	ferrous	machine made	architecture	general construction	
106969	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	1	washer	fragment	Metal	ferrous	machine made	furniture/household equip.	hardware	
106986	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	5	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
106966	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	3	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
106975	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	1	mortar	fragment	Mineral	composite	mortar	architecture	general construction	
106965	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	1	asphalt	fragment	Synthetic	synthetic	asphalt	architecture	roofing	
106987	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	1	paint	fragment	Synthetic	synthetic	indeterminate	architecture	Not Assigned	
106998	Excavation Unit	Unit 2.1 STR01 LEV02 10-20cm MXH170		MXH170	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	rubber	0	Not Assigned	
106838	Excavation Unit	Unit 2.1 STR01 LEV03 20-30cm MXH171		MXH171	Surface/Developing A	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-6/64
106841	Excavation Unit	Unit 2.1 STR01 LEV03 20-30cm MXH171		MXH171	Surface/Developing A	2	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
106860	Excavation Unit	Unit 2.1 STR01 LEV03 20-30cm MXH171		MXH171	Surface/Developing A	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
106851	Excavation Unit	Unit 2.1 STR01 LEV03 20-30cm MXH171		MXH171	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire plain	food/beverage	service	
106848	Excavation Unit	Unit 2.1 STR01 LEV03 20-30cm MXH171		MXH171	Surface/Developing A	20	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106853	Excavation Unit	Unit 2.1 STR01 LEV03 20-30cm MXH171		MXH171	Surface/Developing A	4	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106869	Excavation Unit	Unit 2.1 STR01 LEV03 20-30cm MXH171		MXH171	Surface/Developing A	2	vessel, hollow	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106858	Excavation Unit	Unit 2.1 STR01 LEV03 20-30cm MXH171		MXH171	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
106867	Excavation Unit	Unit 2.1 STR01 LEV03 20-30cm MXH171		MXH171	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	Annular-blue
106842	Excavation Unit	Unit 2.1 STR01 LEV03 20-30cm MXH171		MXH171	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-black
106856	Excavation Unit	Unit 2.1 STR01 LEV03 20-30cm MXH171		MXH171	Surface/Developing A	1	vessel, hollow	handle	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	Annular-brown
106849	Excavation Unit	Unit 2.1 STR01 LEV03 20-30cm MXH171		MXH171	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-orange
106839	Excavation Unit	Unit 2.1 STR01 LEV03 20-30cm MXH171		MXH171	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
106843	Excavation Unit	Unit 2.1 STR01 LEV03 20-30cm MXH171		MXH171	Surface/Developing A	8	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
106844	Excavation Unit	Unit 2.1 STR01 LEV03 20-30cm MXH171		MXH171	Surface/Developing A	2	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
106854	Excavation Unit	Unit 2.1 STR01 LEV03 20-30cm MXH171		MXH171	Surface/Developing A	26	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106863	Excavation Unit	Unit 2.1 STR01 LEV03 20-30cm MXH171		MXH171	Surface/Developing A	3	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106855	Excavation Unit	Unit 2.1 STR01 LEV03 20-30cm MXH171		MXH171	Surface/Developing A	1	vessel, flat	base	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	painted-blue
106850	Excavation Unit	Unit 2.1 STR01 LEV03 20-30cm MXH171		MXH171	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Porcelain	Decorated	food/beverage	service	painted-blue
106845	Excavation Unit	Unit 2.1 STR01 LEV03 20-30cm MXH171		MXH171	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Porcelain	Decorated	food/beverage	service	painted-gray
106852	Excavation Unit	Unit 2.1 STR01 LEV03 20-30cm MXH171		MXH171	Surface/Developing A	1	vessel, flat	body	Ceramic	Stoneware	British brown	food/beverage	Service	
106865	Excavation Unit	Unit 2.1 STR01 LEV03 20-30cm MXH171		MXH171	Surface/Developing A	1	vessel, hollow	body	Ceramic	Stoneware	Westerwald	food/beverage	service	
106857	Excavation Unit	Unit 2.1 STR01 LEV03 20-30cm MXH171		MXH171	Surface/Developing A	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
106836	Excavation Unit	Unit 2.1 STR01 LEV03 20-30cm MXH171		MXH171	Surface/Developing A	4	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
106864	Excavation Unit	Unit 2.1 STR01 LEV03 20-30cm MXH171		MXH171	Surface/Developing A	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
106868	Excavation Unit	Unit 2.1 STR01 LEV03 20-30cm MXH171		MXH171	Surface/Developing A	12	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
106866	Excavation Unit	Unit 2.1 STR01 LEV03 20-30cm MXH171		MXH171	Surface/Developing A	6	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
106840	Excavation Unit	Unit 2.1 STR01 LEV03 20-30cm MXH171		MXH171	Surface/Developing A	5	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
106859	Excavation Unit	Unit 2.1 STR01 LEV03 20-30cm MXH171		MXH171	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
106846	Excavation Unit	Unit 2.1 STR01 LEV03 20-30cm MXH171		MXH171	Surface/Developing A	4	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
106861	Excavation Unit	Unit 2.1 STR01 LEV03 20-30cm MXH171		MXH171	Surface/Developing A	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
106837	Excavation Unit	Unit 2.1 STR01 LEV03 20-30cm MXH171		MXH171	Surface/Developing A	1		whole/intact	Metal	ferrous	Not Assigned	recreation/leisure	toys	
106862	Excavation Unit	Unit 2.1 STR01 LEV03 20-30cm MXH171		MXH171	Surface/Developing A	7	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
106847	Excavation Unit	Unit 2.1 STR01 LEV03 20-30cm MXH171		MXH171	Surface/Developing A	1	rod	fragment	Mineral	graphite	worked	heating, plumbing, electric	device	
106462	Excavation Unit	Unit 2.1 STR01 LEV07 60-70cm MXH190		MXH190	Surface/Developing A	3	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
106928	Excavation Unit	Unit 2.1 STR02 LEV04 30-40cm MXH172		MXH172	Foundation Builder's Trench	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
106931	Excavation Unit	Unit 2.1 STR02 LEV04 30-40cm MXH172		MXH172	Foundation Builder's Trench	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
106926	Excavation Unit	Unit 2.1 STR02 LEV04 30-40cm MXH172		MXH172	Foundation Builder's Trench	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
106929	Excavation Unit	Unit 2.1 STR02 LEV04 30-40cm MXH172		MXH172	Foundation Builder's Trench	2	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
106933	Excavation Unit	Unit 2.1 STR02 LEV04 30-40cm MXH172		MXH172	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
106945	Excavation Unit	Unit 2.1 STR02 LEV04 30-40cm MXH172		MXH172	Foundation Builder's Trench	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
106939	Excavation Unit	Unit 2.1 STR02 LEV04 30-40cm MXH172		MXH172	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire, slipped	food/beverage	service	
106925	Excavation Unit	Unit 2.1 STR02 LEV04 30-40cm MXH172		MXH172	Foundation Builder's Trench	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106944	Excavation Unit	Unit 2.1 STR02 LEV04 30-40cm MXH172		MXH172	Foundation Builder's Trench	11	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106937	Excavation Unit	Unit 2.1 STR02 LEV04 30-40cm MXH172		MXH172	Foundation Builder's Trench	6	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
106935	Excavation Unit	Unit 2.1 STR02 LEV04 30-40cm MXH172		MXH172	Foundation Builder's Trench	11	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106940	Excavation Unit	Unit 2.1 STR02 LEV04 30-40cm MXH172		MXH172	Foundation Builder's Trench	1	vessel, flat	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106930	Excavation Unit	Unit 2.1 STR02 LEV04 30-40cm MXH172		MXH172	Foundation Builder's Trench	2	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	food/beverage	service	
106947	Excavation Unit	Unit 2.1 STR02 LEV04 30-40cm MXH172		MXH172	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Porcelain	English porcelain	food/beverage	service	painted-blue
106922	Excavation Unit	Unit 2.1 STR02 LEV04 30-40cm MXH172		MXH172	Foundation Builder's Trench	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
106932	Excavation Unit	Unit 2.1 STR02 LEV04 30-40cm MXH172		MXH172	Foundation Builder's Trench	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
106936	Excavation Unit	Unit 2.1 STR02 LEV04 30-40cm MXH172		MXH172	Foundation Builder's Trench	17	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
106941	Excavation Unit	Unit 2.1 STR02 LEV04 30-40cm MXH172		MXH172	Foundation Builder's Trench	1	charcoal	fragment	Flora	wood	charcoal	heating, plumbing, electric	fuel	
106942	Excavation Unit	Unit 2.1 STR02 LEV04 30-40cm MXH172		MXH172	Foundation Builder's Trench	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
106923	Excavation Unit	Unit 2.1 STR02 LEV04 30-40cm MXH172		MXH172	Foundation Builder's Trench	1	bottle, wine/liquor/beer	base	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
106934	Excavation Unit	Unit 2.1 STR02 LEV04 30-40cm MXH172		MXH172	Foundation Builder's Trench	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
106938	Excavation Unit	Unit 2.1 STR02 LEV04 30-40cm MXH172		MXH172	Foundation Builder's Trench	2	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
106924	Excavation Unit	Unit 2.1 STR02 LEV04 30-40cm MXH172		MXH172	Foundation Builder's Trench	4	unidentified	fragment	Metal	ferrous	unidentified	0	Not Assigned	
106946	Excavation Unit	Unit 2.1 STR02 LEV04 30-40cm MXH172		MXH172	Foundation Builder's Trench	2	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
106943	Excavation Unit	Unit 2.1 STR02 LEV04 30-40cm MXH172		MXH172	Foundation Builder's Trench	1	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
106927	Excavation Unit	Unit 2.1 STR02 LEV04 30-40cm MXH172		MXH172	Foundation Builder's Trench	2	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
107103	Excavation Unit	Unit 2.1 STR02 LEV05 40-50cm MXH174		MXH174	Foundation Builder's Trench	2	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
107111	Excavation Unit	Unit 2.1 STR02 LEV05 40-50cm MXH174		MXH174	Foundation Builder's Trench	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
107105	Excavation Unit	Unit 2.1 STR02 LEV05 40-50cm MXH174		MXH174	Foundation Builder's Trench	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
107106	Excavation Unit	Unit 2.1 STR02 LEV05 40-50cm MXH174		MXH174	Foundation Builder's Trench	1	vessel, hollow	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107110	Excavation Unit	Unit 2.1 STR02 LEV05 40-50cm MXH174		MXH174	Foundation Builder's Trench	3	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107115	Excavation Unit	Unit 2.1 STR02 LEV05 40-50cm MXH174		MXH174	Foundation Builder's Trench	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107117	Excavation Unit	Unit 2.1 STR02 LEV05 40-50cm MXH174		MXH174	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-blue
107102	Excavation Unit	Unit 2.1 STR02 LEV05 40-50cm MXH174		MXH174	Foundation Builder's Trench	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
107112	Excavation Unit	Unit 2.1 STR02 LEV05 40-50cm MXH174		MXH174	Foundation Builder's Trench	3	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107107	Excavation Unit	Unit 2.1 STR02 LEV05 40-50cm MXH174		MXH174	Foundation Builder's Trench	4	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107114	Excavation Unit	Unit 2.1 STR02 LEV05 40-50cm MXH174		MXH174	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
107101	Excavation Unit	Unit 2.1 STR02 LEV05 40-50cm MXH174		MXH174	Foundation Builder's Trench	1	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
107108	Excavation Unit	Unit 2.1 STR02 LEV05 40-50cm MXH174		MXH174	Foundation Builder's Trench	2	charcoal	fragment	Flora	wood	charcoal	heating, plumbing, electric	fuel	
107104	Excavation Unit	Unit 2.1 STR02 LEV05 40-50cm MXH174		MXH174	Foundation Builder's Trench	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
107113	Excavation Unit	Unit 2.1 STR02 LEV05 40-50cm MXH174		MXH174	Foundation Builder's Trench	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
107109	Excavation Unit	Unit 2.1 STR02 LEV05 40-50cm MXH174		MXH174	Foundation Builder's Trench	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
107116	Excavation Unit	Unit 2.1 STR02 LEV05 40-50cm MXH174		MXH174	Foundation Builder's Trench	6	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
106950	Excavation Unit	Unit 2.1 STR02 LEV06 50-60cm MXH175		MXH175	Foundation Builder's Trench	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
106949	Excavation Unit	Unit 2.1 STR02 LEV06 50-60cm MXH175		MXH175	Foundation Builder's Trench	1	vessel, hollow	base	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
106954	Excavation Unit	Unit 2.1 STR02 LEV06 50-60cm MXH175		MXH175	Foundation Builder's Trench	1	vessel, flat	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106953	Excavation Unit	Unit 2.1 STR02 LEV06 50-60cm MXH175		MXH175	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, transfer printed overglaze	food/beverage	service	transfer print-black
106952	Excavation Unit	Unit 2.1 STR02 LEV06 50-60cm MXH175		MXH175	Foundation Builder's Trench	2	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
106959	Excavation Unit	Unit 2.1 STR02 LEV06 50-60cm MXH175		MXH175	Foundation Builder's Trench	5	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
106962	Excavation Unit	Unit 2.1 STR02 LEV06 50-60cm MXH175		MXH175	Foundation Builder's Trench	11	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106956	Excavation Unit	Unit 2.1 STR02 LEV06 50-60cm MXH175		MXH175	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
106961	Excavation Unit	Unit 2.1 STR02 LEV06 50-60cm MXH175		MXH175	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Porcelain	Decorated	food/beverage	service	gilded-gold
106951	Excavation Unit	Unit 2.1 STR02 LEV06 50-60cm MXH175		MXH175	Foundation Builder's Trench	1	vessel, hollow	foot	Ceramic	Porcelain	Plain	food/beverage	service	
106957	Excavation Unit	Unit 2.1 STR02 LEV06 50-60cm MXH175		MXH175	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
106948	Excavation Unit	Unit 2.1 STR02 LEV06 50-60cm MXH175		MXH175	Foundation Builder's Trench	6	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
106960	Excavation Unit	Unit 2.1 STR02 LEV06 50-60cm MXH175		MXH175	Foundation Builder's Trench	2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
106958	Excavation Unit	Unit 2.1 STR02 LEV06 50-60cm MXH175		MXH175	Foundation Builder's Trench	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
106955	Excavation Unit	Unit 2.1 STR02 LEV06 50-60cm MXH175		MXH175	Foundation Builder's Trench	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
106963	Excavation Unit	Unit 2.1 STR02 LEV06 50-60cm MXH175		MXH175	Foundation Builder's Trench	3	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
106802	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	3	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
106807	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	1	pipe, heel/spur	heel	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
106814	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
106818	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	1	pipe, mouth piece	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
106822	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	2	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
106831	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
106805	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	2	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
106808	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
106792	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	9	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
106780	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	4	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
106781	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	4	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire plain	food/beverage	service	
106798	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	1	vessel, hollow	body	Ceramic	Earthenware, coarse	unidentified	0	Not Assigned	
106784	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	4	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106796	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	96	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106830	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	1	vessel, hollow	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106803	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-brown
106777	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-green
106824	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	4	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-orange
106787	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	7	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
106813	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-black
107151	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	Annular-blue
106812	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	slip-green
106828	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	4	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-yellow
106782	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	3	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
106794	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	6	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
106785	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	43	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
106833	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	3	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
106832	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	2	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
106810	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	6	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106811	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	92	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106815	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	2	teapot	lid	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106820	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106834	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	2	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106821	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	11	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
106778	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Whiteware, transfer printed	food/beverage	service	transfer print-black
106783	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	1	vessel, hollow	body	Ceramic	Porcelain	Decorated	food/beverage	service	
106829	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	1	vessel, hollow	rim	Ceramic	Porcelain	Decorated	food/beverage	service	painted-blue
106779	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	2	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	service	
106789	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	1	vessel, hollow	handle	Ceramic	Porcelain	Plain	food/beverage	service	
106835	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	1	vessel, hollow	rim	Ceramic	Porcelain	Plain	food/beverage	service	
106790	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	1	vessel, hollow	body	Ceramic	Stoneware	British brown	food/beverage	Service	
106806	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	5	vessel, hollow	body	Ceramic	Stoneware	gray salt glazed	food/beverage	storage	
106827	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	1	vessel, hollow	body	Ceramic	Stoneware	Nottingham-type	food/beverage	service	
106795	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	1	vessel, hollow	body	Ceramic	Stoneware	Rhenish Brown	food/beverage	storage	
106773	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	1	vessel, hollow	body	Ceramic	Stoneware	Westerwald	food/beverage	service	
106825	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	2	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
106826	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	1	vessel, hollow	foot	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
106786	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	2	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
106772	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	34	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
106817	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	5	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
106774	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	6	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
106775	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	42	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
106819	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	6	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
106801	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
106776	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
106799	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	7	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
106791	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	1	bottle, wine/liquor/beer	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
106797	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	22	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
106804	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
106793	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	1	drinking glass, tumbler	base	Glass	molded	molded	food/beverage	service	-Clear
106823	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	9	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
106788	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	4	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
106809	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	1	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
106800	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	1	ballast	fragment	Stone	flint	buttes-scotch	architecture	foundation	
106816	Excavation Unit	Unit 2.1 STR02 LEV07 60-70cm MXH177		MXH177	Gravel Fill	1	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
106907	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
106904	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
106909	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	2	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
106892	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	15	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
106895	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	11	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
106885	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	9	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
106899	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	12	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
106918	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire, slipped	food/beverage	service	
106915	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	creamware, hand painted overglaze	food/beverage	service	painted-red
106908	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	2	vessel, flat	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106878	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	65	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106893	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106879	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-blue
106890	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	1	vessel, flat	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
106914	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	painted-blue
106881	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-blue
106913	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	5	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	transfer print-green
106880	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	2	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
106898	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
106896	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	21	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
106903	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
106912	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	3	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
106901	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-green
106887	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	44	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106910	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	3	vessel, flat	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
106877	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Whiteware, hand painted polychrome	food/beverage	service	Annular-brown
106900	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, refined	Whiteware, transfer printed	food/beverage	service	transfer print-green
106888	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	2	vessel, flat	rim	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	painted-blue
106921	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	Nottingham-type	food/beverage	storage	
106906	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	Unidentified	food/beverage	service	Albany slip-brown
106882	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	Unidentified	food/beverage	service	painted-black
106916	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	Westerwald	food/beverage	service	
106883	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	1	vessel, hollow	rim	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
106884	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
106873	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	30	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
106917	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
106902	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	1	tooth	near intact	Fauna	enamel/bone	tooth	food/beverage	acquisition	
106870	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	11	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
106905	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	6	charcoal	fragment	Flora	wood	charcoal	heating, plumbing, electric	fuel	
106911	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	19	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
106886	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	3	window glass, flat	body	Glass	flat	flat	architecture	window	-Clear
106891	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	1	vessel, hollow	base	Glass	indeterminate	indeterminate		Not Assigned	-Clear
106876	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
106889	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
106919	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
106920	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
106872	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	11	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
106874	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
106894	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	1	nail, wire	fragment	Metal	ferrous	machine made	architecture	general construction	
106871	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	20	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
106897	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
106875	Excavation Unit	Unit 2.1 STR03 LEV06 50-60cm MXH176		MXH176	Buried APZ	1	stone, worked	fragment	Stone	marble	Not Assigned	architecture	general construction	
106709	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	2	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
106747	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	5	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
106708	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
106756	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	4	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
106762	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
106763	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	2	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
106728	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	4	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
106766	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	2	vessel, hollow	rim	Ceramic	Earthenware, coarse	Iberian storage jar	food/beverage	storage	
106745	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
106758	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	20	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
106723	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
106725	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	2	vessel, hollow	base	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
106732	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
106744	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	8	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
106767	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire, slipped	food/beverage	service	
106716	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	89	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106739	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	2	vessel, hollow	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106761	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	6	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106733	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-orange
106715	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
106721	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	2	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
106736	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	6	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
106712	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-black
106742	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-blue
106724	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-brown
106770	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-orange
106743	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-yellow

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
106757	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
106750	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
106720	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	5	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
106738	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	28	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
106749	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
106764	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-brown
106714	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	15	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106718	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	1	vessel, hollow	foot	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106748	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	55	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106760	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	6	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106717	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	1	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
106746	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	1	tile, floor	fragment	Ceramic	Porcelain	Decorated	architecture	foundation	
106734	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	1	vessel, hollow	body	Ceramic	Porcelain	Decorated	food/beverage	service	painted-blue
106722	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	1	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	service	
106768	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	2	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	service	
106731	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	Nottingham-type	food/beverage	service	
106755	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	1	bottle, ink	Shoulder	Ceramic	Stoneware	Nottingham-type	personal	other personal possession	
106726	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	2	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
106740	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	1	vessel, hollow	rim	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
106741	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	1	vessel, hollow	foot	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
106705	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	23	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
106771	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	2	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
106706	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	1	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
106752	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	4	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
106730	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	18	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
106751	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	1	vessel, hollow	rim	Glass	indeterminate	indeterminate	0	Not Assigned	-Clear
106737	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	1	vessel, hollow	body	Glass	indeterminate	indeterminate	0	Not Assigned	-Green (light olive)
106753	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	1	lid	fragment	Glass	indeterminate	indeterminate		Not Assigned	-Clear
106729	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
106754	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	11	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
106727	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	11	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
106735	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	1	vessel, hollow	rim	Glass	mold blown	Not Assigned	food/beverage	service	
106711	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	2	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
106707	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	21	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
106769	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
106759	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	3	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
106765	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	1	mortar	fragment	Mineral	composite	mortar	architecture	general construction	
106710	Excavation Unit	Unit 2.1 STR03 LEV08 70-80cm MXH178		MXH178	Buried APZ	3	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
106421	Excavation Unit	Unit 2.1 STR03 LEV09 80-90cm MXH180		MXH180	Buried APZ	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
106422	Excavation Unit	Unit 2.1 STR03 LEV09 80-90cm MXH180		MXH180	Buried APZ	3	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
106414	Excavation Unit	Unit 2.1 STR03 LEV09 80-90cm MXH180		MXH180	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
106427	Excavation Unit	Unit 2.1 STR03 LEV09 80-90cm MXH180		MXH180	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
106426	Excavation Unit	Unit 2.1 STR03 LEV09 80-90cm MXH180		MXH180	Buried APZ	11	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
106415	Excavation Unit	Unit 2.1 STR03 LEV09 80-90cm MXH180		MXH180	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
106425	Excavation Unit	Unit 2.1 STR03 LEV09 80-90cm MXH180		MXH180	Buried APZ	6	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
106424	Excavation Unit	Unit 2.1 STR03 LEV09 80-90cm MXH180		MXH180	Buried APZ	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, unidentified	food/beverage	service	
106423	Excavation Unit	Unit 2.1 STR03 LEV09 80-90cm MXH180		MXH180	Buried APZ	10	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
106420	Excavation Unit	Unit 2.1 STR03 LEV09 80-90cm MXH180		MXH180	Buried APZ	2	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
106419	Excavation Unit	Unit 2.1 STR03 LEV09 80-90cm MXH180		MXH180	Buried APZ	1	shell	fragment	Fauna	shell	mollusk	food/beverage	acquisition	
106418	Excavation Unit	Unit 2.1 STR03 LEV09 80-90cm MXH180		MXH180	Buried APZ	1	charcoal	fragment	Flora	wood	charcoal	heating, plumbing, electric	fuel	
106411	Excavation Unit	Unit 2.1 STR03 LEV09 80-90cm MXH180		MXH180	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua marine*
106413	Excavation Unit	Unit 2.1 STR03 LEV09 80-90cm MXH180		MXH180	Buried APZ	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
106417	Excavation Unit	Unit 2.1 STR03 LEV09 80-90cm MXH180		MXH180	Buried APZ	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
106412	Excavation Unit	Unit 2.1 STR03 LEV09 80-90cm MXH180		MXH180	Buried APZ	2	unidentified	fragment	Metal	ferrous	unidentified	0	Not Assigned	
106416	Excavation Unit	Unit 2.1 STR03 LEV09 80-90cm MXH180		MXH180	Buried APZ	2	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
106428	Excavation Unit	Unit 2.1 STR03 LEV09 80-90cm MXH180		MXH180	Buried APZ	1	pencil	fragment	Stone	Slate	Not Assigned	personal	other personal possession	
107169	Excavation Unit	Unit 2.1 STR04 LEV08 80-90cm MXH181		MXH181	Foundation Builder's Trench	2	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
106443	Excavation Unit	Unit 2.1 STR04 LEV 10 90-100cm MXH183		MXH183	Foundation Builder's Trench	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
106444	Excavation Unit	Unit 2.1 STR04 LEV 10 90-100cm MXH183		MXH183	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-brown
106445	Excavation Unit	Unit 2.1 STR04 LEV 10 90-100cm MXH183		MXH183	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
106447	Excavation Unit	Unit 2.1 STR04 LEV 10 90-100cm MXH183		MXH183	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Stoneware	Westerwald	food/beverage	service	
106442	Excavation Unit	Unit 2.1 STR04 LEV 10 90-100cm MXH183		MXH183	Foundation Builder's Trench	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
106448	Excavation Unit	Unit 2.1 STR04 LEV 10 90-100cm MXH183		MXH183	Foundation Builder's Trench	1	charcoal	fragment	Flora	wood	charcoal	heating, plumbing, electric	fuel	
106446	Excavation Unit	Unit 2.1 STR04 LEV 10 90-100cm MXH183		MXH183	Foundation Builder's Trench	1	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
107523	Excavation Unit	Unit 2.1 STR05 LEV09 80-90cm MXH182		MXH182	B1	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107522	Excavation Unit	Unit 2.1 STR05 LEV09 80-90cm MXH182		MXH182	B1	1	vessel, hollow	body	Ceramic	Tin Glazed	unidentified	food/beverage	service	
107521	Excavation Unit	Unit 2.1 STR05 LEV09 80-90cm MXH182		MXH182	B1	1	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
106464	Excavation Unit	Unit 2.1 STR05 LEV 10 90-100cm MXH183b		MXH183b	B1	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
106463	Excavation Unit	Unit 2.1 STR05 LEV 10 90-100cm MXH183b		MXH183b	B1	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
108033	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
108042	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		4	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
108057	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
108055	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
108054	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		2	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
108017	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
108022	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
108041	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
108036	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	Not Assigned	
108015	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
108019	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
108024	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Staffordshire, slipped	food/beverage	service	
108040	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		2	vessel, hollow	body	Ceramic	Earthenware, refined	creamware, hand painted overglaze	food/beverage	service	painted-green
108023	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		2	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
108047	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		37	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
108048	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		1	vessel, hollow	body	Ceramic	Earthenware, refined	Luster decorated ware	food/beverage	service	luster-purple/manganese
108013	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
108034	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
108049	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		2	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
108032	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-blue
108027	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-brown
108051	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		2	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
108058	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		1	vessel, flat	body	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
108052	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		3	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
108021	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
108025	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		22	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
108018	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		2	vessel, hollow	foot	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
108039	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		53	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
108045	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		2	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
108060	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
108046	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		5	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
108050	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		3	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
108020	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		1	vessel, hollow	rim	Ceramic	Earthenware, refined	unidentified	food/beverage	service	
108062	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		1	vessel, hollow	body	Ceramic	Earthenware, refined	Whiteware, hand painted polychrome	food/beverage	service	painted-brown
108053	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		1	vessel, hollow	rim	Ceramic	Earthenware, refined	Whiteware, undentified	food/beverage	service	
108059	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		3	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
108065	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		2	vessel, hollow	body	Ceramic	Porcelain	Decorated	food/beverage	service	painted-orange
108009	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		2	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	service	
108061	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		2	vessel, hollow	rim	Ceramic	Porcelain	Plain	food/beverage	service	
108031	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		1	vessel, hollow	body	Ceramic	Stoneware	gray salt glazed	food/beverage	service	
108043	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		2	vessel, hollow	body	Ceramic	Stoneware	Nottingham-type	food/beverage	service	
108056	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		2	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
108028	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		1	vessel, indeterminate	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
108029	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		1	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	painted-blue
108035	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		10	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
108026	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		7	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
108012	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		11	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
108014	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		4	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
108044	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
108010	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		4	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
108064	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
108030	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		1	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
108038	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		1	buckle	fragment	Metal	ferrous	machine made	personal	fastener	
108016	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		11	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
108037	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		16	unidentified	fragment	Metal	ferrous	unidentified	architecture	general construction	
108011	Excavation Unit	Unit 2.1+2.2 Wall Fall MXH222		MXH222		9	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
107787	Excavation Unit	Unit 2.2 STR01 LEV01 00-10cm MXH199		MXH199	Surface/Developing A	1	bead	whole/intact	Ceramic	Ball clay	molded	personal	adornment	
107788	Excavation Unit	Unit 2.2 STR01 LEV01 00-10cm MXH199		MXH199	Surface/Developing A	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
107783	Excavation Unit	Unit 2.2 STR01 LEV01 00-10cm MXH199		MXH199	Surface/Developing A	1	vessel, flat	body	Ceramic	Earthenware, coarse	Redware, unglazed	0	Not Assigned	
107801	Excavation Unit	Unit 2.2 STR01 LEV01 00-10cm MXH199		MXH199	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107785	Excavation Unit	Unit 2.2 STR01 LEV01 00-10cm MXH199		MXH199	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
107784	Excavation Unit	Unit 2.2 STR01 LEV01 00-10cm MXH199		MXH199	Surface/Developing A	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107797	Excavation Unit	Unit 2.2 STR01 LEV01 00-10cm MXH199		MXH199	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
107786	Excavation Unit	Unit 2.2 STR01 LEV01 00-10cm MXH199		MXH199	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Whiteware, transfer printed	food/beverage	service	transfer print-blue
107789	Excavation Unit	Unit 2.2 STR01 LEV01 00-10cm MXH199		MXH199	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Whiteware, undecorated	food/beverage	service	
107792	Excavation Unit	Unit 2.2 STR01 LEV01 00-10cm MXH199		MXH199	Surface/Developing A	5	vessel, hollow	body	Ceramic	Earthenware, refined	Whiteware, undecorated	food/beverage	service	
107779	Excavation Unit	Unit 2.2 STR01 LEV01 00-10cm MXH199		MXH199	Surface/Developing A	6	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
107795	Excavation Unit	Unit 2.2 STR01 LEV01 00-10cm MXH199		MXH199	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Amber
107782	Excavation Unit	Unit 2.2 STR01 LEV01 00-10cm MXH199		MXH199	Surface/Developing A	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
107804	Excavation Unit	Unit 2.2 STR01 LEV01 00-10cm MXH199		MXH199	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
107778	Excavation Unit	Unit 2.2 STR01 LEV01 00-10cm MXH199		MXH199	Surface/Developing A	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
107794	Excavation Unit	Unit 2.2 STR01 LEV01 00-10cm MXH199		MXH199	Surface/Developing A	1	figurine	fragment	Glass	indeterminate	indeterminate	personal	other personal possession	-Milk glass/Opaque white
107777	Excavation Unit	Unit 2.2 STR01 LEV01 00-10cm MXH199		MXH199	Surface/Developing A	1	bottle, indeterminate	lip	Glass	molded	molded	food/beverage	storage	-Clear
107796	Excavation Unit	Unit 2.2 STR01 LEV01 00-10cm MXH199		MXH199	Surface/Developing A	1	bottle, indeterminate	lid	Glass	molded	molded	food/beverage	storage	-Clear-manganese ti+nt
107781	Excavation Unit	Unit 2.2 STR01 LEV01 00-10cm MXH199		MXH199	Surface/Developing A	1	handle, cutlery	fragment	Metal	copper alloy	copper alloy	food/beverage	service	
107790	Excavation Unit	Unit 2.2 STR01 LEV01 00-10cm MXH199		MXH199	Surface/Developing A	1	finial	whole/intact	Metal	copper alloy	copper alloy	furniture/household equip.	hardware	
107791	Excavation Unit	Unit 2.2 STR01 LEV01 00-10cm MXH199		MXH199	Surface/Developing A	5	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
107803	Excavation Unit	Unit 2.2 STR01 LEV01 00-10cm MXH199		MXH199	Surface/Developing A	1	wire	fragment	Metal	ferrous	machine made	0	Not Assigned	
107774	Excavation Unit	Unit 2.2 STR01 LEV01 00-10cm MXH199		MXH199	Surface/Developing A	6	nail, indeterminate	whole/intact	Metal	ferrous	machine made	architecture	general construction	
107802	Excavation Unit	Unit 2.2 STR01 LEV01 00-10cm MXH199		MXH199	Surface/Developing A	1	screw	whole/intact	Metal	ferrous	machine made	architecture	general construction	
107793	Excavation Unit	Unit 2.2 STR01 LEV01 00-10cm MXH199		MXH199	Surface/Developing A	1	nail, wire	whole/intact	Metal	ferrous	machine made	architecture	roofing	
107798	Excavation Unit	Unit 2.2 STR01 LEV01 00-10cm MXH199		MXH199	Surface/Developing A	1	coin	whole/intact	Metal	silver	silver	commerce	coin	
107805	Excavation Unit	Unit 2.2 STR01 LEV01 00-10cm MXH199		MXH199	Surface/Developing A	1	stone	fragment	Stone	Felsite	blue-grey	0	Not Assigned	
107780	Excavation Unit	Unit 2.2 STR01 LEV01 00-10cm MXH199		MXH199	Surface/Developing A	1	tile, floor	fragment	Stone	marble	Not Assigned	architecture	foundation	
107775	Excavation Unit	Unit 2.2 STR01 LEV01 00-10cm MXH199		MXH199	Surface/Developing A	2	asphalt	fragment	Synthetic	synthetic	asphalt	architecture	general construction	
107799	Excavation Unit	Unit 2.2 STR01 LEV01 00-10cm MXH199		MXH199	Surface/Developing A	3	mortar	fragment	Synthetic	synthetic	Not Assigned	architecture	window	
107800	Excavation Unit	Unit 2.2 STR01 LEV01 00-10cm MXH199		MXH199	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
107776	Excavation Unit	Unit 2.2 STR01 LEV01 00-10cm MXH199		MXH199	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	styrofoam	0	Not Assigned	
108075	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	2	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
108087	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
108092	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
108073	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	1	marble	whole/intact	Ceramic	Ball clay	molded	recreation/leisure	toys	
108078	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	2	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
108067	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	3	flower pot	body	Ceramic	Earthenware, coarse	Redware, flowerpot	industry, manufacture, trades	gardening/farming	
108068	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	1	flower pot	base	Ceramic	Earthenware, coarse	Redware, flowerpot	industry, manufacture, trades	gardening/farming	
108076	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	2	flower pot	rim	Ceramic	Earthenware, coarse	Redware, flowerpot	industry, manufacture, trades	gardening/farming	
108094	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
108084	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	unidentified	0	Not Assigned	slip-brown
108089	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	11	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
108091	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	1	vessel, hollow	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
108096	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
108100	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	1	vessel, hollow	base	Ceramic	Earthenware, refined	Ironstone	food/beverage	service	
108114	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-orange
108099	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
108113	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
108086	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
108088	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	2	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
108082	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
108083	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	2	vessel, indeterminate	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
108081	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	1	vessel, flat	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
108111	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	food/beverage	service	slip-black
108116	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, refined	Whiteware, undecorated	food/beverage	service	
108080	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	1	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
108108	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	1	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	service	
108070	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
108095	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
108077	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	2	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
108110	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	1	wood, structural	fragment	Flora	wood	unidentified	0	Not Assigned	
108117	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
108104	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	1	rod	fragment	Glass	indeterminate	indeterminate	0	Not Assigned	-Aqua
108090	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Amber
108097	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Amber
108106	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	1	bottle, indeterminate	base	Glass	indeterminate	indeterminate	food/beverage	storage	-Amber
108107	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
108115	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Blue-cobalt
108098	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
108118	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	1	bottle, indeterminate	base	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
108103	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear-manganese ti+nt
108109	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
108066	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	1	spike, cut	near intact	Metal	ferrous	cut	architecture	general construction	
108093	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	1	screw	fragment	Metal	ferrous	machine made	architecture	general construction	
108079	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	1	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
108101	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	3	mica cutout	fragment	Mineral	mica	Not Assigned	architecture	window	
108071	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	1	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
108074	Excavation Unit	Unit 2.2 STR01 LEV02 10-20cm MXH200		MXH200	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
107669	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	4	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
107674	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
107678	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-6/64
107703	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
107696	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
107661	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	2	flower pot	rim	Ceramic	Earthenware, coarse	Redware, flowerpot	industry, manufacture, trades	gardening/farming	
107692	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	10	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
107682	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	1	vessel, hollow	base	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
107684	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
107683	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	1	vessel, hollow	handle	Ceramic	Earthenware, coarse	Staffordshire plain	food/beverage	service	
107664	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	1	vessel, hollow	foot	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107671	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	2	vessel, hollow	handle	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107695	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	34	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107707	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	5	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107689	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	3	vessel, hollow	body	Ceramic	Earthenware, refined	Not Assigned	0	Not Assigned	
107688	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-black
107687	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-green
107675	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	slip-orange
107706	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	Annular-brown
107704	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-brown
107676	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	7	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
107662	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	7	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107697	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	15	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107699	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	4	vessel, hollow	base	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107667	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	2	vessel, hollow	foot	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107677	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	1	teapot	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107691	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	3	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107694	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	32	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107715	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107656	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Refined agate ware	food/beverage	service	
107701	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	7	vessel, hollow	body	Ceramic	Earthenware, refined	Whiteware, undecorated	food/beverage	service	
107713	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	1	vessel, hollow	body	Ceramic	Porcelain	Chinese plain	food/beverage	service	
107660	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	2	vessel, hollow	rim	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
107708	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	1	vessel, flat	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
107668	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Porcelain	Decorated	food/beverage	service	painted-black
107712	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	1	vessel, hollow	base	Ceramic	Porcelain	Decorated	food/beverage	service	Annular-orange
107711	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	1	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	service	
107659	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	1	vessel, hollow	body	Ceramic	Stoneware	British brown	food/beverage	Service	
107693	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	1	vessel, hollow	handle	Ceramic	Stoneware	brown, salt-glazed	food/beverage	storage	
107698	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	1	vessel, hollow	body	Ceramic	Stoneware	Rhenish Brown	food/beverage	service	
107705	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	2	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
107680	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	1	bone	fragment	Fauna	bone	bird	food/beverage	acquisition	
107663	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
107690	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	20	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
107709	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	1	tooth	fragment	Fauna	enamel/bone	tooth	food/beverage	acquisition	
107670	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	6	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
107686	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	6	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
107685	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	10	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
107666	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Amber
107702	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	2	bottle, indeterminate	base	Glass	indeterminate	indeterminate	food/beverage	storage	-Amber
107657	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
107700	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	1	bottle, indeterminate	base	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
107714	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	4	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
107658	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
107710	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	1	light fixture, electric	fragment	Glass	indeterminate	indeterminate	lighting	device	-Clear
107673	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	1	escutcheon, furniture	fragment	Metal	copper alloy	copper alloy	furniture/household equip.	hardware	
107679	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	3	nail, cut	near intact	Metal	ferrous	cut	architecture	general construction	
107665	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	3	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
107672	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	2	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
107681	Excavation Unit	Unit 2.2 STR01 LEV03 20-30cm MXH201		MXH201	Surface/Developing A	1	ballast	fragment	Stone	flint	butterscotch	architecture	foundation	
108254	Excavation Unit	Unit 2.2 STR02 LEV04 30-40cm MXH204		MXH204	Foundation Builder's Trench	3	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
108260	Excavation Unit	Unit 2.2 STR02 LEV04 30-40cm MXH204		MXH204	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
108247	Excavation Unit	Unit 2.2 STR02 LEV04 30-40cm MXH204		MXH204	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
108251	Excavation Unit	Unit 2.2 STR02 LEV04 30-40cm MXH204		MXH204	Foundation Builder's Trench	9	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
108261	Excavation Unit	Unit 2.2 STR02 LEV04 30-40cm MXH204		MXH204	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-yellow
108248	Excavation Unit	Unit 2.2 STR02 LEV04 30-40cm MXH204		MXH204	Foundation Builder's Trench	8	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
108258	Excavation Unit	Unit 2.2 STR02 LEV04 30-40cm MXH204		MXH204	Foundation Builder's Trench	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
108243	Excavation Unit	Unit 2.2 STR02 LEV04 30-40cm MXH204		MXH204	Foundation Builder's Trench	2	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
108259	Excavation Unit	Unit 2.2 STR02 LEV04 30-40cm MXH204		MXH204	Foundation Builder's Trench	1	vessel, hollow	base	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
108252	Excavation Unit	Unit 2.2 STR02 LEV04 30-40cm MXH204		MXH204	Foundation Builder's Trench	7	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
108262	Excavation Unit	Unit 2.2 STR02 LEV04 30-40cm MXH204		MXH204	Foundation Builder's Trench	4	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
108257	Excavation Unit	Unit 2.2 STR02 LEV04 30-40cm MXH204		MXH204	Foundation Builder's Trench	2	vessel, hollow	body	Ceramic	Porcelain	Chinese overglaze enamel	food/beverage	service	
108246	Excavation Unit	Unit 2.2 STR02 LEV04 30-40cm MXH204		MXH204	Foundation Builder's Trench	1	vessel, hollow	foot	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
108240	Excavation Unit	Unit 2.2 STR02 LEV04 30-40cm MXH204		MXH204	Foundation Builder's Trench	8	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
108241	Excavation Unit	Unit 2.2 STR02 LEV04 30-40cm MXH204		MXH204	Foundation Builder's Trench	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
108244	Excavation Unit	Unit 2.2 STR02 LEV04 30-40cm MXH204		MXH204	Foundation Builder's Trench	1	tooth	fragment	Fauna	enamel/bone	tooth	food/beverage	acquisition	
108256	Excavation Unit	Unit 2.2 STR02 LEV04 30-40cm MXH204		MXH204	Foundation Builder's Trench	3	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
108250	Excavation Unit	Unit 2.2 STR02 LEV04 30-40cm MXH204		MXH204	Foundation Builder's Trench	1	vessel, indeterminate	body	Glass	indeterminate	indeterminate	0	Not Assigned	-Aqua
108255	Excavation Unit	Unit 2.2 STR02 LEV04 30-40cm MXH204		MXH204	Foundation Builder's Trench	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
108253	Excavation Unit	Unit 2.2 STR02 LEV04 30-40cm MXH204		MXH204	Foundation Builder's Trench	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
108245	Excavation Unit	Unit 2.2 STR02 LEV04 30-40cm MXH204		MXH204	Foundation Builder's Trench	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
108249	Excavation Unit	Unit 2.2 STR02 LEV04 30-40cm MXH204		MXH204	Foundation Builder's Trench	2	sheet metal	fragment	Metal	ferrous	unidentified	0	Not Assigned	
108242	Excavation Unit	Unit 2.2 STR02 LEV04 30-40cm MXH204		MXH204	Foundation Builder's Trench	3	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
108152	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
108153	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	2	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
108157	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
108168	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
108175	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
108137	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
108165	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, lead glazed	0	Not Assigned	
108169	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
108178	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
108174	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	2	vessel, hollow	base	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
108141	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	39	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
108156	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	2	vessel, hollow	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
108160	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	4	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
108142	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	Not Assigned	food/beverage	service	painted-green
108162	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-orange
108164	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-orange
108166	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
108151	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	10	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
108176	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	1	vessel, flat	base	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
108147	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
108148	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	5	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
108161	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	38	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
108163	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	2	vessel, hollow	body	Ceramic	Earthenware, refined	Whiteware, transfer printed	food/beverage	service	transfer print-blue
108145	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Porcelain	Chinese overglaze enamel	food/beverage	service	
108144	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	service	
108140	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	3	vessel, flat	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	painted-blue
108177	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Tin Glazed	unidentified	0	Not Assigned	
108138	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	16	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
108167	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
108172	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	1	tooth	fragment	Fauna	enamel/bone	tooth	food/beverage	acquisition	
108139	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	10	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
108149	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	15	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
108155	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	1	vessel, indeterminate	rim	Glass	indeterminate	indeterminate		Not Assigned	-Clear
108159	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
108154	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
108158	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
108146	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	7	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
108143	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	6	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
108150	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	3	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
108173	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	1	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
108171	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	1	stone	fragment	Mineral	quartz	crystalline	0	Not Assigned	
108170	Excavation Unit	Unit 2.2 STR02 LEV05 40-50cm MXH205		MXH205	Foundation Builder's Trench	1	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
108191	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	2	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
108198	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
108205	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	2	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
108182	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	2	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
108208	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Coarse agate, buckley ware	food/beverage	storage	
108184	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	1	vessel, hollow	foot	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
108200	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	5	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
108196	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
108209	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	1	vessel, flat	rim	Ceramic	Earthenware, refined	creamware, hand painted overglaze	food/beverage	service	painted-brown
108185	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	16	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
108194	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	1	vessel, hollow	e	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
108213	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-brown
108204	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-brown
108214	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	17	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
108206	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	27	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
108216	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
108211	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	3	vessel, flat	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
108183	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	1	vessel, hollow	rim	Ceramic	Earthenware, refined	unidentified	food/beverage	service	
108202	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	1	vessel, flat	body	Ceramic	Earthenware, refined	Whiteware, transfer printed	food/beverage	service	transfer print-brown
108201	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	Whiteware, unidentified	food/beverage	service	
108203	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Porcelain	Chinese overglaze enamel	food/beverage	service	painted-blue
108207	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Porcelain	Chinese plain	food/beverage	service	
108192	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	1	vessel, hollow	rim	Ceramic	Porcelain	Plain	food/beverage	service	
108188	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Stoneware	Nottingham-type	food/beverage	storage	
108212	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	1	bone	fragment	Fauna	bone	bird	food/beverage	acquisition	
108180	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	14	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
108195	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	6	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
108197	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	3	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
108179	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
108193	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	4	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
108210	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
108189	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	7	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
108199	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	2	unidentified	fragment	Metal	ferrous	unidentified	0	Not Assigned	
108190	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	5	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
108187	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	1	ballast	fragment	Stone	flint	butterscotch	architecture	general construction	
108186	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	1	ballast	fragment	Stone	flint	gray	architecture	foundation	
108181	Excavation Unit	Unit 2.2 STR02 LEV06 50-60cm MXH208		MXH208	Foundation Builder's Trench	1	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
107728	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
107755	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
107764	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
107719	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	3	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
107769	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	7	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
107736	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	luster-gray
107741	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	painted-green
107716	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	49	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
107765	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	2	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
107770	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	9	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
107762	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Cauliflower ware	food/beverage	service	
107748	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	creamware, hand painted overglaze	food/beverage	service	Annular-red
107727	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	84	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107766	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	jackfield type	food/beverage	service	
107767	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	jackfield type	food/beverage	service	
107737	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	12	vessel, hollow	body	Ceramic	Earthenware, refined	Not Assigned	0	Not Assigned	
107771	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-brown
107722	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-orange
107739	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
107758	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
107744	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	Annular-brown
107732	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	3	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
107740	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	3	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
107747	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
107733	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	1	vessel, hollow	handle	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
107721	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	2	vessel, hollow	base	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107751	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	2	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107725	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	26	vessel, indeterminate	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107729	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	54	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107756	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107759	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	2	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107730	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Whieldon (clouded or tortoiseshell)	food/beverage	service	
107738	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	4	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
107750	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	2	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	service	
107742	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	Westerwald	food/beverage	service	
107746	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	2	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
107735	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	1	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
107749	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	1	vessel, hollow	body	Ceramic	Tin Glazed	unidentified	0	Not Assigned	
107752	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	1	vessel, hollow	body	Ceramic	Tin Glazed	unidentified	0	Not Assigned	
107717	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	45	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
107743	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
107761	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	2	tooth	fragment	Fauna	enamel/bone	tooth	food/beverage	acquisition	
107724	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	7	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
107754	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	13	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
107768	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	3	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Green (light olive)
107726	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	5	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
107745	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
107763	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (light olive)
107720	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	12	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
107731	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
107753	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	1	hook	whole/intact	Metal	ferrous	cut	architecture	hardware	
107718	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	11	unidentified	fragment	Metal	ferrous	unidentified	0	Not Assigned	
107723	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	8	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
107734	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	6	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
107757	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	1	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
107760	Excavation Unit	Unit 2.2 STR03 LEV06 50-60cm MXH209		MXH209	Buried APZ	1	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
107816	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	1	vessel, indeterminate	fragment	0	0	Not Assigned	0	Not Assigned	-Aqua marine*
107806	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
107829	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-6/64
107841	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	1	pipe, bowl	bowl	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
107838	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	4	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
107810	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
107812	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	12	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
107832	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
107847	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	2	vessel, hollow	base	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
107860	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	9	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
107807	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	creamware, hand painted overglaze	food/beverage	service	Annular-red
107854	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, handpainted, underglaze	food/beverage	service	painted-black
107834	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, handpainted, underglaze	food/beverage	service	painted-brown
107813	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	53	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107825	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107849	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	jackfield type	food/beverage	service	
107839	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-blue
107843	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	1	vessel, flat	base	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
107809	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	painted-blue
107826	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	4	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
107856	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
107827	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-brown
107808	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-green
107831	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	2	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
107830	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	5	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
107821	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	21	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107845	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	2	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107823	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	59	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107828	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	3	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107848	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	2	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107857	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	3	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107844	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
107862	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	10	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
107818	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	2	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
107851	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	4	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	service	
107842	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	basalt	food/beverage	storage	
107837	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	2	vessel, hollow	body	Ceramic	Stoneware	gray salt glazed	food/beverage	storage	
107820	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	1	vessel, hollow	rim	Ceramic	Stoneware	Nottingham-type	food/beverage	service	
107855	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	1	mug	rim	Ceramic	Stoneware	white salt-glazed	food/beverage	service	slip-brown
107861	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
107863	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	1	vessel, hollow	base	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
107814	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	44	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
107858	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	4	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
107850	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	8	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
107852	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	2	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
107817	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	3	charcoal	fragment	Flora	wood	charcoal	heating, plumbing, electric	fuel	
107815	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	20	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
107824	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	8	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
107833	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
107835	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	8	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
107836	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	1	bottle, indeterminate	lip	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
107822	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	4	nail, cut	near intact	Metal	ferrous	cut	architecture	general construction	
107811	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	11	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
107840	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	2	unidentified	fragment	Metal	lead	Not Assigned	0	Not Assigned	
107859	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	1	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
107853	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	2	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
107846	Excavation Unit	Unit 2.2 STR03 LEV07 60-70cm MXH211		MXH211	Buried APZ	1	unidentified	fragment	Synthetic	synthetic	indeterminate	0	Not Assigned	
107948	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	2	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
107967	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
107969	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	2	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
107931	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	4	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
107940	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
107918	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	4	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
107937	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
107949	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire, slipped	food/beverage	service	
107952	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Cauliflower ware	food/beverage	service	
107926	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	24	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107927	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	4	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107962	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107965	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	jackfield type	food/beverage	service	
107928	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	3	vessel, flat	body	Ceramic	Earthenware, refined	Not Assigned	0	Not Assigned	
107938	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	1	vessel, flat	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
107943	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	painted-blue
107942	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	1	teapot	spout	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-green
107933	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	Annular-black
107923	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-black
107919	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	Annular-brown
107925	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-green

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
107957	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-orange
107955	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	2	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
107956	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
107936	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	6	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107945	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	14	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107960	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-brown
107935	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	2	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107944	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	1	vessel, flat	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107951	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	1	vessel, flat	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107934	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	32	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107950	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107914	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Whiteware, flow blue	food/beverage	service	
107939	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Whiteware, transfer printed	food/beverage	service	transfer print-brown
107920	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	2	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
107930	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	1	vessel, flat	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
107929	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	2	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
107915	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	31	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
107954	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
107968	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	1	tooth	fragment	Fauna	enamel/bone	tooth	food/beverage	acquisition	
107932	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	1	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
107963	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	6	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
107961	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	1	charcoal	fragment	Flora	wood	charcoal	heating, plumbing, electric	fuel	
107921	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	3	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
107922	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	3	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
107959	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
107917	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	4	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
107966	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (light olive)
107964	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	5	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
107946	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	6	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
107941	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	1	vessel, indeterminate	body	Glass	molded	molded	0	Not Assigned	-Clear
107953	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	3	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
107916	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	9	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
107958	Excavation Unit	Unit 2.2 STR03 LEV08 70-80cm MXH213		MXH213	Buried APZ	2	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
108121	Excavation Unit	Unit 2.2 STR03 LEV09 80-90cm MXH214		MXH214	Buried APZ	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-6/64
108120	Excavation Unit	Unit 2.2 STR03 LEV09 80-90cm MXH214		MXH214	Buried APZ	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
108119	Excavation Unit	Unit 2.2 STR03 LEV09 80-90cm MXH214		MXH214	Buried APZ	6	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
108134	Excavation Unit	Unit 2.2 STR03 LEV09 80-90cm MXH214		MXH214	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
108136	Excavation Unit	Unit 2.2 STR03 LEV09 80-90cm MXH214		MXH214	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
108124	Excavation Unit	Unit 2.2 STR03 LEV09 80-90cm MXH214		MXH214	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-green
108128	Excavation Unit	Unit 2.2 STR03 LEV09 80-90cm MXH214		MXH214	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
108125	Excavation Unit	Unit 2.2 STR03 LEV09 80-90cm MXH214		MXH214	Buried APZ	1	vessel, hollow	rim	Ceramic	Porcelain	Decorated	food/beverage	service	painted-blue
108130	Excavation Unit	Unit 2.2 STR03 LEV09 80-90cm MXH214		MXH214	Buried APZ	1	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	service	
108135	Excavation Unit	Unit 2.2 STR03 LEV09 80-90cm MXH214		MXH214	Buried APZ	1	vessel, hollow	rim	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
108122	Excavation Unit	Unit 2.2 STR03 LEV09 80-90cm MXH214		MXH214	Buried APZ	6	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
108127	Excavation Unit	Unit 2.2 STR03 LEV09 80-90cm MXH214		MXH214	Buried APZ	1	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
108129	Excavation Unit	Unit 2.2 STR03 LEV09 80-90cm MXH214		MXH214	Buried APZ	2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
108131	Excavation Unit	Unit 2.2 STR03 LEV09 80-90cm MXH214		MXH214	Buried APZ	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
108132	Excavation Unit	Unit 2.2 STR03 LEV09 80-90cm MXH214		MXH214	Buried APZ	1	vessel, indeterminate	body	Glass	indeterminate	indeterminate	0	Not Assigned	-Aqua
108123	Excavation Unit	Unit 2.2 STR03 LEV09 80-90cm MXH214		MXH214	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
108133	Excavation Unit	Unit 2.2 STR03 LEV09 80-90cm MXH214		MXH214	Buried APZ	1	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
108126	Excavation Unit	Unit 2.2 STR03 LEV09 80-90cm MXH214		MXH214	Buried APZ	2	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
108316	Excavation Unit	Unit 2.2 STR05 LEV09 80-90cm MXH215		MXH215	B1	3	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
108317	Excavation Unit	Unit 2.2 STR05 LEV09 80-90cm MXH215		MXH215	B1	1	mortar	fragment	Mineral	composite	mortar	architecture	general construction	
108318	Excavation Unit	Unit 2.2 STR05 LEV10 90-100cm MXH216		MXH216	B2	1	vessel, flat	body	Ceramic	Earthenware, refined	Whiteware, transfer printed	food/beverage	service	transfer print-blue
108319	Excavation Unit	Unit 2.2 STR05 LEV10 90-100cm MXH216		MXH216	B2	2	charcoal	fragment	Flora	wood	charcoal	heating, plumbing, electric	fuel	
108320	Excavation Unit	Unit 2.2 STR05 LEV10 90-100cm MXH216		MXH216	B2	1	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
108266	Excavation Unit	Unit 2.2 STR05 LEV11 100-110cm MXH218		MXH218	B2	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
108265	Excavation Unit	Unit 2.2 STR05 LEV11 100-110cm MXH218		MXH218	B2	1	charcoal	fragment	Flora	wood	charcoal	heating, plumbing, electric	fuel	
108263	Excavation Unit	Unit 2.2 STR05 LEV11 100-110cm MXH218		MXH218	B2	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
108264	Excavation Unit	Unit 2.2 STR05 LEV11 100-110cm MXH218		MXH218	B2	1	nail, wire	whole/intact	Metal	ferrous	machine made	architecture	general construction	
108267	Excavation Unit	Unit 2.2 STR05 LEV11 100-110cm MXH218		MXH218	B2	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
108335	Excavation Unit	Unit 2.2 STR05 LEV12 110-120cm MXH220		MXH220	C	1	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
104496	Excavation Unit	Unit 3.1 Closing Wall Clean/Fall MXH234		MXH234		2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
104505	Excavation Unit	Unit 3.1 Closing Wall Clean/Fall MXH234		MXH234		1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
104502	Excavation Unit	Unit 3.1 Closing Wall Clean/Fall MXH234		MXH234		8	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104501	Excavation Unit	Unit 3.1 Closing Wall Clean/Fall MXH234		MXH234		1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	Annular-brown
104506	Excavation Unit	Unit 3.1 Closing Wall Clean/Fall MXH234		MXH234		2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-green
104509	Excavation Unit	Unit 3.1 Closing Wall Clean/Fall MXH234		MXH234		1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
104507	Excavation Unit	Unit 3.1 Closing Wall Clean/Fall MXH234		MXH234		1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
104504	Excavation Unit	Unit 3.1 Closing Wall Clean/Fall MXH234		MXH234		1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104508	Excavation Unit	Unit 3.1 Closing Wall Clean/Fall MXH234		MXH234		4	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104510	Excavation Unit	Unit 3.1 Closing Wall Clean/Fall MXH234		MXH234		2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104503	Excavation Unit	Unit 3.1 Closing Wall Clean/Fall MXH234		MXH234		1	vessel, hollow	rim	Ceramic	Porcelain	Decorated	food/beverage	service	Annular-orange
104494	Excavation Unit	Unit 3.1 Closing Wall Clean/Fall MXH234		MXH234		6	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
104493	Excavation Unit	Unit 3.1 Closing Wall Clean/Fall MXH234		MXH234		1	handle, cutlery	handle	Fauna	bone	mammal	food/beverage	service	
104499	Excavation Unit	Unit 3.1 Closing Wall Clean/Fall MXH234		MXH234		1	wood, indeterminate	fragment	Flora	wood	unidentified	0	Not Assigned	
104497	Excavation Unit	Unit 3.1 Closing Wall Clean/Fall MXH234		MXH234		1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
104500	Excavation Unit	Unit 3.1 Closing Wall Clean/Fall MXH234		MXH234		2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
104498	Excavation Unit	Unit 3.1 Closing Wall Clean/Fall MXH234		MXH234		2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
104495	Excavation Unit	Unit 3.1 Closing Wall Clean/Fall MXH234		MXH234		1	drinking glass, tumbler	rim	Glass	molded	molded	food/beverage	service	-Clear
104431	Excavation Unit	Unit 3.1 STR01 LEV01 00-10cm MXH223		MXH223	Surface/Developing A	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
104424	Excavation Unit	Unit 3.1 STR01 LEV01 00-10cm MXH223		MXH223	Surface/Developing A	1	flower pot	body	Ceramic	Earthenware, coarse	Redware, flowerpot	industry, manufacture, trades	gardening/farming	
104448	Excavation Unit	Unit 3.1 STR01 LEV01 00-10cm MXH223		MXH223	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
104421	Excavation Unit	Unit 3.1 STR01 LEV01 00-10cm MXH223		MXH223	Surface/Developing A	3	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104435	Excavation Unit	Unit 3.1 STR01 LEV01 00-10cm MXH223		MXH223	Surface/Developing A	3	tile, floor	fragment	Ceramic	Earthenware, refined	Ironstone	architecture	foundation	
104434	Excavation Unit	Unit 3.1 STR01 LEV01 00-10cm MXH223		MXH223	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	engine turned-green
104428	Excavation Unit	Unit 3.1 STR01 LEV01 00-10cm MXH223		MXH223	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
104441	Excavation Unit	Unit 3.1 STR01 LEV01 00-10cm MXH223		MXH223	Surface/Developing A	1	vessel, hollow	base	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104443	Excavation Unit	Unit 3.1 STR01 LEV01 00-10cm MXH223		MXH223	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104442	Excavation Unit	Unit 3.1 STR01 LEV01 00-10cm MXH223		MXH223	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104444	Excavation Unit	Unit 3.1 STR01 LEV01 00-10cm MXH223		MXH223	Surface/Developing A	2	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
104433	Excavation Unit	Unit 3.1 STR01 LEV01 00-10cm MXH223		MXH223	Surface/Developing A	1	vessel, hollow	body	Glass	indeterminate	indeterminate		storage	-Milk glass/Opaque white
104436	Excavation Unit	Unit 3.1 STR01 LEV01 00-10cm MXH223		MXH223	Surface/Developing A	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
104449	Excavation Unit	Unit 3.1 STR01 LEV01 00-10cm MXH223		MXH223	Surface/Developing A	1	bottle, indeterminate	base	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
104423	Excavation Unit	Unit 3.1 STR01 LEV01 00-10cm MXH223		MXH223	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (bright 7-up)
104425	Excavation Unit	Unit 3.1 STR01 LEV01 00-10cm MXH223		MXH223	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
104437	Excavation Unit	Unit 3.1 STR01 LEV01 00-10cm MXH223		MXH223	Surface/Developing A	2	bottle, indeterminate	lip/neck	Glass	Machine made	machine made	food/beverage	storage	-Clear
104439	Excavation Unit	Unit 3.1 STR01 LEV01 00-10cm MXH223		MXH223	Surface/Developing A	1	bottle, indeterminate	lip	Glass	mold blown	Not Assigned	food/beverage	storage	-Clear-crown
104432	Excavation Unit	Unit 3.1 STR01 LEV01 00-10cm MXH223		MXH223	Surface/Developing A	1	marble	fragment	Glass	molded	molded	recreation/leisure	toys	-Clear
104422	Excavation Unit	Unit 3.1 STR01 LEV01 00-10cm MXH223		MXH223	Surface/Developing A	1	ring	fragment	Metal	ferrous	machine made	0	Not Assigned	
104438	Excavation Unit	Unit 3.1 STR01 LEV01 00-10cm MXH223		MXH223	Surface/Developing A	1	tool	fragment	Metal	ferrous	machine made	0	Not Assigned	
104419	Excavation Unit	Unit 3.1 STR01 LEV01 00-10cm MXH223		MXH223	Surface/Developing A	1	electrical, misc.	fragment	Metal	ferrous	unidentified	heating, plumbing, electric	device	
104446	Excavation Unit	Unit 3.1 STR01 LEV01 00-10cm MXH223		MXH223	Surface/Developing A	1	coin	whole/intact	Metal	steel	steel	commerce	coin	
104426	Excavation Unit	Unit 3.1 STR01 LEV01 00-10cm MXH223		MXH223	Surface/Developing A	2	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
104427	Excavation Unit	Unit 3.1 STR01 LEV01 00-10cm MXH223		MXH223	Surface/Developing A	2	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
104447	Excavation Unit	Unit 3.1 STR01 LEV01 00-10cm MXH223		MXH223	Surface/Developing A	1	stone tube	fragment	Stone	unidentified	Not Assigned	architecture	hardware	
104420	Excavation Unit	Unit 3.1 STR01 LEV01 00-10cm MXH223		MXH223	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	indeterminate	architecture	window	
104445	Excavation Unit	Unit 3.1 STR01 LEV01 00-10cm MXH223		MXH223	Surface/Developing A	2	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
104429	Excavation Unit	Unit 3.1 STR01 LEV01 00-10cm MXH223		MXH223	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	plastic	furniture/household equip.	hardware	
104440	Excavation Unit	Unit 3.1 STR01 LEV01 00-10cm MXH223		MXH223	Surface/Developing A	1	Tube	fragment	Synthetic	synthetic	rubber	0	Not Assigned	
104430	Excavation Unit	Unit 3.1 STR01 LEV01 00-10cm MXH223		MXH223	Surface/Developing A	2	fragment	fragment	Synthetic	synthetic	rubber	heating, plumbing, electric	device	
104552	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
104574	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	1	flower pot	base	Ceramic	Earthenware, coarse	Redware, flowerpot	industry, manufacture, trades	gardening/farming	
104558	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
104573	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	unidentified	0	Not Assigned	
104555	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	7	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104562	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104579	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104563	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	6	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104560	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	3	vessel, hollow	body	Ceramic	Earthenware, refined	Whiteware, undecorated	food/beverage	service	
104580	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Yellow ware, plain	food/beverage	service	
104556	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	1	sewer pipe	fragment	Ceramic	Stoneware	Unidentified	heating, plumbing, electric	device	
104546	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	1	bottle, indeterminate	body	Glass	embossed	embossed	food/beverage	storage	-Clear
104561	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	1	bottle, indeterminate	body	Glass	embossed	embossed	food/beverage	storage	-Clear
104567	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	1	bottle, indeterminate	body	Glass	embossed	embossed	food/beverage	storage	-Clear

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
104577	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	1	bottle, indeterminate	body	Glass	embossed	embossed	food/beverage	storage	-Clear
104550	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	3	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
104575	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	4	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Amber
104559	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
104564	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
104549	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	5	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104565	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	1	bottle, indeterminate	base	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104571	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104553	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	6	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (bright 7-up)
104554	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
104568	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	7	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Milk glass/Opaque white
104576	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	1	bottle, wine/liquor/beer	base	Glass	Machine made	machine made	food/beverage	storage	-Amber-ovoid
104547	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	1	bottle, indeterminate	lip/neck	Glass	mold blown	contact, 2+ with separate base		Not Assigned	-Clear-patent
104545	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	5	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
104570	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	1	cap, screw top	fragment	Metal	steel	steel	food/beverage	storage	
104566	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	1	wire	fragment	Synthetic	synthetic	indeterminate	heating, plumbing, electric	device	
104572	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	1	strap	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
104557	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	1	cup	base	Synthetic	synthetic	plastic	food/beverage	service	
104578	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	1	spoon, general	head	Synthetic	synthetic	plastic	food/beverage	service	
104548	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	plastic	food/beverage	storage	
104551	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	1	Tube	fragment	Synthetic	synthetic	rubber	0	Not Assigned	
104569	Excavation Unit	Unit 3.1 STR01 LEV02 10-20cm MXH224		MXH224	Surface/Developing A	3	fragment	fragment	Synthetic	synthetic	rubber	heating, plumbing, electric	device	
104727	Excavation Unit	Unit 3.1 STR01-02 LEV02 00-20cm MXH235		MXH235		1	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104726	Excavation Unit	Unit 3.1 STR01-02 LEV02 00-20cm MXH235		MXH235		1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
104729	Excavation Unit	Unit 3.1 STR01-02 LEV02 00-20cm MXH235		MXH235		2	vessel, flat	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
104728	Excavation Unit	Unit 3.1 STR01-02 LEV02 00-20cm MXH235		MXH235		1	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	food/beverage	service	painted-blue
104730	Excavation Unit	Unit 3.1 STR01-02 LEV02 00-20cm MXH235		MXH235		2	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
104680	Excavation Unit	Unit 3.1 STR02 LEV02 10-20cm MXH225		MXH225	Foundation Builder's Trench	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
104686	Excavation Unit	Unit 3.1 STR02 LEV02 10-20cm MXH225		MXH225	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
104691	Excavation Unit	Unit 3.1 STR02 LEV02 10-20cm MXH225		MXH225	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
104683	Excavation Unit	Unit 3.1 STR02 LEV02 10-20cm MXH225		MXH225	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
104689	Excavation Unit	Unit 3.1 STR02 LEV02 10-20cm MXH225		MXH225	Foundation Builder's Trench	6	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104693	Excavation Unit	Unit 3.1 STR02 LEV02 10-20cm MXH225		MXH225	Foundation Builder's Trench	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	slip-yellow
104687	Excavation Unit	Unit 3.1 STR02 LEV02 10-20cm MXH225		MXH225	Foundation Builder's Trench	2	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104685	Excavation Unit	Unit 3.1 STR02 LEV02 10-20cm MXH225		MXH225	Foundation Builder's Trench	4	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104692	Excavation Unit	Unit 3.1 STR02 LEV02 10-20cm MXH225		MXH225	Foundation Builder's Trench	2	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104684	Excavation Unit	Unit 3.1 STR02 LEV02 10-20cm MXH225		MXH225	Foundation Builder's Trench	6	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
104695	Excavation Unit	Unit 3.1 STR02 LEV02 10-20cm MXH225		MXH225	Foundation Builder's Trench	1	drinking glass, tumbler	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104688	Excavation Unit	Unit 3.1 STR02 LEV02 10-20cm MXH225		MXH225	Foundation Builder's Trench	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104694	Excavation Unit	Unit 3.1 STR02 LEV02 10-20cm MXH225		MXH225	Foundation Builder's Trench	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
104681	Excavation Unit	Unit 3.1 STR02 LEV02 10-20cm MXH225		MXH225	Foundation Builder's Trench	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Milk glass/Opaque white
104690	Excavation Unit	Unit 3.1 STR02 LEV02 10-20cm MXH225		MXH225	Foundation Builder's Trench	1	bottle, indeterminate	base	Glass	Machine made	machine made	food/beverage	storage	-Clear
104682	Excavation Unit	Unit 3.1 STR02 LEV02 10-20cm MXH225		MXH225	Foundation Builder's Trench	1	bottle, indeterminate	lip	Glass	Machine made	machine made	food/beverage	storage	-Clear-External threads
104596	Excavation Unit	Unit 3.1 STR02 LEV03 20-30cm MXH226		MXH226	Foundation Builder's Trench	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
104626	Excavation Unit	Unit 3.1 STR02 LEV03 20-30cm MXH226		MXH226	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
104623	Excavation Unit	Unit 3.1 STR02 LEV03 20-30cm MXH226		MXH226	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
104627	Excavation Unit	Unit 3.1 STR02 LEV03 20-30cm MXH226		MXH226	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
104614	Excavation Unit	Unit 3.1 STR02 LEV03 20-30cm MXH226		MXH226	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	slip-brown
104584	Excavation Unit	Unit 3.1 STR02 LEV03 20-30cm MXH226		MXH226	Foundation Builder's Trench	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
104604	Excavation Unit	Unit 3.1 STR02 LEV03 20-30cm MXH226		MXH226	Foundation Builder's Trench	1	vessel, hollow	base	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
104603	Excavation Unit	Unit 3.1 STR02 LEV03 20-30cm MXH226		MXH226	Foundation Builder's Trench	1	vessel, hollow	base	Ceramic	Earthenware, coarse	Staffordshire plain	food/beverage	service	
104608	Excavation Unit	Unit 3.1 STR02 LEV03 20-30cm MXH226		MXH226	Foundation Builder's Trench	36	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104617	Excavation Unit	Unit 3.1 STR02 LEV03 20-30cm MXH226		MXH226	Foundation Builder's Trench	2	vessel, hollow	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104625	Excavation Unit	Unit 3.1 STR02 LEV03 20-30cm MXH226		MXH226	Foundation Builder's Trench	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104616	Excavation Unit	Unit 3.1 STR02 LEV03 20-30cm MXH226		MXH226	Foundation Builder's Trench	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
104619	Excavation Unit	Unit 3.1 STR02 LEV03 20-30cm MXH226		MXH226	Foundation Builder's Trench	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	Annular-blue
104585	Excavation Unit	Unit 3.1 STR02 LEV03 20-30cm MXH226		MXH226	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	Annular-brown
104620	Excavation Unit	Unit 3.1 STR02 LEV03 20-30cm MXH226		MXH226	Foundation Builder's Trench	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-brown
104587	Excavation Unit	Unit 3.1 STR02 LEV03 20-30cm MXH226		MXH226	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
104612	Excavation Unit	Unit 3.1 STR02 LEV03 20-30cm MXH226		MXH226	Foundation Builder's Trench	2	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
104611	Excavation Unit	Unit 3.1 STR02 LEV03 20-30cm MXH226		MXH226	Foundation Builder's Trench	4	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
104610	Excavation Unit	Unit 3.1 STR02 LEV03 20-30cm MXH226		MXH226	Foundation Builder's Trench	7	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104595	Excavation Unit	Unit 3.1 STR02 LEV03 20-30cm MXH226		MXH226	Foundation Builder's Trench	19	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104589	Excavation Unit	Unit 3.1 STR02 LEV03 20-30cm MXH226		MXH226	Foundation Builder's Trench	1	vessel, hollow	rim	Ceramic	Porcelain	Chinese overglaze enamel	food/beverage	service	
104613	Excavation Unit	Unit 3.1 STR02 LEV03 20-30cm MXH226		MXH226	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
104607	Excavation Unit	Unit 3.1 STR02 LEV03 20-30cm MXH226		MXH226	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
104618	Excavation Unit	Unit 3.1 STR02 LEV03 20-30cm MXH226		MXH226	Foundation Builder's Trench	1	vessel, hollow	rim	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
104615	Excavation Unit	Unit 3.1 STR02 LEV03 20-30cm MXH226		MXH226	Foundation Builder's Trench	1	tooth	whole/intact	Fauna	enamel/bone	tooth	food/beverage	acquisition	
104593	Excavation Unit	Unit 3.1 STR02 LEV03 20-30cm MXH226		MXH226	Foundation Builder's Trench	7	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
104605	Excavation Unit	Unit 3.1 STR02 LEV03 20-30cm MXH226		MXH226	Foundation Builder's Trench	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
104601	Excavation Unit	Unit 3.1 STR02 LEV03 20-30cm MXH226		MXH226	Foundation Builder's Trench	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104621	Excavation Unit	Unit 3.1 STR02 LEV03 20-30cm MXH226		MXH226	Foundation Builder's Trench	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104624	Excavation Unit	Unit 3.1 STR02 LEV03 20-30cm MXH226		MXH226	Foundation Builder's Trench	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104583	Excavation Unit	Unit 3.1 STR02 LEV03 20-30cm MXH226		MXH226	Foundation Builder's Trench	7	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
104582	Excavation Unit	Unit 3.1 STR02 LEV03 20-30cm MXH226		MXH226	Foundation Builder's Trench	5	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
104622	Excavation Unit	Unit 3.1 STR02 LEV03 20-30cm MXH226		MXH226	Foundation Builder's Trench	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
104599	Excavation Unit	Unit 3.1 STR02 LEV03 20-30cm MXH226		MXH226	Foundation Builder's Trench	1	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
107419	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
107420	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
107462	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	2	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
107448	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	30	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
107452	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
107457	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	15	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
107454	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	luster-gray
107405	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	7	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
107412	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
107461	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	5	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
107424	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	creamware, hand painted overglaze	food/beverage	service	painted-orange
107427	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	87	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107445	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107458	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	2	vessel, hollow	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107417	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	cable-black
107432	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-black
107403	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	painted-orange
107453	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	2	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
107413	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	6	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
107446	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
107459	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-blue
107442	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	Annular-brown
107429	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-green
107456	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	6	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
107415	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	3	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
107409	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-black
107404	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	25	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107428	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	5	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107444	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	3	vessel, hollow	base	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107423	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	43	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107440	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	2	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107460	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	4	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
107408	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	painted-green
107410	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	2	vessel, hollow	rim	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
107411	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	1	vessel, hollow	base	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
107416	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	2	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
107414	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	1	vessel, flat	body	Ceramic	Porcelain	Plain	food/beverage	service	
107435	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	Westerwald	food/beverage	service	
107447	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	1	vessel, hollow	base	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
107449	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
107426	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
107436	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed, scratch blue	food/beverage	service	
107421	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	23	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
107455	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
107451	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	3	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
107418	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	1	charcoal	fragment	Flora	wood	charcoal	heating, plumbing, electric	fuel	
107406	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	13	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
107431	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	4	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
107441	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	1	vessel, hollow	rim	Glass	indeterminate	indeterminate	0	Not Assigned	-Clear
107433	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
107438	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua marine*
107443	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	6	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
107425	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (bright 7-up)
107434	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	15	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
107439	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	1	bottle, indeterminate	lip	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
107422	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	1	vessel, hollow	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
107401	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	1	vessel, hollow	base	Glass	molded	molded	0	Not Assigned	-Clear-pressed pattern
107407	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	1	ring	fragment	Metal	ferrous	unidentified	0	Not Assigned	
107430	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	18	unidentified	fragment	Metal	ferrous	unidentified	0	Not Assigned	
107450	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	14	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
107437	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	5	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
107402	Excavation Unit	Unit 3.1 STR03 LEV04 30-40cm MXH227		MXH227	Buried APZ	2	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
104463	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	2	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
104479	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
104454	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
104480	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
104482	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
104471	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	7	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
104461	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
104467	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	5	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
104478	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
104453	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	luster-gray
104462	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	4	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
104476	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	creamware, hand painted overglaze	food/beverage	service	painted-red
104450	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	50	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104486	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	3	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104468	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	engine turned-blue
104459	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	Annular-black
104487	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-green
104488	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
104466	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-black
104452	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	33	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104474	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	6	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104458	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	43	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104469	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104456	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	1	vessel, hollow	base	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
104475	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	1	vessel, hollow	body	Ceramic	Porcelain	Decorated	food/beverage	service	painted-red
104485	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	1	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	service	
104489	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	1	vessel, hollow	handle	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
104490	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	2	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	painted-blue
104483	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	1	vessel, hollow	body	Ceramic	Tin Glazed	unidentified	food/beverage	service	
104455	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	6	vessel, hollow	body	Ceramic	unidentified	unidentified	0	Not Assigned	
104460	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	10	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
104481	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	2	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
104492	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	1	handle, utensil	handle	Fauna	bone	mammal	food/beverage	service	
104484	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	4	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
104470	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	14	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
104472	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
104464	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
104477	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	3	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104473	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	16	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
104491	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	1	buckle	fragment	Metal	copper alloy	copper alloy	personal	fastener	
104465	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	14	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
104457	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	3	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
104451	Excavation Unit	Unit 3.1 STR03 LEV05 40-50cm MXH228		MXH228	Buried APZ	1	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
104717	Excavation Unit	Unit 3.1 STR04 LEV05 40-50cm MXH231		MXH231	B1	1	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104718	Excavation Unit	Unit 3.1 STR04 LEV05 40-50cm MXH231		MXH231	B1	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104716	Excavation Unit	Unit 3.1 STR04 LEV05 40-50cm MXH231		MXH231	B1	2	charcoal	fragment	Flora	wood	charcoal	heating, plumbing, electric	fuel	
104720	Excavation Unit	Unit 3.1 STR05 LEV08 70-80cm MXH232		MXH232	C	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire plain	food/beverage	service	
104724	Excavation Unit	Unit 3.1 STR05 LEV08 70-80cm MXH232		MXH232	C	1	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104723	Excavation Unit	Unit 3.1 STR05 LEV08 70-80cm MXH232		MXH232	C	2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
104722	Excavation Unit	Unit 3.1 STR05 LEV08 70-80cm MXH232		MXH232	C	2	bone	fragment	Fauna	bone	indeterminate	food/beverage	acquisition	
104721	Excavation Unit	Unit 3.1 STR05 LEV08 70-80cm MXH232		MXH232	C	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
104719	Excavation Unit	Unit 3.1 STR05 LEV08 70-80cm MXH232		MXH232	C	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
104656	Excavation Unit	Unit 3.1 Wall Fall LEV04 00-40cm MXH236		MXH236		1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
104644	Excavation Unit	Unit 3.1 Wall Fall LEV04 00-40cm MXH236		MXH236		1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
104657	Excavation Unit	Unit 3.1 Wall Fall LEV04 00-40cm MXH236		MXH236		8	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104659	Excavation Unit	Unit 3.1 Wall Fall LEV04 00-40cm MXH236		MXH236		1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104648	Excavation Unit	Unit 3.1 Wall Fall LEV04 00-40cm MXH236		MXH236		2	tea bowl	base	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
104646	Excavation Unit	Unit 3.1 Wall Fall LEV04 00-40cm MXH236		MXH236		1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-green
104649	Excavation Unit	Unit 3.1 Wall Fall LEV04 00-40cm MXH236		MXH236		1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	slip-pink
104645	Excavation Unit	Unit 3.1 Wall Fall LEV04 00-40cm MXH236		MXH236		1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
104660	Excavation Unit	Unit 3.1 Wall Fall LEV04 00-40cm MXH236		MXH236		1	vessel, flat	body	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
104647	Excavation Unit	Unit 3.1 Wall Fall LEV04 00-40cm MXH236		MXH236		1	vessel, flat	body	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
104651	Excavation Unit	Unit 3.1 Wall Fall LEV04 00-40cm MXH236		MXH236		1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104641	Excavation Unit	Unit 3.1 Wall Fall LEV04 00-40cm MXH236		MXH236		1	vessel, flat	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104650	Excavation Unit	Unit 3.1 Wall Fall LEV04 00-40cm MXH236		MXH236		13	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104654	Excavation Unit	Unit 3.1 Wall Fall LEV04 00-40cm MXH236		MXH236		1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
104655	Excavation Unit	Unit 3.1 Wall Fall LEV04 00-40cm MXH236		MXH236		10	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
104658	Excavation Unit	Unit 3.1 Wall Fall LEV04 00-40cm MXH236		MXH236		1	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
104661	Excavation Unit	Unit 3.1 Wall Fall LEV04 00-40cm MXH236		MXH236		2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
104643	Excavation Unit	Unit 3.1 Wall Fall LEV04 00-40cm MXH236		MXH236		1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104640	Excavation Unit	Unit 3.1 Wall Fall LEV04 00-40cm MXH236		MXH236		2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
104642	Excavation Unit	Unit 3.1 Wall Fall LEV04 00-40cm MXH236		MXH236		1	bottle, indeterminate	base	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
104653	Excavation Unit	Unit 3.1 Wall Fall LEV04 00-40cm MXH236		MXH236		1	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
104652	Excavation Unit	Unit 3.1 Wall Fall LEV04 00-40cm MXH236		MXH236		1	unidentified	fragment	Synthetic	synthetic	Not Assigned	0	Not Assigned	
107655	Excavation Unit	Unit 3.2 STR Wall CleanFall LEV01-08 10-80cm MXH233		MXH233		2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
107540	Excavation Unit	Unit 3.2 STR Wallfall LEV1-4 00-40cm MXH255		MXH255		1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
107542	Excavation Unit	Unit 3.2 STR Wallfall LEV1-4 00-40cm MXH255		MXH255		1	vessel, hollow	spout	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
107531	Excavation Unit	Unit 3.2 STR Wallfall LEV1-4 00-40cm MXH255		MXH255		6	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
107545	Excavation Unit	Unit 3.2 STR Wallfall LEV1-4 00-40cm MXH255		MXH255		4	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
107525	Excavation Unit	Unit 3.2 STR Wallfall LEV1-4 00-40cm MXH255		MXH255		5	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107533	Excavation Unit	Unit 3.2 STR Wallfall LEV1-4 00-40cm MXH255		MXH255		1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	slip-black
107536	Excavation Unit	Unit 3.2 STR Wallfall LEV1-4 00-40cm MXH255		MXH255		2	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-yellow
107528	Excavation Unit	Unit 3.2 STR Wallfall LEV1-4 00-40cm MXH255		MXH255		3	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107534	Excavation Unit	Unit 3.2 STR Wallfall LEV1-4 00-40cm MXH255		MXH255		14	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107532	Excavation Unit	Unit 3.2 STR Wallfall LEV1-4 00-40cm MXH255		MXH255		1	vessel, hollow	body	Ceramic	Earthenware, refined	Whieldon (clouded or tortoiseshell)	food/beverage	service	
107527	Excavation Unit	Unit 3.2 STR Wallfall LEV1-4 00-40cm MXH255		MXH255		1	vessel, hollow	body	Ceramic	Earthenware, refined	Yellow ware, plain	food/beverage	service	
107529	Excavation Unit	Unit 3.2 STR Wallfall LEV1-4 00-40cm MXH255		MXH255		3	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
107539	Excavation Unit	Unit 3.2 STR Wallfall LEV1-4 00-40cm MXH255		MXH255		1	drinking glass, tumbler	rim	Glass	indeterminate	indeterminate	food/beverage	storage	
107538	Excavation Unit	Unit 3.2 STR Wallfall LEV1-4 00-40cm MXH255		MXH255		1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
107537	Excavation Unit	Unit 3.2 STR Wallfall LEV1-4 00-40cm MXH255		MXH255		1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
107541	Excavation Unit	Unit 3.2 STR Wallfall LEV1-4 00-40cm MXH255		MXH255		2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
107535	Excavation Unit	Unit 3.2 STR Wallfall LEV1-4 00-40cm MXH255		MXH255		1	bottle, indeterminate	lip	Glass	mold blown	Not Assigned	food/beverage	storage	-Green (olive)-blob top (1880-1910)
107524	Excavation Unit	Unit 3.2 STR Wallfall LEV1-4 00-40cm MXH255		MXH255		8	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
107526	Excavation Unit	Unit 3.2 STR Wallfall LEV1-4 00-40cm MXH255		MXH255		2	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
107530	Excavation Unit	Unit 3.2 STR Wallfall LEV1-4 00-40cm MXH255		MXH255		7	plaster, plain	fragment	Mineral	composite	plaster	architecture	general construction	
107543	Excavation Unit	Unit 3.2 STR Wallfall LEV1-4 00-40cm MXH255		MXH255		4	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
107544	Excavation Unit	Unit 3.2 STR Wallfall LEV1-4 00-40cm MXH255		MXH255		2	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
107550	Excavation Unit	Unit 3.2 STR Wallfall Wallclean LEV01-11 10-110cm MXH256		MXH256		2	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
107546	Excavation Unit	Unit 3.2 STR Wallfall Wallclean LEV01-11 10-110cm MXH256		MXH256		1	unidentified	fragment	Metal	ferrous	unidentified	0	Not Assigned	
107547	Excavation Unit	Unit 3.2 STR Wallfall Wallclean LEV01-11 10-110cm MXH256		MXH256		1	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
107548	Excavation Unit	Unit 3.2 STR Wallfall Wallclean LEV01-11 10-110cm MXH256		MXH256		3	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
107549	Excavation Unit	Unit 3.2 STR Wallfall Wallclean LEV01-11 10-110cm MXH256		MXH256		2	mortar	fragment	Mineral	composite	mortar	architecture	general construction	
104540	Excavation Unit	Unit 3.2 STR01 LEV01 00-10cm MXH237		MXH237	Surface/Developing A	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
104536	Excavation Unit	Unit 3.2 STR01 LEV01 00-10cm MXH237		MXH237	Surface/Developing A	1	vessel, flat	rim	Ceramic	Earthenware, refined	creamware, hand painted overglaze	food/beverage	service	painted-green
104537	Excavation Unit	Unit 3.2 STR01 LEV01 00-10cm MXH237		MXH237	Surface/Developing A	1	vessel, flat	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
104524	Excavation Unit	Unit 3.2 STR01 LEV01 00-10cm MXH237		MXH237	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Ironstone	food/beverage	service	
104528	Excavation Unit	Unit 3.2 STR01 LEV01 00-10cm MXH237		MXH237	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Not Assigned	food/beverage	service	
104539	Excavation Unit	Unit 3.2 STR01 LEV01 00-10cm MXH237		MXH237	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
104535	Excavation Unit	Unit 3.2 STR01 LEV01 00-10cm MXH237		MXH237	Surface/Developing A	5	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
104542	Excavation Unit	Unit 3.2 STR01 LEV01 00-10cm MXH237		MXH237	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Yellow ware, banded	food/beverage	service	Banded-brown
104523	Excavation Unit	Unit 3.2 STR01 LEV01 00-10cm MXH237		MXH237	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
104533	Excavation Unit	Unit 3.2 STR01 LEV01 00-10cm MXH237		MXH237	Surface/Developing A	4	tile, floor	fragment	Ceramic	Porcelain	Plain	architecture	foundation	
104518	Excavation Unit	Unit 3.2 STR01 LEV01 00-10cm MXH237		MXH237	Surface/Developing A	1	vessel, flat	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
104522	Excavation Unit	Unit 3.2 STR01 LEV01 00-10cm MXH237		MXH237	Surface/Developing A	1	pencil	fragment	Composite Artifact	composite artifact	composite artifact	personal	other personal possession	
104512	Excavation Unit	Unit 3.2 STR01 LEV01 00-10cm MXH237		MXH237	Surface/Developing A	2	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
104517	Excavation Unit	Unit 3.2 STR01 LEV01 00-10cm MXH237		MXH237	Surface/Developing A	1	tile, floor	fragment	Glass	flat	flat	architecture	foundation	-Aqua
104529	Excavation Unit	Unit 3.2 STR01 LEV01 00-10cm MXH237		MXH237	Surface/Developing A	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
104541	Excavation Unit	Unit 3.2 STR01 LEV01 00-10cm MXH237		MXH237	Surface/Developing A	4	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
104532	Excavation Unit	Unit 3.2 STR01 LEV01 00-10cm MXH237		MXH237	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Amber
104521	Excavation Unit	Unit 3.2 STR01 LEV01 00-10cm MXH237		MXH237	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
104525	Excavation Unit	Unit 3.2 STR01 LEV01 00-10cm MXH237		MXH237	Surface/Developing A	6	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104538	Excavation Unit	Unit 3.2 STR01 LEV01 00-10cm MXH237		MXH237	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
104531	Excavation Unit	Unit 3.2 STR01 LEV01 00-10cm MXH237		MXH237	Surface/Developing A	1	bottle, indeterminate	base	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (bright 7-up)
104514	Excavation Unit	Unit 3.2 STR01 LEV01 00-10cm MXH237		MXH237	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
104544	Excavation Unit	Unit 3.2 STR01 LEV01 00-10cm MXH237		MXH237	Surface/Developing A	1	vessel, hollow	rim	Glass	indeterminate	indeterminate	food/beverage	storage	-Milk glass/Opaque white
104515	Excavation Unit	Unit 3.2 STR01 LEV01 00-10cm MXH237		MXH237	Surface/Developing A	1	bottle, indeterminate	lip/neck	Glass	Machine made	machine made	food/beverage	storage	-Clear-External threads
104519	Excavation Unit	Unit 3.2 STR01 LEV01 00-10cm MXH237		MXH237	Surface/Developing A	1	bottle, indeterminate	lip	Glass	Machine made	machine made	food/beverage	storage	-Clear-External threads
104520	Excavation Unit	Unit 3.2 STR01 LEV01 00-10cm MXH237		MXH237	Surface/Developing A	1	bottle, indeterminate	lip/neck	Glass	mold blown	contact, 2-piece mold	food/beverage	storage	-Clear-External threads
104534	Excavation Unit	Unit 3.2 STR01 LEV01 00-10cm MXH237		MXH237	Surface/Developing A	1	button, one hole	near intact	Glass	molded	molded	personal	fastener	-Green (v. dark/black)
104511	Excavation Unit	Unit 3.2 STR01 LEV01 00-10cm MXH237		MXH237	Surface/Developing A	1	Tube	whole/intact	Metal	copper alloy	copper alloy	0	Not Assigned	
104530	Excavation Unit	Unit 3.2 STR01 LEV01 00-10cm MXH237		MXH237	Surface/Developing A	1	nail, cut	whole/intact	Metal	ferrous	cut	architecture	general construction	
104526	Excavation Unit	Unit 3.2 STR01 LEV01 00-10cm MXH237		MXH237	Surface/Developing A	1	nail, wire	whole/intact	Metal	ferrous	machine made	architecture	general construction	
104527	Excavation Unit	Unit 3.2 STR01 LEV01 00-10cm MXH237		MXH237	Surface/Developing A	1	Tube	whole/intact	Metal	steel	steel	furniture/household equip.	hardware	
104543	Excavation Unit	Unit 3.2 STR01 LEV01 00-10cm MXH237		MXH237	Surface/Developing A	3	mortar	fragment	Mineral	composite	mortar	architecture	general construction	
104513	Excavation Unit	Unit 3.2 STR01 LEV01 00-10cm MXH237		MXH237	Surface/Developing A	1	paint	whole/intact	Synthetic	synthetic	plastic	furniture/household equip.	Not Assigned	
104516	Excavation Unit	Unit 3.2 STR01 LEV01 00-10cm MXH237		MXH237	Surface/Developing A	1	comb, hair	fragment	Synthetic	synthetic	rubber	personal	toiletry/hygiene	
107282	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	2	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
107268	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Manganese Mottled	food/beverage	service	
107249	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
107254	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
107263	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
107252	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
107243	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire, slipped	food/beverage	service	
107248	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire, slipped	food/beverage	service	
107253	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107257	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	9	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107242	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
107281	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	9	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
107266	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	slip-orange
107285	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-green
107250	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	28	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107258	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107256	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Whiteware, undecorated	food/beverage	service	
107279	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	1	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
107275	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	1	tile, floor	fragment	Ceramic	Porcelain	Plain	architecture	foundation	
107244	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	3	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	service	
107246	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	1	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	service	
107260	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Porcelain	Plain	food/beverage	service	
107277	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Porcelain	Plain	food/beverage	service	
107251	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	1	vessel, hollow	body	Ceramic	Stoneware	British brown	food/beverage	Service	
107255	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
107261	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
107241	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	2	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	
107294	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
107290	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	3	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
107288	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	2	seed	fragment	Flora	seed/pit/nut	peach	food/beverage	acquisition	
107278	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	12	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
107259	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	3	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
107272	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	1	bottle, indeterminate	base	Glass	indeterminate	indeterminate	food/beverage	storage	-Amber
107276	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Amber
107262	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	5	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
107298	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
107245	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	7	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (bright 7-up)
107247	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	1	bottle, indeterminate	lip	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (bright 7-up)
107267	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	1	bottle, indeterminate	base	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (bright 7-up)
107283	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
107293	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	9	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Milk glass/Opaque white
107237	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	1	lamp, base	base	Glass	indeterminate	indeterminate	lighting	device	-Amber
107274	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	1	bottle, indeterminate	lip/neck	Glass	Machine made	machine made	food/beverage	storage	-Clear
107239	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	1	bottle, indeterminate	neck	Glass	Machine made	machine made	food/beverage	storage	-Green (bright 7-up)
107296	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	1	bottle, indeterminate	base	Glass	Machine made	machine made	food/beverage	storage	-Clear-machine made (1903)
107238	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	1	bottle, food	lid	Glass	mold blown	indeterminate	food/beverage	storage	-Clear
107265	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	1	nail, wire	whole/intact	Metal	ferrous	machine made	architecture	general construction	
107271	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	1	unidentified	fragment	Metal	ferrous	unidentified	0	Not Assigned	
107269	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	4	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
107270	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	5	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
107284	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	1	mortar	fragment	Mineral	composite	mortar	architecture	general construction	
107273	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	7	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
107240	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	19	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
107264	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	1	comb, hair	fragment	Synthetic	synthetic	rubber	personal	other personal possession	
107280	Excavation Unit	Unit 3.2 STR01 LEV02 MXH238		MXH238	Surface/Developing A	2	unidentified	fragment	Synthetic	synthetic	styrofoam	0	Not Assigned	
107621	Excavation Unit	Unit 3.2 STR01 LEV03 00-30cm MXH257		MXH257	Surface/Developing A	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
107611	Excavation Unit	Unit 3.2 STR01 LEV03 00-30cm MXH257		MXH257	Surface/Developing A	2	vessel, flat	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107617	Excavation Unit	Unit 3.2 STR01 LEV03 00-30cm MXH257		MXH257	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	jackfield type	food/beverage	service	
107620	Excavation Unit	Unit 3.2 STR01 LEV03 00-30cm MXH257		MXH257	Surface/Developing A	1	vessel, flat	body	Ceramic	Earthenware, refined	Not Assigned	food/beverage	service	
107622	Excavation Unit	Unit 3.2 STR01 LEV03 00-30cm MXH257		MXH257	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	Annular-brown
107613	Excavation Unit	Unit 3.2 STR01 LEV03 00-30cm MXH257		MXH257	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107623	Excavation Unit	Unit 3.2 STR01 LEV03 00-30cm MXH257		MXH257	Surface/Developing A	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107618	Excavation Unit	Unit 3.2 STR01 LEV03 00-30cm MXH257		MXH257	Surface/Developing A	1	vessel, flat	rim	Ceramic	Porcelain	Decorated	food/beverage	service	painted-blue
107619	Excavation Unit	Unit 3.2 STR01 LEV03 00-30cm MXH257		MXH257	Surface/Developing A	1	vessel, hollow	body	Ceramic	Stoneware	British brown	food/beverage	Service	
107614	Excavation Unit	Unit 3.2 STR01 LEV03 00-30cm MXH257		MXH257	Surface/Developing A	4	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
107612	Excavation Unit	Unit 3.2 STR01 LEV03 00-30cm MXH257		MXH257	Surface/Developing A	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
107625	Excavation Unit	Unit 3.2 STR01 LEV03 00-30cm MXH257		MXH257	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Milk glass/Opaque white
107624	Excavation Unit	Unit 3.2 STR01 LEV03 00-30cm MXH257		MXH257	Surface/Developing A	2	unidentified	fragment	Metal	ferrous	unidentified	0	Not Assigned	
107610	Excavation Unit	Unit 3.2 STR01 LEV03 00-30cm MXH257		MXH257	Surface/Developing A	2	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
107616	Excavation Unit	Unit 3.2 STR01 LEV03 00-30cm MXH257		MXH257	Surface/Developing A	2	plaster, plain	fragment	Mineral	composite	plaster	architecture	general construction	
107615	Excavation Unit	Unit 3.2 STR01 LEV03 00-30cm MXH257		MXH257	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	plastic	0	Not Assigned	
107372	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	2	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
107335	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Manganese Mottled	food/beverage	service	
107370	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	5	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
107361	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	1	vessel, hollow	rim	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
107368	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
107376	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
107352	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
107364	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire, slipped	food/beverage	storage	
107340	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	6	vessel, hollow	body	Ceramic	Earthenware, coarse	unidentified	0	Not Assigned	
107333	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, factory-made slipware	food/beverage	service	slip-blue
107348	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	51	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107353	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	4	vessel, hollow	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107367	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107371	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	5	vessel, indeterminate	rim	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107381	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	1	vessel, hollow	handle	Ceramic	Earthenware, refined	Ironstone, molded	food/beverage	service	
107377	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Not Assigned	food/beverage	service	
107378	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	1	vessel, flat	rim	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	Annular-green
107343	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
107375	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
107350	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	2	vessel, flat	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-brown
107358	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-orange
107359	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	4	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
107380	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	4	vessel, indeterminate	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
107341	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	2	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107346	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	16	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107351	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	70	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107385	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	3	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107374	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	1	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	food/beverage	service	slip-blue
107342	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	4	vessel, hollow	body	Ceramic	Earthenware, refined	Whiteware, undecorated	food/beverage	service	

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
107362	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	1	vessel, indeterminate	body	Ceramic	Earthenware, refined	Yellow ware, plain	food/beverage	service	
107338	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	1	vessel, hollow	base	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
107382	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	1	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
107389	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	2	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
107334	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	1	vessel, hollow	base	Ceramic	Porcelain	Plain	food/beverage	service	
107387	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	1	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	service	
107355	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	1	vessel, hollow	handle	Ceramic	Stoneware	Bristol type	food/beverage	storage	
107388	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	1	vessel, flat	body	Ceramic	Stoneware	dry-bodied red	food/beverage	service	
107363	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	1	vessel, hollow	base	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
107386	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	2	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
107356	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	1	tack, furniture	fragment	Composite Artifact	composite artifact	composite artifact	furniture/household equip.	hardware	
107349	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	4	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
107360	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	20	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
107373	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
107379	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	6	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
107365	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	11	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
107354	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Milk glass/Opaque white
107383	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	2	bottle, indeterminate	lip/neck	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)-Stacked Ring
107369	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	1	bottle, indeterminate	body	Glass	molded	molded	food/beverage	storage	-Amber
107337	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	1	unidentified	fragment	Metal	ferrous	Not Assigned	0	Not Assigned	
107366	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	25	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
107336	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
107344	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	5	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
107364	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	12	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
107347	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	1	ballast	fragment	Stone	flint	gray	0	Not Assigned	
107339	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	6	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
107357	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	indeterminate	0	Not Assigned	
107345	Excavation Unit	Unit 3.2 STR01 LEV03 20-30cm MXH240		MXH240	Surface/Developing A	1	unidentified	fragment	Synthetic	synthetic	styrofoam	0	Not Assigned	
107650	Excavation Unit	Unit 3.2 STR02 LEV02 10-20cm MXH239		MXH239	Redeposited Foundation Soils	2	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107653	Excavation Unit	Unit 3.2 STR02 LEV02 10-20cm MXH239		MXH239	Redeposited Foundation Soils	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-blue
107652	Excavation Unit	Unit 3.2 STR02 LEV02 10-20cm MXH239		MXH239	Redeposited Foundation Soils	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107647	Excavation Unit	Unit 3.2 STR02 LEV02 10-20cm MXH239		MXH239	Redeposited Foundation Soils	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107644	Excavation Unit	Unit 3.2 STR02 LEV02 10-20cm MXH239		MXH239	Redeposited Foundation Soils	5	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
107646	Excavation Unit	Unit 3.2 STR02 LEV02 10-20cm MXH239		MXH239	Redeposited Foundation Soils	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
107645	Excavation Unit	Unit 3.2 STR02 LEV02 10-20cm MXH239		MXH239	Redeposited Foundation Soils	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
107649	Excavation Unit	Unit 3.2 STR02 LEV02 10-20cm MXH239		MXH239	Redeposited Foundation Soils	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
107648	Excavation Unit	Unit 3.2 STR02 LEV02 10-20cm MXH239		MXH239	Redeposited Foundation Soils	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (bright 7-up)
107654	Excavation Unit	Unit 3.2 STR02 LEV02 10-20cm MXH239		MXH239	Redeposited Foundation Soils	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
107651	Excavation Unit	Unit 3.2 STR02 LEV02 10-20cm MXH239		MXH239	Redeposited Foundation Soils	1	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
107636	Excavation Unit	Unit 3.2 STR02 LEV03 20-30cm MXH241		MXH241	Foundation Builder's Trench	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
107641	Excavation Unit	Unit 3.2 STR02 LEV03 20-30cm MXH241		MXH241	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
107643	Excavation Unit	Unit 3.2 STR02 LEV03 20-30cm MXH241		MXH241	Foundation Builder's Trench	2	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
107634	Excavation Unit	Unit 3.2 STR02 LEV03 20-30cm MXH241		MXH241	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire, slipped	food/beverage	service	
107638	Excavation Unit	Unit 3.2 STR02 LEV03 20-30cm MXH241		MXH241	Foundation Builder's Trench	11	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107628	Excavation Unit	Unit 3.2 STR02 LEV03 20-30cm MXH241		MXH241	Foundation Builder's Trench	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
107629	Excavation Unit	Unit 3.2 STR02 LEV03 20-30cm MXH241		MXH241	Foundation Builder's Trench	4	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107631	Excavation Unit	Unit 3.2 STR02 LEV03 20-30cm MXH241		MXH241	Foundation Builder's Trench	1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107637	Excavation Unit	Unit 3.2 STR02 LEV03 20-30cm MXH241		MXH241	Foundation Builder's Trench	7	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107639	Excavation Unit	Unit 3.2 STR02 LEV03 20-30cm MXH241		MXH241	Foundation Builder's Trench	2	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107633	Excavation Unit	Unit 3.2 STR02 LEV03 20-30cm MXH241		MXH241	Foundation Builder's Trench	1	vessel, hollow	rim	Ceramic	Porcelain	Decorated	food/beverage	service	Annular-blue
107642	Excavation Unit	Unit 3.2 STR02 LEV03 20-30cm MXH241		MXH241	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
107635	Excavation Unit	Unit 3.2 STR02 LEV03 20-30cm MXH241		MXH241	Foundation Builder's Trench	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
107632	Excavation Unit	Unit 3.2 STR02 LEV03 20-30cm MXH241		MXH241	Foundation Builder's Trench	5	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
107630	Excavation Unit	Unit 3.2 STR02 LEV03 20-30cm MXH241		MXH241	Foundation Builder's Trench	4	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
107640	Excavation Unit	Unit 3.2 STR02 LEV03 20-30cm MXH241		MXH241	Foundation Builder's Trench	4	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
107487	Excavation Unit	Unit 3.2 STR02 LEV04 30-40cm MXH242		MXH242	Foundation Builder's Trench	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
107488	Excavation Unit	Unit 3.2 STR02 LEV04 30-40cm MXH242		MXH242	Foundation Builder's Trench	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
107489	Excavation Unit	Unit 3.2 STR02 LEV04 30-40cm MXH242		MXH242	Foundation Builder's Trench	1	pipe, bowl	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
107464	Excavation Unit	Unit 3.2 STR02 LEV04 30-40cm MXH242		MXH242	Foundation Builder's Trench	1	vessel, hollow	handle	Ceramic	Earthenware, coarse	Manganese Mottled	food/beverage	service	
107480	Excavation Unit	Unit 3.2 STR02 LEV04 30-40cm MXH242		MXH242	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
107493	Excavation Unit	Unit 3.2 STR02 LEV04 30-40cm MXH242		MXH242	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
107471	Excavation Unit	Unit 3.2 STR02 LEV04 30-40cm MXH242		MXH242	Foundation Builder's Trench	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
107465	Excavation Unit	Unit 3.2 STR02 LEV04 30-40cm MXH242		MXH242	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire, slipped	food/beverage	service	
107479	Excavation Unit	Unit 3.2 STR02 LEV04 30-40cm MXH242		MXH242	Foundation Builder's Trench	9	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107477	Excavation Unit	Unit 3.2 STR02 LEV04 30-40cm MXH242		MXH242	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
107476	Excavation Unit	Unit 3.2 STR02 LEV04 30-40cm MXH242		MXH242	Foundation Builder's Trench	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	painted-blue
107473	Excavation Unit	Unit 3.2 STR02 LEV04 30-40cm MXH242		MXH242	Foundation Builder's Trench	6	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107475	Excavation Unit	Unit 3.2 STR02 LEV04 30-40cm MXH242		MXH242	Foundation Builder's Trench	1	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107474	Excavation Unit	Unit 3.2 STR02 LEV04 30-40cm MXH242		MXH242	Foundation Builder's Trench	9	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107472	Excavation Unit	Unit 3.2 STR02 LEV04 30-40cm MXH242		MXH242	Foundation Builder's Trench	4	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
107492	Excavation Unit	Unit 3.2 STR02 LEV04 30-40cm MXH242		MXH242	Foundation Builder's Trench	2	vessel, hollow	body	Ceramic	Porcelain	Plain	food/beverage	service	
107490	Excavation Unit	Unit 3.2 STR02 LEV04 30-40cm MXH242		MXH242	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
107485	Excavation Unit	Unit 3.2 STR02 LEV04 30-40cm MXH242		MXH242	Foundation Builder's Trench	1	vessel, hollow	rim	Ceramic	Stoneware	white salt-glazed	food/beverage	service	slip-brown
107491	Excavation Unit	Unit 3.2 STR02 LEV04 30-40cm MXH242		MXH242	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed, scratch blue	food/beverage	service	
107482	Excavation Unit	Unit 3.2 STR02 LEV04 30-40cm MXH242		MXH242	Foundation Builder's Trench	3	bone	whole/intact	Fauna	bone	bird	food/beverage	acquisition	
107484	Excavation Unit	Unit 3.2 STR02 LEV04 30-40cm MXH242		MXH242	Foundation Builder's Trench	5	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
107466	Excavation Unit	Unit 3.2 STR02 LEV04 30-40cm MXH242		MXH242	Foundation Builder's Trench	1	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
107468	Excavation Unit	Unit 3.2 STR02 LEV04 30-40cm MXH242		MXH242	Foundation Builder's Trench	2	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
107469	Excavation Unit	Unit 3.2 STR02 LEV04 30-40cm MXH242		MXH242	Foundation Builder's Trench	5	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
107483	Excavation Unit	Unit 3.2 STR02 LEV04 30-40cm MXH242		MXH242	Foundation Builder's Trench	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
107467	Excavation Unit	Unit 3.2 STR02 LEV04 30-40cm MXH242		MXH242	Foundation Builder's Trench	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
107470	Excavation Unit	Unit 3.2 STR02 LEV04 30-40cm MXH242		MXH242	Foundation Builder's Trench	14	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
107486	Excavation Unit	Unit 3.2 STR02 LEV04 30-40cm MXH242		MXH242	Foundation Builder's Trench	4	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
107481	Excavation Unit	Unit 3.2 STR02 LEV04 30-40cm MXH242		MXH242	Foundation Builder's Trench	1	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
107478	Excavation Unit	Unit 3.2 STR02 LEV04 30-40cm MXH242		MXH242	Foundation Builder's Trench	2	plaster, plain	fragment	Mineral	composite	plaster	architecture	general construction	
107560	Excavation Unit	Unit 3.2 STR02 LEV05 40-50cm MXH243		MXH243	Foundation Builder's Trench	3	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
107553	Excavation Unit	Unit 3.2 STR02 LEV05 40-50cm MXH243		MXH243	Foundation Builder's Trench	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
107572	Excavation Unit	Unit 3.2 STR02 LEV05 40-50cm MXH243		MXH243	Foundation Builder's Trench	4	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
107562	Excavation Unit	Unit 3.2 STR02 LEV05 40-50cm MXH243		MXH243	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	-blue
107558	Excavation Unit	Unit 3.2 STR02 LEV05 40-50cm MXH243		MXH243	Foundation Builder's Trench	7	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
107567	Excavation Unit	Unit 3.2 STR02 LEV05 40-50cm MXH243		MXH243	Foundation Builder's Trench	10	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107551	Excavation Unit	Unit 3.2 STR02 LEV05 40-50cm MXH243		MXH243	Foundation Builder's Trench	1	vessel, hollow	rim	Ceramic	Earthenware, refined	jackfield type	food/beverage	service	
107576	Excavation Unit	Unit 3.2 STR02 LEV05 40-50cm MXH243		MXH243	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-blue
107565	Excavation Unit	Unit 3.2 STR02 LEV05 40-50cm MXH243		MXH243	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	Annular-brown
107575	Excavation Unit	Unit 3.2 STR02 LEV05 40-50cm MXH243		MXH243	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	
107556	Excavation Unit	Unit 3.2 STR02 LEV05 40-50cm MXH243		MXH243	Foundation Builder's Trench	3	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107564	Excavation Unit	Unit 3.2 STR02 LEV05 40-50cm MXH243		MXH243	Foundation Builder's Trench	5	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107573	Excavation Unit	Unit 3.2 STR02 LEV05 40-50cm MXH243		MXH243	Foundation Builder's Trench	1	vessel, flat	body	Ceramic	Earthenware, refined	unidentified	food/beverage	service	
107559	Excavation Unit	Unit 3.2 STR02 LEV05 40-50cm MXH243		MXH243	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	Whiteware, hand painted blue	food/beverage	service	painted-blue
107570	Excavation Unit	Unit 3.2 STR02 LEV05 40-50cm MXH243		MXH243	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Tin Glazed	Dutch (delft)	food/beverage	service	painted-blue
107557	Excavation Unit	Unit 3.2 STR02 LEV05 40-50cm MXH243		MXH243	Foundation Builder's Trench	1	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
107568	Excavation Unit	Unit 3.2 STR02 LEV05 40-50cm MXH243		MXH243	Foundation Builder's Trench	2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
107571	Excavation Unit	Unit 3.2 STR02 LEV05 40-50cm MXH243		MXH243	Foundation Builder's Trench	5	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
107574	Excavation Unit	Unit 3.2 STR02 LEV05 40-50cm MXH243		MXH243	Foundation Builder's Trench	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green*
107554	Excavation Unit	Unit 3.2 STR02 LEV05 40-50cm MXH243		MXH243	Foundation Builder's Trench	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Milk glass/Opaque white
107563	Excavation Unit	Unit 3.2 STR02 LEV05 40-50cm MXH243		MXH243	Foundation Builder's Trench	1	button	whole/intact	Metal	ferrous	machine made	personal	fastener	
107552	Excavation Unit	Unit 3.2 STR02 LEV05 40-50cm MXH243		MXH243	Foundation Builder's Trench	6	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
107566	Excavation Unit	Unit 3.2 STR02 LEV05 40-50cm MXH243		MXH243	Foundation Builder's Trench	4	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
107569	Excavation Unit	Unit 3.2 STR02 LEV05 40-50cm MXH243		MXH243	Foundation Builder's Trench	1	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
107555	Excavation Unit	Unit 3.2 STR02 LEV05 40-50cm MXH243		MXH243	Foundation Builder's Trench	2	plaster, plain	fragment	Mineral	composite	plaster	architecture	general construction	
107561	Excavation Unit	Unit 3.2 STR02 LEV05 40-50cm MXH243		MXH243	Foundation Builder's Trench	8	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
107316	Excavation Unit	Unit 3.2 STR02 LEV06 50-60cm MXH245		MXH245	Foundation Builder's Trench	1	pipe, bowl	bowl	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
107331	Excavation Unit	Unit 3.2 STR02 LEV06 50-60cm MXH245		MXH245	Foundation Builder's Trench	1	pipe, stem	fragment	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	
107309	Excavation Unit	Unit 3.2 STR02 LEV06 50-60cm MXH245		MXH245	Foundation Builder's Trench	2	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
107318	Excavation Unit	Unit 3.2 STR02 LEV06 50-60cm MXH245		MXH245	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, black glazed	food/beverage	preparation	
107307	Excavation Unit	Unit 3.2 STR02 LEV06 50-60cm MXH245		MXH245	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
107314	Excavation Unit	Unit 3.2 STR02 LEV06 50-60cm MXH245		MXH245	Foundation Builder's Trench	6	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
107327	Excavation Unit	Unit 3.2 STR02 LEV06 50-60cm MXH245		MXH245	Foundation Builder's Trench	3	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
107312	Excavation Unit	Unit 3.2 STR02 LEV06 50-60cm MXH245		MXH245	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Staffordshire, slipped	food/beverage	service	
107313	Excavation Unit	Unit 3.2 STR02 LEV06 50-60cm MXH245		MXH245	Foundation Builder's Trench	2	vessel, hollow	base	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107329	Excavation Unit	Unit 3.2 STR02 LEV06 50-60cm MXH245		MXH245	Foundation Builder's Trench	12	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107324	Excavation Unit	Unit 3.2 STR02 LEV06 50-60cm MXH245		MXH245	Foundation Builder's Trench	1	vessel, hollow	lid	Ceramic	Earthenware, refined	Pearlware, factory-made slipware	food/beverage	service	Annular-brown
107322	Excavation Unit	Unit 3.2 STR02 LEV06 50-60cm MXH245		MXH245	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted blue underglaze	food/beverage	service	
107302	Excavation Unit	Unit 3.2 STR02 LEV06 50-60cm MXH245		MXH245	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, hand painted polychrome	food/beverage	service	painted-green
107311	Excavation Unit	Unit 3.2 STR02 LEV06 50-60cm MXH245		MXH245	Foundation Builder's Trench	3	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, shell-edge blue	food/beverage	service	

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
107330	Excavation Unit	Unit 3.2 STR02 LEV06 50-60cm MXH245		MXH245	Foundation Builder's Trench	1	vessel, hollow	handle	Ceramic	Earthenware, refined	Pearlware, shell-edge green	food/beverage	service	
107319	Excavation Unit	Unit 3.2 STR02 LEV06 50-60cm MXH245		MXH245	Foundation Builder's Trench	2	vessel, hollow	rim	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107320	Excavation Unit	Unit 3.2 STR02 LEV06 50-60cm MXH245		MXH245	Foundation Builder's Trench	1	vessel, hollow	base	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107310	Excavation Unit	Unit 3.2 STR02 LEV06 50-60cm MXH245		MXH245	Foundation Builder's Trench	2	vessel, hollow	rim	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107332	Excavation Unit	Unit 3.2 STR02 LEV06 50-60cm MXH245		MXH245	Foundation Builder's Trench	21	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107315	Excavation Unit	Unit 3.2 STR02 LEV06 50-60cm MXH245		MXH245	Foundation Builder's Trench	2	vessel, flat	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
107321	Excavation Unit	Unit 3.2 STR02 LEV06 50-60cm MXH245		MXH245	Foundation Builder's Trench	2	vessel, hollow	body	Ceramic	Porcelain	Chinese underglaze blue	food/beverage	service	
107328	Excavation Unit	Unit 3.2 STR02 LEV06 50-60cm MXH245		MXH245	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Stoneware	Westerwald	food/beverage	service	
107317	Excavation Unit	Unit 3.2 STR02 LEV06 50-60cm MXH245		MXH245	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Stoneware	white salt-glazed	food/beverage	service	
107301	Excavation Unit	Unit 3.2 STR02 LEV06 50-60cm MXH245		MXH245	Foundation Builder's Trench	1	shell, clam	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
107325	Excavation Unit	Unit 3.2 STR02 LEV06 50-60cm MXH245		MXH245	Foundation Builder's Trench	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
107308	Excavation Unit	Unit 3.2 STR02 LEV06 50-60cm MXH245		MXH245	Foundation Builder's Trench	3	window glass, flat	fragment	Glass	flat	flat	food/beverage	storage	-Aqua
107323	Excavation Unit	Unit 3.2 STR02 LEV06 50-60cm MXH245		MXH245	Foundation Builder's Trench	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
107326	Excavation Unit	Unit 3.2 STR02 LEV06 50-60cm MXH245		MXH245	Foundation Builder's Trench	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (light olive)
107305	Excavation Unit	Unit 3.2 STR02 LEV06 50-60cm MXH245		MXH245	Foundation Builder's Trench	2	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
107306	Excavation Unit	Unit 3.2 STR02 LEV06 50-60cm MXH245		MXH245	Foundation Builder's Trench	1	drinking glass, tumbler	rim	Glass	molded	molded	food/beverage	storage	-Clear
107299	Excavation Unit	Unit 3.2 STR02 LEV06 50-60cm MXH245		MXH245	Foundation Builder's Trench	2	rod	fragment	Metal	ferrous	machine made	heating, plumbing, electric	device	
107303	Excavation Unit	Unit 3.2 STR02 LEV06 50-60cm MXH245		MXH245	Foundation Builder's Trench	6	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
107304	Excavation Unit	Unit 3.2 STR02 LEV06 50-60cm MXH245		MXH245	Foundation Builder's Trench	4	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
107300	Excavation Unit	Unit 3.2 STR02 LEV06 50-60cm MXH245		MXH245	Foundation Builder's Trench	1	plaster, plain	fragment	Mineral	composite	plaster	architecture	general construction	
107508	Excavation Unit	Unit 3.2 STR02 LEV07 60-70vm MXH246		MXH246	Foundation Builder's Trench	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-4/64
107505	Excavation Unit	Unit 3.2 STR02 LEV07 60-70vm MXH246		MXH246	Foundation Builder's Trench	2	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107496	Excavation Unit	Unit 3.2 STR02 LEV07 60-70vm MXH246		MXH246	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	Earthenware, refined	pearlware, transfer printed	food/beverage	service	transfer print-blue
107503	Excavation Unit	Unit 3.2 STR02 LEV07 60-70vm MXH246		MXH246	Foundation Builder's Trench	1	vessel, hollow	base	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107499	Excavation Unit	Unit 3.2 STR02 LEV07 60-70vm MXH246		MXH246	Foundation Builder's Trench	1	vessel, hollow	rim	Ceramic	Porcelain	Plain	food/beverage	service	
107502	Excavation Unit	Unit 3.2 STR02 LEV07 60-70vm MXH246		MXH246	Foundation Builder's Trench	1	vessel, hollow	body	Ceramic	unidentified	Not Assigned	0	Not Assigned	
107507	Excavation Unit	Unit 3.2 STR02 LEV07 60-70vm MXH246		MXH246	Foundation Builder's Trench	14	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
107495	Excavation Unit	Unit 3.2 STR02 LEV07 60-70vm MXH246		MXH246	Foundation Builder's Trench	1	shell, oyster	fragment	Fauna	shell	bivalve	food/beverage	acquisition	
107500	Excavation Unit	Unit 3.2 STR02 LEV07 60-70vm MXH246		MXH246	Foundation Builder's Trench	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
107506	Excavation Unit	Unit 3.2 STR02 LEV07 60-70vm MXH246		MXH246	Foundation Builder's Trench	1	vessel, hollow	rim	Glass	indeterminate	indeterminate		Not Assigned	-Clear
107497	Excavation Unit	Unit 3.2 STR02 LEV07 60-70vm MXH246		MXH246	Foundation Builder's Trench	1	bottle, indeterminate	base	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (v. dark/black)
107504	Excavation Unit	Unit 3.2 STR02 LEV07 60-70vm MXH246		MXH246	Foundation Builder's Trench	8	unidentified	fragment	Metal	ferrous	unidentified	0	Not Assigned	
107498	Excavation Unit	Unit 3.2 STR02 LEV07 60-70vm MXH246		MXH246	Foundation Builder's Trench	14	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
107494	Excavation Unit	Unit 3.2 STR02 LEV07 60-70vm MXH246		MXH246	Foundation Builder's Trench	1	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
107501	Excavation Unit	Unit 3.2 STR02 LEV07 60-70vm MXH246		MXH246	Foundation Builder's Trench	2	plaster, plain	fragment	Mineral	composite	plaster	architecture	general construction	
107399	Excavation Unit	Unit 3.2 STR06 LEV07 60-70cm MXH247		MXH247	Feature 6 Interior Sand Fill	10	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
107395	Excavation Unit	Unit 3.2 STR06 LEV07 60-70cm MXH247		MXH247	Feature 6 Interior Sand Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Creamware, lighter yellow glaze	food/beverage	service	
107393	Excavation Unit	Unit 3.2 STR06 LEV07 60-70cm MXH247		MXH247	Feature 6 Interior Sand Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107398	Excavation Unit	Unit 3.2 STR06 LEV07 60-70cm MXH247		MXH247	Feature 6 Interior Sand Fill	1	vessel, hollow	base	Ceramic	Earthenware, refined	Yellow ware, plain	food/beverage	service	slip-yellow
107397	Excavation Unit	Unit 3.2 STR06 LEV07 60-70cm MXH247		MXH247	Feature 6 Interior Sand Fill	1	unidentified	fragment	Metal	ferrous	unidentified	0	Not Assigned	
107391	Excavation Unit	Unit 3.2 STR06 LEV07 60-70cm MXH247		MXH247	Feature 6 Interior Sand Fill	14	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
107400	Excavation Unit	Unit 3.2 STR06 LEV07 60-70cm MXH247		MXH247	Feature 6 Interior Sand Fill	5	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
107396	Excavation Unit	Unit 3.2 STR06 LEV07 60-70cm MXH247		MXH247	Feature 6 Interior Sand Fill	3	plaster, plain	fragment	Mineral	composite	plaster	architecture	general construction	
107392	Excavation Unit	Unit 3.2 STR06 LEV07 60-70cm MXH247		MXH247	Feature 6 Interior Sand Fill	2	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
107394	Excavation Unit	Unit 3.2 STR06 LEV07 60-70cm MXH247		MXH247	Feature 6 Interior Sand Fill	7	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
107514	Excavation Unit	Unit 3.2 STR06 LEV08 70-77cm MXH248		MXH248	Feature 6 Interior Sand Fill	2	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
107519	Excavation Unit	Unit 3.2 STR06 LEV08 70-77cm MXH248		MXH248	Feature 6 Interior Sand Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107517	Excavation Unit	Unit 3.2 STR06 LEV08 70-77cm MXH248		MXH248	Feature 6 Interior Sand Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	Whiteware, transfer printed	food/beverage	service	transfer print
107518	Excavation Unit	Unit 3.2 STR06 LEV08 70-77cm MXH248		MXH248	Feature 6 Interior Sand Fill	1	vessel, hollow	rim	Ceramic	Porcelain	Decorated	food/beverage	service	painted-red
107512	Excavation Unit	Unit 3.2 STR06 LEV08 70-77cm MXH248		MXH248	Feature 6 Interior Sand Fill	2	bottle, indeterminate	lip/neck	Glass	Machine made	machine made	food/beverage	storage	-Milk Glass/Blue-External threads
107520	Excavation Unit	Unit 3.2 STR06 LEV08 70-77cm MXH248		MXH248	Feature 6 Interior Sand Fill	1	tool	whole/intact	Metal	copper alloy	copper alloy	0	Not Assigned	
107509	Excavation Unit	Unit 3.2 STR06 LEV08 70-77cm MXH248		MXH248	Feature 6 Interior Sand Fill	17	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
107513	Excavation Unit	Unit 3.2 STR06 LEV08 70-77cm MXH248		MXH248	Feature 6 Interior Sand Fill	2	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
107510	Excavation Unit	Unit 3.2 STR06 LEV08 70-77cm MXH248		MXH248	Feature 6 Interior Sand Fill	2	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
107515	Excavation Unit	Unit 3.2 STR06 LEV08 70-77cm MXH248		MXH248	Feature 6 Interior Sand Fill	2	plaster, plain	fragment	Mineral	composite	plaster	architecture	general construction	
107516	Excavation Unit	Unit 3.2 STR06 LEV08 70-77cm MXH248		MXH248	Feature 6 Interior Sand Fill	1	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
107511	Excavation Unit	Unit 3.2 STR06 LEV08 70-77cm MXH248		MXH248	Feature 6 Interior Sand Fill	1	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
107609	Excavation Unit	Unit 3.2 STR06 LEV08 77-80cm MXH249		MXH249	Feature 6 Interior Sand Fill	1	bone	fragment	Fauna	bone	bird	food/beverage	acquisition	
107608	Excavation Unit	Unit 3.2 STR06 LEV08 77-80cm MXH249		MXH249	Feature 6 Interior Sand Fill	11	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
107606	Excavation Unit	Unit 3.2 STR06 LEV08 77-80cm MXH249		MXH249	Feature 6 Interior Sand Fill	3	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
107607	Excavation Unit	Unit 3.2 STR06 LEV08 77-80cm MXH249		MXH249	Feature 6 Interior Sand Fill	5	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
107595	Excavation Unit	Unit 3.2 STR08 LEV08 70-80cm MXH250		MXH250	Feature 6 Organic Fill	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, unglazed	food/beverage	preparation	
107601	Excavation Unit	Unit 3.2 STR08 LEV08 70-80cm MXH250		MXH250	Feature 6 Organic Fill	1	mortar	fragment	Composite Artifact	composite artifact	composite artifact	architecture	general construction	
107602	Excavation Unit	Unit 3.2 STR08 LEV08 70-80cm MXH250		MXH250	Feature 6 Organic Fill	1	unidentified	fragment	Composite Artifact	composite artifact	composite artifact	architecture	general construction	
107605	Excavation Unit	Unit 3.2 STR08 LEV08 70-80cm MXH250		MXH250	Feature 6 Organic Fill	6	bone	fragment	Fauna	bone	bird	food/beverage	acquisition	
107599	Excavation Unit	Unit 3.2 STR08 LEV08 70-80cm MXH250		MXH250	Feature 6 Organic Fill	3	shell	fragment	Fauna	shell	crustacean	food/beverage	acquisition	
107596	Excavation Unit	Unit 3.2 STR08 LEV08 70-80cm MXH250		MXH250	Feature 6 Organic Fill	1	unidentified	fragment	Metal	copper alloy	copper alloy	0	Not Assigned	
107594	Excavation Unit	Unit 3.2 STR08 LEV08 70-80cm MXH250		MXH250	Feature 6 Organic Fill	7	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
107600	Excavation Unit	Unit 3.2 STR08 LEV08 70-80cm MXH250		MXH250	Feature 6 Organic Fill	15	strap	fragment	Metal	ferrous	unidentified	0	Not Assigned	
107593	Excavation Unit	Unit 3.2 STR08 LEV08 70-80cm MXH250		MXH250	Feature 6 Organic Fill	11	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
107598	Excavation Unit	Unit 3.2 STR08 LEV08 70-80cm MXH250		MXH250	Feature 6 Organic Fill	5	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
107604	Excavation Unit	Unit 3.2 STR08 LEV08 70-80cm MXH250		MXH250	Feature 6 Organic Fill	1	plaster, plain	fragment	Mineral	composite	plaster	architecture	general construction	
107597	Excavation Unit	Unit 3.2 STR08 LEV08 70-80cm MXH250		MXH250	Feature 6 Organic Fill	1	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
107603	Excavation Unit	Unit 3.2 STR08 LEV08 70-80cm MXH250		MXH250	Feature 6 Organic Fill	1	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
107196	Excavation Unit	Unit 3.2 STR08 LEV09 80-90cm MXH251		MXH251	Feature 6 Organic Fill	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
107192	Excavation Unit	Unit 3.2 STR08 LEV09 80-90cm MXH251		MXH251	Feature 6 Organic Fill	3	vessel, hollow	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107193	Excavation Unit	Unit 3.2 STR08 LEV09 80-90cm MXH251		MXH251	Feature 6 Organic Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Whiteware, transfer printed	food/beverage	service	transfer print-blue
107197	Excavation Unit	Unit 3.2 STR08 LEV09 80-90cm MXH251		MXH251	Feature 6 Organic Fill	1	vessel, hollow	handle	Ceramic	Earthenware, refined	Whiteware, transfer printed	food/beverage	service	transfer print-blue
107195	Excavation Unit	Unit 3.2 STR08 LEV09 80-90cm MXH251		MXH251	Feature 6 Organic Fill	1	strap	fragment	Composite Artifact	composite artifact	composite artifact	0	Not Assigned	
107198	Excavation Unit	Unit 3.2 STR08 LEV09 80-90cm MXH251		MXH251	Feature 6 Organic Fill	1	unidentified	fragment	Composite Artifact	composite artifact	composite artifact	0	Not Assigned	
107179	Excavation Unit	Unit 3.2 STR08 LEV09 80-90cm MXH251		MXH251	Feature 6 Organic Fill	4	handle, utensil	fragment	Composite Artifact	composite artifact	composite artifact	food/beverage	service	
107181	Excavation Unit	Unit 3.2 STR08 LEV09 80-90cm MXH251		MXH251	Feature 6 Organic Fill	1	buckle	fragment	Composite Artifact	composite artifact	composite artifact	personal	fastener	
107183	Excavation Unit	Unit 3.2 STR08 LEV09 80-90cm MXH251		MXH251	Feature 6 Organic Fill	7	Snap	fragment	Composite Artifact	composite artifact	composite artifact	personal	other personal possession	
107176	Excavation Unit	Unit 3.2 STR08 LEV09 80-90cm MXH251		MXH251	Feature 6 Organic Fill	65	bone	fragment	Fauna	bone	bird	food/beverage	acquisition	
107177	Excavation Unit	Unit 3.2 STR08 LEV09 80-90cm MXH251		MXH251	Feature 6 Organic Fill	60	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
107180	Excavation Unit	Unit 3.2 STR08 LEV09 80-90cm MXH251		MXH251	Feature 6 Organic Fill	3	bone	fragment	Fauna	bone	Not Assigned	food/beverage	acquisition	
107201	Excavation Unit	Unit 3.2 STR08 LEV09 80-90cm MXH251		MXH251	Feature 6 Organic Fill	10	shell	fragment	Fauna	shell	crustacean	food/beverage	acquisition	
107191	Excavation Unit	Unit 3.2 STR08 LEV09 80-90cm MXH251		MXH251	Feature 6 Organic Fill	4	shell, eggs	fragment	Fauna	shell, egg	bird	food/beverage	acquisition	
107190	Excavation Unit	Unit 3.2 STR08 LEV09 80-90cm MXH251		MXH251	Feature 6 Organic Fill	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
107189	Excavation Unit	Unit 3.2 STR08 LEV09 80-90cm MXH251		MXH251	Feature 6 Organic Fill	14	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
107174	Excavation Unit	Unit 3.2 STR08 LEV09 80-90cm MXH251		MXH251	Feature 6 Organic Fill	4	bottle, food	base	Glass	mold blown	contact, 2+ with separate base	food/beverage	storage	
107173	Excavation Unit	Unit 3.2 STR08 LEV09 80-90cm MXH251		MXH251	Feature 6 Organic Fill	4	bottle, food	body	Glass	mold blown	contact, 2+ with separate base	food/beverage	storage	-Green (olive)
107172	Excavation Unit	Unit 3.2 STR08 LEV09 80-90cm MXH251		MXH251	Feature 6 Organic Fill	1	bottle, food	whole/intact	Glass	mold blown	contact, 2+ with separate base	food/beverage	storage	-Aqua-circular-machine made (1903)
107170	Excavation Unit	Unit 3.2 STR08 LEV09 80-90cm MXH251		MXH251	Feature 6 Organic Fill	1	bottle, indeterminate	whole/intact	Glass	mold blown	contact, 2+ with separate base	food/beverage	storage	-Clear-rectangular, rounded corners-smooth base 1840s+-patent
107175	Excavation Unit	Unit 3.2 STR08 LEV09 80-90cm MXH251		MXH251	Feature 6 Organic Fill	1	bottle, pharmaceutical	whole/intact	Glass	mold blown	contact, 2-piece mold	medical/chemical	storage	-Aqua-ovoid-machine made (1903)-patent
107199	Excavation Unit	Unit 3.2 STR08 LEV09 80-90cm MXH251		MXH251	Feature 6 Organic Fill	1	bottle, indeterminate	body	Glass	mold blown	Not Assigned	food/beverage	storage	-Clear
107171	Excavation Unit	Unit 3.2 STR08 LEV09 80-90cm MXH251		MXH251	Feature 6 Organic Fill	2	drinking glass, tumbler	whole/intact	Glass	molded	molded	food/beverage	service	-Clear
107184	Excavation Unit	Unit 3.2 STR08 LEV09 80-90cm MXH251		MXH251	Feature 6 Organic Fill	2	strap	fragment	Metal	copper alloy	copper alloy	0	Not Assigned	
107200	Excavation Unit	Unit 3.2 STR08 LEV09 80-90cm MXH251		MXH251	Feature 6 Organic Fill	1	unidentified	fragment	Metal	copper alloy	copper alloy	0	Not Assigned	
107194	Excavation Unit	Unit 3.2 STR08 LEV09 80-90cm MXH251		MXH251	Feature 6 Organic Fill	1	nail, wire	fragment	Metal	copper alloy	copper alloy	furniture/household equip.	hardware	
107186	Excavation Unit	Unit 3.2 STR08 LEV09 80-90cm MXH251		MXH251	Feature 6 Organic Fill	10	strap	fragment	Metal	ferrous	unidentified	0	Not Assigned	
107182	Excavation Unit	Unit 3.2 STR08 LEV09 80-90cm MXH251		MXH251	Feature 6 Organic Fill	15	nail, indeterminate	fragment	Metal	ferrous	unidentified	architecture	general construction	
107185	Excavation Unit	Unit 3.2 STR08 LEV09 80-90cm MXH251		MXH251	Feature 6 Organic Fill	7	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
107188	Excavation Unit	Unit 3.2 STR08 LEV09 80-90cm MXH251		MXH251	Feature 6 Organic Fill	1	plaster, plain	fragment	Mineral	composite	plaster	architecture	general construction	
107187	Excavation Unit	Unit 3.2 STR08 LEV09 80-90cm MXH251		MXH251	Feature 6 Organic Fill	1	cinder	fragment	Other	cinder	Not Assigned	heating, plumbing, electric	fuel	
107202	Excavation Unit	Unit 3.2 STR08 LEV09 80-90cm MXH251		MXH251	Feature 6 Organic Fill	1	tile, roof	fragment	Stone	Slate	Not Assigned	architecture	roofing	
107178	Excavation Unit	Unit 3.2 STR08 LEV09 80-90cm MXH251		MXH251	Feature 6 Organic Fill	2	unidentified	fragment	Synthetic	synthetic	Not Assigned	0	Not Assigned	
107213	Excavation Unit	Unit 3.2 STR08 LEV10 90-100cm MXH252		MXH252	Feature 6 Organic Fill	5	unidentified	fragment		0	Not Assigned	0	Not Assigned	
107226	Excavation Unit	Unit 3.2 STR08 LEV10 90-100cm MXH252		MXH252	Feature 6 Organic Fill	1	pipe, stem	stem	Ceramic	Ball clay	molded	recreation/leisure	smoking/tobacco	-5/64
107215	Excavation Unit	Unit 3.2 STR08 LEV10 90-100cm MXH252		MXH252	Feature 6 Organic Fill	1	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
107223	Excavation Unit	Unit 3.2 STR08 LEV10 90-100cm MXH252		MXH252	Feature 6 Organic Fill	1	vessel, hollow	body	Ceramic	Earthenware, coarse	Redware, lead glazed	food/beverage	preparation	
107227	Excavation Unit	Unit 3.2 STR08 LEV10 90-100cm MXH252		MXH252	Feature 6 Organic Fill	2	vessel, flat	body	Ceramic	Earthenware, refined	Pearlware, undecorated	food/beverage	service	
107209	Excavation Unit	Unit 3.2 STR08 LEV10 90-100cm MXH252		MXH252	Feature 6 Organic Fill	1	vessel, hollow	body	Ceramic	Earthenware, refined	unidentified	0	Not Assigned	
107214	Excavation Unit	Unit 3.2 STR08 LEV10 90-100cm MXH252		MXH252	Feature 6 Organic Fill	2	cup	rim	Ceramic	Earthenware, refined	Whiteware, transfer printed	food/beverage	service	
107218	Excavation Unit	Unit 3.2 STR08 LEV10 90-100cm MXH252		MXH252	Feature 6 Organic Fill	1	vessel, hollow	handle	Ceramic	Earthenware, refined	Whiteware, transfer printed	food/beverage	service	transfer print-blue
107217	Excavation Unit	Unit 3.2 STR08 LEV10 90-100cm MXH252		MXH252	Feature 6 Organic Fill	1	vessel, hollow	base	Ceramic	Earthenware, refined	Whiteware, undecorated	food/beverage	service	
107206	Excavation Unit	Unit 3.2 STR08 LEV10 90-100cm MXH252		MXH252	Feature 6 Organic Fill	3	strap	fragment	Composite Artifact	composite artifact	composite artifact	0	Not Assigned	
107216	Excavation Unit	Unit 3.2 STR08 LEV10 90-100cm MXH252		MXH252	Feature 6 Organic Fill	28	bone	fragment	Fauna	bone	bird	food/beverage	acquisition	
107229	Excavation Unit	Unit 3.2 STR08 LEV10 90-100cm MXH252		MXH252	Feature 6 Organic Fill	2	bone	fragment	Fauna	bone	fish	food/beverage	acquisition	
107228	Excavation Unit	Unit 3.2 STR08 LEV10 90-100cm MXH252		MXH252	Feature 6 Organic Fill	1	bone	fragment	Fauna	bone	mammal	0	Not Assigned	
107231	Excavation Unit	Unit 3.2 STR08 LEV10 90-100cm MXH252		MXH252	Feature 6 Organic Fill	2	bone	fragment	Fauna	bone	mammal	0	Not Assigned	
107212	Excavation Unit	Unit 3.2 STR08 LEV10 90-100cm MXH252		MXH252	Feature 6 Organic Fill	5	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
107222	Excavation Unit	Unit 3.2 STR08 LEV10 90-100cm MXH252		MXH252	Feature 6 Organic Fill	11	bone	fragment	Fauna	bone	mammal	food/beverage	acquisition	
107236	Excavation Unit	Unit 3.2 STR08 LEV10 90-100cm MXH252		MXH252	Feature 6 Organic Fill	2	shell, eggs	fragment	Fauna	shell, egg	bird	food/beverage	acquisition	
107221	Excavation Unit	Unit 3.2 STR08 LEV10 90-100cm MXH252		MXH252	Feature 6 Organic Fill	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua

Artifact Lot ID	Unit Type	Unit Name	FeatureNumber	AltDesignation	Strata Function	Count	Object	Part	material	sub material	sub sub material	Function	sub-function	Comments
107225	Excavation Unit	Unit 3.2 STR08 LEV10 90-100cm MXH252		MXH252	Feature 6 Organic Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Aqua
107219	Excavation Unit	Unit 3.2 STR08 LEV10 90-100cm MXH252		MXH252	Feature 6 Organic Fill	8	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Clear
107234	Excavation Unit	Unit 3.2 STR08 LEV10 90-100cm MXH252		MXH252	Feature 6 Organic Fill	1	bottle, indeterminate	body	Glass	indeterminate	indeterminate	food/beverage	storage	-Green (olive)
107230	Excavation Unit	Unit 3.2 STR08 LEV10 90-100cm MXH252		MXH252	Feature 6 Organic Fill	1	bottle, indeterminate	base	Glass	indeterminate	indeterminate	food/beverage	storage	-Milk Glass/Blue
107233	Excavation Unit	Unit 3.2 STR08 LEV10 90-100cm MXH252		MXH252	Feature 6 Organic Fill	1	bottle, indeterminate	body	Glass	mold blown	indeterminate	food/beverage	storage	-Aqua
107235	Excavation Unit	Unit 3.2 STR08 LEV10 90-100cm MXH252		MXH252	Feature 6 Organic Fill	1	bottle, indeterminate	body	Glass	mold blown	indeterminate	food/beverage	storage	-Clear
107204	Excavation Unit	Unit 3.2 STR08 LEV10 90-100cm MXH252		MXH252	Feature 6 Organic Fill	3	drinking glass, tumbler	rim	Glass	molded	molded	food/beverage	service	-Clear
107205	Excavation Unit	Unit 3.2 STR08 LEV10 90-100cm MXH252		MXH252	Feature 6 Organic Fill	1	drinking glass, tumbler	base	Glass	molded	molded	food/beverage	service	-Clear
107220	Excavation Unit	Unit 3.2 STR08 LEV10 90-100cm MXH252		MXH252	Feature 6 Organic Fill	3	drinking glass, tumbler	body	Glass	molded	molded	food/beverage	service	-Clear
107224	Excavation Unit	Unit 3.2 STR08 LEV10 90-100cm MXH252		MXH252	Feature 6 Organic Fill	2	drinking glass, tumbler	rim	Glass	molded	molded	food/beverage	service	-Clear
107203	Excavation Unit	Unit 3.2 STR08 LEV10 90-100cm MXH252		MXH252	Feature 6 Organic Fill	1	bottle, ink	whole/intact	Glass	molded	molded	medical/chemical	storage	-Clear-rectangular, flat panels
107210	Excavation Unit	Unit 3.2 STR08 LEV10 90-100cm MXH252		MXH252	Feature 6 Organic Fill	20	unidentified	fragment	Metal	copper alloy	Not Assigned	0	Not Assigned	
107208	Excavation Unit	Unit 3.2 STR08 LEV10 90-100cm MXH252		MXH252	Feature 6 Organic Fill	2	strap	fragment	Metal	ferrous	unidentified	0	Not Assigned	
107207	Excavation Unit	Unit 3.2 STR08 LEV10 90-100cm MXH252		MXH252	Feature 6 Organic Fill	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
107211	Excavation Unit	Unit 3.2 STR08 LEV10 90-100cm MXH252		MXH252	Feature 6 Organic Fill	5	slag, coal	fragment	Mineral	Coal	slag	heating, plumbing, electric	fuel	
107232	Excavation Unit	Unit 3.2 STR08 LEV10 90-100cm MXH252		MXH252	Feature 6 Organic Fill	2	unidentified	fragment	Synthetic	synthetic	indeterminate	0	Not Assigned	
107627	Excavation Unit	Unit 3.2 STR09 LEV10 90-100cm MXH253		MXH253	Feature 6 Organic Fill	1	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
107626	Excavation Unit	Unit 3.2 STR09 LEV10 90-100cm MXH253		MXH253	Feature 6 Organic Fill	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
107588	Excavation Unit	Unit 3.2 STR09 LEV11 100-103cm MXH254		MXH254	Feature 6 Organic Fill	2	brick	fragment	Ceramic	Brick	Standard American	architecture	general construction	
107590	Excavation Unit	Unit 3.2 STR09 LEV11 100-103cm MXH254		MXH254	Feature 6 Organic Fill	1	vessel, hollow	rim	Ceramic	Earthenware, refined	Rockingham-type	food/beverage	service	
107577	Excavation Unit	Unit 3.2 STR09 LEV11 100-103cm MXH254		MXH254	Feature 6 Organic Fill	1	tooth	whole/intact	Ceramic	Porcelain	Plain	personal	other personal possession	
107587	Excavation Unit	Unit 3.2 STR09 LEV11 100-103cm MXH254		MXH254	Feature 6 Organic Fill	1	rivet	fragment	Composite Artifact	composite artifact	composite artifact	0	Not Assigned	
107585	Excavation Unit	Unit 3.2 STR09 LEV11 100-103cm MXH254		MXH254	Feature 6 Organic Fill	5	bone	fragment	Fauna	bone	bird	food/beverage	acquisition	
107591	Excavation Unit	Unit 3.2 STR09 LEV11 100-103cm MXH254		MXH254	Feature 6 Organic Fill	2	shell, eggg	fragment	Fauna	shell, egg	bird	food/beverage	acquisition	
107581	Excavation Unit	Unit 3.2 STR09 LEV11 100-103cm MXH254		MXH254	Feature 6 Organic Fill	2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Aqua
107583	Excavation Unit	Unit 3.2 STR09 LEV11 100-103cm MXH254		MXH254	Feature 6 Organic Fill	2	window glass, flat	fragment	Glass	flat	flat	architecture	window	-Clear
107589	Excavation Unit	Unit 3.2 STR09 LEV11 100-103cm MXH254		MXH254	Feature 6 Organic Fill	1	lamp, glass fragment	fragment	Glass	indeterminate	indeterminate		Not Assigned	-Clear
107584	Excavation Unit	Unit 3.2 STR09 LEV11 100-103cm MXH254		MXH254	Feature 6 Organic Fill	1	rivet	fragment	Metal	copper alloy	copper alloy		Not Assigned	
107582	Excavation Unit	Unit 3.2 STR09 LEV11 100-103cm MXH254		MXH254	Feature 6 Organic Fill	3	nail, cut	fragment	Metal	ferrous	cut	architecture	general construction	
107578	Excavation Unit	Unit 3.2 STR09 LEV11 100-103cm MXH254		MXH254	Feature 6 Organic Fill	1	unidentified	fragment	Metal	ferrous	unidentified	0	Not Assigned	
107579	Excavation Unit	Unit 3.2 STR09 LEV11 100-103cm MXH254		MXH254	Feature 6 Organic Fill	3	unidentified	fragment	Metal	ferrous	unidentified	0	Not Assigned	
107586	Excavation Unit	Unit 3.2 STR09 LEV11 100-103cm MXH254		MXH254	Feature 6 Organic Fill	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
107592	Excavation Unit	Unit 3.2 STR09 LEV11 100-103cm MXH254		MXH254	Feature 6 Organic Fill	1	Coal	fragment	Mineral	Coal	Not Assigned	heating, plumbing, electric	fuel	
107580	Excavation Unit	Unit 3.2 STR09 LEV11 100-103cm MXH254		MXH254	Feature 6 Organic Fill	2	mortar	fragment	Mineral	composite	mortar	architecture	general construction	