




South End Landmarks Application

Window Replacement, Railing and Decks



Carl and Michelle Hediger
Hediger Homes, LLC.

85 Chandler Street
Boston, MA 02116



Replace existing 1 over 1 clad and vinyl windows , to conform with Landmarks 2/2 wood exterior black windows.



Replace existing wrought iron railing to more closely resemble original wrought iron railing pictured here in 1941.






Build new roof deck with full access stair case per architectural plans. Deck to be oriented on the back 2/3 of the roof to keep out of view from street level.

Rear roof deck to be added on existing roof, full walk out with no sightlines from any public way.

Two existing lower decks to be reduced in size. No sightlines from any public way.



Rear Deck Sightlines



Holding camera up over 6 foot fence, looking through private yard and walkway

Looking down private walkway

Site A


Site B

Site C

Site D

Site E

Site F



Site A



Site B



Site C



Site D



Site E



Site F

