

Rich Atkins 511 Beacon St #10 Boston MA 02215

Remove and replace a total of one existing two-wide casement window. Existing casement window is made of metal with a white exterior.

JB Sash to replace existing casement with two double hung windows with a wood exterior, painted white

Rear Elevation Floor 5 – Remove one 2-wide metal casement window and replace with one 2-wide double hung window, painted white to match building.

Rich Atkins 511 Beacon St #10 Boston MA 02215



FRONT ELEVATION

Rich Atkins 511 Beacon St #10 Boston MA 02215



WINDOW 1 INTERIOR

Rich Atkins 511 Beacon St #10 Boston MA 02215



WINDOW 1 INTERIOR

Rich Atkins 511 Beacon St #10 Boston MA 02215



BROKEN PANE ON WINDOW 1

Rich Atkins 511 Beacon St #10 Boston MA 02215




REAR ELEVATION

Rich Atkins 511 Beacon St #10 Boston MA 02215



REAR ELEVATION – CLOSE UP OF THE ONE WINDOW TO
BE REPLACED

Rich Atkins 511 Beacon St #10 Boston MA 02215



SPECIFICATIONS

Product Line: Ultimate Wood
Unit Description: Marvin Assembly

2 WIDE MARVIN ULTIMATE

SCALE: 3/4" = 1'-0"

$\frac{1}{2}$ Head
 $\frac{4}{2}$ Sill

$\frac{2}{2}$ Jamb
 $\frac{5}{2}$ Checkrail

$\frac{3}{2}$ Vertical Mullion