


Agenda

- Recap
- 100% Design Development Review
 - Portico Vestibule
 - Exterior Elevation & Material Update
 - Lighting Scheme
 - Technical Update
- Discussion


Recap Apr 2016 - Section and Elevation at Shattuck St.



Recap Apr 2016 - Proposed Window Details




AXON - NTS




WINDOW HEAD

INSIDE



WINDOW JAMB





EXISITING WINDOW




HISTORICAL WINDOW





Recap Apr 2016 - Proposed Door Details












DOOR SILL




EXISTING DOOR




DOOR ELEVATION



Recap Apr 2016 - Plan of Vestibule at Shattuck St.






EXISTING PLINTH



Recap Apr 2016 - Option 1 Location: Portico Vestibule



Interior of Portico Vestibule



Exterior Elevation Update




Exterior Lighting Scheme



Reassembly Technical Update

Development of technical details for reassembly in attempt to match original handling and disposition:

- Minimize refabrication of pieces
- Same or less loading/stress
- Similar handling back into place
- Mason design assist to follow
- Integration with modern exterior envelope
- A mass masonry veneer



Discussion

