

Present-Day Condition of Carriage House Rear Wall

(August 11, 2016)





Left: Carriage House rear door before repaving project



Right: Carriage House rear door after repaving project



Left: Carriage House rear door before repaving project

Right: Carriage House rear door after repaving



Left: Carriage House corner before repaving project with granite bollard and berm

Right: Carriage House corner after repaving with no granite bollard and berm



Left: Carriage House rear drainpipe before repaving project with granite block

Right: Carriage House rear drainpipe after repaving with no granite block

Views of Spruce Place from Spruce Street



Views down Spruce Place to Spruce Street

