

REAR OF 77 PINCKNEY ST, GROVE SQ.



EXISTING GARAGE DOOR (photo: Jan '15)



REAR OF 77 PINCKNEY ST, GROVE SQ.




REAR
OF
HOUSE
ENTRANCE
GARDEN
APT
ENTRANCE




OPENING WHERE NEW GARAGE DOOR
IS NEEDED; EXISTING TOO RISKY TO CLOSE

REAR OF 77 PINCKNEY, GROVE SQUARE




SCREWS NO LONGER BITING
BECAUSE WOOD IS TOO ROTTEN

REAR OF 77 PICKNEY ST, GROVE SQUARE



WOOD GNAWED BY RATS
(DAMAGED: SUMMER 2016)

REAR OF 77 PINCKNEY, GROVE SQUARE



WOOD ROTTED BY WATER



WOOD GNAWED BY RATS


Proposed replacement garage door for
REAR OF 77 PINKNEY, GROVE SQUARE 02114



WAYNE-DALTON, A DIVISION OF
OVERHEAD DOOR CORPORATION

RESIDENTIAL DEPICTION DRAWING

FOR MORE INFO VISIT WWW.WAYNE-DALTON.COM
THANK YOU FOR YOUR PARTNERSHIP WITH
WAYNE-DALTON



8' X 6' - 6" MODEL 9700 CHARLESTON DESIGN
SOLID SQUARE TOP

WAYNE-DALTON, A DIVISION OF OVERHEAD DOOR CORPORATION
CONFIDENTIAL PROPRIETARY. NOT TO BE DUPLICATED OR REPRINTED.
THE INTENT OF THIS DRAWING IS TO SHOW BASIC APPEARANCE AND
NOT EXACT DETAILS. DOORS MUST BE INSTALLED IN STRICT
ACCORDANCE WITH WAYNE-DALTON INSTALLATION INSTRUCTIONS.
WAYNE-DALTON RECOMMENDS INSTALLATION BY YOUR WAYNE-DALTON
DEALER.