
5 CLAREMONT PARK BOSTON, MASSACHUSETTS DJ WATSON DEVELOPMENT


SELDC

JUNE 13, 2017










5 CLAREMONT PARK

AERIAL VIEW

BIRD'S EYE VIEW



5 CLAREMONT PARK



SITE LOCATION

5 CLAREMONT PARK BOSTON, MASSACHUSETTS

06/1317 |



CLAREMONT PARK FACING NORTH



FRONT ELEVATION | 5 CLAREMONT PARK

CLAREMONT PARK FACING SOUTH





SITE CONTEXT

5 CLAREMONT PARK BOSTON, MASSACHUSETTS

0

06/13/17 |



REAR ALLEY FACING NORTH



CURRENT CONDITION OF REAR ELEVATION - 5 CLAREMONT PARK







3

06/13/17



EXISTING FIRST FLOOR WINDOW GRILLES TO BE REMOVED



EXISTING DOOR TO BE REPAIRED AND RESTORED STOOP TO BE REPAIRED AND RESTORED






EXISTING METAL GARDEN RAIL TO BE REPAIRED AND REPAINTED BLACK

EXISTING CONDITIONS

5 CLAREMONT PARK BOSTON, MASSACHUSETTS



06/13/17 |



A R C H I T E C T U R E + D E S I G N

REPAIR AND REPLACE EXISTING CLAPBOARD SIDING, AS REQUIRED. REPAINT HC-69.

REPLACE EXISTING DECK DOOR WITH NEW WOOD AND GLASS DOOR.

REPAIR AND RESTORE EXISTING BROWNSTONE DECORATION, AS REQUIRED.

REPAIR AND RESTORE EXISTING STOOP AND BROWNSTONE, AS REQUIRED.

SITE PLAN AND FRONT ELEVATION

5

5 CLAREMONT PARK BOSTON, MASSACHUSETTS



WINDOW WELL AT 3 CLAREMONT PARK



WINDOW WELL AT 2 CLAREMONT PARK






WINDOW WELL WITH WINDOW EXPOSED ABOVE GRATE AT 1 CLAREMONT PARK

WINDOW WELL PRECEDENTS 5 CLAREMONT PARK BOSTON, MASSACHUSETTS



06/09/17






PROPOSED WINDOW WELLS

5 CLAREMONT PARK BOSTON, MASSACHUSETTS 7

06/13/17 |




ARCHITECTURE+DESIGN

REAR ELEVATION

5 CLAREMONT PARK BOSTON, MASSACHUSETTS



06/13/17 |



copyright: EMBARC Studio, IIc.| 6/13/2017 2:59:40 PM | C:\Users\kwidulinski\Documents\16081_5 Claremont Park_Pricing Set_kwidulinski.rvt

ARCHITECTURE + DESIGN

ROOF DECK 5 CLAREMONT PARK BOSTON, MASSACHUSETTS



06/13/17 |