


# **Existing Condition Photos**



View from a vehicle exiting the garage

# **Existing Condition Photos**



View looking from across the plaza at exit of ramp and corner of building with Huntington Ave

# **Existing Condition Photos**



View looking at exit from the plaza

# Representative Photos other Pedestrian Safety Bollards on the Plaza





#### Bollard Spec – in Anodized Silver to match other bollards on site

