

Anthony W. Macchi a r c h i t e c t

42 Beacon Street Gloucester, MA. 01930 c. 617-688-1528 e. awmacchi@gmail.com

2 Worthington Street - Boston, MA.2 Worthington Street LLC Commision Hearing Existing Front Elevation and Details Landsmarks



Existing Soffit Details



Discolored Existing Masonry Detail



Discolored Existing Masonry



Existing Front Elevation



Existing Front Entry Stairs



2 Worthington Street - Front Entry Sample



2 Worthington Street - Stair Detail Sample | Proposed Marble Entry Stair Sample



Proposed Mansard Slate Pattern



7" Wide Poured Concrete Closed Stringer Coated to Match Front Elevation Stone





3/16" = 1'-0"

11/12/19

Date

Anthony W. Macchi architect

42 Beacon Street Gloucester, MA. 01930 c. 617-688-1528 e. awmacchi@gmail.com

Boston, MA Commision Hearing Street LLC Front Elevation Proposed Details Street Worthington Worthington Landsmarks

4 of 7

Typical Meeting Rail Interior



Typical Window Sill Interior



Exterior Muntin from Interior



Typical Window Sill Exterior



Typical Meeting Rail Exterior



Typical 2/2 Window Elevation



Typical 1/1 Window Elevation

11/12/19

Anthony W. Macchi a r c h i t e c t


Date

42 Beacon Street Gloucester, MA. 01930 c. 617-688-1528 e. awmacchi@gmail.com

2 Worthington Street - Boston, MA.2 Worthington Street LLCLandsmarks Commision Hearing

Existing Window Conditions

5 of 7



Date

Anthony W. Macchi a r c h i t e c t

42 Beacon Street Gloucester, MA. 01930 c. 617-688-1528

e. awmacchi@gmail.com

Boston, MA Landsmarks Commision Hearing Street LLC Street Worthington


Proposed Window Well Worthington 2 2


MIN. 3'X3' FLAT SURFACE AT WINDOW WELL.

7 of 7



Previously constructed window well 9 Wigglesworth





Bedroom Egress Window Well 1/2" = 1'-0"