

Boston Landmarks Commission Presentation

Location: 31 Milford St, Boston MA

Date: 12/7/21

Security Materials

Scope	Location	Description
Overview	Front Facade	The residents of 31 Milford St are intersted in installing two small security cameras that are common in the area.
		The request for two cameras is due to range of view. Their locations have been proposed by a security professional with a reputable alarm company that services many residences in Boston. With an eye for helping make the second (lower) camera disappear it has been located in a shadowy area almost near ground level that would make it difficult to notice but clear to anyone descending the steps to below the stoop. The upper camera would have a clear view of all activity on the front steps as well as the gate at which the family locks their bike(s) regularly, both in the daytime and in the nighttime. The cameras will be painted to match the gray mortar between the bricks, helping them disappear into their surroundings.
		 Recent attempted break in (photos) and general concern over criminal activity in the immediate area Two young children in the home that often commute by foot to local activities Inability to put quality cameras inside the home to view the exterior through a window Multiple bikes stolen and attempts on current bike Regular absence from the home leaving it unattended for up to 1 or more weeks at a time.

Two (2) Vivotek IT9360-H security cameras (painted to match mortar)







