

Padraig Smith

Red Sky Construction

Feb 24, 2026 | 44 Photos

101 Myrtle Windows



101 Myrtle Window Report




101 Myrtle St Front View

Project: 101 Myrtle Window Report
Date: Nov 6, 2025, 3:38 PM
Creator: Padraig Smith



Window key


Project: 101 Myrtle Window Report
Date: Nov 6, 2025, 3:38 PM
Creator: Padraig Smith



Customized Marvin Casement Shop Drawing.

- Full units
- Brick prep frames
- Historic sills
- Exterior painted black
- True Divided light. 1 1/2 bars. Light cut 1 wide, 4 high per sash
- Single glass


Project: Myrtle Windows
Date: Mar 11, 2026, 8:36 AM
Creator: Padraig Smith



Detailing for Customized Marvin Casements

Project: Myrtle Windows
Date: Mar 11, 2026, 8:36 AM
Creator: Padraig Smith

5



JB Sash Proper Bostonian Single Hung windows.

- Full units
- Brick frames
- Historic sills
- Exterior painted black
- True Divided light, 2/2 vertical. Insulated Glass


Project: Myrtle Windows
 Date: Mar 11, 2026, 8:36 AM
 Creator: Padraig Smith

6



Replacement basement windows to receive leading treatment from local leading company in order to match existing.

Project: 101 Myrtle Window Report
 Date: Feb 23, 2026, 10:13 AM
 Creator: Padraig Smith




Glass repaired with glue in multiple locations

Project: 101 Myrtle Window Report
Date: Feb 23, 2026, 10:13 AM
Creator: Padraig Smith



Glass repaired with glue in multiple locations

Project: 101 Myrtle Window Report
Date: Feb 23, 2026, 10:13 AM
Creator: Padraig Smith




Glass repaired with glue in multiple locations

Project: 101 Myrtle Window Report
Date: Feb 23, 2026, 10:13 AM
Creator: Padraig Smith



Project: 101 Myrtle Window Report
Date: Feb 23, 2026, 10:14 AM
Creator: Padraig Smith



Current window 3 interior. Window does not close so resident has sealed off window.

Project: 101 Myrtle Window Report
Date: Feb 23, 2026, 10:19 AM
Creator: Padraig Smith



Deteriorated muntin bars

Project: 101 Myrtle Window Report
Date: Nov 20, 2025, 11:59 AM
Creator: Padraig Smith




Deteriorated window sash & frame

Project: 101 Myrtle Window Report
Date: Jan 16, 2026, 7:24 AM
Creator: Padraig Smith



Current window 4 interior. Window does not close so resident has sealed off window.


Project: 101 Myrtle Window Report
Date: Feb 23, 2026, 10:19 AM
Creator: Padraig Smith



15

Deteriorated muntin bars

Project: 101 Myrtle Window Report
Date: Nov 20, 2025, 11:59 AM
Creator: Padraig Smith



16

Deteriorated window sash & frame

Project: 101 Myrtle Window Report
Date: Nov 20, 2025, 11:43 AM
Creator: Padraig Smith


17

Deteriorated window sash & frame




Project: 101 Myrtle Window Report
Date: Nov 20, 2025, 11:43 AM
Creator: Padraig Smith


18



Project: 101 Myrtle Window Report
Date: Feb 23, 2026, 10:22 AM
Creator: Padraig Smith




Project: 101 Myrtle Window Report
Date: Feb 23, 2026, 10:22 AM
Creator: Padraig Smith



Window 6 detailing

Project: 101 Myrtle Window Report
Date: Feb 23, 2026, 10:24 AM
Creator: Padraig Smith




Window 6 detailing

Project: 101 Myrtle Window Report
Date: Feb 23, 2026, 10:24 AM
Creator: Padraig Smith



Window 6 detailing

Project: 101 Myrtle Window Report
Date: Feb 23, 2026, 10:24 AM
Creator: Padraig Smith



Project: 101 Myrtle Window Report
Date: Feb 23, 2026, 10:22 AM
Creator: Padraig Smith



Project: 101 Myrtle Window Report
Date: Jan 16, 2026, 7:38 AM
Creator: Padraig Smith


Deteriorated sill as is consistent across all windows

25



Project: 101 Myrtle Window Report
Date: Nov 20, 2025, 12:04 PM
Creator: Padraig Smith

26



Project: 101 Myrtle Window Report
Date: Feb 24, 2026, 10:08 AM
Creator: Padraig Smith


Deteriorated sill as is consistent across all windows

27



Project: 101 Myrtle Window Report
Date: Nov 20, 2025, 12:06 PM
Creator: Padraig Smith

28



Project: 101 Myrtle Window Report
Date: Feb 24, 2026, 10:08 AM
Creator: Padraig Smith

29



Project: 101 Myrtle Window Report
Date: Nov 20, 2025, 11:40 AM
Creator: Padraig Smith

30



Project: 101 Myrtle Window Report
Date: Nov 20, 2025, 11:41 AM
Creator: Padraig Smith

31




Deteriorated sill as is consistent across all windows

Project: 101 Myrtle Window Report
Date: Nov 20, 2025, 12:05 PM
Creator: Padraig Smith

32




Project: 101 Myrtle Window Report
Date: Feb 24, 2026, 10:08 AM
Creator: Padraig Smith



Window 10 detailing

Project: 101 Myrtle Window Report
Date: Feb 24, 2026, 10:09 AM
Creator: Padraig Smith




Window 10 detailing

Project: 101 Myrtle Window Report
Date: Feb 24, 2026, 10:09 AM
Creator: Padraig Smith



Project: 101 Myrtle Window Report
Date: Nov 20, 2025, 11:41 AM
Creator: Padraig Smith




Project: 101 Myrtle Window Report
Date: Nov 20, 2025, 11:41 AM
Creator: Padraig Smith



Deteriorated sill as is consistent across all windows


Project: 101 Myrtle Window Report
Date: Nov 20, 2025, 12:07 PM
Creator: Padraig Smith



Project: 101 Myrtle Window Report
Date: Feb 23, 2026, 10:28 AM
Creator: Padraig Smith



Project: 101 Myrtle Window Report
Date: Feb 23, 2026, 10:28 AM
Creator: Padraig Smith



Project: 101 Myrtle Window Report
Date: Feb 23, 2026, 10:28 AM
Creator: Padraig Smith



Project: 101 Myrtle Window Report
Date: Feb 23, 2026, 10:29 AM
Creator: Padraig Smith



Project: 101 Myrtle Window Report
Date: Feb 23, 2026, 10:29 AM
Creator: Padraig Smith

43


Replacement sash & deteriorated frame as is consistent across windows 11, 12, & 13



Project: Myrtle Windows
 Date: Nov 20, 2025, 11:38 AM
 Creator: Padraig Smith

44

Owner Signature Page



Project: Myrtle Windows
 Date: Mar 11, 2026, 8:38 AM
 Creator: Padraig Smith